Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

CICS - Irving Park 66074 **Building ID:** 4913 School: **Oracle Unit:** Address: 3820 N. Spaulding Region: Mail Room: Asbestos Surveyor: JTORRES214 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2018 Email Address: itorres@chicagointl.org A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Other Each child's backpack Notice printed in school's calendar Material Description HA No Material Material Location Asbestos Material Friable Damage Damage Change in Assessment Category Damage Quantity Units Type Category Type Quantity YES 01 Breaching/Exhaust Packing 150 SF 0 X NO Maintenance Hall TSI Yes None 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

02	MJP on Non-Suspect Fiberglass	500	LF	Boiler Rm, Pipe Chases, and Most Likely Concealed Behind Walls and Ceilings.		TSI	Yes	None	0		YES X NO
2017 - Fall	: No Change]						
Comments	:										
2018 - Fall	: No Change				-						
Comments	:]						
2018 - Spri	ing : No Change										
Comments	:										
					1						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	1'X1' Acoustical Tiles	25000	SF	Throughout Bldg (See Hatching Floor Plans)		Miscellaneous	Yes	None	0		YES X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08	Acoustical Plaster on Ceiling	3000	SF	Gym, Boiler Rm, Gym Storage		Surface	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2018 - Fall: N	lo Change											
Comments:	U											
2018 - Spring	ı : No Change											
Comments:	, o o											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09	Plaster	1200	SF	Mechanical Rm, Storages		Surface	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2018 - Fall: N	lo Change											
Comments:	io onango											
2019 Spring	: No Change											
Comments:	1. No Change											
2 2												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
10	Terrazzo	28000	SF	Throughout Bldg (See Hatchings Floor Plans)		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	•											
2018 - Spring	g : No Change											
Comments:	g · · · · · · · · · · · · · · · · · · ·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
11	12"x12" Gray VFT	2000	SF	Gym and Gym Storage		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change											
Comments:	3											
2018 - Fall: N	No Change											
Comments:	10 Onlango											
2019 Spring	a · No Chango											
Comments:	g : No Change											
Commonto.					-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
11A	12"x12" Gray VFT Mastic	2000	SF	Gym and Gym Storage		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	Ü											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
12	12"X12" Maroon VFT	600	SF	Gym		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:	Ü											
2018 - Spring	· No Change											
Comments:	THE CHANGE											
2018 - Fall: N	o Change											
Comments:	o onange											
]							

12A	12"X12" Maroon VFT Mastic	600	SF	Gym		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change				1							
Comments:					-							
2018 - Spring	g : No Change				-							
Comments:	•				1							
2018 - Fall: N	lo Change											
Comments:					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13	2'X4' White Ceiling Tiles	200	SF	North Entrance Vestibule		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:					1							
2018 - Spring	g : No Change											
Comments:	•				1							
2018 - Fall: N	lo Change				-							
Comments:		1										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

Material

Quantity

Material

Units

Material Location

14	Pipe Insulation (Non- Fiberglass)	1200	LF	Crawl Spaces	TSI	Yes	None	0	YES	X NO
2017 - Fall: N	lo Change									
2018 - Fall: N	lo Change									
2018 - Spring Comments:	g : No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	MJP on Pipe Insulation (Non-Fiberglass)	300	LF	Crawl Spaces		TSI	Yes	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

	16	12"x12" White w/ black and gray streaks VFT	1100	SF	rm 107 and offices next to room 107 main building		Miscellaneous	No	None	0	YES	X NO
	2017 - Fall: N	o Change]						
	Comments:											
	2018 - Spring	: No Change										
-	Comments:											
ľ	2018 - Fall: N	o Change										

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A	12"x12" white w/ black and gray streaks VFTMastic	1100	SF	rm 107 and offices next to rm 107- main bldg		Miscellaneous	No	None	0		YES X NO

2017 Fall: No Chango
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

17	12"x12" black w/ white streaks VFT	800	SF	gym storage/ office main building	Miscellaneous	No	None	0	YES	X NO
2017 - Fa	ill: No Change									
Commen	ts:									
	oring : No Change									
Commen	ts:									
	III: No Change									
Commen	ts:									

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	12"x12" black w/ white streaks VFTMastic	800	SF	gym storage/ officemain building		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	18"x18" off white w/ blue streaks VFT	2000	SF	kindergarten rooms annex 1 and 2, corridor annex building		Miscellaneous	No	None	0		YES X NO
2017 - Fall: N Comments:	lo Change										

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	18"x18" off white w/ blue streaks VFTMastic	2000	SF	kindergarten rooms annex 1 and 2, corridor annex building		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
19	18"x18" Red streaked VFT	700	SF	kindergarten rooms annex 1 and 2, corridor annex building		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N Comments:	lo Change											
2018 - Fall: N	lo Change											

					-						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	18"x18" Red streaked	700	SF	kindergarten rooms annex 1 and 2, corridor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

annex building

2018 - Spring : No Change

VFT--Mastic

Comments:

					, ·	0 ,		,,	,		<u> </u>	
20	18"x18" blue streaked VFT	100	SF	corridorannex building		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change]							
Comments:	<u> </u>											
2018 - Spring	: No Change											
Comments:					 							
2018 - Fall: N	o Change											
Comments:					1							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20A	18"x18" blue streaked VFTMastic	100	SF	corridorannex building		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2018 - Spring	: No Change				-							
Comments:												
2018 - Fall: N	2018 - Fall: No Change											
Comments:	Comments:											

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

21	18"x18" orange streaked VFT	100	SF	corridorannex building	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N Comments:	o Change									
2018 - Spring Comments:	: No Change									
2018 - Fall: N Comments:	o Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	18"x18" orange streaked VFTMastic	100	SF	corridorannex building		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change					
Comments:					
2018 - Spring : No Change					
Comments:					
2018 - Fall: No Change					
Comments:					

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
22	2'x4' ceiling tilewhite	150	SF	corridorannex building		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: N	No Change											
Comments:				-								
2018 - Fall: No Change				-								
Comments:												
2018 - Spring	a · No Change				-							
Comments:	2018 - Spring : No Change											
]							
LIA NIS	Material Decembring	Matarial	Matarial	Matarial Lagation	Ashastas	Matarial	Tuiable.	D	Damana	Domese	Change in Asse	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
23	drywall system	2500	SF	throughout annex building		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: No Change				1								
Comments:												
2018 - Fall: No Change				-								
Comments:												
	0040 O				1							
2018 - Spring : No Change				-								
Comments:				-								

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: CICS - Irving Park
Date: 12/18/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.