Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

66075

Oracle Unit:

CICS - Loomis Primary

School:

Address: 9535 South Loomis Street Region: Mail Room: Asbestos Surveyor: JTORRES214 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2018 Email Address: itorres@chicagointl.org A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Type Category Quantity Type Throughout Building with YES X NO 12"x12" Light Brown Mix the exception of the 01 37800 SF Miscellaneous No None 0 Floor Tile Patterns washrooms, kitchen and mechanical rooms 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

4914

Building ID:

						<u> </u>						
02	Adhesive Associated with 12"x12" Light Brown Mix Floor Tile w/Blue and Orange Tile Patterns	37800	SF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change				1							
Comments:	<u> </u>]							
2018 - Fall:	No Change				1							
Comments:												
2018 - Sprin	ng : No Change				_							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
03	4" Light Brown Baseboard	3800	LF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change				1							
Comments:]							
2018 - Fall:	No Change				-							
Comments:	<u> </u>				1							
					1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

2018 - Spring : No Change

Comments:

Material

Quantity

Material

Units

Material Location

Page 2

04	4" Light Brown Baseboard Adhesive	3800	LF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms		Miscellaneous	No	None	0		YES X	NO
2017 - Fa	ıll: No Change				7							
Comment	· ·				1							
2018 - Fa	III: No Change				=							
Comment	ts:											
2018 - Sp	oring : No Change				_							
Comment	ts:											
					٦							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment (Category
05	2'x4' Lay In Ceiling Panels	40472	SF	Throughout Building with the Exception of Mechanical Areas		Miscellaneous	Yes	None	0		YES X	NO
2017 - Fa	ıll: No Change				7							
Comment												
2018 - Fa	ıll: No Change			·	=							
2010-1 a	III. INO CHAINGE				4							

Category

Asbestos

Type

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

2018 - Spring : No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
06	Brown and Black Carpet Adhesive	1080	SF	Library		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2018 - Fall: N	lo Change											
Comments:	J											
2018 - Spring	ı · No Change											
Comments:	,											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
07	Ceramic Floor Tile Grout	2672	SF	Washrooms Throughout Building		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change				7							
Comments:												
2018 - Fall: N	lo Change											
Comments:	o Change											
	. No Change											
2018 - Spring Comments:	i : No Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
08	Ceramic Floor Tile Adhesive	2672	SF	Washrooms Throughout Building		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change]							
Comments:												
2018 - Fall: N	No Change				-							
Comments:	•											
2018 - Spring	g : No Change				1							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
09	Terrazzo	1100	SF	Stairways and First Floor Hall		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change				1							
Comments:	· ·											
2018 - Fall: N	No Change				_							
Comments:	To Change											
2018 - Spring	g : No Change				1							
Comments:	g . 140 Change				-							

10	Whiteboard Adhesive	2200	SF	Classrooms		Miscellaneous	No	None	0	YES	X NO
2017 - Fall:	No Change										
Comments:					-						
2018 - Fall:	No Change										
Comments:					1						
	g : No Change										
Comments:											
					J						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12 x 12 VFT Purple Mixed Speckled	600	SF	Rms. 309, 212, 201, 122, 113 and 100. 3rd, 2nd, and 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO
					1						

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12 x 12 VFT Orange Mixed Speckled	1050	SF	3rd, 2nd, 1st Floor Corridor Rm 095 and LunchRoom		Miscellaneous	No	None	0		YES X NO
	-	•	•	•	1	•	•	•	•	•	•

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12M	12 x 12 Purple Mixed Speckled Mastic	600	SF	Rms 309, 212, 201, 122, 113 and 100. 3rd, 2nd and 1st Flr Corridor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12 x 12 Mastic Orange Mixed Speckled	1050	SF	3rd, 2nd, 1st Floor Corridor Rm 095 and Lunchroom		Miscellaneous	No	None	0		YES X NO
0045 5 11 11		•	•		1	•	•	•	•	•	•

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12 x 12 VFT Blue Mixed Speckled	350	SF	Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Page 8

15	12 x 12 Mastic Blue Mixed Speckled	350	SF	Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Type	Damage Quantity	Units Units	Change in Assessment Category

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12 x 12 VFT Red Mixed Speckled	600	SF	Rm. 128, 305, 208, 118, 115, 096 and 3rd, 2nd, 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

17	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
1st Floor Corridor	17	12 x 12 Mastic Red Mixed Speckled	600	SF			Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12 X 12 VFT Green Mixed Speckled	600	SF	Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19		12 x 12 Green Mixed Speckled Mastic	600	SF	Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO
004	47 F.U.N.	. 01	•	•	•	1	•	•	•	•	•	•

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12 x 12 VFT Yellow Mixed Speckled	600	SF	Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Assessment Category
21	12 x 12 Mastic Yellow Mixed Speckled	600	SF	Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor		Miscellaneous	No	None	0		YES X NO
2017 - Fall:	No Change	-	•	· · · · · · · · · · · · · · · · · · ·]	•					

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12 x 12 VFT Tan Mixed Speckled	2100	SF	Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

F
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

23	12 x 12 Mastic Tan Mixed Speckled	2100	SF	Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor	Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change		•	•	•	•	•	•	•	•	
Comments:	-										
2018 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	2 x 2 CT White	5000	SF	3rd, 2nd, 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
25	Carpet Mastic	700	SF	Rm 110		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change											
2018 - Fall: N	No Change											
	g : No Change											
Comments:	g . 140 Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
26	2 x 4 CT Smooth White	500	SF	Kitchen		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change	•						•				
Comments:												
2018 - Fall: N	No Change											
Comments:	Comments:											
2018 - Spring	2018 - Spring : No Change											
Comments:												

		Quantity	Units		Type	Category		Type	Quantity	Units		
29	Exterior Window Caulk	2000	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2018 - Fall: I	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
MCA	Metal Pan Ceiling - REMOVED			Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												

Asbestos

Damage

Friable

Damage

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u> </u>	
МСВ	Metal Pan Ceiling - REMOVED			Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Fall: N	No Change											
Comments:	-											
2018 - Spring	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MCC	1'x1' Fissured Ceiling Tile and Mastic	23000	SF	Throughout Building		Miscellaneous	No	None			YES	X NO
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	-											

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

		Quantity	Units		Type	Category		Type	Quantity	Units		
MFA	9"x9" Floor Tile - ABATED		SF	Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
MFB	12"x12" Floor Tile - ABATED		SF	Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : No Change											
Comments:	-											

Asbestos

Damage

Friable

Damage

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
MM1	Baseboard Mastic - ABATED		LF	Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall: N	lo Change											
Comments.												
2018 - Spring	g : No Change											
Comments:												
2010 Falls N	la Changa											
2018 - Fall: N	io Change				_							
Comments.					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
MMA	9"x9" Floor Tile Mastic - ABATED		SF	Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall: N	lo Change											
Comments:	J											
0040 5 11 1	. 01											
2018 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
MMB	12"x12" Floor Tile Mastic - ABATED		SF	Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall: N	lo Change											
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	; No Change											
Comments:	· ·											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
TIATO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Onange in Asset	33mem Category
MMB (1)	Blackboards - ABATED		SF	Classrooms		Miscellaneous	No				YES	X NO
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Fall: N	lo Chango											
Comments:	io Change											
	j : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
ММС	Residual Mastic - ABATED		SF	Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall: N Comments:	o Change											
2018 - Fall: N	o Change											
Comments:												
2018 - Spring Comments:	: No Change											
Commonto.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
MMD	Black Baseboard (Removed)			Throughout Building		Miscellaneous					YES	X NO
2017 - Fall: N Comments:	o Change											
2018 - Fall: N	o Change											
Comments:												
2018 - Spring Comments:	: No Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MME	Black Baseboard Adhesive (Removed)			Throughout Facility							YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	; No Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MMF	Gray Baseboard - Removed			Throughout Building		Miscellaneous					YES	X NO
2017 - Fall: N	lo Change											
Comments:	, and the second											
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	ı : No Change											
Comments:	. Ho onango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MMG	Gray Baseboard Adhesive - Removed			Throughout Building		Miscellaneous					YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	.											
2018 - Fall: N	lo Chango				_							
Comments:	io Change											
Goriii i i i i i i i i i i i i i i i i i												
	T	_								_		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
ММН	Brown Baseboard - ABATED		LF	Throughout Building		Miscellaneous					YES	X NO
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Fall: N	lo Chango											
Comments:	io Change											
	g : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MMJ	Beige Baseboard - Removed			Throughout Facility		Miscellaneous					YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MMK	Beige Baseboard Adhesive - Removed			Throughout Building		Miscellaneous					YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	ј : No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MML	Terrazzo Mastic - ABATED			Stairways		Miscellaneous					YES	X NO
2017 - Fall: N	lo Change				\exists							
Comments.												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	g . No Change											
осинистко.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MMM	Vibration Dampers	15	SF	Mechanical Room		Miscellaneous		None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
0040 Craria	. Na Ohaana											
Comments:	g : No Change											
Comments.												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MMN	Terrazzo - ABATED			Stairways		Miscellaneous					YES	X NO
2017 - Fall: N Comments:	lo Change											
Comments.												
2018 - Spring	: No Change											
Comments:												
2010 Fall N	la Changa											
2018 - Fall: N Comments:	lo Change											
Comments.												
												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
ММО	Brown Carpet Adhesive - Removed			Throughout Building		Miscellaneous					YES	X NO
2017 - Fall: N	lo Change											
Comments:	io oriango											
	ı : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
MMQ	Soundproof Panels - ABATED					Miscellaneous					YES	X NO
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
	g : No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
MMS (1)	Insulation in Fire Doors	288	SF	Entrances		TSI	Yes	None	0		YES	X NO
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
MMT	Floor Filler	23000	SF	Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall: N Comments: 2018 - Fall: N												
Comments:												
	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
MMU	Elevator Brake Shoes	10	SF	Ground Floor		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N Comments: 2018 - Fall: N Comments:	•											

		Quantity	Units		Type	Category		Type	Quantity	Units	•	
MMV	Incinerator Bricks	50	SF	Incinerator		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Fall: N	No Change											
Comments:												
	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
MMV (1)	Fire Brick in Boilers	200	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
	g : No Change											
Comments:	<u> </u>											

Asbestos

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
MXA	Drywall	46000	SF	Throughout Building		Miscellaneous	No				YES	X NO
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
MXB	Drywall Compound	12000	SF	Throughout Building		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	-											

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
SFA	Soundproofing	40000	SF	Throughout Building		Surface	Yes	None			YES	X NO
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
	ng : No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
SPA	Wall Plaster	23000	SF	Throughout Building		Surface	No	None	0		YES	X NO
2017 - Fall:	No Change											
Comments:												
	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:					_							

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
SPB	Ceiling Plaster	38000	SF	Throughout Building		Surface	No	None	0		YES	X NO
2017 - Fall: N	No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
	g : No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
SPC	Popcorn Ceiling - ABATED		SF	Chapel		Surface	No				YES	X NO
2017 - Fall: N	No Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:					_							
L												

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

		Quantity	Units		Type	Category		Type	Quantity	Units		
SPC (1)	Popcorn Ceiling - ABATED			Chapel		Miscellaneous					YES	X NO
2017 - Fall: I	No Change											
Comments:					_							
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
ТВА	Insulation on East Boiler	250	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2017 - Fall: I	No Change											
Comments:	-											
2018 - Fall: I	No Change											
Comments:	Ü											
2018 - Sprin	g : No Change											
Comments:	g : 110 Chango											

Asbestos

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
ТВВ	Insulation on West Boiler	250	SF	Boiler Room		TSI	Yes	Loc	10		YES	X NO
2017 - Fall: N Comments:	o Change]							
2018 - Fall: N	o Change											
Comments:	: No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
TGA	Boiler Gaskets	50	LF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
	: No Change				_							
Comments:	. No Change				_							
2018 - Fall: N	o Change				-							
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
TJA	Joint Insulation on Fiberglass Insulated Domestic Water Pipes	10	LF	Boiler Room and Tunnel from Aquinus Building		TSI	Yes	None	0		YES X NO
		•	•	-	i	•	•	•		•	_

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
TJB	Joint Insulation on Fiberglass Insulated Mechanical Pipes	22	LF	Boiler Room, Mechanical Room and Tunnel from Aquinus Building		Miscellaneous	Yes	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 34

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
TJC	Black Tar Wrap	25	LF	Boiler Room		TSI	No	None	0		YES	X NO
2017 - Fall: N Comments:	lo Change											
2018 - Fall: N Comments:	lo Change											
2018 - Spring Comments:	j : No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
TJD	White Tar Wrap	40	SF	Boiler Room		TSI	No	None	0		YES	X NO
2017 - Fall: N Comments: 2018 - Spring Comments: 2018 - Fall: N Comments:	j : No Change											

TPA Fiberglass Pipe Insulation on Domestic Water Pipes 450 LF Throughout Building Including: Boiler Room, Mechanical Room, Tunnel to Aquinus Building and Pipe Chases	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	ТРА		450	LF	Including: Boiler Room, Mechanical Room, Tunnel to Aquinus		TSI	Yes	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
ТРВ	Fiberglass Insulation on Mechanical Pipes	325	LF	Throughout Building Including: Boiler Room, Mechanical Room, Tunnel to Aquinus Building and Pipe Chases		TSI	Yes	None	0		YES X NO	

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
TTA	Insulation on Tank	150	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: No Change												
Comments:					_							
2018 - Spring	018 - Spring : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
TTD	Duct Insulation	500	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: No Change												
Comments:												
2018 - Spring : No Change												
Comments:												

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: CICS - Loomis Primary
Date: 12/18/2018
·
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.