Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

66076

Oracle Unit:

CICS - Lloyd Bond

School:

Address: 13300 S Langley Avenue Region: Mail Room: Asbestos Surveyor: JTORRES214 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2018 Email Address: itorres@chicagointl.org A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity 12 x 12 Beige and Grey S Hallway, and Rooms YES 01 SF 0 X NO 2000 Miscellaneous No None Floor Tile 101-108 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change Comments:

8049

Building ID:

											·	
01M	12 x 12 Beige and Grey Floor Tile Mastic	2000	SF	S Hallway, and Rooms 101-108		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	J											
2018 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
02	4" Brown Baseboard	250	LF	S Hallway, and Rooms 101-108		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change				7							
Comments:	J											
2018 - Fall: N	o Change				1							
Comments:												
2018 - Spring	: No Change				1							
Comments:												

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
02M	4" Brown Baseboard Mastic	250	LF	S Hallway, and Rooms 101-108		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change				1							
Comments:	-]							
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change				-							
Comments:	_											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
03	Drywall	75000	SF	Throughout Building		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: N	o Change				1							
Comments:	<u> </u>]							
2018 - Fall: N	o Change				1							
Comments:	J											
2018 - Spring	: No Change				_							
Comments:]							
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
04	Drywall Tape and Joint Compound	75000	SF	Throughout Building		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
05	12 x 12 Blue Floor Tile	50	SF	Hallways		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:												

HA No

05M	12 x 12 Blue Floor Tile Mastic	50	SF	Hallways		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2018 - Fall: N	lo Change				<u> </u>							
Comments:												
2018 - Spring	g : No Change				<u> </u>							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
06	12 x 12 Beige Pattern Floor Tile	30500	SF	Hallways and Classrooms		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	io onango											
2018 - Fall: N	lo Change				-							
Comments:	io change				-							
2018 - Spring	g : No Change											

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
06M	12 x 12 Beige Pattern Floor Tile Mastic	30500	SF	Hallways and Classrooms		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	<u> </u>											
2018 - Spring	: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
07	12 x 12 Orange Floor Tile	3500	SF	Hallways		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:	J											
2018 - Fall: N	o Change				_							
Comments:	o o nango											
2018 - Spring	· No Change				_							
Comments:	1. 140 Onlange				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
07M	12 x 12 Orange Floor Tile Mastic	3500	SF	Hallways		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:	•											
2018 - Spring	g : No Change				<u> </u>							
Comments:	, o o											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08	4" Cream Baseboard	550	LF	Throughout North Section of Building		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	to enange				-							
2019 Spring	x · No Chango]							
Comments:	g : No Change				-							
Commond.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08M	4" Cream Baseboard Mastic	550	LF	Throughout North Section of Building		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	_											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09	12 x 12 Green Floor Tile	25	SF	Hallways Classroom Entrances		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2018 - Fall: N	o Change											
Comments:	V											
2018 - Spring	: No Change											
Comments:]							

09M	12 x 12 Green Floor Tile Mastic	25	SF	Hallways Classroom Entrances		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change				1							
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change				-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
10	12 x 12 Yellow Floor Tile	35	SF	Hallways Classroom Entrances		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change				1							
Comments:												
2018 - Fall: N	o Change				_							
Comments:					=							

Category

Asbestos

Type

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

2018 - Spring : No Change

Comments:

Material

Quantity

Material

Units

Material Location

10M	12 x 12 Yellow Floor Tile Mastic	35	SF	Hallways Classroom Entrances	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N Comments:	o Change									
2018 - Fall: N Comments:	o Change									
2018 - Spring Comments:	: No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	5" x 5" Brown Ceramic Tile Grout	1050	SF	Washroom in Classroom 110 and North Side Washrooms		Miscellaneous	Yes	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11M	5" x 5" Brown Ceramic Tile Adhesive	1050	SF	Washroom in Classroom 110 and North Side Washrooms		Miscellaneous	No	None	0		YES X NO
2017 - Fall: N	lo Change										

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	4" x 4" Yellow Ceramic Tile Grout	3700	SF	Washroom in Classroom 110 and North Side Washrooms		Miscellaneous	Yes	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

12M	4" x 4" Yellow Ceramic Tile Adhesive	3700	SF	Washroom in Classroom 110 and North Side Washrooms		Miscellaneous	No	None	0	YES	X NO
2017 - Fall:	No Change		<u> </u>	<u> </u>]						
Comments:]						
2018 - Fall:	No Change										
Comments:											
2018 - Sprin	g : No Change				_						
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Washroom in Classroom

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Brown Carpet Mastic	1500	SF	Main Office, Principals Office and Library		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	Boiler Gaskets	3	LF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15	Interior Boiler Brick	200	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Mudded Ceiling Material	450	SF	Boiler Room		Surface	Yes	None	0		YES X NO
2017 - Fal	I: No Change				7						
Comments	3:										
2018 - Fal	I: No Change										
Comments	3:										
2018 - Spr	ring : No Change				_						
Comments	S:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12 x 12 Beige with Grey Floor Tile	2000	SF	Lobby, Offices, Kitchen, Teachers Lounge (Not observed), Storage and Gym		Miscellaneous	No	None	0		YES X NO
2017 - Fal	I: No Change										
Comments											
2018 - Fal	I: No Change										
Comments											

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
17M	12 x 12 Beige with Grey Floor Tile Mastic	2000	SF	Lobby, Offices, Kitchen, Teachers Lounge(Not Observed), Storage and Gym		Miscellaneous	No	None	0		YES	X NO
2017 - Fall	I: No Change				1							
Comments												
2018 - Fall	I: No Change											
Comments	S:]							
2018 - Spri	ring : No Change				-							
Comments												
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	4" Black Baseboard - not observed	0	LF	Lobby, Offices, Kitchen, Teachers Lounge, Storage and Gym		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

18M	4" Black Baseboard Mastic - not observed	0	LF	Lobby, Offices, Kitchen, Teachers Lounge, Storage and Gym	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	lo Change	•		•	•		•			
2018 - Fall: N	lo Change									
Comments:										
2018 - Spring Comments:	g : No Change									

Category

Asbestos

Type

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12 x 12 Red Floor Tile	100	SF	Teachers Lounge(Not Observed) and Gym		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

19M	12 x 12 Red Floor Tile Mastic	100	SF	Teachers Lounge(Not Observed) and Gym		Miscellaneous	No	None	0		YES	X NO
2017 - Fal	II: No Change				1							
Comment					-							
2018 - Fal	II: No Change											
Comment	S:											
2019 Sp	ring : No Chango				_							
	ring : No Change				4							
Comment	S:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
20	4" x 4" Beige and Tan Ceramic Tile Grout	500	SF	Boy's Washroom		Miscellaneous	Yes	None	0		YES	X NO
	Ceramic Tile Grout											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

2017 - Fall: No Change

Material Description

20M	4" x 4" Beige and Tan Ceramic Tile Adhesive	500	SF	Boy's Washroom		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change]										
Comments:												
2018 - Fall:	No Change				-							
Comments:					-							
2018 - Sprir	ng : No Change											
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Yes

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

YES

Units

Units

Change in Assessment Category

X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Quantity

750

Material

Quantity

Material

Units

Units

SF

Material Location

Girls' Washroom

HA No

21

Material Description

4" x 4" Tan/Green Ceramic

Tile Grout

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessm	ent Category
21M	4" x 4" Tan/Green Ceramic Tile Adhesive	750	SF	Girls' Washroom		Miscellaneous	No	None	0		YES		X NO
2017 - Fall: N	o Change												
Comments:					_								
2018 - Fall: N	o Change												
Comments:	5												
0040 Conin	. No Observe												
Comments:	: No Change				-								
Comments.					-								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	ent Category
22	White Window Glazing	2750	LF	Gym Balcony Level		Miscellaneous	No	None	0		YES		X NO
2017 - Fall: N	o Change												
Comments:	J												
0040 Falls N	la Ohanana				_								
2018 - Fall: No Change Comments:					_								
Comments.													
2018 - Spring : No Change													
Comments:													

23	12 x 12 Brown Floor Tile VFT	320	SF	Teacher's Lounge		Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	lo Change										
2018 - Fall: No Change											
Comments:											
2018 - Spring : No Change Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12 x 12 Brown Floor Tile Mastic	320	SF	Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Skylight Caulk	400	LF	Throughout		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Oracle Unit: 66076

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: CICS - Lloyd Bond
Date: 12/18/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 66076

SCHOOL'S ASBESTOS MANAGEMENT PLAN.