Chicago Public Schools 6 Month Asbestos Surveillance

2018 - Fall

| | School:Acero ChAddress:2651 W. | arter Schools 23rd St | s - Octavio F | az Campus | | | | Pracle Unit: Region: | 661: 02 | 31 | Buildin Mail Ro | | d |
|------------|------------------------------------|--------------------------|-------------------|----------------|--------------|------------------|----------------------|-------------------------|----------------|--------------------|--------------------|----------------|-----------------|
| | | | | | Asbesto | s Surveyor: | NSANCI | HEZ1 | | | | | |
| X CHEC | CK HERE IF NO CH | ANGE TO | O ASBE | STOS | Survey I | Date: | 1/3/2019 |) | | | | | |
| | | | | | Email A | ddress: | nsanche chools.o | z@unochart rg | ers | | | | |
| | A copy of the2016/20 | 17 notice to | parents and | d staff regard | ling the asb | estos manag | ement plan no | tifications w | vas distribute | d via: | | | |
| | Each child's backpa | ack | Notice | printed in sc | hool's new | sletter | Notice pr | inted in sch | ool's calenda | r Otl | her | | |
| HA No | Material Description | Material Quantity | Material Units | Material Lo | ocation | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | ssment Category |
| 01 | MJP on Corrugated Pipe Covering | 270 | LF | Tunnel | | | TSI | Yes | Dist | 230 | | YES | X NO |
| 2016 - Fal | I: No Change | | | | | 7 | | | | | | | |
| Comments | S: | | | | | | | | | | | | |
| 2017 - Spr | ring: No Change | | | | | _ | | | | | | | |
| Comments | S: | | | | | _ | | | | | | | |
| 2017 - Fal | I: No Change | | | | | _ | | | | | | | |
| Comments | S: | | | | | _ | | | | | | | |
| 2018 - Spr | ring : No Change | | | | | - | | | | | | | |
| Comments | S: | | | | | | | | | | | | |
| 2018 - Fal | I: No Change | | | | | - | | | | | | | |
| Comments | s: | | | | |] | | | | | | | |
| | | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 02 | Corrugated Pipe Covering | 1400 | LF | Tunnel | | TSI | Yes | Dist | 1190 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 03 | 9"x9" Floor Tile | 100 | SF | All Floors of Building | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|----------------------|-------------------|------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 04 | Vinyl Floor Tile Mastic | 1000 | SF | All Floors of Building | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 05 | Linoleum | 8100 | SF | All Floors of Building | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | 0 | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|------------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 06 | | MJP on Corrugated Pipe Covering | 40 | LF | Boiler Room #1 Boiler Storage and Tunnels | | TSI | Yes | Dist | 34 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 07 | MJP on Wrapped Pipe Covering | 6 | LF | Boiler Room #1Boiler Storage and Tunnels | | TSI | Yes | Dist | 5 | | YES X NO |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 08 | Corrugated Pipe Covering | 300 | LF | Boiler Room #1Boiler Storage and Tunnels | | TSI | Yes | Dist | 255 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 09 | Wrapped Pipe Covering | 70 | LF | Boiler Room #1Boiler Storage and Tunnels | | TSI | Yes | Dist | 59 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| 2018 - Fall: No Change | |
| | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 10 | Fire Door Insulation | 28 | SF | Basement | | TSI | Yes | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 11 | 12"x12" Blue w/Dk Blue & White Streaks Floor Tile | 916 | SF | Room 104- Principle's Office, Main Office, Teacher's Lounge | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 12 | 12"x12" Blue w/Dark Blue & White Streaks FT Mastic | 916 | SF | Room 104-Principle's Office, Main Office, Teacher's Lounge | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 13 | 9"x9" Tan w/ Dark Streaks Floor Tile | 620 | SF | Room 101 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 14 | 9"x9" Tan w/Dark Streaks Floor Tile Mastic | 620 | SF | Room 101 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 15 | 9"x9" Maroon w/Dark Streaks Floor Tile | 30 | SF | Room 101 | | Miscellaneous | No | None | 0 | | YES X NO |

| | - |
|---------------------------|---|
| 2016 - Fall: No Change | |
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA | No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----|----|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 16 | | 9"x9" Maroon w/Dark Streaks Floor Tile Mastic | 30 | SF | Room 101 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 17 | 12"x12" White w/Multi- Colored Streaks FT | 12125 | SF | Kindergarten, Rooms 105,106, 103, 207, 208, 209, 210, 211, 213, 213 closet, 212, 215, 216, 218 | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

VFT = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.*

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 18 | 12"x12" White w/Multi- Colored Streaks FT Mastic | 12125 | SF | Kindergarten, Rooms 105, 106, 103, 207m 208, 209, 211, 210, 213, 213 closet, 212, 214, 215, 216, 217 | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 19 | 9"x9" Red Floor Tile | 1950 | SF | 1st & 2nd Floor Hallways | | Miscellaneous | No | None | 0 | | YES XNO |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| 2018 - Spring : No Change |
| |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 20 | 9"x9" Red Floor Tile Mastic | 1950 | SF | 1st & 2nd Floor Hallways | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 21 | 9"x9" Black Floor Tile | 1950 | SF | 1st & 2nd Floor Hallways | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| ł | HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---|-------|----------------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| | 22 | 9"x9" Black Floor Tile Mastic | 1950 | SF | 1st & 2nd Floor Hallways | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| 2018 - Spring : No Change |
| |
| Comments: |
| 2019 Eall: No Change |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA | A No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----|------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 23 | < | 12"x12" Off-White w/Brn, Wht,& Gry Strks Floor Tile | 4050 | SF | Gym and Stage | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 24 | 12"x12" Off-White w/Brn, Wht,& Gry Strks FT Mastic | 4050 | SF | Gym and Stage | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 25 | 2" Black Mop Board | 270 | LF | Gym Stage | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 26 | 2" Black Mop Board Adhesive | 270 | LF | Gym Stage | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 27 | Grey Carpet Mastic | 750 | SF | Room 102 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 100 | Plaster | 300000 | SF | Throughout | | Surface | Yes | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 101 | Window Caulk | 3000 | LF | Throughout | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| 2018 - Spring : No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 102 | Door Caulk | 3000 | LF | Throughout | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | C | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 103 | | Green Terrazzo | 2500 | SF | RR's | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 104 | 12" X 12" Black VFT | 200 | SF | Elevator and Basement | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2017 - Spring: No Change | |
| Comments: | |
| 2018 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |

| HAN | 10 | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-----|----|----------------------------|----------------------|-------------------|-----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 105 | | 12" X 12" Black VFT Mastic | 200 | SF | Elevator and Basement | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 106 | Boiler Insulator | 200 | SF | Both Boilers | | TSI | Yes | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|---------------------------|--|
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| 2018 - Spring : No Change | |
| Comments: | |
| | |
| 2018 - Fall: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 107 | Boiler Gasket | 10 | SF | Both Boilers | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|---------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| 2018 - Spring : No Change |
| |
| Comments: |
| 2018 - Fall: No Change |
| Comments: |
| |

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

| School: | Acero Charter Schools - Octavio Paz Campus |
|---------|--|
| Date: | 1/25/2019 |

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

CHECK ONE

| A copy of this notice was sent home in each child's backpack | ί. |
|--|----|
|--|----|

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.