Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

66137

Oracle Unit:

Building ID: Address: 5025 St. Louis Region: Mail Room: Asbestos Surveyor: NSANCHEZ1 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/3/2019 Email Address: nsanchez@unocharters chools.org A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other Material Description HA No Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Quantity Units Category Type 12"x12" White Floor Tile Throughout all X NO 1 SF YES 10000 Miscellaneous No None (Main Type) Classrooms 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Acero Charter Schools - Victoria Soto

School:

Oracle Unit: 66137

55038

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	12"x12" Blue Floor Tile (Accent Tile)	1500	SF	300, 301, 302, 303, 304, 310		Miscellaneous	No	None	1500		YES X NO

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	12"x12" Orange Floor Tile (Accent Tile)	1500	SF	300, 301, 302, 303, 304, 310		Miscellaneous	No	None			YES X NO

2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12"x12" Blue/Gray Floor Tile (Accent Tile)	1500	SF	209, 210, 211, 212, 213, 214		Miscellaneous	No	None			YES X NO
2017 - St	oring: No Change										

2017 - Spring: No Change	
Comments:	
-	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	12"x12" Yellow/Green Floor Tile (Accent Tile)	1500	SF	209, 210, 211, 212, 213, 214		Miscellaneous	No	None			YES X NO

2047 Caring No Change	
2017 - Spring: No Change	
Comments:	
	-
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 3

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	12"x12" Yellow floor Tile (Accent Tile)	2000	SF	200, 201, 202, 203, 204, 205, 206, 208, 220		Miscellaneous	No	None			YES X NO
2017 - Spring	ı: No Change										

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	12"x12" Bright Red Floor Tile (Accent Tile)	2000	SF	200, 201, 202, 203, 204, 205, 206, 208, 220		Miscellaneous	No	None			YES X NO

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	12"x12" Red/Orange Floor Tile (Accent Tile)	1500	SF	102, 103, 104, 109, 110, 111, 112, 113, 114		Miscellaneous	No	None			YES X NO
0047 0 :	N. 01				1						

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	12"x12" Purple Floor Tile (Accent Tile)	1500	SF	102, 103, 104, 109, 110, 111, 112, 113, 114		Miscellaneous	No	None			YES X NO

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Light Gray Floor Tile	3000	SF	102, 103, 104, 109, 110, 111, 112, 113, 114, 200, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 212, 213, 214, 220, 305, 306		Miscellaneous	No	None			YES X NO
2017 - Spri	ng: No Change										
Comments					_						
2017 - Fall:	: No Change										
Comments	:										
2018 - Spri	ng : No Change										
Comments	:										
2018 - Fall:	: No Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Dark Gray Floor Tile (Accent Tile)	3000	SF	102, 103, 104, 109, 110, 111, 112, 113, 114, 200, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 212, 213, 214, 220, 305, 306		Miscellaneous	No	None			YES X NO

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

12	Mastic associated with Floor Tiles HA-01 thru HA- 09	29000	SF	Throughout all Classrooms	Miscellaneous	No	None		YES	X NO
2017 - Spring	g: No Change			•						
Comments:	J. 110 G. lange									
2017 Falls N	la Changa									
2017 - Fall: N	io Change									
Comments:										
2018 - Spring	g : No Change									
Comments:	-									
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
13	Adhesive associated with Multi colored Carpet Squares	1200	SF	Student Resource Area, Main Office, 123B, 214A, 214B, 215, 217, 218, 309		Miscellaneous	No	None			YES	X NO
2017 - Spring Comments:	: No Change											

2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

14	Gray Carpet	800	SF	Main Entry and Vestibule		Miscellaneous	No	None			YES	X NO
2017 - Spring	g: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15	Adhesive associated with Rubber Flooring on Stairwell Landings	2000	SF	Stairs		Miscellaneous	No	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

16	Rubber Flooring on Stair Treads	2000	SF	Stairs		Miscellaneous	No	None	2000		YES	X NO
	•	•	•	•	7	•		•	•	•		
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
					1							
2018 - Sprin	g : No Change											
Comments:	•											
					1							
2018 - Fall: I	No Change											
Comments:	<u> </u>											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
17	Adhesive associated with 4" Vinyl Baseboards	8000	SF	Throughout Building		Miscellaneous	No	None			YES	X NO
2017 - Spring: No Change Comments:												
2017 - Fall: No Change												

2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Adhesive associated with

2018 - Fall: No Change Comments:

18	Gym Floor Mastic	9000	SF	Gymnasium		Miscellaneous	No	None			YES	X NO
2017 - Spring	g: No Change]							
Comments:	, <u> </u>											
2017 - Fall: No Change												
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	Adhesive Associated with 6" Black Vinyl Gym Style Baseboard	25	SF	Gymnasium		Miscellaneous	No	None	,		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

Damage

Units

20	Drywall - Gypsum Board	100000	SF	Throughout Building		Miscellaneous	No	None			YES	X NO
2017 - Spring	g: No Change				7							
Comments:	, <u> </u>											
2017 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21	Drywall Joint Compound	100000	SF	Throughout Building		Miscellaneous	No	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

22	Marker Board Adhesive	2500	SF	Throughout Building		Miscellaneous	No	None			YES	X NO
2017 - Spring	: No Change]							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:					- -							
2018 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
23	2'x2' Beveled Ceiling Tile	74000	SF	Throughout Building		Miscellaneous	Yes	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Surface

Asbestos

Type

Material

Category

Miscellaneous

Friable

Yes

Yes

Damage

Type

None

None

Damage

Quantity

Damage

Units

50000

Material

Quantity

2000

Material

Units

SF

SF

Material Location

Receiving, Kitchen

Throughout Building

HA No

24

25

Material Description

2'x4' Vinyl Faced Ceiling

Light Tan Sprayed-on

Fireproofing

Change in Assessment Category

X NO

X NO

YES

YES

26	Red Fire Stop	5000	SF	Throughout Building		Miscellaneous	No	None			YES	X NO
2017 - Sprin	g: No Change				7							
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
	g : No Change											
Comments:					_							
2018 - Fall: I	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
27	Gray/Brown Duct Mastic	5000	SF	Throughout Building		Miscellaneous	No	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

2018 - Spring: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

28	Lab Benchtops	250	SF	303		Miscellaneous	No	None			YES	X NO
2017 - Spring	: No Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:					1							
2018 - Spring	: No Change				-							
Comments:					-							
2018 - Fall: N	o Change				1							
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

Damage

Units

2017 - Spring: No Change										
Comments:										
2017 - Fall: N	2017 - Fall: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										
2018 - Spring	2018 - Spring : No Change									
Comments:										

30

Material

Quantity

Material

Units

SF

Material Location

306

HA No

29

Material Description

Fume Hood Liner

YES

X NO

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Acero Charter Schools - Victoria Soto								
Date: 1/25/2019								
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.								
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.								
CHECK ONE								
A copy of this notice was sent home in each child's backpack.								
A copy of this notice was printed in the school's newsletter and sent home with each child								
A copy of this notice was printed in the school's calendar and sent home with each child								
Other.								
A COPY OF THIS NOTICE MUST BE PLACED IN THE								

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.