

Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

School: Noble - Rauner College Prep
Address: 1337 W Ohio

Oracle Unit: 66143
Region: 02

Building ID: 1930-O
Mail Room: 35

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: SZHAO9
Survey Date: 12/19/2018
Email Address: szhao@noblenetwork.org

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	MJP on Paperwrap Pipe Insulation	120	LF	All Floors in Building, Heating Water Lines		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Abated
Comments: Removed and abated pipe insulation in summer 2018

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	Paperwrap Pipe Insulation (Abated)			All Floors, Heating Water Lines		TSI					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	MJP on Paperwrap Pipe Cover (Abated)			All Floor. Domestic Cold Water Lines		TSI					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Paperwrap Pipe Insulation (Abated)			All Floors in Building, Domestic Cold Water		TSI					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Aircell Pipe Insulation (Abated)			Throughout Facility		TSI					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	Acoustical Plaster	9500	SF	Basement		Surface	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	MJP on Aircell Pipe Insulation	60	LF	Basement, Domestic Hot Water System		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	9"x9" Green Vinyl Floor Tile - mostly abated	300	SF	Third Floor Stair Landing of the East Stairwell		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated Comments: Completely abated
2017 - Fall: No Change Comments:
2017 - Spring: No Change Comments: Completely Abated
2018 - Spring : No Change Comments: Completely abated
2018 - Fall: No Change Comments: completely abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09A	9"x9" Green Floor Tile Mastic	300	SF	Third Floor Stair Landing of the East Stairwell		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated Comments: Completely abated
2017 - Spring: No Change Comments: Completely Abated
2017 - Fall: No Change Comments:
2018 - Spring : No Change Comments: Completely abated
2018 - Fall: No Change Comments: completely abated

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9"x9" Black Vinyl Floor Tile	300	SF	Third Floor Stair Landing of the East Stairwell		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated Comments: Completely abated
2017 - Fall: No Change Comments:
2017 - Spring: No Change Comments: Completely Abated
2018 - Spring : No Change Comments: Completely abated
2018 - Fall: No Change Comments: completely abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	9"x9" Black Floor Tile	300	SF	Third Floor Stair Landing of the East Stairwell		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated Comments: Completely abated
2017 - Spring: No Change Comments: Completely Abated
2017 - Fall: No Change Comments:
2018 - Spring : No Change Comments: Completely abated
2018 - Fall: No Change Comments: completely abated

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9"x9" Gray Vinyl Floor Tile	2175	SF	Rooms 101, 103, and 105 (Beneath Carpet) NE Stairwell 3rd Floor Landing		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	9"x9" Brown Vinyl Floor Tile	25	SF	Throughout Facility NE Stairwell 3rd Floor Landing Border		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments:Stairwell was abated
2017 - Spring: No Change
Comments:Stairwell Abated
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:Stairwell was abated
2018 - Fall: No Change
Comments:stairwell was abated

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Beige Vinyl Floor Tile	160	SF	First Floor in Principal's Office		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated Comments: Completely abated
2017 - Fall: No Change Comments:
2017 - Spring: No Change Comments: Completely Abated
2018 - Spring : No Change Comments: Completely abated
2018 - Fall: No Change Comments: completely abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	9"x9" Beige Vinyl Floor Tile	160	SF	First Floor Principal's Office		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated Comments: Completely abated
2017 - Spring: No Change Comments: Completely Abated
2017 - Fall: No Change Comments:
2018 - Spring : No Change Comments: Completely abated
2018 - Fall: No Change Comments: completely abated

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9"x9" Red Vinyl Floor Tile	25	SF	First Floor Kindergarden and Nursery Room NE Stairwell 3rd Floor Landing (as patch in Repl. Tiles)		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated Comments:Northeast seccion of first floor abated in 2015
2017 - Spring: No Change Comments:Northeast section of first floor abated in 2015
2017 - Fall: No Change Comments:
2018 - Spring : No Change Comments:Northeast section of 1st floor abated in 2015
2018 - Fall: No Change Comments:NE section of first floor abated in 2015

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"x9" Cream Vinyl Floor Tile- Abated			First Floor Kindergarden and Nursery Room		Miscellaneous					<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated Comments:Northeast seccion of first floor abated in 2015
2017 - Spring: No Change Comments:Northeast section of first floor abated in 2015
2017 - Fall: No Change Comments:
2018 - Spring : No Change Comments:Northeast section of 1st floor abated in 2015
2018 - Fall: No Change Comments:NE section of first floor abated in 2015

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	9"x9" Gray Vinyl Floor Tile Mastic (Beneath Carpet)	2100	SF	Rooms 101, 103, 105 (Beneath Carpet)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" White w/Gray Speckles Floor Tile- Abated			All Floors in the Building- Abated		Miscellaneous					<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments:Northeast seccion of first floor abated in 2015
2017 - Spring: No Change
Comments:Northeast section of first floor abated in 2015
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:Northeast section of 1st floor abated in 2015
2018 - Fall: No Change
Comments:NE section of first floor abated in 2015

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Dark Green Floor Tile- Abated			All Floors in the Building		Miscellaneous					<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments:Northeast section of first floor abated in 2015
2017 - Spring: No Change
Comments:Northeast corner of first floor abated in 2015
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:Northeast section of 1st floor abated in 2015
2018 - Fall: No Change
Comments:NE section of first floor abated in 2015

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" White with Green Specks Vinyl Floor Tile - Abated			All Floors in the Building		Miscellaneous					<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments:Northeast section of first floor abated in 2015
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:Northeast corner of first floor abated in 2015
2018 - Fall: No Change
Comments:NE section of first floor abated in 2015
2018 - Spring : No Change
Comments:Northeast section of 1st floor abated in 2015

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	MJP on Paperwrap Pipe Insulation	70	LF	Boiler Room (Dom Cold and Hot Water, Heating water) Basement JC		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Paperwrap Pipe Insulation	200	LF	Boiler Room (Domestic Cold and Heating water) Basement JC		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Aircell Pipe Insulation	60	LF	Storage and Boiler Room (Domestic Hot Water)		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Black Floor Tile	70	SF	First Floor- Room 100 Closet		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments:Completely abated
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:Completely Abated
2018 - Fall: No Change
Comments:abated
2018 - Spring : No Change
Comments:Completely abated

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Black Floor Tile Mastic	70	SF	First Floor- Room 100 Closet		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments: Completely abated
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments: Completely Abated
2018 - Fall: No Change
Comments: abated
2018 - Spring : No Change
Comments: Completely abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Ceramic Tile Grout	600	SF	All Washrooms in Facility		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Ceramic Tile Adhesive	600	SF	All Washrooms in Facility		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	2' x 4' White Sculpted Ceiling Tile	10000	SF	Throughout 1st , 2nd and 3rd Floor Corridors and Classrooms.		Miscellaneous		None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Terrazzo Flooring	2000	SF	Throughout - Stairwell Landings and steps.		Miscellaneous		None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated Comments: Completely abated
2017 - Fall: No Change Comments:
2017 - Spring: No Change Comments: Completely Abated
2018 - Spring : No Change Comments: Completely abated
2018 - Fall: No Change Comments: abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Drywall System	1500	SF	#300, #C1 Closet,		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change Comments:
2017 - Fall: No Change Comments:
2017 - Spring: No Change Comments:
2018 - Spring : No Change Comments:
2018 - Fall: No Change Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Hard Coat Plaster	40000	SF	Throughout the building.		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
EE	12"x 12" Green with White Specks Floor Tile	10000	SF	Throughout School		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments:Northeast section of first floor abated in 2015
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:Northeast section of first floor abated in 2015
2018 - Fall: No Change
Comments:NE section of first floor abated in 2015
2018 - Spring : No Change
Comments:Northeast section of 1st floor abated in 2015

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FF	12"x 12" Green with White Specks Floor Tile Mastic	10000	SF	Throughout School		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments:Northeast section of first floor abated in 2015
2017 - Spring: No Change
Comments:Northeast corner of first floor abated in 2015
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:Northeast section of 1st floor abated in 2015
2018 - Fall: No Change
Comments:NE corner of first floor abated in 2015

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GG	12"x 12" White with Tan Specks Floor Tile	7500	SF	Throughout School		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments:Northeast section of first floor abated in 2015
2017 - Spring: No Change
Comments:Northeast corner of first floor abated in 2015
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:NE corner of first floor abated in 2015
2018 - Spring : No Change
Comments:Northeast section of 1st floor abated in 2015

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HH	12"x 12" White with Tan Specks Floor Tile Mastic	7500	SF	Throughout School		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2016 - Fall: Abated
Comments:Northeast secon of first floor abated in 2015
2017 - Spring: No Change
Comments:Northeast corner of first floor abated in 2015
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:NE corner of first floor abated in 2015
2018 - Spring : No Change
Comments:Northeast section of 1st floor abated 2015

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
II	12"x 12" Gray Floor Tile	1300	SF	Basement Gymnasium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
JJ	12"x 12" Gray Floor Tile Mastic	1300	SF	Basement Gymnasium		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Robert Christlieb

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Noble - Rauner College Prep

Date: 9/1/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.