Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

66161

Oracle Unit:

CICS - Prairie

School:

Address: 11530 S. Prairie Region: 02 Mail Room: Asbestos Surveyor: JTORRES214 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2018 Email Address: itorres@chicagointl.org A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other Material Description HA No Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity All Floors in Building YES 01 MJP on Non-suspect Pipe LF 0 X NO 115 TSI Yes None including Art Room 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change Comments:

4220

Building ID:

02	MJP on Non-Suspect Pipe	80	LF	All floors in building including Art Room		TSI	Yes	None	0		YES	X NO
2017 - Fall: N	No Chango				1							
	NO Change											
Comments:												
2018 - Spring	g : No Change				1							
Comments:												
2018 - Fall: N	No Change				1							
Comments:	-				1							
	_	•	•	_	-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
		Qualitity	Office	1	Type	Calegory		1 ype	Quantity	Office		

Type

Material

Category

TSI

Friable

Yes

Damage

Туре

None

0

Damage

Quantity

Damage

Units

YES

03	Cover	20	LF	kitchen, cafeteria, boys + girls toiletsbasement
2017 - Fall: N	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				

20

Material

Quantity

Material

Units

LF

Material Location

All Floors in Building

including Art Room,

HA No

03

Material Description

MJP on Corrugated Pipe

Change in Assessment Category

X NO

04	Corrugated Pipe Covering	80	LF	All floors in building including Art Room		TSI	Yes	None	0	YES	X NO
2017 - Fall: No Change Comments:											
2018 - Fall: N Comments:	o Change										
2018 - Spring Comments:	2018 - Spring : No Change										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	MJP on Wrapped Pipe Insulation	45	LF	All floors in building including Art Room		TSI	Yes	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

06	Wrapped Paper Pipe Cover	300	LF	All Floors in Building including Art Room		TSI	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	J											
2018 - Spring	ı : No Change											
Comments:	<u> </u>											
2018 - Fall: N	lo Change											
Comments:	•											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
07	2x4 Drop/Lay-In Panel	3650	SF	primary bldg classrooms		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2018 - Spring	ı : No Change											
Comments:												
2018 - Fall: N	2018 - Fall: No Change											
Comments:												
					i							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No

Material Description

Material

Quantity

Material

Units

08	9 x 9 Gray Vinyl floor tile	7000	SF	Multipurpose Room		Miscellaneous	No	None	0		YES	X NO
001= = !! 1					1							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

1,1110	Material Becomption	Quantity	Units	Waterial Location	Туре	Category	Tidolo	Type	Quantity	Units	Onango in Alooca	Joinion Catogory
09	9 x 9 Black and Grey Vinyl Floor Tile	243	SF	Girls Washroom Hallway primary bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	018 - Spring : No Change											

2018 - Fall: No Change

Comments:

Comments:

HA No

Material Description

Material

Quantity

Material

Units

10	MJP on Non-suspect Pipe	110	LF	All Floors in Building including Art Room		TSI	Yes	None	0	YES	X NO
2017 - Fall: N	lo Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:											
	: No Change										
Comments:											
					I						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9 x 9 Red and Black Vinyl Floor Tile	6233	SF	309, 310, 311, 312, 413, 414, Deans office, Janitors closets, main office		Miscellaneous	No	None	0		YES X NO
2017 - Fall: No Change											

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Units

Material Quantity

Material Location

HA No

Material Description

12	12 x 12 Green Vinyl Floor Tile	1632	SF	1st floor Hallways		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:												
2019 Spring	· No Chango											
2018 - Spring Comments:	. No Change											
Comments.												
2018 - Fall: N	o Change											
Comments:												
<u>r</u>		1			1	T				r		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13	Plaster	40000	SF	Throughout School		Surface	Yes	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:	J											
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	2018 - Spring : No Change											
Comments:												

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	ment Category
14	Beige Terrazzo	5000	SF	Ground Floor Cafeteria upper school bldg		Miscellaneous	No	None	0		YES	X NO
Comments 2018 - Spr Comments	ing : No Change s: : No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	ment Category
15	Red Terrazzo	5000	SF	Stairwells upper school, 001, computer rm, main hallway, social worker office		Miscellaneous	No	None	0		YES	X NO
Comments	ing : No Change											
	: No Change				-							

Comments:

16	Carpet Masticnot observed	1800	SF	Rooms 102, 103, 205, 206, 207, 208		Miscellaneous	No				YES	X NO
2017 - Fall: N	o Change				1							
Comments:	J											
2018 - Fall: N	o Change				1							
Comments:	o Onange				-							
	N. O.											
2018 - Spring	: No Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
17	9 x 9 Gray Floor Tile Mastic	7000	SF	Multipurpose Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change				1							
Comments:	<u> </u>											
2018 - Fall: N	o Change				1							
Comments:	o Onange											
	: No Change											
Comments:												

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No

Material Description

Material

Quantity

Material

Units

18	9 x 9 Black and Grey Floor Tile Mastic	243	SF	Girls Washroom Hallway primary school		Miscellaneous	No	None	0	YES	X NO
2017 - Fall	: No Change]						
Comments	:				1						
2018 - Spri	ing : No Change				=						
Comments	:										
2018 - Fall	: No Change										
Comments											

Material

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9 x 9 Red and Black Floor Tile Mastic	6233	SF	309, 310, 311, 312, 413, 414, Deans office, janitors closets		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

20	12 x 12 Green Floor Tile Mastic	1632	SF	1st floor hall		Miscellaneous	No	None	0		YES	Х NO
2017 - Fa	II: No Change											
Comment												
2018 - Fa	II: No Change											
Comment												
2018 - Sp	ring : No Change				_							
Comment												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	12x12 Red VFT	1500	SF	Rooms 101-104, 205- 208, primary building		Miscellaneous	No	None	0		YES	X NO
2017 - Fa	II: No Change											
Comment												
2018 - Sn	ring : No Change											
Comment												

Material

Category

Asbestos

Type

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

22	12x12 Red VFT Mastic	1500	SF	rooms 101-104, 205-208, primary bldg	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	o Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										
2018 - Spring	: No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12x12 Grey VFT	1600	SF	rooms 101-104, coat room and toilet, primary bldg, 205-208, asst principal office and toilet, 2nd fl janitors closet		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12x12 Grey VFT Mastic	1600	SF	rooms 101-104, coat room and toilet primary building, 205-208, asst principal office and toilet, 2nd fl janitors closet		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12x12 Light Grey w/ grey specs VFT	2000	SF	primary bldg 2nd fl corridor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change Comments:	
2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Fall: No Change
Comments: 2018 - Spring : No Change	Comments:
Comments: 2018 - Spring : No Change	
2018 - Spring : No Change	2018 - Fall: No Change
·	Comments:
Comments:	2018 - Spring : No Change
	Comments:

26	12x12 light grey w/ grey specs VFT Mastic	2000	SF	primary bldg 2nd fl corridor	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N Comments:	o Change									
2018 - Spring Comments:	: No Change									
2018 - Fall: N Comments:	o Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12x12 Cream w/ beige specs VFT	400	SF	teachers lounge upper school upper school bldg		Miscellaneous	No	None	0		YES X NO
2017 - Fall: N	2017 - Fall: No Change										

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

Material Location

28	12c12 Cream w/ beige specs VFT Mastic	400	SF	teachers lounge upper school upper school bldg	Miscellaneous	No	None		YES	X NO
2017 - Fall: N Comments:	lo Change									
2018 - Fall: N Comments:	lo Change									
2018 - Spring Comments:	: No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Black, white + beige terazzo	300	SF	primary bldg stairwells		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

30	12x12 beige + tan specs VFT	500	SF	kitchenprimary bldg	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	lo Change									
2018 - Fall: N	lo Change									
Comments:										
2018 - Spring Comments:	: No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12x12 beige = tan specs VFT mastic	500	SF	kitchen primary bldg		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

32	9x9 black w/ grey specs + VFT	3000	SF	1st + 2nd fl hallway upper level bldg	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N Comments:	lo Change									
2018 - Spring Comments:	j : No Change									
2018 - Fall: N Comments:	lo Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	9x9 Black w/ grey specs VFT Mastic	3000	SF	1st + 2nd fl hallway upper level bldg		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

34	9x9 Tan w/ red sreaks VFT	3000	SF	1st and 2nd fl hallway upper level bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Fal	II: No Change]							
Comment												
2018 - Sp	oring : No Change				-							
Comment	ts:											
2018 - Fal	II: No Change											
Comment	s:]							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
35	9x9 tan w/ red streaks VFT Mastic	3000	SF	1st and 2nd fl hallway upper level bldg		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N Comments:	o Change											

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

HA No

Material Description

Material

Quantity

Material

Units

36	9x9 white + pink VFT	600	SF	Room 400 and hallway to multi-purpose room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall	I: No Change				1							
Comments	<u> </u>				1							
2018 - Spr	ring : No Change											
Comments	S:				-							
	l: No Change											
Comments	5:				-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

600

Material

Quantity

Material

Units

SF

Material Location

Room 400 and hallway to

multi-purpose room

HA No

37

Material Description

9x9 White + pink VFT

Mastic

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
38	12x12 Gold VFT	400	SF	rooms 415 + 416		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: I	No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:	g . He enange											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	a managa managa	
39	12x12 gold VFT mastic	400	SF	rooms 415 + 416		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: I	No Change											
Comments:	J											
2018 - Fall: I	No Chango											
Comments:	No Change											
2018 - Spring : No Change												
Comments:												

40	12x12 White w/ Gold specs	400	SF	roooms 415 + 416		Miscellaneous	No	None	0		YES	X NO
2017 - Fall	: No Change				1							
Comments]							
	ing : No Change											
Comments) <u>:</u>											
	: No Change											
Comments) <u>:</u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

400

Material

Quantity

Material

Units

SF

Material Location

rooms 415 + 416

HA No

41

Material Description

12x12 white w/ gold specs

VFT mastic

Page 21

Change in Assessment Category

X NO

YES

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _(CICS - Prairie
Date: _1	12/18/2018
	tify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of
	s Management Plan is available at each school during school hours by appointment.
Requests to	review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please	be advised that CPS conducts asbestos inspections of all Schools every three years.
•	pection was completed in 2016.
Asbestos su	rveillances are conducted every six months.
CHECK ONE	=
<u>OHEOR ONE</u>	-
A cop	by of this notice was sent home in each child's backpack.
A cop	by of this notice was printed in the school's newsletter and sent home with each child
A cop	by of this notice was printed in the school's calendar and sent home with each child
Other	r.
A COPY	OF THIS NOTICE MUST BE PLACED IN THE
	OOL'S ASBESTOS MANAGEMENT PLAN.