Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

	Address: Asian Hur		s - Passages	Charter School			acle Unit: egion:	661 02	91	Buildin Mail Ro	•		
X CHECK	HERE IF NO CHA	ANGE TO	O ASBE	STOS Surve	stos Surveyor: ey Date: I Address:								
	A copy of the2016/201	7 notice to p	parents and	staff regarding the a	asbestos manage	ement plan not	ifications w	as distribute	d via:				
	Each child's backpa	ck	Notice	orinted in school's ne	ewsletter	Notice prin	nted in sch	ool's calenda	r Ot	her			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assessm	nent Category
21	Ceiling roof panels	1200	SF	Attic- slanted roof		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	o Change												
Comments:													
2017 - Fall: N	o Change												
Comments:													
2017 - Spring	: No Change												
Comments:													
2018 - Spring	: No Change												
Comments:				·									

Oracle Unit: 66191

22	Black felt paper	100	SF	Attic		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	3											
2017 - Fall:	No Change				1							
Comments:	<u> </u>											
2017 - Sprin	ng: No Change				1							
Comments:												
2018 - Sprin	ng : No Change				1							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Yes

None

0

Friable

Damage

Туре

Damage

Quantity

Damage

Units

		room, food storage room
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		

8000

HA No

23

Material Description

1x1 Ceiling Tile w/ holes

Material

Quantity

Material

Units

SF

Material Location

1st floor corridor, stairwell

landings, Rooms 211, 212, 213, 214, 215, 217,

lunchroom, kitchen, utility

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	1x1 Ceiling Tile w/ holes Mastic	8000	SF	1st floor corridor, stairwell landings, Rooms 211, 212, 213, 214, 215, 217, lunchroom, kitchen, utility room, food storage room		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	13x24 Brown w/ streaks VFT	390	SF	Stairwells, 1st floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 3

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	13x24 Brown w/ streaks VFT Mastic	390	SF	Stairwells, 1st floor corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9x9 Beige w/streaks VFT	2000	SF	Rooms 211, 212, 213, 214, 216		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	9x9 Beige w/streaks VFT Mastic	2000	SF	Rooms 211, ,212, 213, 214, 216		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12x12 Brown w/ streaks VFT	360	SF	Stairwell steps		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

30	12x12 Brown w/ streaks VFT Mastic	360	SF	Stairwell steps		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: No Change											
Comments:											
2017 - Fall: I	No Change										
Comments:											
	g: No Change										
Comments:											
2018 - Sprin	g : No Change										

Material

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	6x6 Blue w/ streaks VFT	12	SF	elevator		Miscellaneous	No	None	0		YES X NO

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Spring	: No Change		
Comments:			

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
32	6x6 Blue w/ streaks VFT Mastic	12	SF	Elevator		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	9x9 Brown w/ streaks VFT	2000	SF	Rooms 211, 212, 213, 214, 216, North stairwells		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmer	nt Category
34	9x9 Brown w/ streaks VFT Mastic	2000	SF	Rooms 211, 212, 213, 214, 216, North stairwells		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	9x9 Tan w/ streaks VFT	1400	SF	Stairwells, 1st floor corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment C	ategory
36	9x9 Tan w/ streaks VFT Mastic	1400	SF	Stairwells, 1st floor corridor		Miscellaneous	No	None	0		YES X	10
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	1x1 Red w/ streaks VFT	110	SF	Basement corridor by west stairwell		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	1x1 Red w/ streaks VFT Mastic	110	SF	Basement corridor by west stairwell		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	9x9 Gray w/ black and tan streaks VFT	2800	SF	Lunch room, utility room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment C	ategory
40	9x9 Gray w/ black and tan streaks VFT Mastic	2800	SF	Lunch room, utility room		Miscellaneous	No	None	0		YES X	10
2016 - Fall: N	lo Change]							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	MJP on aircell pipe insulation	4	SF	Kitchen		TSI	Yes	Loc	1		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

42	Aircell pipe insulation	22	LF	Kitchen	TSI	Yes	Loc	3	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N Comments:	o Change									
2018 - Spring Comments:	: No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-01	12" x 12" Beige VFT	4000	SF	Bsmt Cafeteria, Food Storage Room, Vestibule by Cafeteria, Bsmt Main Corridor, Janitor's Closet, Teacher's Lounge, Water Pump Closet, Music Room Storage, Physical Ed. Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-01M	12" x 12" Beige VFT Mastic	4000	SF	Bsmt Cafeteria, Food Storage Room, Vestibule by Cafeteria, Bsmt Main Corridor, Janitor's Closet, Teacher's Lounge, Water Pump Closet, Music Room Storage, Physical Ed. Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2047 Chairm No Change
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-02	12" x 12" Off White w/Tan Specks VFT	1800	SF	Rooms 105, 106, Bsmt South Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
PCS-02M	12" x 12" Off White w/Tan Specks VFT Mastic	1800	SF	Rooms 105, 106, Bsmt South Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-03	12" x 12" Blue VFT	1600	SF	Bsmt Special Ed Room, Storage Room, Art Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

PCS-03M	12" x 12" Blue VFT Mastic	1600	SF	Bsmt Special Ed Room, Storage Room, Art Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					<u> </u>							
2017 - Spring	g: No Change				_							
Comments:	, J											
2017 - Fall: N	lo Change											
Comments:]							
2018 - Spring	g : No Change				-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

1 00 04	o x o marcon vi i	200	O.	Carpet)
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:				

250

Material

Quantity

Material

Units

SF

Material Location

2nd Floor Dean's Office

Closet, Room 106 (Under

HA No

PCS-04

Material Description

9" x 9" Maroon VFT

Change in Assessment Category

X NO

YES

PCS-04M	9" x 9" Maroon VFT Mastic	250	SF	2nd Floor Dean's Office Closet, Room 106 (Under Carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				1							
Comments:					=							
2017 - Sprin	g: No Change				-							
Comments:												
2017 - Fall: I	No Change											
Comments:					=							
2018 - Sprin	g : No Change											
Comments:					=							
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessr	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

None

No

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

PCS-05	9" x 9" Olive Green VFT	20	SF	Closet
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Spring	: No Change			
Comments:				

Quantity

20

Units

SF

Material

Units

Material

Quantity

Material Location

2nd Floor Dean's Office

2nd Floor Dean's Office

HA No

PCS-05

Material Description

9" x 9" Olive Green VFT

Page 16

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
PCS-05M	9" x 9" Olive Green VFT Mastic	20	SF	2nd Floor Dean's Office Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-06	8" x 16" Black VFT	10	SF	2nd Floor Dean's Office Closet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

PCS-06M	8" x 16" Black VFT Mastic	10	SF	2nd Floor Dean's Office Closet		Miscellaneous	No	None	0	YES	X NO
					i						
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2018 - Spring	g : No Change										
Comments:	_										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-07	9" x 9" Off White VFT	1200	SF	Room 106 (Under Carpet), Bsmt Music Room (Under Carpet)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

PCS-07M	9" x 9" Off White VFT Mastic	1200	SF	Room 106 (Under Carpet), Bsmt Music Room (Under Carpet)		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change]						
Comments:					_						
2017 - Spring	j: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	; No Change										
Comments:											
					J						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-08	Carpet Mastic	5000	SF	Rooms 208, 207, 206, 205, 202, Dean's Office, Computer Room, 108, 107, 106, 105, 104, 103, 101, Main Office, Principle's Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: I	No Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

PCS-09	Terrazzo	5000	SF	1st and 2nd Floor Corridors and Stariwells		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				1							
Comments:	10 Change				-							
2017 - Fall: I	No Change				-							
Comments:					1							
2017 - Sprin	g: No Change											
Comments:					 							
2018 - Sprin	g : No Change											
Comments:					-							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Yes

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Spring	: No Change		
Comments:	_	•	

Quantity

800

Units

Room 205

SF

Material

Units

Material

Quantity

Material Location

HA No

PCS-10

Material Description

1 x 1 White Ceiling Tile

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
PCS-10M	1 x 1 White Ceiling Tile Mastic	800	SF	Room 205		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:]							
2017 - Fall: N	No Change				_							
Comments:					-							
2017 - Spring	g: No Change											
Comments:					_							
2018 - Spring	g : No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-11	2 x 4 White Ceiling Tile	180	SF	1st Floor Boy's Toliet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

PCS-12	Plaster	10000	SF	Throughout Building		Surface	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
	g: No Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:					_							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

None

0

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

PCS-13	Aircell Pipe Insulation	1800	LF	Throughout Bsmt above Plaster Ceilings
2016 - Fall: N	lo Change			
Comments:				
2017 - Spring	g: No Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2018 - Spring	g : No Change			
Comments:				

Material

Quantity

Material

Units

Material Location

Pipe Chases, Art Room,

HA No

Material Description

YES

X NO

PCS-14	MJP on Aircell Pipe Insulation	150	LF	Pipe Chases, Art Room, Throughout Bsmt above Plaster Ceilings		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Chango	•		•	1	•	•	•	•	•	•	
2016 - Fall. I	No Change											
Comments:												
0047 Cmmin	Na Obasas											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	la Changa				-							
	NO Change											
Comments:												
2010 Carin	a . No Chongo				1							
12010 - Spring	g : No Change											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-15	Carboard Pipe Insulation	500	LF	Pipe Chases and Bsmt above Plaster Ceilings		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-16	MJP on Cardboard Pipe Insulation	100	LF	Pipe Chases and Bsmt above Plaster Ceilings		Surface	Yes	None	0		YES X NO
0040 5 11 1	. 0				1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-17	MJP on Fiberglass	30	LF	Bsmt Mechanical / Utility Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
PCS-18	9"x9" Maroon VFT	80	SF	Lower level storage room next to the girls' toilet		Miscellaneous	No	Loc	3		YES	X NO
2016 - Fall:	No Change]							
Comments:]							
2017 - Fall: I	No Change											
Comments:					<u> </u>							
2017 - Sprin	g: No Change											
Comments:					-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-18A	9"x9" Maroon VFT MASTIC	80	SF	Lower level storage room next to the girls' toilet		Miscellaneous	No	Loc	3		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

PCS-19	9"x9" black MASTIC	80	SF	Lower level storage room		Miscellaneous	No	Loc	3		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					l							
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

TIANO	Material Description	Quantity	Units	iviaterial Education	Type	Category	Thable	Type	Quantity	Units	Change in Asses	Sament Category
PCS-19A	9"x9" Black VFT MASTIC	80	SF	Lower level storage room		Miscellaneous	No	Loc	3		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											

Comments:

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

2018 - Spring : No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
PCS-20	Ceiling tile 2'x2' textured	160	SF	Principal's office		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Asian Human Services - Passages Charter School Date:
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.