Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

CICS - Northtown 66241 Building ID: 7740 School: **Oracle Unit:** Address: 3900 W. Peterson Region: 02 Mail Room: Asbestos Surveyor: JTORRES214 **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 12/18/2018 Email Address: itorres@chicagointl.org A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other other Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type Between rm 202 & 203, YES X NO between room 201 & 202, 10 Curtain wall 600 SF between counseling Miscellaneous No None 0 center and community room. 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

11	12"x12" gray w/ light gray and black specks VFT	800	SF	Room 106, HUB,220		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

11A	and black specks VFT MASTIC	and black specks VFT 650 SF Room 10										
2017 - Fall	: No Change											
Comments	Comments:											
	: No Change											
Comments	Comments:											
2018 - Spr	2018 - Spring : No Change											
Comments:												

Material

Quantity

Material

Units

Material Location

HA No

Material Description

12"x12" gray w/ light gray

Change in Assessment Category

X NO

YES

12	12"x12" white w/ tan and beige streaks VFT	600	SF	Room 105		Miscellaneous	No	None	0	YES	X NO
2017 - Fall: I	No Change]						
Comments:	-										
	g : No Change				-						
Comments:					-						
2018 - Fall: I	No Change										
Comments:					-						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	12"x12" white w/ tan and beige streaks VFT MASTIC	600	SF	Room 105		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

13	12"x12" Gray with white and black specks VFT	1500	SF	Rooms 109, 111, 112, 220, Nurse, Music Room #7, Kitchenette		Miscellaneous	No	None	0	YES	X NO
2017 - Fall	No Change		•	·	1					•	
Comments:					-						
2010 0 1											
	ng : No Change										
Comments:											
2018 - Fall:	No Change										

Material

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	12"x12" light brown w/ white and brown streaks VFT	6500	SF	Rooms 122, 110, 209, 101, copy room, counseling center, community room, 217, 215, 213, 218, 214, 216,		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Assessment Category
	113A	12"x12" light brown w/ white and brown streaks VFT MASTIC	6500	SF	Room 122, 110, 209, 101, copy room, counseling center, community room, 217, 215, 213, 218, 214, 216, 208		Miscellaneous	No	None	0		YES X NO
ſ	2017 - Fall: N	o Change]						

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: Abated
Comments:Community room and counseling suite abated.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	Linoleum gray and blue VFT	1600	SF	Girls and boys locker rooms		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

114A	Linoleum gray and blue VFT MASTIC	1600	SF	Girls and boys locker rooms		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	No Change				7							
Comments:	<u> </u>											
2018 - Fall: N	No Change				-							
Comments:	J											
2018 - Spring	g : No Change				+							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
115	1'x1' Ceiling tiles with grooves	40000	SF	Throughout		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: N	No Change				7							
Comments:												
2018 - Fall: N	No Change				_							
Comments:												
2018 - Spring	g : No Change				1							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
116	Drywall system	2000	SF	Dressing room		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:					+							
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	· No Change				+							
Comments:	. No Change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Domogo	Change in Asses	noment Cotegory
TIA NO	Material Description	Quantity	Units	Waterial Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asses	Sillent Category
117	Black lab table tops	800	SF	Rooms 205, 208, 206		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	· No Changa				4							
Comments:	. No Change				_							
2018 - Fall: N	o Change											
Comments:					-							
L												

118	Preformed insulation magblock	500	SF	Janitorial supply room- found below a layer of black duct insulation wrap (HA GC-F01)	Miscellaneous	Yes	None	0	YES	X NO
	: No Change									
Comments	S:									
2018 - Fal	l: No Change									
Comments	S:									
2018 - Spr	ing : No Change									
Comments	S:									

Material

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-01	9"x9" beige with red and black VFT	400	SF	main office storage, safe rm, 212 (under carpet)		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

		Quantity	Units		Type	Category		Type	Quantity	Units		
GC-A-01M	9" x 9" Beige w/Red & Black VFT Mastic	400	SF	Main Office Storage, Safe Room, 212 (under carpet), Administrative Offices (under carpet)		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:	o onango											
2019 Fall: N	o Chango											

Material

Asbestos

Damage

Friable

Damage

2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Material Location

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-02	9"x9" bluewith white VFT	500	SF	Gym Balcony, Closet & Mechanical Rooms,110, Rm 111 (under carpet), Book Storage 1st Floor by Rm 111, Rm 200, Rm off 112		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
GC-A-02M	9"x9" bluewith white VFT Mastic	500	SF	Gym Balcony, Closet & Mechanical Rooms,110, Rm 111 (under carpet), Book Storage 1st Floor by Rm 111, Rm 200, Rm off 112		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change]							
Comments:	•											
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change				-							
Comments:												
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-03	9"x9" gray with red and white VFT	1800	SF	Rm 115/117 (under carpet) & Closet, Storage Rm by 203, Rm 109 (under carpet), 2nd Floor Private Toilet by Girl's Toilet, Storage Rms by Student Services Office, Dressing Rms and Copy Room 2nd Floor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-03M	9"x9" gray with red and white VFT Mastic	1800	SF	Rm 115/117 (under carpet) & Closet, Storage Rm by 203, Rm 109 (under carpet), 2nd Floor Private Toilet by Girl's Toilet, Storage Rms by Student Services Office, Dressing Rms and Copy Room 2nd Floor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-04	9"x9" white with blue and gray VFT	900	SF	Audio-Vis Lobby and Hall, Rm 112 (under carpet), Storage, Hall by Rm 104, 103/104 and Office		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-04M	9"x9" whit with blue and gray VFT Mastic	900	SF	Audio-Vis Lobby and Hall, Rm 112 (under carpet), Storage, Hall by Rm 104, 103/104 and Office		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-05	12"x12" white with gray VFT- NOT OBSERVED	1800	SF	xerox rm, rm: 105		Miscellaneous	Yes	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

GC-A-05M	12"x12" white with gray VFT Mastic- NOT OBSERVED	1800	SF	xerox rm, rm: 105	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	lo Change		-	•	•	•	•	•		
Comments:										
2018 - Fall: N	lo Change									
Comments:										
2018 - Spring	: No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-06	9"x9" red with white VFT	2500	SF	Music Studios 1,2,3,4,5,6,8,9, Library, Library Storage and Conf., 1st Floor Storage by Rm 107, Rm 106		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-06M	9"x9" red with white VFT Mastic	2500	SF	Music Studios 1,2,3,4,5,6,8,9, Library, Library Storage and Conf., 1st Floor Storage by Rm 107, Rm 106		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-07	9"x9" gray with white, blue and red VFT	500	SF	storage rms 112, audiovis storages & math resource, rms 104,112-under carpet mastic,216, SW storage, Rm 205 Closet, Rm 211		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
GC-A-07M	9"x9" gray with white, blue and red VFT Mastic	500	SF	storage rms 112, audiovis storages & math resource, rms 104,112-under carpet mastic,216, SW storage, Rm 205 Closet, Rm 211		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change				1							
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
GC-A-08	9"x9" gray with white and black VFT	4000	SF	Kit R/R,SW cafe store, rooms off stage,rooms. 3,5,220, library, LAB storage,		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change				†							
Comments:												
2018 - Fall: N	lo Change											

Comments:

GC-A-08M	9"x9" gray with white and black VFT Mastic	4000	SF	Kit R/R,SW cafe store, rooms off stage,rooms. 3,5,220, library, LAB storage,		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: I	No Change				7							
Comments:												
2018 - Sprin	g : No Change											
Comments:					4							
2018 - Fall: I	No Change											
Comments:					4							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmen	nt Category
GC-A-09	9"x9" gray with white and black VFT	500	SF	Lit R/R, publication rm		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: I	No Change				7							
Comments:	Ţ.											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
GC-A-09M	9"x9" gray with white and black VFT Mastic	500	SF	Lit R/R, publication rm		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change				1							
Comments:	_]							
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
			1									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
GC-A-10	9"x9" It green with white and dark blue VFT- NOT OBSERVED	250	SF	Rms. 108 & 110		Miscellaneous	Yes	None			YES	X NO
2017 - Fall: N	o Change				1							
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	2018 - Fall: No Change											
Comments:	•]							
					1							

GC-A-11	9"x9" gray with ehite, black and orange VFT	160	SF	Office between 113 and 115		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change]							
Comments:												
2018 - Fall:	No Change											
Comments:	<u> </u>				-							
2018 - Sprir	ng : No Change											
Comments:	·				_							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

TIATIO	Material Description	Quantity	Units	Waterial Eocation	Type	Category	Thabic	Type	Quantity	Units	Onlange in Asses	Sment Gategory
GC-A-11M	9"x9" gray with ehite, black and orange VFT	160	SF	Office between 113 and 115		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: No Change Comments:												
2018 - Spring	: No Change											

2018 - Fall: No Change

Comments:

Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

GC-A-12	9"x9" tan with white and brown VFT- NOT OBSERVED	150	SF	Rm 116		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: I	No Change		•]	•	•	•	•	•	•	
Comments:					1							
2018 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-13	9"x9" gray with blue VFT	600	SF	2nd floor, stage storage and green room		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

9"x9" tan with white and

2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change Comments: 4018 - Fall: No Change Comments: 4019 - Friable Damage Quantity Units Damage Quantity Units Pripe Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category 4019 - Friable Damage Quantity Units Change in Assessment Category	GC-A-13M	9"x9" gray with blue VFT Mastic	600	SF	2nd floor, stage storage and green room		Miscellaneous	No	None	0		YES	X NO
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change Comments: HA No Material Description Material Material Location Asbestos Type Material Friable Damage Type Quantity Units Change in Assessment Category GC-A-14 12"X12" white with brown 600 SE Rm 204 projection prom	2017 Fall N	la Changa											
2018 - Spring : No Change Comments: 2018 - Fall: No Change Comments: HA No Material Description Material Material Location Asbestos Type Material Category Type Quantity Units Prince Damage Damage Quantity Units Prince Damage Damage Quantity Units Prince Damage Damage Damage Quantity Units Prince Damage Dama		io Change											
2018 - Spring : No Change Comments: 2018 - Fall: No Change Comments: HA No Material Description Material Material Location Asbestos Type Material Category Type Quantity Units Prince Damage Damage Quantity Units Prince Damage Damage Quantity Units Prince Damage Damage Damage Quantity Units Prince Damage Dama	Comments:												
Comments: 2018 - Fall: No Change Comments: HA No Material Description Material Quantity Units Material Location Asbestos Type Category Type Quantity Units Damage Quantity Units Provided From Miscellaneous No. None O. Non													
2018 - Fall: No Change Comments: HA No Material Description Material Quantity Units Material Location Asbestos Type Category Type Quantity Units Change in Assessment Category GC-A-14 12"X12" white with brown 600 SE Rm 204 projection room Miscellaneous No. None 0	2018 - Spring	ı : No Change											
Comments: HA No Material Description Material Quantity Units Material Location Asbestos Type Category Type Quantity Units Damage Quantity Units Prize Quantity Units None On SE Rm 204 projection room Miscellaneous No. None On None	Comments:												
Comments: HA No Material Description Material Quantity Units Material Location Asbestos Type Category Type Quantity Units Damage Quantity Units Prize Quantity Units None On SE Rm 204 projection room Miscellaneous No. None On None													
HA No Material Description Material Material Location Asbestos Material Friable Damage Damage Damage Damage Units Category Type Category Type Quantity Units Provided to the Control of the Category Category Category Category Category Units No.	2018 - Fall: N	lo Change											
Quantity Units Type Category Type Quantity Units CC_A_14	Comments:	-											
Quantity Units Type Category Type Quantity Units CC_A_14													
Quantity Units Type Category Type Quantity Units CC_A_14													
Quantity Units Type Category Type Quantity Units CC_A_14	HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
(=1 = 1 = 1 = 1 = 1 = 1 = 1 = 1 = 1 = 1		·	Quantity	Units			Category				Units	G	0 ,
and gray ver	GC-A-14		600	SF	Rm. 204, projection room		Miscellaneous	No	None	0		YES	X NO
		and gray vr i			. ,								

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-A-14M	12"X12" white with brown and gray VFT Mastic	600	SF	Rm. 204, projection room		Miscellaneous	No	None	0		YES X NO
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
					J						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-B-01	12"x12" white Ceiling Tile with waves	3500	SF	Audio-Vis lobby,Rm 112, Pop rm,Cafeteria, corridors,utility,dining, mailrm		Miscellaneous	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
GC-B-02	12"x12" white ceiling tile with dots	3000	SF	Near main office, center,		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: I	No Change											
	g : No Change				- -							
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
GC-B-03	2'x2' white textured ceiling tile	700	SF	Faculty lounge		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: I	No Change											
Comments:					_							
2018 - Sprin	g : No Change											
Comments:]							
2018 - Fall: N	No Change				1							
Comments:	J											

GC-B-04	12"x12" white ceiling tile with pin holes	200	SF	Kitchen cooking room		Miscellaneous	Yes	None	0		YES	X NO
					ĺ							
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
GC-D-01	Mud elbow on f/g pipe insulation	750	LF	Kitchen,boiler rm,pipe tunnels,balc AHU,Stage, Library AHU,gen.off. AHU chase and R/R		TSI	Yes	Dist	42		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

		Chase and TVTC	
2017 - Fall: No Change			
Comments:			
2018 - Fall: No Change			
Comments:			
2018 - Spring : No Change			
Comments:			

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
GC-F-01	2'x2' duct insulation	300	SF	Incinerator, boiler room		TSI	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change				7							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:	Ü											
2018 - Spring	g : No Change				-							
Comments:	, · · · · · · · · · · · · · · · · · · ·											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
GC-H-01	Chalk-like trowel-on material	400	SF	Stairwells 1,2,3,4,5,6, stairs to balcony		Surface	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change				7							
Comments:												
2018 - Spring	g : No Change				-							
Comments:	g . No Change				-							
2040 Falls N	la Changa]							
2018 - Fall: N	io Change				-							
Comments.					4							

GC-H-02 Plaster 20000 SF Intraces, kitchen, green room, stage storage, GYM Surface No None 0	essment Category	Change in Asses	Damage Units	Damage Quantity	Damage Type	Friable	Material Category	Asbestos Type	Material Location	Material Units	Material Quantity	Material Description	HA No
stair,balcony storage.	Х NO	YES		0	None	No	Surface		halls, classrooms entrances,kitchen,green room,stage storage,GYM	SF	20000	Plaster	GC-H-02

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GC-M-01	Boiler gasket	10	SF	Boiler room		Surface	Yes	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
GC-N-01	Transite Laboratory Hood	25	SF	Room 208		Miscellaneous	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
2018 - Spring	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
GC-R-02	Tank Insulation	150	SF	Hot Water Tank in boiler room		TSI	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change				1							
Comments:	•											
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	g . No Onange											
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
N-HA-01	Carpet Mastic	5500	SF	Senior Lounge, Rms 115, 117, 212, 200, Library Office, Gym Office, Comm. Rm		Miscellaneous	No	None	0		YES	X NO
2017 - Fall:	No Change				1							
Comments:]							
2018 - Fall:	No Change				-							
Comments:												
2018 - Sprin	g : No Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N-HA-02	12" x 12" Brown / White VFT	8000	SF	Rms 108, 107, 113, 114, 116, 118, 119, 120, 102, 122, 207, 206, 109, 210, 1st Floor Conf. Rm, Library		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N-HA-02M	12" x 12" Brown / White VFT Mastic	8000	SF	Rms 108, 107, 113, 114, 116, 118, 119, 120, 102, 122, 207, 206, 109, 210, 1st Floor Conf. Rm, Library		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N-HA-03	12" x 12" Gray / White VFT	2000	SF	201,202,203		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
N-HA-03M	12" x 12" Gray / White VFT MASTIC	2000	SF	201,202,203		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	Ü											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
N-HA-04	12" x 12" Light Brown VFT	500	SF	Rm 100		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:	J											
2018 - Fall: N	o Change											
Comments:												
2018 - Spring : No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
N-HA-04M	12" x 12" Light Brown VFT Mastic	500	SF	Rm 100		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:	-											
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
N-HA-05	12" x 12" White / Tan VFT	500	SF	Rm 99		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: No Change												
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
N-HA-05M	12" x 12" White / Tan VFT Mastic	500	SF	Rm 99		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:					4							
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change				-							
Comments:	Ţ											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
N-HA-06	12" x 12" Tan VFT	200	SF	ADA Restroom		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change				7							
Comments:	Ü											
2018 - Spring	: No Change				-							
Comments:												
2018 - Fall: No Change												
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
N-HA-06M	12" x 12" Tan VFT Mastic	200	SF	ADA Restroom		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
N-HA-07	2' x 2' Ceiling Tile	200	SF	ADA Restroom		Miscellaneous	No	Dist	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												

Friable

Material

Asbestos

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No

Material Description

Material

	II											
N-HA-08	12"x12" Yellow VFT	1200	SF	Main Office Public Space, Mail Room and Copy Rm		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
N-HA-08M	12"x12" Yellow VFT Mastic	1200	SF	Main Office Public Space, Mail Room and Copy Rm		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N-HA-09	Terrazzo	15000	SF	Corridors 1st and 2nd, Stariwells, Gym Lobby, Exit Vestibules, 1st Floor Restrooms, Cafeteria		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: CICS - Northtown
Date: 12/18/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. other
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 66241

SCHOOL'S ASBESTOS MANAGEMENT PLAN.