Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

		nentary Char Nashtenaw	ter School					acle Unit: gion:	6633 02	31	Buildin Mail Ro			
X CHECK	K HERE IF NO CH	ANGE T	O ASBE	STOS	Asbestos Survey Da Email Add				<u> </u>					
	A copy of the2016/201	17 notice to	parents and	staff regardi	ing the asbe	stos manage	ement plan noti	fications w	as distributed	l via:				
	Each child's backpa	ack	Notice	orinted in sch	hool's newsl	letter	Notice prin	nted in sch	ool's calendar	Ot	her			
HA No	Material Description	Material Quantity	Material Units	Material Loc	cation	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessme	nt Category
001	1' x 1' Decorative Ceiling Tile			School Foyer			Miscellaneous					YES		X NO
2016 - Fall: I	No Change													
Comments:														
2017 - Fall:	No Change													
Comments:														
2017 - Sprin	g: No Change													
Comments:														
2018 - Sprin	g : No Change													
Comments:														

Oracle Unit: 66331

002	1'x1' Fissured Ceiling Tile			School Foyer		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
003	1'x1' Decorative/Fissured Ceiling Tile Adhesive			School Foyer		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

004	2'x4' Fissured Lay In Ceiling Panels			School Multi-Purpose Room		Miscellaneous					YES	X NO
2016 - Fall	: No Change											
					4							
Comments	:											
2017 - Fall	: No Change											
Comments	:											
					1							
2017 - Spri	ng: No Change											
Comments	:				1							
					1							
2018 - Spri	ng : No Change											
Comments	:											
	_		•		_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	·	Quantity	Units		Type	Category		Туре	Quantity	Units		- ,
				Classrooms 207, 301,								

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

500

SF

HA No

005

Material Description

9"x9" Gray Floor Tile

Material

Quantity

Material

Units

Material Location

303, 307, 3rd Floor Lounge

YES

X NO

006	9"x9" Gray Floor Tile Mastic	500	SF	Classrooms 207, 301, 303, 307, 3rd Floor Lounge		Miscellaneous	No	None	0	YES	X NO
		-	·	•	1	·	•	•			
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:	-]						
2018 - Spring	g : No Change										
Comments:	•										
					1						
					•						

Type

Asbestos

Type

Material

Category

Material

Category

Friable

Friable

No

Damage

Damage

Type

None

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

007	9"x9" Green Floor Tile	1500	SF	Main Office and Room 308	Miscellaneous
2016 - Fall: N	o Change				
Comments:					
2017 - Fall: N	o Change				
Comments:					
2017 - Spring	: No Change				
Comments:					
2018 - Spring	: No Change				
Comments:					

Material

Quantity

Material

Quantity

Material

Material

Units

Units

Material Location

Material Location

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
008	9"x9" Green Floor Tile Mastic	1500	SF	Main Office and Room 308		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
009	9"x9" Brown w/Brown and White Streaks Floor Tile	14950	SF	Throughout Classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

010	9"x9" Brown w/Brown and White Streaks Floor Tile Mastic	15350	SF	Throughout Classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change		·							·		
Comments:												
2017 - Fall: I	No Change											
Comments:												
	g: No Change											
Comments:												
	g : No Change											
Comments:												
					I							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
011	12"x12" Brown Designed Floor Tile	400	SF	Space Behind Stage		Miscellaneous	No	None	0		YES X NO
0040 E II N	. 01				1						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

012	12"x12" Brown Designed Floor Tile Mastic	1800	SF	Space Behind Satge		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments					1							
	-											
2017 - Fall	: No Change											
Comments	: -											
2017 Cnri	na. No Chonas				4							
	ng: No Change				_							
Comments	:				4							
2018 - Spri	ng : No Change				-							
Comments	· ·				-							
Comments	•				+							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units		
012	Provin and White Torrazza	2520	SE.	Boy's and Girl's Washrooms, First Floor		Missellaneous	No	None			YES	X NO

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Material Location

Teacher's Washroom and Slop Sink Room,

2530

SF

HA No

013

Material Description

Brown and White Terrazzo

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
014	Black with White and Green Terrazzo	8900	SF	Basement Lunchroom, Kitchen, Sorage Room, School Stairways, Corridors, Girl's and Boy's Washrooms, Teacher's Washrooms, Slop Sink Rooms, Entry Foyer		Miscellaneous	No	None	0		YES X NO

[00.40
2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
015	Green Terrazzo	160	SF	Entry Foyer		Miscellaneous	No	None	0		YES X NO

_	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

016	Paneling	900	SF	All Purpose Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

017	4" Brown Baseboard	70	LF	Area Behind Stage		Miscellaneous	No	None	0	YES
2016 - Fa	III: No Change	•]					
Comment	ts:]					
2017 - Fa	III: No Change									
Comment	ts:				_					
2017 - Sp	oring: No Change				<u> </u>					
Comment	ts [.]									

Comments: 2018 - Spring : No Change Comments:

HA No

016

Material Description

Adhesive Beneath Wood

Material

Quantity

900

Material

Units

SF

Material Location

All Purpose Room

Change in Assessment Category

YES

X NO

X NO

018	4" Brown Baseboard Adhesive	70	LF	Area Behind Stage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change]							
Comments]							
2017 - Fall	I: No Change											
Comments	3:]							
	ring: No Change											
Comments	5:				-							
2018 - Spr	ring : No Change											
Comments	3:				-							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
019	Door Caulk	900	LF	Classrooms and Office Doors Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N	lo Change											

Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Comments:

020	Insulation on Roof Drain Piping	25	LF	Third Floor Lounge		TSI	Yes	None	0	YES	X NO
2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:	Material location needs	to be upd	ated to As	sst. Principals Office							
Room 302											
<u>'</u>					l						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
021	Pipe Joint Fittings on Fiberglass Pipe Insulation	6	SF	Throughout Facility in Pipe Chases and Maintenance Storage Room		Surface	Yes	None	0		YES X NO
					Ī						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

022	Breaching Insulation Adhesive	20	LF	Boiler Room		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	la Changa				1						
	io Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	j: No Change										
Comments:											
2018 - Spring	j : No Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
023	Hard Plaster Ceiling	12000	SF	Throughout School Facility in Washrooms, Stairways, Slop Sink Rooms, Kitchen, Basement Storage and Third Floor Lounge		Surface	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

Breaching Insulation

Material

Units

Material

Quantity

Material Location

024	Boiler Gasket	20	LF	Boiler Room	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Spring	: No Change									
Comments:	<u>-</u>	·		<u>-</u>						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Units	Material Location	Asbestos Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
025	Carpet Adhesive	400	SF	Multi-Purpose Room Stage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
2017 - Fall: N	o Change											

Comments:

2017 - Spring: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2018 - Spring : No Change Comments:

026	Acoustical Ceiling Plaster	7000	SF	Classrooms and Corridor, lunchroom/multipurpose room, stairwell ceilngs		Surface	Yes	None	0		YES	X NO
		•			1	•	•	•	•	•		
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:	-											
2018 - Spring	j : No Change											
Comments:												
					-							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
027	2' x 2' Textured Ceiling Tiles	7850	SF	1st, 2nd, and 3rd Floor Hallways, Rooms 109, 113-118, Main Lobby G14 and G10		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	No Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

028	Drywall	10000	SF	Throughout New Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:					1							
2017 - Fall: N	No Change				-							
Comments:					-							
	g: No Change				- - -							
Comments:												
2018 - Spring	g : No Change				-							
Comments:					<u> </u>							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
1	+	+	1		1		1	1	1	<u> </u>		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Material Location

Throughout New Addition

HA No

029

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Spring : No Change

Material Description

Drywall Compound

Material

Quantity

2000

LF

Material

Units

YES

X NO

030	12" x 12" White, Red, Blue, and Yellow Pattern Floor Tile	2000	SF	1st, 2nd, 3rd, Floor Hallways, and Main Lobby		Miscellaneous	No	None	0		YES	X NO
	•	•	•		1	•	•	•	•	•	•	
2016 - Fall: N	lo Change											
Comments:												
					1							
2017 - Fall: N	lo Change				1							
Comments:	-]							
2017 - Spring	g: No Change											
Comments:	-											
					1							
2018 - Spring	g : No Change											
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
031	Mastic Associated w/ 12" x 12" White, Red, Blue, and Yellow Pattern Floor Tile	2000	SF	1st, 2nd, 3rd, Floor Hallways, and Main Lobby		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
032	Yellow Carpet Mastic	2500	SF	Room 113, 114, G16, G12, G10, G09, G14		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Erie Elementary Charter School Date:
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.