Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

66381

Oracle Unit:

Building ID:

3180

CICS - Wrightwood

School:

Address: 8130 S. California Ave. Region: 02 Mail Room: Asbestos Surveyor: JTORRES214 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2018 Email Address: itorres@chicagointl.org A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Material Friable Damage Damage Change in Assessment Category Damage Quantity Units Type Category Type Quantity Cafeteria, Basement/Pipe YES 01 LF 0 X NO Pipe Insulation 1350 TSI Yes None Chases 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

02	Pipe Joint Insulation	3150	LF	Cafeteria, Basement/Pipe Chases		TSI	Yes	None	0		YES	X NO
2017 - Fall: N	lo Change											
Comments:	J]							
2018 - Fall: N	lo Change											
Comments:	•											
2018 - Spring	; No Change											
Comments:	•											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
03	12"x12" Beige Floor Tile Mastic	9000	SF	Kitchen/Basement		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	J											
2018 - Spring	ı : No Change											
Comments:	,											
2018 - Fall: No Change												
Comments:	y -]							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No

Material Description

Material

Quantity

Material

Units

04	12"x12" Red Floor Tile Mastic	968	SF	Science/Storage		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change				1							
Comments:	o onango											
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	· No Change											
Comments:	. No Change											
Commonto.					-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
05	12"x12" Ceiling Tile Glue	18000	SF	Corridors/Basement, Rooms 1 - 8, 25-27, 30- 32		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change]							
Comments:	<u> </u>											
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	o Griange				-							
Comments.					1							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9"x9" Green Floor Tile - not observed	0	SF	Rooms 19, 20, 21, 28, 29, 31, 32, 33, 35		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9"x9" Tan Floor Tile - not observed	0	SF	Rooms 19, 20, 21, 28, 31, 32, 33, 35, 37		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08	Spray-on Ceiling	1464	SF	Art Room		Surface	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09	9"x9" Gray Floor Tile	0	SF	Room 11		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change											
Comments:	J											
2018 - Spring	: No Change				_							
Comments:	<u> </u>											
2018 - Fall: N	lo Change				\dashv							
Comments:												

10	Boiler Insulation (ABATED 2004)			Boiler Room		TSI	Yes	None			YES	X NO
2017 - Fall: N	o Change]							
Comments:	J											
2018 - Spring	· No Change											
Comments:	. No onango											
2018 - Fall: N	o Change											
Comments:	o onange											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
11	12"x12" Floor Tile	100	SF	1st Floor Storage Room		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	o Change]							
Comments:	U											
2018 - Spring	: No Change											
Comments:	J											
2018 - Fall: N	o Change											
Comments:												
					J							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	2x4 Ceiling Tile	20000	SF	Bldg A - 1st and 2nd Floor Hallways, principal, main, and counselor's offices, E and W boys, girls, men, women bathrooms, cafeteria, all purpose room, library, computer lab, nurse office, boiler office		Miscellaneous	Yes	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Red and Beige Terrazzo	15000	SF	Buildings A and B - Hallways, Stairwells, Bathroom		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

14	Carpet Mastic over Tile - not observed	0	SF	Rooms 11, 17-18, 21, 25- 32, and Library Offices		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	<u> </u>											
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
15	12 x 12 Brown Floor Tile	1500	SF	Rooms 12, 19, 20		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	-											
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	2018 - Spring : No Change											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Material Description

Material

Quantity

Material

Units

16	12 x 12 Brown Floor Tile Mastic	1500	SF	Rooms 12, 19, 20		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	go				- -							
2018 - Spring	g : No Change											
Comments:	, J				- -							
2018 - Fall: N	lo Change				1							
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
17	12 x 12 Beige Floor Tile	9000	SF	Kitchen/Basement		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: N	lo Change]							
Comments:	<u> </u>											
2018 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	2018 - Spring : No Change											
Comments:												

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

18	12 x 12 Red Floor Tile	968	SF	Science / Storage	Miscellaneous	No	None	0	YES	X NO
2017 - Fall: N	No Change									
Comments:										
2018 - Fall: N	No Change									
Comments:										
2018 - Spring	g : No Change									
Comments:										

Type

Material

Category

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9 x 9 Green Floor Tile Mastic	0	SF	Rooms 4, 8, 19, 20-21, 28, 31, 33, 35, 37		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9" x 9" Tan Floor Tile Mastic	0	SF	Rooms 4, 8, 19-21, 28, 31, 33, 35 & 37		Miscellaneous	No	None	0		YES X NO
•											

2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12" x 12" Beige Floor Tile w/Gray Streaks	3600	SF	Rooms 10, 14, 17, 22 & 24		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" Beige Floor Tile w/Gray Streaks Mastic	3600	SF	Rooms 10, 14, 17, 22 & 24		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12" x 12" Tan Floor Tile w/Brown Streaks	7438	SF	Rooms 2, 4, 6, 7, 8, 14, 15, 23, 30		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" Tan Floor Tile w/Brown Streaks Mastic	7438	SF	Rooms 2, 4, 6, 7, 8, 14, 15, 23, 30		Miscellaneous	No	None	0		YES X NO
•											

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	1' x 1' White Ceiling Tile w/Deep Fissures	11650	SF	Rooms 1-8, 25-28 & 30- 32		Miscellaneous	Yes	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
26	12" x 12" Dark Gray Floor Tile w/Black Streaks	12988	SF	Rooms 1, 3, 5, 9, 11, 13, 16, 18, 21, 26-29, 31, 32, principal's, main, counselor's office		Miscellaneous	No	None	0		YES	X NO
2017 - Fall: No Change Comments:												

Comments.
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" Dark Gray Floor Tile w/Black Streaks Mastic	12988	SF	Rooms 1, 3, 5, 9, 11, 13, 16, 18, 21 & 26-29, 31, 32, add principal's, main, counselor's office		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

	'	Quantity	Units		Туре	Category		Туре	Quantity	Units	Ü	0 ,
28	Plaster	30000	SF	Classrooms 9-24, East wing 1st and 2nd floor		Surface	No	None	0		YES	X NO
2017 - Fall:	No Change]							
Comments:												
2018 - Sprin	ıg : No Change											
Comments:												
2018 - Fall:	No Change]							
Comments:					1							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
29	Mortar- CMU	35000	SF	Throughout building - west wing, classrooms 1- 8, 25-28, corridors, boys and girls restrooms		Surface	No	None	0		YES	X NO
2017 - Fall:	No Change				1							

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Comments:

Comments:

Comments:

2018 - Fall: No Change

2018 - Spring : No Change

Material Description

Material

Material

Material

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30M	9"x9" brown w/ peach streaks VFT mastic	20	SF	main office storage closet		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Red duct sealant	50	LF	Boiler room		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: CICS - Wrightwood
Date: 12/18/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 66381

SCHOOL'S ASBESTOS MANAGEMENT PLAN.