## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

66392

**Oracle Unit:** 

Address: 1641 W 16th St Region: Mail Room: Asbestos Surveyor: **MRNAGODE** X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/4/2019 Email Address: mnagode@chicagointl. org A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other HA No Material Description Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Quantity Units Type Throughout Building X NO YES LF Perimeter Walls and First 001 Aircell Pipe Insulation 1280 TSI Yes Dist 128 Floor Northeast Stairs 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Acero Charter Schools - Bartolomé de las Casas

School:

Oracle Unit: 66392

UNOB

**Building ID:** 

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
002	Joint Insulation on Aircell Insulated Piping	120	LF	Throughout Building Perimeter Walls and First Floor Northeast Stairs		TSI	Yes	Dist	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change					•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
003	Plaster Walls	24000	SF	Throughout Building		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
004	Plaster Ceilings	14700	SF	Throughout Building		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	ј : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
005	9"x9" Black Floor Tile	1350	SF	1st & 2nd Floor Corridors, 2nd Floor East & West Stair Foyers		Miscellaneous	No				YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 3

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
006	Mastic Associated with 9" x9" Black Floor Tile	1350	SF	1st & 2nd Floor Corridors, 2nd Floor East & West Stair Foyers		Miscellaneous	No	None			YES		X NO
2016 - Fall	: No Change	•	•	•	]	•	•			•	•		
Comments	S:				- -								
2017 - Spr	ing: No Change												
Comments	S:				1								
2017 - Fall	: No Change												
Comments	): :												
2018 - Spr	ing : No Change				-								
Comments	<u> </u>				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
007	9"x9" Green Floor Tile	1350	SF	1st & 2nd Floor Corridors, 2nd Floor East & West Stair Foyers		Miscellaneous	No	None			YES X NO

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
008	Mastic Associated with 9" x9" Green Floor Tile	1350	SF	1st & 2nd Floor Corridors, 2nd Floor East & West Stair Foyers		Miscellaneous	No	None			YES		X NO
2016 - Fall:	No Change	•		*	]	•	•	•	•	•			
Comments:					1								
2017 - Spri	ng: No Change				_								
Comments:					1								
2017 - Fall:	No Change												
Comments:					_								
2018 - Spri	ng : No Change				-								
Comments:					1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
009	Floor Tile Beneath 9"x9" Grn & Blk Floor Tile	2700	SF	1st & 2nd Floor Corridors, 2nd Floor East & West Stair Foyers		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
010	Mastic Associated w/Bottom Layer of Floor Tile	2700	SF	1st & 2nd Floor Corridors, 2nd Floor East & West Stair Foyers		Miscellaneous	No	None			YES	X NO
2016 - Fal	I: No Change				]			•	•	•		
Comments												
2017 - Spi	ring: No Change				-							
Comments	S:											
2017 - Fal	l: No Change											
Comments	S:											
2018 - Spi	ing : No Change				-							
Comments	S:				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
011	12"x12" Brown Floor Tile	25	SF	2nd Floor East Washroom		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

Page 6

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
012	Mastic Associated with 12" x12" Brown Floor Tile	25	SF	2nd Floor East Washroom		Miscellaneous	No	None			YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
013	12"x12" Reddish-Brown Floor Tile w/White Streaks	875	SF	Garden Level		Miscellaneous	No	None			YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
014	Mastic Assoc. w/12"x12" Reddish Brown Floor Tile	875	SF	Garden Level		Miscellaneous	No	None			YES		X NO
2016 - Fall: N	lo Change							•					
Comments:													
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:													
2018 - Spring	g : No Change												
Comments:	,												
2018 - Fall: N	lo Change												
Comments:	-												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
015	12"x12" Light Brown Floor Tile	114	SF	Garden Level		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
016	Mastic Assoc. w/12"x12" Light Brown Floor Tile	114	SF	Garden Level		Miscellaneous	No	None			YES	X NO
2016 - Fall:	No Change											
Comments:	-											
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	-											
1					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
017	12"x12" Beige Floor Tile	582	SF	Room 105		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
018	Mastic Assoc. w/12"x12" Beige Floor Tile	582	SF	Room 105		Miscellaneous	No				YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:		•										

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
019	Black Linoleum	247	SF	1st Floor West Staircase		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
020	Black Linoleum Adhesive	247	SF	1st Floor West Staircase		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	2018 - Fall: No Change											
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
021	Blackboard Material	880	SF	Rooms 101-105, 201-205		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
022	1'x1' Ceiling Tile	1113	SF	Garden Level		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Spring: No Change					1							

2017 - Fall: No Change Comments:

2018 - Spring : No Change

Comments:

2018 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
023	1'x1' Ceiling Tile Adhesive	1113	SF	Garden Level		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
024	Interior Window Glaze	150	LF	Rooms 104 & 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	•											
2017 - Fall:	No Change											
Comments:	· · · · · · · · · · · · · · · · · · ·											
2017 - Sprir	ng: No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
025	Interior Window Caulk	700	LF	Garden Level		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
026	Drywall	20	SF	Throughout		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	:											
2017 - Spri	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Spri	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
027	1'x1' Fissured Ceiling Tile	900	SF	Room 101		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
028	1'x1' Fissured Ceiling Tile Adhesive	900	SF	Room101		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
029	12 x 12 blue floor tile	10000	SF	Ground level, 1st and 2nd floor hallways		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
030	Mastic for 12" x 12" Blue floor tile	10000	SF	Ground level, 1st and 2nd floor hallways		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Spring: No Change Comments:												

2017 - Fall: No Change

Comments:

2018 - Spring : No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
031	12" x 12" Yellow floor tile	1000	SF	Ground level lunch room, 1s and 2nd floor halls		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
032	Mastic for 12" x 12" yellow floor tile	1000	SF	Ground level lunch room, 1st and 2nd floor halls		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Sprin	ıg: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
033	2' x 2' Ceiling tile white	5000	SF	Office, storage 014		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
034	12" x 12" white floor tile with brown and green specks	10000	SF	Elevator lobby, 101, 102, 103,104, 105, 201, 203, 205, 206, 208, 213		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
035	Mastic for 12" x 12" white floor tile with brown and green specks	10000	SF	Elevator lobby, 101, 102, 103,104, 105, 201, 203, 205, 206, 208, 213		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36	2x4 Ceiling tile white- smooth	300	SF	Pantry		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												
0047 On via	a. Na Obasa											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	4" Blue vinyl base cove	3000	LF	Throughout		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

		Quantity	Units		Type	Category		Type	Quantity	Units		
038	Mastic for 4" base cove	3000	LF	Throughout		Miscellaneous	No	None	0		YES	X NO
	: No Change											
Comments	•											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	: No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments												
2018 - Fall:	: No Change											
Comments												

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
039	Blue vinyl stair tread	500	SF	East Stariwell		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
40	Adhesive for blue vinyl stair tread	500	SF	East stairwell		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change							•				
Comments:	_											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:	<del></del>											
2018 - Fall: I	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Purple vinyl stair tread	500	SF	West stairwell.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units	_	
42	Adhesive for purple stair tread	500	SF	West stariwell		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	<b>:</b>											
2017 - Fall	: No Change											
Comments	<b>:</b>											
2018 - Spr	ing : No Change											
Comments	S:											
2018 - Fall	: No Change											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
043	Drywall	27000	SF	Throughout school		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No

Comments:

Material Description

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
43	White Sink Insulation	2	EA	Teacher's Lounge (206)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change				-							
Comments	:											
2017 - Fall:	: No Change				-							
Comments	:											
2018 - Spri	ng : No Change				-							
Comments	:											
2018 - Fall:	: No Change				-							
Comments	:				1							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
044	Drywall joint compound	2700	SF	Throughout school		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
44	Aircell on Ducting	100	LF	Church Boiler Room		TSI	Yes	Dist	100		YES	X NO
2016 - Fall: No Change												
Comments:												
2017 - Spring	: No Change											
Comments:	•											
2017 - Fall: N	lo Change				_							
Comments:					]							
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change				1							
Comments:	Ŭ											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
045	Light brown carpet mastic	100	SF	Entrance landings		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 24

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Acero Charter Schools - Bartolom© de las Casas
Date: 1/25/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.