## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Acero Charter Schools - Major Hector P. Garcia MD 66394 3343 School: **Oracle Unit: Building ID:** Address: 4248 W 47th St. Region: Mail Room: Asbestos Surveyor: NSANCHEZ1 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/4/2019 Email Address: nsanchez@unocharters chools.org A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other HA No **Material Description** Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Quantity Units Type Throughout 1st & 2nd X NO 1 SF YES Drywall 14000 Miscellaneous No None 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
2	Drywall Joint Compound	9000	SF	Throughout 1st & 2nd Floors		Miscellaneous	No	None			YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	12" X 12" Light Blue Mix Floor Tile	23325	SF	1st Floor Halls, Classrooms, Teachers Offices, Vestibules , Bathrooms		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
4	12' X 12" Blue Mix Floor Tile	1250	SF	1st Floor halls, Engineers office		Miscellaneous	No	None			YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
1 9
Comments:
2040 Falls Na Ohanna
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	12" x 12" Dark Blue Mix Floor Tile	55	SF	1st Floor Halls and Engineers office		Miscellaneous	Yes	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
6	12" X 12" White with Gray Mix Floor Tile	13675	SF	1st Floor Halls, teachers offices, bathrooms, and resource room		Miscellaneous	Yes	None			YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	12" x 12" White with Blue Specks Floor Tile	270	SF	1st Floor Teachers Office 1-50		Miscellaneous	Yes	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

9	12" x 12" Green Mix Floor Tile	1250	SF	2nd Floor - Halls, Engineer's office		Miscellaneous	Yes	None		YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Mastic used for Floor Tiles	78400	SF	1st & 2nd Floor Halls, Vestibule, Teachers Offices, Bathrooms. Classrooms, Engineers Office		Miscellaneous	Yes	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categorial	ory
13	Carpet Adhesive for Blue and Black Striped Carpet Tiles	275	SF	1st floor small corner offices		Miscellaneous	Yes	None			YES X NO	
2016 - Fall: N	No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Carpet adhesive for Green/Yellow Striped Carpet Tile	275	SF	2nd Floor Small Corner Offices		Miscellaneous	Yes	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
15	4" Sky Blue Baseboard	5400	LF	Throughout 1st Floor		Miscellaneous	Yes	None			YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	ı: No Change				_							
Comments:	•											
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	ı : No Change				1							
Comments:	· ·											
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	4" Light Green Baseboards	5520	LF	Throughout 2nd Floor		Miscellaneous	Yes	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
17	Mastic used for baseboards	10920	LF	Throughout 1st and 2nd Floor		Miscellaneous	Yes	None			YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	2' X 2' White Ceiling Tiles	28000	SF	1st & 2nd Floor Halls, Vestibule , Teachers Office		Miscellaneous	Yes	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

19	2' X 4' Drop Face White with Pin Dots Ceiling Tile	21875	SF	1st and 2nd Floor Classrooms and Multi- Purpose Room		Miscellaneous	Yes	None		YES	X NO
2016 - Fall:	No Change	•	<u> </u>	·	7						
	140 Orlange				4						
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2017 - Fall: No Change					1						
Comments:											
2018 - Spring : No Change											
Comments:											
					1						
2018 - Fall: No Change											
Comments:				1							
					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
20	sinks	14		4 classrooms ( 2 Arts Rooms & 2 Science Rooms) in 1st & 2nd Floors, and Multi-Purpose Rooms		Miscellaneous	Yes	None			YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

21	Roof Field	67000	SF	Roof		Miscellaneous	Yes	None			YES	X NO
2016 - Fall: No Change					7							
Comments:					]							
2017 - Spring	ı: No Change				1							
Comments:	, <u> </u>											
2017 - Fall: N	lo Change				1							
Comments:				_								
2018 - Spring : No Change				-								
Comments:												
2018 - Fall: No Change				_								
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
22	Roof Flashing	2500	LF	Roof		Miscellaneous	Yes	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

2016 - Fall: No Change

Material Description

Material

Units

Material

Quantity

Material Location

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Acero Charter Schools - Major Hector P. Garcia MD
Date:1/25/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 66394