Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Acero Charter Schools - PFC Omar E. Torres 66396 3345 School: **Oracle Unit: Building ID:** Address: 4248 W 47th St. Region: Mail Room: Asbestos Surveyor: NSANCHEZ1 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/4/2019 Email Address: nsanchez@unocharters chools.org A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other HA No **Material Description** Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Quantity Units Type X NO 1 SF 0 YES Drywall 14000 Throughout 2nd Floor Miscellaneous No None 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
2	Drywall Joint Compound	9000	SF	Throughout 2nd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:	-											
2018 - Fall: N	lo Change											
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
8	12" X 12" Light Green Mix Floor Tile	23325	SF	2nd Floor halls, Classrooms, Teacher office, Bathrooms		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
8M	12" X 12" Light Green Mix Floor Tile Mastic	23325	SF	2nd Floor Halls, Classrooms, Teacher office, Bathrooms		Miscellaneous	No	None	0		YES X NO		
2016 - Fall: No Change													

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	12" X 12" Green Mix Floor Tile	1250	SF	2nd Floor Halls , Engineers office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9M	12" X 12" Green Floor Tile Mastic	1250	SF	2nd Floor Halls, Engineers office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2010 0 : 11 01
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
10	12" X 12" Dark Green Mix Floor Tile	50	SF	2nd Floor Halls and Engineers Office		Miscellaneous	No	None	0		YES X NO		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

10M	12" X 12" Dark Green Mix Floor Tile Mastic	50	SF	2nd Floor Halls and Engineers Office		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:	-										
2018 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:	-										
		-		•	•						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12" X 12" White with Green Specks Floor Tile	15000	SF	2nd Floor Halls, teachers offices, bathrooms, resource room, and multi- purpose room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Page 5

	·	Quantity	Units		Type	Category		Type	Quantity	Units		
11M	12" X 12" White with Green Specks Floor Tile Mastic	15000	SF	2nd Floor halls, teachers offices, bathrooms , resource room, and multi- purpose room		Miscellaneous	No	None	0		YES	х мо
2016 - Fal	II: No Change											
Comments	S:											
2017 - Spr Comments	ring: No Change s:											

Material

Friable

Damage

Damage

2017 - Fall: No Change
Comments:

2018 - Spring : No Change
Comments:

Material

Material Material Location

2018 - Fall: No Change Comments:

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Carpet Adhesive for Green/Yellow Striped Carpet Tile	275	SF	2nd Floor Small Corner Offices		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

16	4" Light Green baseboards	5520	LF	Throughout 2nd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring: No Change												
Comments:	•											
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
17	Mastic used for baseboards	10920	LF	Throughout 2nd Floor		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	2' X 2' White Ceiling Tiles	28000	SF	2nd Floor Halls, Vestibule, Teachers Offices		Miscellaneous	Yes	None	0		YES X NO
2016 Fall: N	lo Chango	•	•	•]	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	2' X 4' Drop Face White with Pin Dots Ceiling Tile	21875	SF	2nd Floor Classrooms and Multi- Purpose room		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 8

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Sinks	14		2 Classrooms (Art Room & Science Room) in 2nd Floors, and Multi Purpose Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Acero Charter Schools - PFC Omar E. Torres
Date: 1/25/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.