## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2018 - Fall

Acero Charter Schools - Esmeralda Santiago 66601 5780 School: **Oracle Unit: Building ID:** Address: 2510 W Cortez Region: 02 Mail Room: Asbestos Surveyor: NSANCHEZ1 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/4/2019 Email Address: nsanchez@unocharters chools.org A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other HA No Material Description Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Quantity Units Type Cementitious Pipe Joint TSI X NO YES LF 001 on Low Pressure Steam Throughout Facility TSI (NOT OBSERVED) 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 66601

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
002	Insulation on Low Pressure Steam Piping (NOT OBSERVED)	250	LF	Throughout Facility		TSI					YES	X NO
	: No Change			•			•	•		•	•	
Comments	:											
2017 - Spr	ng: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2018 - Spr	ng : No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
003	Cementitious Pipe Joint TSI - Domestic Cold Water	3	LF	Cafeteria		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
004	Paperwrap Pipe TSI on Dom. Cold Water Piping	40	LF	Cafeteria- All Purpose Room		TSI	Yes	Dist	1		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
005	Cementitious Joint Insulation on Fiberglass Piping	12	LF	Basement		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006	Cementitious Joint TSI on Corrugated Pipe TSI	3	LF	Cafeteria		TSI	Yes	None	0		YES X NO
2016 Fall No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
007	Aircell Pipe Insulation	40	LF	Ground Floor, Cafeteria		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
800	Vinyl Floor Tile and Mastic (NOT OBSERVED)	6500	SF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall	No Change				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
009	Vinyl Floor Tile and Mastic (NOT OBSERVED)	600	SF	Ground Floor		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
010	Linoleum (NOT OBSERVED)	400	SF	Throughout Facility		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				=							
Comments:												
2018 - Spring	g : No Change				=							
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
011	Linoleum Adhesive (NOT OBSERVED)	400	LF	Throughout Facility		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
012	Flooring Material (NOT OBSERVED)	270	SF	Ground Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments	:				-							
2017 - Spri	ing: No Change											
Comments	Comments:											
2017 - Fall: No Change												
Comments	S:											

2018 - Spring : No Change

Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
013	White Vinyl Floor Tile (NOT OBSERVED)	270	SF	Second Floor		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

014	White Floor Tile Mastic (NOT OBSERVED)	270	SF	Second Floor		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	la Changa										
	io Change										
Comments:											
2017 - Spring	j: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	j : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	-										
					]						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
015	9"x9" Brown Mix Floor Tile	468	SF	Maintenance Room, Cafeteria Storage Room 001		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Page 8

016	Mastic Associated with 9" x9" Brown Mix Floor Tile	468	SF	Maintenance Room, Cafeteria Storage Room 001		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change	•	•	•	]	•	•	•	•	•	•	
Comment												
2017 - Sp	ring: No Change											
Comment												
2017 - Fa	II: No Change											
Comment	S:											
2018 - Sp	ring : No Change											
Comment	S:											
2018 - Fa	II: No Change											
Comment	S:											

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
017	Hard Wall and Ceiling Plaster	8500	SF	Throughout Facility		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
018	12"x 12" Green Floor Tile	856	SF	First & Second Floor Corridors		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
Commond.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
019	Mastic Associated with 12"x 12" Green Floor Tile	856	SF	First and Second Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

		Quantity	Units		Туре	Category		Type	Quantity	Units		
020	12"x 12" White w/Green & Brown Specks Floor Tile	2000	SF	First and Second Floor Corridors		Miscellaneous	No	None	0		YES	X NO
004C Fall N	- Ob				1							
2016 - Fall: N	o Cnange											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	-											

Material

Friable

Damage

Damage

Asbestos

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
021	12"x12" White w/Green & Brown Specks Floor Tile Mastic	2000	SF	First and Second Floor Corridors		Miscellaneous	No	None	0		YES X NO

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
022	12"x 12" Blue Mix Floor Tile (Not Observed)	5040	SF	Lunchroom and Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:					]							
2017 - Spring	g: No Change											
Comments:					]							
2017 - Fall: N	No Change				_							
Comments:					]							
2018 - Spring	g : No Change				_							
Comments:	-											
2018 - Fall: N	No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
023	12"x 12" Blue Mix Floor Tile Mastic (NOT OBSERVED)	5040	SF	Lunchroom and Kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 12

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
024	12"x 12" Beige w/Brown Specks Floor Tile	176	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
025	12"x 12" Beige w/Brown Specks Floor Tile Mastic	176	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
026	12"x 12" Wood Patterned Floor Tile	30	SF	Boys Washroom Landing Only		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
027	12"x12" Wood Patterned Floor Tile Mastic	30	SF	Boys Washrooms Landing Only		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

028	12"x 12" Brown w/White Specks Floor Tile (NOT OBSERVED)	312	SF	Kitchen		Miscellaneous			YES	X NO
2016 - Fall: N	lo Change									
Comments:										
Commonto.										
2017 - Spring: No Change										
Comments:										
0047 Fall N	I. Oli									
2017 - Fall: N	lo Change									
Comments:										
2019 Spring	g : No Change									
	j . No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										
Comments.										
					1					

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
029	Mastic Assoc. w/12"x12" Brn w/Wh Specks Floor Tile (NOT OBSERVED)	312	SF	Kitchen		Miscellaneous					YES X NO

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Page 15

030	12"x 12" Brown Swirl Floor Tile (NOT OBSERVED)	8	SF	Kitchen		Miscellaneous			YES	X NO
0040 5-11 1	I . Ol				Ī					
2016 - Fall: N	io Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
0040 5.11 1	I. Ob									
2018 - Fall: N	lo Change									
Comments:										
2018 - Spring	g : No Change									
Comments:	Comments:									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
031	12"x12" Brown Swirl Floor Tile Mastic (NOT OBSERVED)	8	SF	Kitchen		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Type	Category		Type	Quantity	Units		
032	Textured Paint on Pipe	5	LF	Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	j : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												

Material

Damage

Friable

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
033	2'x4' Lay In Ceiling Panels	4576	SF	Lunchroom		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
034	Interior Window Glaze (NOT OBSERVED)	384	SF	Ground Floor Windows		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
035	Interior Window Caulk (NOT OBSERVED)	384	SF	Ground Floor Windows		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
036	Interior Window Glaze (NOT OBSERVED)	1500	SF	First and Second Floors		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change				-							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
037	Chalk Board Adhesive	2400	SF	Classrooms and Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
038	Red with Tan Streaks Vinyl Stair Treads	0	SF	Stairways		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				]							
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:		·										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
039	Red with Tan Streaks Vinyl Stair Treads Adhesive	0	SF	Stairways		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
040	Insulation in Fire Door	28	SF	Mechanical Room Entrance		TSI	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Green Ceramic Floor Tile Grout	216	SF	Basement Boys Toilet		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	,	Quantity	Units		Type	Category		Туре	Quantity	Units	Ü	3 ,
42	Green Ceramic Floor Tile Adhesive	216	SF	Basement Boys Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comments	3:											
2017 - Spr	ring: No Change											
Comments	3:											
2017 - Fal	I: No Change											
Comments	3:											
2018 - Spr	ring : No Change											
Comments	S:											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Pink Ceramic Floor Tile Grout	216	SF	Basement Girls Toilet		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

2018 - Fall: No Change

Comments:

Material Description

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
44	Pink Ceramic Floor Tile Adhesive	216	SF	Basement Girls Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Blue with Tan Carpet Adhesive	100	SF	1st Floor by DePaul Room (Engineer Office)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12 x 12 Tan Ceramic Floor Tile Grout	180	SF	2nd Floor Mens and Womens Toilets		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12 x 12 Tan Ceramic Floor Tile Adhesive	180	SF	2nd Floor Mens and Womens Toilets		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
48	Blue Carpet Adhesive	144	SF	2nd floor by Erikson Institute Lounge (MDF Room 208)		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change	<u> </u>			1							
Comment												
2017 - Sp	oring: No Change											
Comment	ts:											
2017 - Fa	II: No Change											
Comment	ts:											
2018 - Sp	oring : No Change											
Comment	ts:											

I	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
	50	Green Vinyl Stair Treads	2160	SF	Stairways - Throughout Bldg		Miscellaneous		None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

Page 25

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
51	Mastic associated with New HA #50 -Green Vinyl Stair Treads	2160	SF	Stairways throughout building.		Miscellaneous		None	0		YES	X NO
2016 - Fall	: No Change					•	•					
Comments	): :											
2017 - Spr	ing: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments												
2018 - Spr	ing : No Change											
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
52	12"x 12" Orange VFT	100	SF	Cafeteria Storage Room #001 (Maint. Room)		Miscellaneous		None			YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
53	Mastic associated with New HA# 52 - Orange VFT	100	SF	Cafeteria Storage Room #001 Maint.Room.		Miscellaneous		None			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring:	: No Change											
Comments:												
2017 - Fall: No	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12"x12" Gray w/Dark and Light Gray VFT	3500	SF	Cafeteria		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12"x12" Gray w/Dark and Light Gray VFT (Mastic)	3500	SF	Cafeteria		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12"x12" Tan w/White and Tan Streaks VFT	300	SF	Kitchen and Kitchen Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12"x12" Tan w/White and Tan Streaks VFT (Mastic)	300	SF	Kitchen and Kitchen Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

_	Acero Charter Schools - Esmeralda Santiago
Date: _	1/25/2019
the Asbesto	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of os Management Plan is available at each school during school hours by appointment. o review the Asbestos Management Plan must be made at least 24 hours in advance.
The last ins	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2016. urveillances are conducted every six months.
CHECK ON	<u>E</u>
A col	py of this notice was sent home in each child's backpack.
A co	py of this notice was printed in the school's newsletter and sent home with each child
A co	py of this notice was printed in the school's calendar and sent home with each child
Othe	er.
	OF THIS NOTICE MUST BE PLACED IN THE OOL'S ASBESTOS MANAGEMENT PLAN.