Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

		cero Charter Schools 420 Fairfield	- Brighton	Park			racle Unit: egion:	666	02	Building Mail Roo		1	
					os Surveyor:	NSANCH	IEZ1						
X CHECK	HERE IF NO	CHANGE TO) ASBE	STOS Survey	Date:	1/4/2019							
				Email A	ddress:	nsanchez chools.or	z@unocharto g	ers					
	A copy of the2	016/2017 notice to p	parents and	I staff regarding the as	bestos manag	ement plan not	ifications w	vas distribute	d via:				
	Each child's	backpack	Notice	printed in school's new	vsletter	Notice prin	Notice printed in school's cale		r Ot	her			
HA No	Material Descript	ion Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	lssess	ment Category
1	Drywall	60000	SF	Throughout Classrooms and Corridors		Miscellaneous	No	None	0		YES		X NO
2017 - Fall: N	o Change												
Comments:	0												

2018 - Fall: No Change

Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	Drywall Joint Compound	25000	SF	Throughout Classrooms and Corridors		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change	
Comments:	
Johnnends.	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	12"x12" White with Black Specks Floor Tile	25000	SF	Throughout Classrooms, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ЗA	Mastic associated with 12" x12" White with Black Specks Floor Tile	25000	SF	Throughout Classrooms, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES XNO

2017 - Fall: No Change
Comments:
2017 Spring: No Change
2017 - Spring: No Change Comments:
2018 - Fall: No Change
Comments:
2010 Carling No. Observe
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12"x12" Green Mottled Floor Tile	10000	SF	Throughout Classrooms, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4A	Mastic associated with 12" x12" Green Mottled Floor Tile	10000	SF	Throughout Classrooms, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
bomments.	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	2'x2' Ceiling Tile - White Gouges and Pinholes	4500	SF	1st Floor Classrooms		Miscellaneous	Yes	None	0		

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	4" Brown Baseboard	8000	LF	Classrooms and Corridors		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change	
Comments:	
2017 Falls No Change	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A	4" Brown Baseboard Adhesive	8000	LF	Classrooms and Corridors		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	White Acoustical Ceiling Plaster	9000	SF	1st Floor Lobby, Main Office, Lunch Room, 23, 24, 25, 26, 201, 242, 2nd Floor South Corridor		Surface	Yes	None	0		

2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	Terrazzo Floor - Beige, Green, Gray	8000	SF	Lunchroom, 2nd Floor South Corridor		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Green Sheet Flooring	3600	SF	Kitchen		Miscellaneous	No	None	0		YES X NO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9A	Adhesive associated with Green Sheet Flooring	3600	SF	Kitchen		Miscellaneous	No	None	0		YES X NO

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	2'x2' Smooth White Ceiling Tile	3600	SF	Kitchen		Miscellaneous	Yes	None			YES X NO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9"x9" Green and White Floor Tile	100	SF	MDF Room 26		Miscellaneous	No	None			YES X NO

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	Mastic associated with 9" x9" Green and White Floor Tile	100	SF	MDF Room 26		Miscellaneous	No	None			YES X NO

2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	1'x1' Glued on White with Even Holes Ceiling Tile	1600	SF	31, 36, 37, 38		Miscellaneous	Yes	None			YES XNO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	Adhesive associated with 1'x1' White with Even Holes Ceiling Tile	1600	SF	31, 36, 37, 38		Miscellaneous	No	None			YES XNO

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Acero Charter Schools - Brighton Park
Date:	1/25/2019

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

CHECK ONE

A copy of this notice was sent home in each child's backpace	:k.
--------------------------------------------------------------	-----

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.