Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

YCCS-West HS 66628 Building ID: 1121B School: **Oracle Unit:** Address: 4909 W. Division Region: Mail Room: Asbestos Surveyor: ABALLARD1 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/21/2018 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other Letter Mailed Each child's backpack Notice printed in school's calendar Damage HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 2 x 4 Ceiling Tile - NOT IN YES X NO 01 USE, MOVED FROM 1ST Miscellaneous TO 2ND FLOOR 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

02	2 x 2 Smooth Ceiling Tile - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	3											
2017 - Spring	: No Change											
Comments:	J											
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2018 - Spring	: No Change											
Comments:	•											
2018 - Fall: N	o Change											
Comments:	J											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Type

Type

Material

Category

Category

Damage

Туре

Type

Damage

Quantity

Damage

Units

Units

YES

X NO

Quantity

Friable

03	2 x 2 Rough Ceiling Tile - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR			Miscellaneous		
2016 - Fa	all: No Change					
Commen	ts:					
2017 - Sp	oring: No Change					
Commen	ts:					
2017 - Fa	all: No Change					
Commen	ts:					
2018 - Sp	oring : No Change					

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Material

Units

Material

Quantity

Quantity

Units

Material Location

HA No

Comments:

Comments:

2018 - Fall: No Change

Material Description

Oracle Unit: 66628

Page 2

04	Brown Carpet Mastic - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:	•											
0047 Falls	No Oboros											
	No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:												
	•											
2018 - Fall:	No Change											
Comments:	·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
05	Blue Carpet Mastic - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
06	Brown Baseboard - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:					_							
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:	•											
2018 - Fall: N	o Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
07	Black Baseboard Mastic - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES	Х мо
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	J											
2017 - Fall: N	o Change											
Comments:	- J -											

2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08	Drywall - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES	X NO
2016 - Fall: I	No Change				7							
Comments:	•											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09	Drywall Joint Compound - NOT IN USE, MOVED FROM 1ST TO 2ND					Miscellaneous					YES	X NO

FLOOR	,			
2016 Falls No Change				
2016 - Fall: No Change				
Comments:				
2017 - Spring: No Change				
Comments:				
2017 - Fall: No Change				
Comments:				
2018 - Spring : No Change				
Comments:				
2018 - Fall: No Change				
Comments:				•
		•	·	·

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		0 ,
10	Vibration Dampers - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	Ü											
2017 - Spring	g: No Change											
Comments:	J											
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
	1		1									

TSI

Asbestos

Material

Friable

Damage

Damage

Damage

Material Location

		,		
11	Fittings on Pipe with Fiberglass Insulation - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR			
0010 5 11 11				
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:			•	
	-	·	·	

HA No

Material Description

Material

Material

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12 x 12 Blue Floor Tile - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 66628

Page 7

13	12 x 12 Blue Floor Tile Mastic - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change				=							
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					4							
					_							
LIA NI-	Material Described as	NA-t-d-1	NA - t - of - 1	Martin della and Com	A -11	NA - (2 - 1	Estable.	D	D	D	Ol '- A	

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	12 x 12 White with Beige Floor Tile - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES	X NO
2016 - Fall: I	No Change]							

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12 x 12 White with Beige Floor Tile Mastic - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12x12 Light blue w/ specks VFT	5000	SF	Rooms 200, 202, 203, 204, 205, 206, 207, 208A, 208B, 208C, 209, Main office, 2nd floor corridors and resource center		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A	12x12 Light blue w/ specks VFT Mastic	5000	SF	Rooms 200, 202, 203, 204, 205, 206, 207, 208A, 208B, 208C, 209, Main office, 2nd floor corridors and resource center		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
17	2x2 Ceiling Tile wormy w/dots white	450	SF	2nd floor corridors, mens toilet and refuse room		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	: No Change]							
Comments	:											
2017 - Spri	ing: No Change											
Comments	:				1							
2017 - Fall:	: No Change				-							
Comments	:				1							
2018 - Spri	ing : No Change											
Comments	:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	2x4 Ceiling Tile white wormy w/dots	4000	SF	Throughout 2nd Floor		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
19	Baseboard Mastic	350	SF	Throughout 2nd floor		Miscellaneous	No	None	0		YES	X NO
	: No Change											
Comments	:				4							
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	: No Change											
Comments	:											
2018 - Spri	ing : No Change											
Comments	:											
2018 - Fall:	: No Change											
Comments	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12x12 Offwhite VFT	45	SF	Janitors closet & electrical room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20A	12x12 Offwhite VFT Mastic	45	SF	janitors closet & electrical room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	g : No Change				<u> </u>							
Comments:					_							
2018 - Fall: N	lo Change]							
Comments:					_							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Spray-on Insulation - NOT IN USE, MOVED FROM 1ST TO 2ND FLOOR					Surface					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

	YCCS-West HS
Date: _	12/21/2018
the Asbesto	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of os Management Plan is available at each school during school hours by appointment. o review the Asbestos Management Plan must be made at least 24 hours in advance.
The last ins	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2016. surveillances are conducted every six months.
CHECK ON	<u>IE</u>
A co	opy of this notice was sent home in each child's backpack.
A co	opy of this notice was printed in the school's newsletter and sent home with each child
A co	opy of this notice was printed in the school's calendar and sent home with each child
X Othe	er. Letter Mailed

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.