## **Chicago Public Schools**

### 6 Month Asbestos Surveillance

2018 - Fall

	School: Address:	Peace and Education Coalition High School 4541 S. Wood St.		Oracle Unit: Region:	67021 04	Building ID: Mail Room:	1123 42
Х СНЕСК Н	ERE IF N	IO CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date: Email Address:	Collins, Michael 1/10/2019			

	A copy of the2016/201	7 notice to	parents and	I staff regarding the asl	pestos manag	ement plan not	ifications w	as distribute	d via:			
	Each child's backpack Notice printed in school's ne			sletter								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
1M	9" x 9" Red & White Floor Tile	700	SF	Wardrobe Closets for Rooms 700, 701 & 1st Floor Landing		Miscellaneous	No				YES	XNO
2018 - Fall: I Comments:	No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9" x 9" Dark Brown Floor Tile	6	SF	Boy's & Girl's Washroom		Miscellaneous	No				YES X NO

2018 - Fall: No Change
Comments:

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1U	9" x 9" Purple Swirl Floor Tile	100	SF	Stairway		Miscellaneous	No				YES XNO

2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1V	9" x 9" White Floor Tile	100	SF	Throughout Building		Miscellaneous	No				YES X NO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1W	9" x 9" Orange Floor Tile	200	SF	First Floor		Miscellaneous	No				YES X NO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3M	9" x 9" Red & White Floor Tile Mastic	700	SF	Wardrobe Closets for Room 700, 701, and 1st Floor Landing		Miscellaneous	No				YES X NO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" Drak Brown Floor Tile Mastic	715	SF	Boy's & Girl's Washrooms		Miscellaneous	No				YES XNO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ЗU	9" x 9" Purple Swirl Floor Tile Mastic	100	SF	Stairway		Miscellaneous	No				YES XNO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3V	9" x 9" White Floor Tile Mastic	200	SF	First Floor		Miscellaneous	No				YES X NO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3W	9" x 9" Orange Floor Tile Mastic	165	SF	First Floor and Room 700		Miscellaneous	No				YES X NO

2018 - Fall: No Change
Comments:

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6		6" Black Vinyl Baseboard	0		Throughout Building		Miscellaneous	No				YES X NO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	6" Black Vinyl Baseboard Mastic	0		Throughout Building		Miscellaneous					YES XNO

2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Hard Coat Plaster	0		Throughout Building		Surface	Yes				YES X NO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12" x 12" White Floor Tile w/Brown Streaks Mastic	0		Room 701		Miscellaneous					YES X NO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12" x 12" White Floor Tile w/Brown Streaks	0		Room 701		Miscellaneous	No				YES XNO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Exterior Brick Mortar - Not AHERA	0		Building Exterior		Miscellaneous	No				YES XNO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Interior Brick	10000	SF	Throughout Building		Miscellaneous	No				YES X NO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Interior Brick Mortar	10000	SF	Throughout Building		Miscellaneous	No				YES XNO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Adhesive Beneath Chalkboards	70	SF	Classrooms		Miscellaneous	No				YES XNO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Mortar Between Glass Block Windows	500	SF	Throughout Building		Miscellaneous	No				YES X NO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A1	Aircell Pipe Insulation	150	LF	Throughout Boy's & Girl's Washrooms		TSI	Yes				YES XNO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Hard Elbow & Joint Compound on Aircell	37	LF	Throughout Boy's & Girl's Washrooms		TSI	Yes				YES XNO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C2	Cardboard Pipe Insulation	20	LF	Throughout Building		TSI	Yes				YES XNO

2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D2	Hard Joint Compound on Cardboard Pipe Insulation	5	LF	Throughout Building		TSI	Yes				

2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Alunha /2

Robert Christlieb

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Peace and Education Coalition High School
Date:	1/10/2019

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

A copy of this notice was sent home in each child's backpac	۲.
---	----

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.