

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2024 Fall Six Month Survey

**School:** Orville T Bright Elementary School  
**Address:** 10740 S. Calhoun

**Oracle Unit:** 22331  
**Region:** 06

**Building ID:** 2390  
**Mail Room:** 47

☒ **CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Oshea, John  
**Survey Date:** 11/25/2024  
**Email Address:** jmoshea1@cps.edu

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ Each child's backpack ☐ Notice printed in school's newsletter ☐ Notice printed in school's calendar ☐ Other

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 01    | Hard Coat Plaster    | 50000             | SF             | Throughout Facility |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2022 Fall Six Month Survey: No Change

Comments:

2023 Fall Six Month Survey: No Change

Comments:

2023 Spring Six Month Survey: No Change

Comments:

2024 Fall Six Month Survey: No Change

Comments:

2024 Spring Six Month Survey: No Change

Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 22331

Page 1

| HA No | Material Description                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02    | 9x9 Floor Tile Beige Specks NOT OBSERVED | 0                 | SF             | Not Observed      |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03    | Canvas Wall Covering | 15000             | SF             | Throughout Facility |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                   | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04    | 12x12 White w/Black Streaks Floor Tile | 8000              | SF             | 1921 Building- 2nd & 3rd Floor Corridors & Room 105 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description   | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04A   | 12x12 Brown Floor Tile | 610               | SF             | Teachers' Lounge, Room 204 |               | Miscellaneous     | No      | None        | 0               |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: Abated                          |
| Comments:contractors new tile                               |
|   |
| 2023 Spring Six Month Survey: Abated                        |
| Comments:contractors installed new tile                     |
|   |
| 2023 Fall Six Month Survey: No Change                       |
| Comments:   |
|   |
| 2024 Spring Six Month Survey: No Change                     |
| Comments:abated new tile 2022                               |
|   |
| 2024 Fall Six Month Survey: No Change                       |
| Comments:Had new tiles a couple of years ago , Not asbestos |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04B   | 12x12 Cream Floor Tile | 1176              | SF             | Room 204 and Dress Room 109B |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description        | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05    | 2'x4' Lay In Ceiling Panels | 900               | SF             | Room 105, Janitor's Closet 107A |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                          | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06    | 12x12 White w/Black Streaks Floor Tile Mastic | 2406              | SF             | 1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07    | 9x9 Beige Speck Floor Tile Mastic | 0                 |                | Not Observed      |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08    | 12x12 White w/Black Streaks Floor Tile | 2406              | SF             | 1938 Addition- 2nd & 3rd Floor Corridors & Stair Landings |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                          | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09    | 12x12 White w/Black Streaks Floor Tile Mastic | 8000              | SF             | 1921 Building- 2nd & 3rd Floor Corridors & Room 105 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09A   | 12x12 Floor Tile Mastic | 610               | SF             | Teachers' Lounge, Room 204 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|  |
|--|
| 2022 Fall Six Month Survey: No Change                          |
| Comments:  |
|  |
| 2023 Spring Six Month Survey: No Change                        |
| Comments:  |
|  |
| 2023 Fall Six Month Survey: Abated                             |
| Comments:Last year new floor added                             |
|  |
| 2024 Spring Six Month Survey: No Change                        |
| Comments:abated in 2022 new tiles                              |
|  |
| 2024 Fall Six Month Survey: No Change                          |
| Comments:Non asbestos. Tiles changed out a couple of years ago |
|  |

| HA No | Material Description          | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09B   | 12x12 Cream Floor Tile Mastic | 1176              | SF             | Room 204 and Dress Room 109B |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10    | Black Vinyl Strip Border | 900               | LF             | 1921 Building- 2nd & 3rd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description            | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11    | Black Vinyl Strip Border Mastic | 900               | LF             | 1921 Building- 2nd & 3rd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description     | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12    | Black Vinyl Strip Border | 210               | LF             | 1938 Addition- 2nd & 3rd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description            | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13    | Black Vinyl Strip Border Mastic | 210               | LF             | 1938 Addition- 2nd & 3rd Floor Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14    | 12x12 Cream w/Tan Specks Floor Tile | 700               | SF             | Office            |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15    | 12x12 White w/Black Specks Floor Tile | 5500              | SF             | 1998 Mobile Unit Classrooms and Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                         | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15A   | 12x12 White w/Black Specks Floor Tile Mastic | 5500              | SF             | 1998 Mobile Unit Classrooms and Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description      | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | Grey Baseboard and Mastic | 2000              | LF             | 1998 Mobile Unit Classrooms and Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | 2'x2' Ceiling Tile   | 5500              | SF             | 1998 Mobile Unit Classrooms and Corridors |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description          | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | Black w/Tan Speckles Terrazzo | 7500              | SF             | 1st Floor Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | Emerald w/Black Speckles Terrazzo Floor | 9500              | SF             | 1st, 2nd & 3rd Floor Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | Ivory w/Black Speckles Terrazzo Floor | 7500              | SF             | 1st Floor Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | Smooth Plaster Walls and Ceilings | 35000             | SF             | Throughout        |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22    | Plaster Walls (Lower Wall, Block Pattern) | 15000             | SF             | Throughout        |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23    | White Ceiling Tile   | 200               | SF             | 1st Floor Elevator Vestibule |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description            | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | Green Mosaic Ceramic Tile Grout | 800               | SF             | 2nd & 3rd Floor Boys' Toilet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | Green Carpet Mastic  | 450               | SF             | Room 306          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description      | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26    | Yellow Ceramic Tile Grout | 450               | SF             | 3rd Floor Girls' Toilet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description    | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27    | Blue Ceramic Tile Grout | 450               | SF             | 2nd Floor Girls' Toilet |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28    | Gray Carpet Mastic   | 800               | SF             | Room 106A Counselor's Office & 106B Speech Therapy Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A     | Mag Block Tank Insulation | 300               | SF             | 1921 Building Basement |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No        | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|--------------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A- Annex "C" | Aircell Pipe Cover   | 700               | LF             | Annex C- Boiler Room & Attic |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B     | Aircell Pipe Insulation | 600               | LF             | 1921 Building- Restrooms and Classrooms & Basement |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BB-1  | Baseboard            | 170               | LF             | Room 104 and Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| BBM-1 | Baseboard Mastic     | 170               | LF             | Room 104 and Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description      | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C     | Cardboard Pipe Insulation | 25                | LF             | 1921 Building- Basement and Toilet |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CM-1  | Baseboard Carpet Mastic | 0                 | SF             | Room 104 -        |               | Miscellaneous     |         | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CM-2  | Blue Carpet Mastic   | 200               | SF             | Room 206          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: Abated      |
| Comments:carpet removed a few years ago |
|   |
| 2023 Spring Six Month Survey: Abated    |
| Comments:contractors put in new tile    |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:Carpet taken out years ago     |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:no carpet for years            |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| CM-3  | Gray Carpet Mastic   | 1230              | SF             | North & South Sky Boxes, and MDF Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description      | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D     | Preformed Pipe Insulation | 156               | LF             | 1921 Building Basement |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                 | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E     | MJP E/F/V on Aircell Pipe Insulation | 25                | LF             | Throughout 1921 Building |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description          | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-1  | 12x12 Beige Specks Floor Tile | 1900              | SF             | Lunchroom Room 108 and Dress Room 109B |               | Miscellaneous     | No      | None        | 0               |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: Abated                          |
| Comments:contractors new tile                               |
|   |
| 2023 Fall Six Month Survey: Abated                          |
| Comments:tiles replaced in lunch room a couple of years ago |
|   |
| 2023 Spring Six Month Survey: Abated                        |
| Comments:contractors new tile in cafe                       |
|   |
| 2024 Fall Six Month Survey: No Change                       |
| Comments:Removed tiles 2 years ago non asbestos             |
|   |
| 2024 Spring Six Month Survey: Abated                        |
| Comments:abated in 2022 new tiles                           |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FT-2  | 12x12 Tan Floor Tile | 520               | SF             | Room 308          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description    | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-1 | 12x12 Floor Tile Mastic | 1900              | SF             | Lunchroom and Dress Room 109B |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change             |
| Comments:   |
|   |
| 2023 Fall Six Month Survey: No Change             |
| Comments:   |
|   |
| 2023 Spring Six Month Survey: Abated              |
| Comments:contractors put in new tile              |
|   |
| 2024 Fall Six Month Survey: No Change             |
| Comments:removed tiles two years ago non asbestos |
|   |
| 2024 Spring Six Month Survey: No Change           |
| Comments:   |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| FTM-2 | 12x12 Tan Floor Tile Mastic | 520               | SF             | Room 308          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G     | MJP E/F/V on Cardboard Pipe Insulation | 6                 | LF             | Throughout 1921 Building |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                   | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H     | MJP E/F/V on Preformed Pipe Insulation | 20                | LF             | Throughout 1921 Building |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description    | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I     | Aircell Pipe Insulation | 0                 | SF             | 1938 Addition-Washrooms and Classrooms |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I-1   | Aircell Pipe Insulation | 800               | LF             | 1938 Addition- Air Tunnel |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description    | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J     | Preform Pipe Insulation | 100               | LF             | 1938 Addition- Tunnel |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                 | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K     | MJP E/F/V on Aircell Pipe Insulation | 20                | LF             | 1938 Addition-Mechanical |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L     | MJP E/F/V on Preformed Pipe Insulation | 50                | LF             | 1938 Addition- Basement |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| M     | Cardboard Pipe Insulation | 40                | LF             | Air Tunnel        |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| N     | MJP E/F/V on Cardboard Pipe Insulation | 8                 | LF             | Air Tunnel        |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| NEW   | Newly Installed Suspect ACM |                   |                | Installed After Implementation of Managment Plan and After Renovations |               | Miscellaneous     |         | Unknown     |                 |              | <input type="checkbox"/> YES             <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| O     | MJP E/F/V on Fiberglass Pipe Insulation | 700               | LF             | Engine Room, Janitor's Closets, Restrooms, Doctor's Office, Room 104, Storage Room and Main Office |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:ok                             |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

*ALL LEA Responsibilities, for this school, will be met.*

A handwritten signature in black ink, appearing to read 'R. Schleyer', is positioned above a horizontal line.

Richard J. Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***



NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Orville T Bright Elementary School

Date: 1/10/2025

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.  
Asbestos surveillances are conducted every six months.

**CHECK ONE**

- ☐ A copy of this notice was sent home in each child's backpack.
- ☐ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☐ Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***