Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Lyman A Budlong Elementary School 22391 School: **Oracle Unit: Building ID:** 2440 Address: 2701 W Foster Avenue Region: 01 Mail Room: Asbestos Surveyor: Greene, Joseph X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/25/2024 Email Address: jgreene14@cps.k12.il.us A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Category Quantity Type Type Room 101, closet & toilet 12"x12" Blue with Speckles YES X NO 04 1100 SF and Room 103 - 1907 Miscellaneous No None 0 Building 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Red w/ yellow streaks VFT	410	SF	Main Office & Storage (Under the Carpet) - 1907 Building		Miscellaneous	No	None	0		YES X NO
•	•	•	•	•		•	•	•	•	-	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Blue with Speckles VFT Mastic	1100	SF	Room 101, closet & toilet and Room 103 - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

07	9"x9" Red w/Yellow Streaks VFT Mastic	410	SF	Main Office & Storage (Under carpet) - 1907 Building		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange									
	Month Survey: No Ch	ange									
Comments:											
2023 Spring S	Six Month Survey: No	Change									
Comments:	•										
2024 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Fall Six Comments:	Month Survey: No Ch	ange			_						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Tan w/ Brown Speckles VFT	2330	SF	Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955 Addition		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" Tan w/ Brown Speckles VFT Mastic	2330	SF	Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955 Addition		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9"x9" Brown VFT (ABATED)			Toilet in 1st Floor Main Office - 1907 Building		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

	·	Quantity	Units		Туре	Category	Туре	Quantity	Units		
10A	9"x9" Brown VFT Mastic (ABATED)			Toilet in 1st Floor Main Office - 1907 Building		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			7						
Comments:											
2023 Fall Six	Month Survey: No Ch	ange									
Comments:											
2023 Spring S	Six Month Survey: No	Change			1						
Comments:					4						
2024 Spring S	Six Month Survey: No	Change									
Comments:					4						
	Month Survey: No Ch	ange									
Comments:					4						

Material

Friable

Damage

Damage

Damage

HA N	lo	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11		12"x12' Light Blue VFT	600	SF	Room 102 - 1907 Building		Miscellaneous	No	None	0		YES X NO
2022	2 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	12"x12" Light Blue VFT Mastic	600	SF	Room 102 - 1907 Building		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Che	2000									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
, v
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Off White w/ Tan Streaks VFT	2600	SF	1st Floor Corridor and Room 101 and Toilet - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	12"x12" Off White w/ Tan Streaks VFT Mastic	2600	SF	1st Floor Corridor and Room 101 and Toilet - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Off White w/ Gray Streaks VFT	1100	SF	Rooms 105, 118 and Hallway by 118 - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	12"x12" Off White w/ Gray Streaks VFT Mastic	1100	SF	Rooms 105, 118 and Hallway by 118 - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9"x9" Brown w/ White Streaks VFT	760	SF	Room 118b (under carpet) & 118C (under HA #13) - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	9"x9" Brown w/ White Streaks VFT Mastic	760	SF	Room 118b (under carpet) & 118C (under HA #13) - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Light Brown w/ white & brown specks VFT	200	SF	Engineer's old office - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
15A	12"x12" Light Brown w/ white & brown specks VFT Mastic	200	SF	Engineer's old office - 1907 Building		Miscellaneous	No	None	0		YES	X NO
		•		•	•			•	•	•	-	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Cream VFT	20	SF	Janitor's closet by Principal's office - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No M	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A 12	12"x12" Cream VFT Mastic	20	SF	Janitor's closet by Principal's office - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" White VFT (Abated)			Room 111 - 1955 Addition (Abated)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
17A	12"x12" White VFT Mastic (Abated)			Room 111 - 1955 Addition (Abated)		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch	ange			_ _ _							
2023 Spring Comments:	Six Month Survey: No	Change			_							
2024 Spring Comments:	Six Month Survey: No	Change			- 							
2024 Fall Six Comments:	Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Peach VFT (ABATED)			1st Floor Middle Hallway - 1955 Addition (ABATED)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

18A	9"x9" Peach VFT Mastic - (ABATED)		1st Floor Middle Hallway - 1955 Addition (ABATED)		Miscellaneous			YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange							
2023 Fall Six	Month Survey: No Cha	ange							
Comments:									
2023 Spring S Comments:	Six Month Survey: No (Change							
2024 Spring S Comments:	Six Month Survey: No (Change							
2024 Fall Six Comments:	Month Survey: No Cha	ange							
]					

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Tan VFT (ABATED)			1st Floor NW Corridor Hallway - 1955 Addition (ABATED)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19A	9"x9" Tan VFT Mastic (ABATED)			1st Floor NW Corridor Hallway - 1955 Addition (ABATED)		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No C	hange	-	•		•	•	•	•	•		
Comments		<u> </u>										
2023 Fall S	Six Month Survey: No C	hange			-							
Comments	:											
2023 Sprin	g Six Month Survey: N	o Change										
Comments	:											
2024 Sprin	g Six Month Survey: N	o Change										
Comments	:	<u> </u>			_							
2024 Fall S	Six Month Survey: No C	hange			1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Tan Spotted VFT (ABATED)			1st Floor NW Corridor Hallway - 1955 Addition (ABATED)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20A	9"x9" Tan Spotted VFT Mastic (ABATED)			1st Floor NW Corridor Hallway - 1955 Addition (ABATED)		Miscellaneous					YES X NO
-	•	•	•		•	*	*	•	•	*	•

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Gray w/ Pink & White Streaks VFT	850	SF	Room 112 - 1955 Addition		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21A	12"x12" Gray w/ Pink & White Streaks VFT Mastic	850	SF	Room 112 - 1955 Addition		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Beige w/ White Speckles VFT	1500	SF	Exit Door, Rooms 113, 114 (under carpet) - 1955 Addtion		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	12"x12" Beige w/ White Speckles VFT Mastic	1500	SF	Exit Door, Rooms 113, 114 (under carpet) - 1955 Additon		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Green w/ Black & White VFT (ABATED)			Room 111 - 1955 Addition (now HA34+35)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
23A	12"x12" Green w/ White & Black VFT Mastic - (ABATED)			Room 111 - 1955 Addition		Miscellaneous					YES	X NO
2022 Fall	Six Month Survey: No Ch	nange	<u> </u>	<u> </u>	j						·	
Comment	S:	•										
2023 Sprii	ng Six Month Survey: No	Change										
Comment	S:											
2023 Fall	Six Month Survey: No Ch	nange			<u></u>							
Comment	S:											
2024 Spri	na Six Month Survey: No	Change										

2021 Ophing Cix Month Carvey: No Change
Comments:
2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Rust Brown w/ White & Brown Streaks VFT - (ABATED)			Room 110 - 1955 Addition		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	12"x12" Rust Brn w/ White & Brn Streaks VFT Mastic - (ABATED)			Room 110 - 1955 Addition		Miscellaneous					YES X NO
2022 Fall Six	Month Survey: No Ch	ange]	-		-			

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Grey VFT	8800	SF	All Rooms Except Boiler Rm, Electrical Rms, Gym and toilets - 1997 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 19

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	12"x12" Grey VFT Mastic	8800	SF	All Rooms Except Boiler Rm, Electrical Rms, Gym and Toilets - 1997 Annex		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change Comments:											
2023 Fall Six Month Survey: No Change											
Cammantai											

2022 Fall Six Month Survey. No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Vinyl Baseboard			All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

26A	Vinyl Baseboard Mastic		All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex				YES	X NO
2022 Fall Six	Month Survey: No Cha	nae						
Comments:		3 -						
2023 Fall Six	Month Survey: No Cha	nge						
Comments:								
2023 Spring	Six Month Survey: No C	Change						
Comments:								
2024 Spring	Six Month Survey: No C	Change						
Comments:								
2024 Fall Six	Month Survey: No Cha	nge						
Comments:								

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	2'x4' Ceiling Tile			All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
28	2'x4' Ceiling Tile			All Rooms Except Bathrooms & Mechanical Rooms - 1998 Fieldhouse							YES	X NO
2022 Fall S	ix Month Survey: No C	hange		•]		•	•	•	•	•	
Comments		<u> </u>			1							
2023 Fall S	ix Month Survey: No C	hange										
Comments												
2023 Sprin	g Six Month Survey: No	Change										
Comments												
2024 Sprin	g Six Month Survey: No	Change										
Comments					_							
2024 Fall S	ix Month Survey: No C	hange			1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Vinyl Baseboard			Throughout 1998 Fieldhouse							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
30	Vinyl Baseboard Mastic			Throughout 1998 Fieldhouse							YES	X NO
2022 Fall Six	Month Survey: No Ch	nange			7							
Comments:	,]							
2023 Fall Six	Month Survey: No Ch	nange										
Comments:	•											
2023 Spring S	Six Month Survey: No	Change			-							
Comments:												
2024 Spring S	Six Month Survey: No	Change			-							
Comments:												
2024 Fall Six	Month Survey: No Ch	nange										
Comments:	•											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Vinyl Baseboard			Throughout 2000 Mobile - Removed from school property		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
32	Vinyl Baseboard Mastic			Throughout 2000 Mobile - Removed from school property		Miscellaneous					YES	X NO
		-	•	•	1	•	•	•	•		•	
2022 Fall Six	Month Survey: No Cha	ange										
Comments:												
2023 Fall Six	Month Survey: No Cha	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:	•	-										
					1							

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" Coffee w/ cream streaks VFT	300	SF	Room 117		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

2024 Fall Six Month Survey: No Change

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	12"x12" Coffee w/ cream streaks VFT Mastic	300	SF	Room 117		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" White w/Black Specks Floor Tile	3200	SF	Lunchroom, Kitchen Office and Corridor - 1955 Additon		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

35	12"x12" White w/Black Specks Floor Tile MASTIC	3200	SF	Lunchroom, Kitchen Office and Corridor - 1955 Addition		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange	•	•	7	•	•	•	•	•	•	
Comments:	Civional Carvey. 140 On	arigo			1							
Comments.					-							
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
					4							
	Six Month Survey: No	Change										
Comments:												
00045 !! 0	14 (1 0 1)				4							
	Month Survey: No Ch	ange			_							
Comments:												

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Terrazzo - NOT OBSERVED	1200	SF	3rd Floor Boys and Mens Toilet and 2nd Floor Girls and Women'sToilet - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Mastic Under Rubber Stair Tread	800	SF	Stairwell - 1907 Building		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Carpet Mastic	3000	SF	Assembly Hall Balcony, Assistant Principal's Office, Room 101, 104, 106, 204, 102 ward, Main office, Principal's Office Basement Rm 116 (Old Library) - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"X12" White w/ Gray Specks VFT	800	SF	Basement Rm 115 - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39A	12"X12" White w/ Gray Specks VFT Mastic	800	SF	Basement Rm 115 - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	2' x 4' Ceiling Tile	9500	SF	3rd, 2nd and 1st Floor Corridors, Room 204, Main Office, Room 107, Basement Room 116, 117, 115, Basement Engineer Office, Room 119, 118B, 118C, Corridor by 118C & 118B - 1907 Building		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" White with Brown Streaks VFT	300	SF	Basement Room 117 - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41A	12" x 12" White with Brown Streaks VFT Mastic	300	SF	Basement Room 117 - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" Blue VFT NOT OBSERVED	41	SF	Lunch Room - 1955 Addition		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42A	12" x 12" Blue VFT Mastic - NOT OBSERVED	41	SF	Lunch Room - 1955 Addition		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Red VFT NOT OBSERVED	41	SF	Lunch Room - 1955 Addition		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 5 11 2: 14 11 2 11 21
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43A	12" X 12" Red VFT Mastic - NOT OBSERVED	41	SF	Lunch Room - 1955 Addition		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	1' x 1' White Groove Ceiling Tile	5000	SF	Throughout 1955 Addition		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Aqua Green VFT	160	SF	Classrooms and Corridor - 1997 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45A	12" x 12" Aqua Green VFT Mastic	160	SF	Classrooms and Corridor - 1997 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12" x 12" Beige VFT	160	SF	Classrooms and Corridor - 1997 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46A	12" x 12" Beige VFT Mastic	160	SF	Classrooms and Corridor - 1997 Annex		Miscellaneous	No	None	0		YES X NO
2022 Fall Civ	Month Cumas a No Cha										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" x 12" Blue VFT	160	SF	Classroom and Corridor - 1997 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
47A	12" x 12" Blue VFT Mastic	160	SF	Classroom and Corridor - 1997 Annex		Miscellaneous	No	None	0		YES X	NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
Commonic.
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" x 12" Off White VFT	160	SF	Classrooms and Corridor - 1997 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48A	12" x 12" Off White VFT Mastic	160	SF	Classrooms and Corridor - 1997 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Tank Insulation	20	SF	Tank Room - 1907 Building		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
50	2'x4' White Smooth Ceiling Tile	800	SF	Old Girls Playroom - 1907 Building		Miscellaneous	Yes	None	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Textured Paint on Drywall ceiling	700	SF	Basement- Girls and boys Toilet - 1907 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Carpet Mastic	1200	SF	Room 114 - 1955 Addition		Miscellaneous	No	None	0		YES X NO
					i						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Drywall System	4000	SF	All Restrooms - 1907 Building		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	MJP E/F/V on Fiberglass Pipe Insulation	430	EA	Boiler, Tank & Fan Rooms, Room Facing 119, Basement Boys & Girls Toilets - 1907 Building		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Cardboard Pipe Insulation	1148	LF	Throughout - 1907 Building (See Hatching Maps)		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	MJP E/F/V on Cardboard Pipe Insulation	91	EA	Throughout - 1907 Building (See Hatching Maps)		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 22391

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Aircell Pipe Insulation	492	LF	Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907 Building		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	MJP E/F/V on Aircell Pipe Insulation	45	EA	Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907 Building		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Oracle Unit: 22391

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Cardboard Pipe Insulation	80	LF	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955 Addition		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	MJP E/F/V on Cardboard Pipe Insulation	70	EA	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955 Addition		TSI	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Aircell Pipe Insulation	30	LF	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955 Addition		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	MJP E/F/V on Aircell Pipe Insulation	80	EA	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955 Addition		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	White Spray Applied Fireproofing	5000	SF	Gym - 1997 Annex		Surface	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmer	nt Category
L	Drywall			Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex							YES	NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:	,]							
2023 Spring S	Six Month Survey: No	Change										
Comments:]							
	Month Survey: No Ch	ange			-							
Comments:					-							
	Six Month Survey: No	Change										
Comments:					1							
2024 Fall Six	Month Survey: No Ch	ange]							
Comments:												
<u> </u>					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Drywall Tape			Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asse	ssment Category
N	Drywall Joint Compound			Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex							YES	X NO
2022 Fall Six	Month Survey: No Ch	ongo			1							
	R Month Survey. No Ch	ange										
Comments:												
0000 Fall Ci-	. Manth Ournes v. Na Ob											
	Month Survey: No Ch	ange										
Comments:												
					-							
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Drywall			Men & Womens Bathrooms, Mechanical Room - 1998 Fieldhouse							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Р	Drywall Joint Compound			Mens & Womens Bathrooms, Mechanical Room - 1998 Fieldhouse							YES	X NO
2022 Fall S	ix Month Survey: No C	hange			1							
Comments:		· · · · · · · · · · · · · · · · · · ·										
2022 Fall S	ix Month Survey: No C	hango										
Comments:		nange			1							
					=							
	g Six Month Survey: No	Change										
Comments:	:											
2024 Fall S	ix Month Survey: No C	hange										
Comments:												
2024 Spring	g Six Month Survey: No	Change										
Comments:	·	, onango			1							
	Take 11D 12		T	I sa e e e e	T	T. A	Levis	1.5	T 5	T 5		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Q	Vinyl Covered Drywall			Throughout 2000 Mobile - Removed from school		Miscellaneous					YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

property

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	Textured Covered Drywall			Throughout 2000 Mobile - Removed from school property		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

_	Lyman A Budlong Elementary School
Date: _	10/25/2024
the Asbesto	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of os Management Plan is available at each school during school hours by appointment. o review the Asbestos Management Plan must be made at least 24 hours in advance.
The last ins	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2022. urveillances are conducted every six months.
CHECK ON	<u>E</u>
A co	py of this notice was sent home in each child's backpack.
X A co	py of this notice was printed in the school's newsletter and sent home with each child
A co	py of this notice was printed in the school's calendar and sent home with each child
Othe	er.
A co	ppy of this notice was printed in the school's calendar and sent home with each child

VFT = Vinyl Floor Tile
Oracle Unit: 22391

SCHOOL'S ASBESTOS MANAGEMENT PLAN.