Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Ira F Aldridge Elementary School 22641 2710 School: **Oracle Unit:** Building ID: Address: 630 E. 131st St. Region: 06 Mail Room: Asbestos Surveyor: Danciu, Richard **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 11/12/2024 Email Address: rfdanciu@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Type Category Quantity Type 1960 and 1962 Buildings-YES X NO 02 12" x 12" Ceiling Tile SF 20000 Throughout Both Miscellaneous Yes None 0 Buildings 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
03	9"x 9" Gray Floor Tile	3400	SF	Classrooms 101, 105, 110, 114, Special Ed Rooms		Miscellaneous	No	None	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x 12" Cream Floor Tile	800	SF	1962 Building- 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
05	9"x9" Gray Floor Tile	8140	SF	1962 Building- 2nd Floor Classrooms and Storage Room		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]		-			•		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Room 228 and part of corridor abated, Spring 2024
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9" x 9" Gray Floor Tile Mastic	3400	SF	Classrooms 101, 105, 110, 114, Special Ed Rooms		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
07	12" x 12" Cream Floor Tile Mastic	800	SF	1962 Building- 2nd Floor Corrido		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:	•	<u> </u>										
2023 Spring	Six Month Survey: No	Change			-							
Comments:	j											
2024 Spring	Six Month Survey: No	Change			_							
Comments:	,											
2024 Fall Six	Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9"x9" Gray Floor Tile Mastic	8140	SF	1962 Building- 2nd Floor Classrooms and Storage Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Room 228 and part of corridor abated Spring 2024
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Hardcoat Plaster	15000	SF	1962 Building- Classrooms, Offices and Miscellaneous Rooms		Surface	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Hardcoat Plaster	12760	SF	1962 Building- 1st and 2nd Floor Classrooms		Surface	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11	Insulation in Fire Rated Door	32	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Vinyl Baseboard	200	LF	All Purpose Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
13	Vinyl Baseboard Mastic	200	LF	All Purpose Room		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:	•											
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:	•	<u> </u>										
2023 Spring	Six Month Survey: No	Change			_							
Comments:	,											
2024 Spring S	Six Month Survey: No	Change			_							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange			1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Vinyl Baseboard	200	LF	1962 Building- Southwest Section of South Corridor and Faculty Lounge I		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15	Vinyl Baseboard Mastic	200	LF	1962 Building- Southwest Section of South Corridor and Faculty Lounge I		Miscellaneous	No	None	0		YES	X NO
2022 Fall S	Six Month Survey: No C	hange	•	~]	•	•		•	•	•	
Comments		<u> </u>										
2023 Fall S	Six Month Survey: No C	hange			-							
Comments	:											
2023 Sprin	g Six Month Survey: No	Change										
Comments	:				1							
2024 Sprin	g Six Month Survey: No	Change										
Comments	:				1							
2024 Fall S	Six Month Survey: No C	hange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	9" x 9" Orange Floor Tile	3965	SF	Classrooms 103, 107, 108, 111, 112, 116, Corridor Storage, Health Room, All Purpose Room Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Orange Floor Tile Mastic	3965	SF	Classrooms 103, 107, 108, 111, 112, 116, Corridor Storage, Health Room, All Purpose Room Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 22641

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
18	9"x9" Light Brown Floor Tile	650	SF	All Purpose Room Vault and Principal's Office (Under carpet)		Miscellaneous	No	None	0		YES	X NO
		*	•	•	1	•	•	•	•	•	•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Light Brown Floor Tile Mastic	655	SF	All Purpose Room Vault and Principal's Office (Under carpet)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Orange Floor Tile	4066	SF	1962 Building- Rooms 103, 104, 107, 108, 109, 111, 112, 116, All Purpose Room, Corridor Storage, and Health Room, Library		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Library floor abated Summer 2023
•
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 22641

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Orange Floor Tile Mastic	4066	SF	1962 Building- Rooms 103, 104, 107, 108, 109, 111, 112, 116, All Purpose Room, Corridor Storage, and Health Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 22641

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Light Brown Floor Tile	650	SF	1962 Building- Janitor's Closet and Counselor's Office Storage Room		Miscellaneous	No	None	0		YES X NO
		•	•	•	1	•	•	•	•	•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9"x9" Light Brown Floor Tile Mastic	650	SF	1962 Building- Janitor's Closet and Counselor's Office Storage Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:2nd floor janitor's closet abated Spring 2024
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Cream Floor Tile	720	SF	1962 Building- 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Some abatement Spring 2024
2024 Fall Six Month Survey: Other
Comments:some abatement near custodial closet

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Cream Floor Tile Mastic	120	SF	1962 Building- 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Some abatement Spring 2024
2024 Fall Six Month Survey: Other
Comments:some abatement near custodial closet

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Black Floor Tile	400	SF	1962 Building- Faculty Lounge		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Black Floor Tile Mastic	400	SF	1962 Building- Faculty Lounge		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Green Floor Tile- NOT OBSERVED	0	SF	1962 Building- Public Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Public office now "Main Office"
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Green Floor Tile Mastic-NOT OBSERVED	0	SF	1962 Building- Public Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change Comments:	
2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change	
2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Spring Six Month Survey: No Change Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Spring Six Month Survey: No Change Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change	Comments:
Comments:Public office now "Main Office 2024 Fall Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change	2024 Spring Six Month Survey: No Change
· · · · · · · · · · · · · · · · · · ·	Comments: Public office now "Main Office
· · · · · · · · · · · · · · · · · · ·	
Comments:	2024 Fall Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Light Brown Floor Tile	3320	SF	Room 102, All Purpose Room, Engineer's Office, Janitor's Closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:All purpose Room (Gym) tile covered by wooden flooring
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Light Brown Floor Tile Mastic	3320	SF	Room 102, All Purpose Room, and Engineer's Office, Janitor's Closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:All purpose room (Gym) tile under wooden flooring
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" Cream Floor Tile ABATED			1960 Building- Pre- Kindergarten Room 100		Miscellaneous					X YES NO

2022 Fall Six Month Survey: Abated
Comments: Abated Summer 2022
2023 Fall Six Month Survey: Abated
Comments: ABATED SUMMER 2022 IDPH Project No. 32638
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Abated 2022
2024 Fall Six Month Survey: Abated
Comments:Now Library Room 104

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" Cream Floor Tile Mastic ABATED			1960 Building- Pre- Kindergarten Room 100		Miscellaneous					X YES NO

Comments: Abated Summer 2022 2023 Fall Six Month Survey: Abated Comments: ABATED SUMMER 2022 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: Abated 2022 2024 Fall Six Month Survey: Abated	
2023 Fall Six Month Survey: Abated Comments:ABATED SUMMER 2022 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:Abated 2022 2024 Fall Six Month Survey: Abated	2022 Fall Six Month Survey: Abated
Comments: ABATED SUMMER 2022 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: Abated 2022 2024 Fall Six Month Survey: Abated	Comments: Abated Summer 2022
Comments: ABATED SUMMER 2022 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: Abated 2022 2024 Fall Six Month Survey: Abated	
2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:Abated 2022 2024 Fall Six Month Survey: Abated	2023 Fall Six Month Survey: Abated
Comments: 2024 Spring Six Month Survey: No Change Comments:Abated 2022 2024 Fall Six Month Survey: Abated	Comments:ABATED SUMMER 2022
Comments: 2024 Spring Six Month Survey: No Change Comments:Abated 2022 2024 Fall Six Month Survey: Abated	
2024 Spring Six Month Survey: No Change Comments:Abated 2022 2024 Fall Six Month Survey: Abated	2023 Spring Six Month Survey: No Change
Comments:Abated 2022 2024 Fall Six Month Survey: Abated	Comments:
Comments:Abated 2022 2024 Fall Six Month Survey: Abated	
2024 Fall Six Month Survey: Abated	2024 Spring Six Month Survey: No Change
	Comments: Abated 2022
Comments:Now Library Room 104	2024 Fall Six Month Survey: Abated
	Comments:Now Library Room 104

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Brown Floor Tile	1580	SF	All Purpose Room Offices, Rooms 106 & 106A		Miscellaneous	No	None	0		YES X NO
	•	•	•		1		•	•	•		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Brown Floor Tile Mastic	1580	SF	All Purpose Room Offices, Rooms 106 & 106A		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
36	White Terrazo	15000	SF	Hallways and Stairwells		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	2022 Fall Six Month Survey: No Change Comments:											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Blue Vinyl Floor Tile	210	SF	Main Office Waiting Area, All Purpose Room Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	gory
38	12"x12" Blue Vinyl Floor Tile Mastic	210	SF	Main Office Waiting Area, All Purpose Room Office		Miscellaneous	Yes	None	0		YES X NO	
2022 Fall Six Comments:	Month Survey: No Cha	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
, ,
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Brown Carpet Mastic	150	SF	Principal's Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" Blue w/Gray Specks Vinyl Floor Tile	1200	SF	Room 122, 123, 124, 125, 126, 127, & 128		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Blue w/Gray Specks Vinyl Floor Tile Mastic	1200	SF	Room 122, 123, 124, 125, 126, 127, & 128		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Brown and Tan Ceramic Tile Grout	200	LF	1962 Building- Boys' and Girls' Toilets 1st & 2nd Floor, Principal's Office Toilet and Women's Toilet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:1st floor Northeast abated Summer 2023
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Some abatement Summer 2023, Boys' and Girls' Toilet
Northeast 1st Floor and Women's Toilet (Now Single Stall Multi-Sex by
Room 120)
2024 Fall Six Month Survey: Other
Comments:'62 bldg boys and girls toilets 1st floor abated, women's toilet
abated (now Cluster Classroom dedicated restroom)
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP E/F/V on Fiberglass Pipe Insulation	5	LF	1960 & 1962 Buildings		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Tank Insulation	180	SF	1960 Building		TSI	Yes	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:Non-existant asset
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:Non-extant, Boiler manufactured 2007
2024 Fall Six Month Survey: Abated
Comments:Boilers 2007 installed
2024 Spring Six Month Survey: Inaccessible
Comments:No longer extant

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Boiler Gasket-NOT OBSERVED	0	LF	1960 Building- Boiler Room		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:Replaced 2007
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:Non-extant, Boiler manufactured 2007
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:Boilers 2007 installed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Boiler Breaching-NOT OBSERVED	0	LF	1960 Building- Boiler Room		TSI	Yes	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:Replaced
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:Non-extant, breaching installed c. 2019
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:Breaching replaced circa 2020

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Boilers #1 & #2: Insulation Under Steel Jacket	320	SF	Boiler Room		TSI	Yes	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:Boilers replaced in 2007
·
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:Non-extant, Boiler manufactured 2007
2024 Fall Six Month Survey: Abated
Comments:Boilers 2007 installed
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Caulk on Boiler	8	LF	Boiler Room		TSI	No	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:Boilers replaced in 2007
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: Abated
Comments:Boilers 2007 installed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Troweled on Ceiling	2000	SF	Boiler Room		Surface	Yes	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
, ,
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Thermal System Insulation in Tunnel	120	LF	1960 Building- Boiler Room Tunnels		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Drywall /Compound	207	SF	110, 113, Pre-K (Room 100)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:Material abated in Pre-K Summer 2022
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Soom abatement Room 100 in Summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Blue Carpet Mastic	500	SF	1962 Building- Public Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Black Baseboard	50	LF	Rooms 110, 113 and 100		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:Material abated in Pre-K Summer 2022
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Black Baseboard Mastic	50	LF	Room 100 (Pre-K), 110 & 113		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:Abated in Room 100 (Pre-K)
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:Material abated in Pre-K Summer 2022
2024 Spring Six Month Survey: Other
Comments:Some abatement Room 100 in Summer 2022
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
·

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ira F Aldridge Elementary School
Date:11/18/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 22641

SCHOOL'S ASBESTOS MANAGEMENT PLAN.