

Chicago Public Schools  
6 Month Asbestos Surveillance  
2024 Fall Six Month Survey

School: Thomas Chalmers STEAM Elementary School  
Address: 2745 W. Roosevelt

Oracle Unit: 22671  
Region: 03

Building ID: 2740  
Mail Room: 38

☒ CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Mendez, Kyle  
Survey Date: 11/13/2024  
Email Address: kmendez31@cps.k12.il.us

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ Each child's backpack ☒ Notice printed in school's newsletter ☐ Notice printed in school's calendar ☐ Other

| HA No | Material Description    | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5     | Masonite ceiling panels |                   |                | Boy's Bathroom in 1963 Addition |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

2022 Fall Six Month Survey: No Change

Comments:

2023 Fall Six Month Survey: No Change

Comments:

2023 Spring Six Month Survey: No Change

Comments:

2024 Spring Six Month Survey: No Change

Comments:

2024 Fall Six Month Survey: No Change

Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 22671

Page 1

| HA No | Material Description                     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6A    | 9" x 9" Brown w/Beige Streaks Floor Tile | 24000             | SF             | Throughout Classrooms and Corridors on the 1st and 2nd Floors |               | Miscellaneous     | No      | Loc         | 5               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6B    | 9" x 9" Tan w/Beige Dots Floor Tile | 3000              | SF             | Room 107 and Room 109 in the 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                        | Material Quantity | Material Units | Material Location                                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6C    | 9" x 9" Tan w/Dark Beige Streaks Floor Tile | 500               | SF             | Southeast Entrance and Corridor in 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6D    | 9" x 9" Tan w/Dark Streaks Floor Tile | 300               | SF             | Patching in Corridors in 1959 Original Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6E    | 9" x 9" Brown w/Beige Streaks Floor Tile | 14000             | SF             | Throughout 1963 Addition |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6F    | 9" x 9"Tan w/Dark & Light Beige Streaks Floor Tile | 3500              | SF             | Gym and Patching Throughout 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7A    | 12" x 12" Beige Speckled Floor Tile | 300               | SF             | Bathrooms in 107 and 109 in 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7B    | 12" x 12" Brown Speckled Floor Tile | 120               | SF             | South Entry Vestibule and Northwest Entrance in 1959 Building |               | Miscellaneous     | No      | Loc         | 25              | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7C    | 12" x 12" Beige Speckled Floor Tile | 150               | SF             | 1st Floor Corridor and Patching in Kitchen in 1963 Addition, 2nd floor corridor, 215, cafeteria |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7D    | 12" x 12" Dark Brown Speckled Floor Tile | 1500              | SF             | 1st Floor Corridor in 1963 Addition |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7E    | 12" x 12" Beige Speckled Floor Tile | 10                | SF             | Southeast Entrance of 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8A    | 9" x 9" Brown w/Beige Streaks Floor Tile Mastic | 24000             | SF             | Throughout Classrooms and Corridors on the 1st and 2nd Floors |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8B    | 9" x 9" Tan w/Beige Dots Floor Tile Mastic | 2000              | SF             | Rooms 107-109 in 1959 Original Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location                                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8C    | 9" x 9" Tan w/Dark Beige Streaks Floor Tile Mastic | 500               | SF             | Southeast Entrance and Corridor in 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description                         | Material Quantity | Material Units | Material Location                                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8D    | 9" x 9" Tan w/Dark Streaks Floor Tile Mastic | 300               | SF             | Patching in Corridors of the 1959 Original Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8E    | 9" x 9" Brown w/Beige Streaks Floor Tile Mastic | 14000             | SF             | Throughout 1963 Addition |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                       | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8F    | 9" x 9" Tan w/Dark & Light Beige Streaks Floor Tile Mastic | 3500              | SF             | Gym and Patching Throughout 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9A    | 12" x 12" Beige Speckled Floor Tile Mastic | 1500              | SF             | Bathrooms in Rooms 107 and 109 in 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9B    | 12" x 12" Brown Speckled Floor Tile Mastic | 300               | SF             | South Entrance Vestibule & Southwest Entrance in 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9C    | 12" x 12" Beige Speckled Floor Tile Mastic |                   |                | 1st Floor Corridor and Patching in Kitchen in 1963 Addition, cafeteria |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                            | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9D    | 12" x 12" Dark Brown Speckled Floor Tile Mastic |                   |                | 1st Floor Corridor in 1963 Addition |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9E    | 12" x 12" Beige Speckled Floor Tile Mastic | 35                | SF             | Southeast Entrance of 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10    | 1' x 1' Ceiling Tile Large Hole Patterned |                   |                | Throughout the Majority of 1959 Original Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10M   | 1' x 1' Ceiling Tile Large Hole Patterned Adhesive |                   |                | Throughout the majority of 1959 Original Building, Hallways and Main Office |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11    | 1' x 1' Ceiling Tile Small Hole Patterned |                   |                | 2nd Floor Teacher's Lounge in the 1959 Original Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11M   | 1' x 1' Ceiling Tile Small Hole Patterned Adhesive |                   |                | 2nd Floor Teacher's Lounge in the 1959 Original Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12    | Acoustical/textured plaster |                   |                | Throughout the Majority of 1959 Original Building |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13    | Brown vinyl baseboard |                   |                | Rooms101-105-107-109-113-114, Majority of 2nd FL Class - 1st/2nd FL Corridors in 1959 Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14    | Brown vinyl baseboard mastic |                   |                | Rooms 101,105,107,109,113, & 114, Majority of 2nd Floor Classrooms1st/2nd Floor Corridors 1959 Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.



| HA No | Material Description  | Material Quantity | Material Units | Material Location                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15    | Spray-on fireproofing |                   |                | Boiler Room Ceiling in 1959 Original Building |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description       | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | Exterior brick - Non-AHERA |                   |                | 1959 Original Building Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | Exterior brick mortar - Non-AHERA |                   |                | 1959 Original Building Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | 1' x 1' Off- White Ceiling Tile Worm Patterned |                   |                | Throughout the Majority of 1963 Addition |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                         | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | 1' x 1' White Ceiling Tile<br>Worm Patterned |                   |                | Corridors Throughout the<br>1963 Addition |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | Roof core - Non-AHERA |                   |                | Roof              |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | Roof flashing - Non-AHERA |                   |                | Roof              |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description  | Material Quantity | Material Units | Material Location                             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22    | Brown vinyl baseboard |                   |                | All Classrooms<br>Throughout 1963<br>Addition |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location                                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23    | Brown vinyl baseboard mastic | 1700              | LF             | All Classrooms Throughout 1963 Addition, 115-118 |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description  | Material Quantity | Material Units | Material Location                               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | Spray-on fireproofing |                   |                | Pipe Chase in Girl's Bathrooms in 1963 Addition |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | Exterior brick - Non-AHERA |                   |                | 1963 Addition Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description              | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26    | Exterior brick mortar - Non-AHERA |                   |                | 1963 Addition Exterior |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                               | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27    | 12" x 12" White w/Green & Brown Streaks Floor Tile | 2400              | SF             | Rooms 106 Bathroom, 107, 109 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                                      | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28    | 12" x 12" White w/Green & Brown Streaks Floor Tile Mastic | 2400              | SF             | Rooms 106 Bathroom, 107, 109 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29    | 4" Green baseboard   | 72                | LF             | Room 106 Bathroom, 107, 109 |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description      | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30    | 4" Green baseboard mastic | 72                | LF             | Room 106 Bathroom, 107, 109 |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31    | 6" Green baseboard   | 60                | LF             | Room 107          |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32    | 5" Green baseboard mastic | 60                | LF             | Room 107          |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33    | 6" Gray baseboard    | 38                | LF             | Room 109          |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34    | 6" Gray baseboard mastic | 38                | LF             | Room 109          |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35    | 12" x 12" Beige Floor Tile (as Patching) | 78                | SF             | Rooms 110, 202    |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36    | 12" x 12" Beige Floor Tile Mastic (as Patching) | 78                | SF             | Rooms 110, 202    |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37    | Purple carpet adhesive | 800               | SF             | Room 104          |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38    | Blue carpet adhesive | 820               | SF             | Room 212          |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39    | Red carpet adhesive  |                   |                | Room 206          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40    | Acoustical Drywall on Partitions | 170               | SF             | Room 206          |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41    | Sink undercoat       | 14                | LF             | Rooms 107, 109, 209. 211, 214, 114, Library of 1959 Building |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42    | 2' x 2' Ceiling Panels | 44                | SF             | Room 106 Bathroom |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43    | Vault door           | 18                | SF             | Office            |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44    | Chalkboard adhesive  |                   |                | Throughout Building in all classrooms |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45    | Posterboard adhesive | 250               | SF             | Throughout Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description           | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46    | 1' x 1' Fissured Ceiling Tiles | 600               | SF             | GWR across from 218.<br>GWR across from 118.<br>MWR across from 118 |               | Miscellaneous     | Yes     | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description                   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46M   | 1' x 1' Fissured Ceiling Tile Adhesive | 600               | SF             | GWR across from 218.<br>GWR across from 118.<br>MWR across from 118 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47    | 12" x 12" burgandy ceramic floor tile grout | 85                | SF             | Main Office       |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48    | Yellow ceramic floor tile grout | 700               | SF             | 1st and 2nd Floors Girls and boys Bathrooms, 1959 Bld Slop Sink Closet |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description          | Material Quantity | Material Units | Material Location                                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49    | Pink ceramic floor tile grout | 300               | SF             | 1st Fl Hall, 2nd Floor Mens and Womens Bathrooms |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50    | Drywall              | 280               | SF             | Stage, Gym, Sink Closet, Wheel Chair Lift and Room to Stage 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51    | Drywall joint compound | 100               | LF             | Stage, Gym, Sink Closet, Wheel Chair Lift and Room to Stage 1959 Building |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52    | Drywall joint tape   | 100               | LF             | Stage, Gym, Sink Closet, Wheel Chair Lift and Room to Stage 1959 Building |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53    | Dark red carpet mastic | 820               | SF             | Room 206 over the 9" X 9" Floor Tile |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description           | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54    | Brick ceramic floor tile grout | 150               | SF             | 1st Floor Faculty Bathroom |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55    | 2" Brown vinyl base board | 80                | LF             | Rooms 215 - 218 and 2nd Floor Stairs 1963 Building |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description               | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56    | 2" Brown vinyl base board adhesive | 80                | LF             | Rooms 215 - 218 and 2nd Floor Stairs 1963 Building |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57    | Sink undercoating    | 3                 | SF             | Room 216 1963 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58    | 12" x 12" beige speckled floor tile | 800               | SF             | 2004 Addition classrooms, 2nd fl Foyer 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59    | 12" x 12" beige speckled floor tile mastic | 800               | SF             | 2004 Addition classrooms, 2nd fl Foyer 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                 | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60    | 12" x 12" yellow speckled floor tile | 50                | SF             | 2004 Addition classrooms, 2nd fl Foyer 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description                        | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61    | 12" x 12" yellow speckled floor tile mastic | 50                | SF             | 2004 Addition classrooms, 2nd fl Foyer 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62    | 12" x 12" green speckled floor tile | 138               | SF             | 2004 Addition classrooms, 2nd fl Foyer 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63    | 12" x 12" green speckled floor tile mastic | 138               | SF             | 2004 Addition classrooms, 2nd fl Foyer 1959 Building |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64    | 4" Vinyl base board  | 180               | LF             | 2004 Addition Elevator Hall and Electrical Closet |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65    | 4" Vinyl base board adhesive | 180               | LF             | 2004 Addition Elevator Hall and Electrical Closet |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66    | Drywall              | 800               | SF             | 2004 Addition Elevator Hall and Electrical Closet |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 67    | Drywall joint compound | 130               | LF             | 2004 Addition Elevator Hall and Electrical Closet |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 68    | Drywall joint tape   | 130               | LF             | 2004 Addition Elevator Hall and Electrical Closet |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 70    | Brick expansion joint | 12                | LF             | 2004 Addition Elevator Hall and Electrical Closet |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description  | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 71    | 2' x 2' ceiling tiles | 400               | SF             | 2004 Addition 1st and 2nd floor Elevator Halls |               | Miscellaneous     | Yes     | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 72    | Duct vibration collars | 30                | LF             | Basement Boiler Room |               | Miscellaneous     | No      | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 73    | 12" x 12" Red w/ Gray Specks Floor Tile | 15                | SF             | Main office in front of Vault door |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                           | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 74    | 12" x 12" Red w/ Gray Specks Floor Tile Mastic | 15                | SF             | Main office in fornt of Vault Door |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 75    | Gray carpet adhesive | 550               | SF             | Principal's Office, Main Office |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 76    | Mastic Under Gray/Gray and Green Carpet | 1090              | SF             | Library (Room 211) |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 77    | 12" x 12" Light Brown Speckled Floor Tile | 700               | SF             | Rooms 216, 207, 208 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description                                    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 78    | Mastic Associated w/12" x 12" Brown Speckled Floor Tile | 700               | SF             | Rooms 216, 207, 208 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description              | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 79    | 1' x 1' ceiling tiles w/ fissures | 2000              | SF             | 2nd floor corridor east, 215, 216, 217, 218, cafeteria, kitchen, food service storage, 118 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                            | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 80    | Adhesives for 1' x 1' ceiling tiles w/ fissures | 2000              | SF             | 2nd floor corridor east, 215, 216, 217, 218, cafeteria, kitchen, food service storage, 118 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                      | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 81    | 12 " x 12" Light gray Speckled Floor Tile | 800               | SF             | Rooms 206, 107, 109,113, 114 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                 | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 82    | Mastic for 12 " x 12" Light gray Speckled Floor Tile | 800               | SF             | Rooms 206, 107, 109,113, 114 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 83    | 12 " x 12" gray Speckled Floor Tile | 800               | SF             | Room 206          |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 84    | Mastic for 12 " x 12" gray Speckled Floor Tile | 800               | SF             | Room 206          |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 85    | Vinyl Plank flooring | 1500              | SF             | Gym               |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 86    | Tongue & groove wood floor | 500               | SF             | Gym stage         |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description      | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B     | Boiler breeching - abated |                   |                | Boiler Room 1959 Original Building |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D1    | Elbows on Fiberglass Pipe Runs |                   |                | Throughout 1959 Original Building |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description                         | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D2    | Joint Compound on Fiberglass Pipe Insulation |                   |                | Throughout 1959 Original Building |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G     | Paperwrap pipe insulation | 1400              | LF             | Pipe Chases 1959 Original Building |               | TSI               | Yes     | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description                | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H     | Elbows on Paperwrap Pipe Insulation | 185               | LF             | Pipe Chase in 1959 Original Building |               | TSI               | Yes     | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

A handwritten signature in black ink, appearing to read "Richard J. Schleyer", written in a cursive style.

---

Richard J. Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***



NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Thomas Chalmers STEAM Elementary School

Date: 9/23/2024

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.

CHECK ONE

- ☐ A copy of this notice was sent home in each child's backpack.
- ☒ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☐ Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**