## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Henry Clay Elementary School 22731 2790 School: **Oracle Unit:** Building ID: Address: 13231 S. Burley Region: 06 Mail Room: Asbestos Surveyor: Rollins, Frank X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/10/2024 Email Address: frollins4@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other CPS Website Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 12x12 Dark Brown Floor YES 01 SF X NO Main Entrance Miscellaneous No None 0 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
02	12x12 White & Beige Floor Tile NOT OBSERVED			1929 Addition- 1st & 2nd Floor Teachers' Lounge		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	_				1							
2023 Fall Six	Month Survey: No Ch	ange			=							
Comments:												
2023 Spring S	Six Month Survey: No	Change			_							
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:					=							
	Month Survey: No Ch	ange										
Comments:					=							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Lab Tables NOT OBSERVED			Room 310		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
06	Insulation in Fire Rated Doors	6	EA	Sealed Doors		TSI	No	None	0		YES	X NO
2022 Fall S	Six Month Survey: No C	hange										
Comments	:											
2023 Fall S	Six Month Survey: No C	hange										
Comments	:											
2023 Sprin	g Six Month Survey: No	Change										
Comments	S:											
2024 Sprin	g Six Month Survey: No	Change										
Comments	··											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12x12 White & Beige Floor Tile Mastic - NOT OBSERVED			1929 Addition- 1st & 2nd Floor Teachers' Lounge		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12x12 White w/Black Streaks Floor Tile	2200	SF	1916 Building- 1st floor Hallway, Rooms 303, 308A, Gym Office		Miscellaneous	No	Loc	30		YES X NO
•	•	<u>.</u>	·		•	•	•	•	•	='	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0000 F # 01 H
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09A	12x12 Tan w/White Specks Floor Tile NOT OBSERVED			1916 Building- Teachers' Lounge, 1st floor		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" White w/Black Streaks Floor Tile Mastic	2200	SF	1916 Building- 1st, 2nd & 3rd Floor Hallways, Room 303, 310, 306, 308A & Gym Office		Miscellaneous	No	Loc	20		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	12x12 Tan w/White Specks Floor Tile Mastic-NOT OBSERVED			1926 Building- 1st Floor Teachers' Lounge		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

11	Attic Spray-on Fire Proofing	20150	SF	Throughout Attic Space		Surface	Yes	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:					_							
2024 Spring	Six Month Survey: No	Change										
Comments:					_							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Surface

No

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

Change in Assessment Category

X NO

YES

93000

SF

Material Description

Hardcoat Plaster

2022 Fall Six Month Survey: No Change

Material

Quantity

Material

Units

Material Location

Throughout School

HA No

12

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Off White Streaked Floor Tile	576	SF	Rooms 302A and 308A		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
0004 F II 0' M
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13M	12"x12" Off-White Streaked Floor Tile Mastic	576	SF	Rooms 302A and 308A		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" White w/Multicolored Specks Floor Tile	16763	SF	2nd & 3rd Floor Corridors, 1st Floor North, South and West Corridors, 1st Floor Lunchroom, Main Office & Stairway Landings		Miscellaneous	No	Dist	650		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 8

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14M	12"x12" White w/Multicolored Specks Floor Tile Mastic	16763	SF	2nd and 3rd Floor Corridors, 1st Floor North, South and West Corridors, 1st Floor Lunchroom, Main Office & Stairway Landings		Miscellaneous	No	Loc	650		YES X NO

Comments:  2023 Fall Six Month Survey: No Change Comments:  2023 Spring Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:	
2023 Fall Six Month Survey: No Change Comments:  2023 Spring Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments:  2023 Spring Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	Comments:
Comments:  2023 Spring Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	
2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	Comments:
Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Fall Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change	2024 Spring Six Month Survey: No Change
	Comments:
Comments:	2024 Fall Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	White Ceramic Tile Grout	1076	SF	3rd Floor North Boys Washroom, 2nd Floor North Girls' Washroom, 1st Floor N and NE Exits		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	White Ceramic Tile Adhesive	1076	SF	3rd Floor North Boys' Washroom, and 2nd Floor North Girls' Washroom, 1st Floor N and NE Exits		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Grey Ceramic Tile Grout	3024	SF	1st, 2nd & 3rd Floor Girls' and Boys' Washrooms		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

					71 -	3 ,		71' "			
18	Grey Ceramic Tile Adhesive	3024	SF	1st, 2nd & 3rd Floor Girls' and Boys' Washrooms		Miscellaneous	No	None	0	YES	X NO
2022 Fall	Six Month Survey: No (	Change			]						
Commen	ts:	-									
2023 Fall	Six Month Survey: No	Change									
Commen	ts:				1						
	ing Six Month Survey: N	lo Change			-						
Commen	ts:				-						
2024 Spri	ing Six Month Survey: N	lo Change									
Commen	ts:				-						
	Six Month Survey: No 0	Change									
Comment	ts:				  -						
					J						

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

No

Damage

Type

None

Damage

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

2022 Fall Six	Month Survey: No Cha	ange		
Comments:				
2023 Fall Six	Month Survey: No Cha	ange		
Comments:				
2023 Spring S	Six Month Survey: No (	Change		
Comments:				
2024 Spring S	Six Month Survey: No (	Change		
Comments:				
2024 Fall Six	Month Survey: No Cha	ange		
Comments:				
·		•	•	

Material

Quantity

40

HA No

HA No

19

Material Description

Material Description

Brown Ceramic Tile Grout

Material

Quantity

Material

Material

Units

SF

Units

Material Location

Material Location

Main Office Restroom

Change in Assessment Category

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Brown Ceramic Tile Adhesive	40	SF	Main Office Restroom		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
21	Pink and Tan Terrazzo	156	SF	1st Floor NW Exit		Miscellaneous	No	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
22	Green Terrazzo Floor NOT OBSERVED	480	SF	Pre-Kindergarten Building		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												
2023 Fall Six Month Survey: No Change												

Comments:

2023 Spring Six Month Survey: No Change

Comments:

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Beige Mottled Floor Tile	2400	SF	Lunchroom, Storage Areas in Auditorium		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Mastic associated w/12" x12" Beige Mottled Floor Tile SF Lunchroom, Storage Rooms in Auditorium Miscellaneous No None 0 YES XNO	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	23A	x12" Beige Mottled Floor	2400	SF			Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Yellow Mottled Floor Tile	2100	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	Mastic associated w/12" x12" Yellow Mottled Floor Tile	2100	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO
0000 = 11.01		•		•		•	•	•	•	•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
Comments.
2024 Fall Six Month Survey: No Change
Comments:
2004 Caria a Ciu Marth Curray Na Channa
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Teal Mottled Floor Tile	2100	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	Mastic associated w/12" x12" Teal Mottled Floor Tile	2100	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Brown w/White Streaks Floor Tile	600	SF	Assistant Principal's Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
26A	Mastic associated w/12" x12" Brown w/White Streaks Floor Tile	600	SF	Assistant Principal's Office		Miscellaneous	No	None	0		YES	X NO

<u> </u>
2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Beige w/Tan Streaks Floor Tile	230	SF	MDF Room in Assistant Principal's Office & Room 111B		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	Mastic associated w/12" x12" Beige w/Tan Streaks Floor Tile	230	SF	MDF Room in Assistant Principal's Office & Room 111B		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Mag Block Boiler Insulation NOT OBSERVED			Boiler Room		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Aircell TSI	1500	LF	1916 Building- Boiler Room, Coal Room, Tank Room, Shower, Girls' Toilet, Air Chamber, 1st Floor Hall & Throughout Main Office		TSI	Yes		0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Cardboard TSI	800	LF	1916 Building- Boiler Room, Coal Room, Tank Room, Shower, Girls' Toilet, Air Chamber, 1st Floor Hall		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Pre-Form TSI (Mag)	200	LF	1916 Building- Boiler Room, Air Chamber, Fan Room, Basement Rooms & 1st Floor Hall		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Cardboard Fittings	60	LF	1916 Building- Boiler Room, Air Chamber, Fan Room, Basement Rooms & 1st Floor Hall		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

	·	Quantity	Units		Type	Category		Туре	Quantity	Units		,
G	Aircell TSI	1500	LF	1916 Building- Fan Room, 1st Floor Hall		TSI	Yes	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring S Comments:	Six Month Survey: No	Change										
2023 Fall Six Comments:	Month Survey: No Ch	ange			<u>-</u> -							
2024 Fall Six Comments:	Month Survey: No Ch	ange										
2024 Spring S Comments:	Six Month Survey: No	Change										

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Aircell Fittings	30	LF	1929 Building- Fan Room & 1st Floor		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

		Quantity	Units		Type	Category		Type	Quantity	Units		
L	Aircell Hard Fittings	100	FITTING	1916 Building- Boiler Room, Air Chamber, Basement Rooms, 1st Floor Hall		TSI	Yes	None	0		YES	X NO
2022 Fall	Six Month Survey: No	Change										
Comment	·	g-										
2023 Fall	Six Month Survey: No	Change										
Comment	ts:				]							
2023 Spri	ing Six Month Survey: N	lo Change										
Comment	ts:				_							
	ing Six Month Survey: N	lo Change										
Comment	ts:											

Material

Damage

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Brown Sheet Vinyl Flooring NOT OBSERVED			Auditorium		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Material Description

2024 Fall Six Month Survey: No Change

Material

Material Location

HA No

Comments:

NEW	Newly Installed Suspect ACM	Installed After Implementation of Management Plan and after Renovations		Miscellaneous	Unknown		YES	X NO
2022 Fall Six Month Survey: No Change								
Comments:								
2023 Spring Six Month Survey: No Change								
Comments:			-					
2023 Fall Six Month Survey: No Change			1					
Comments:			-					
2024 Fall Six Month Survey: No Change								
Comments:								
2024 Spring Six Month Survey: No Change			<u> </u>					
Comments:	, J							
			]					

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
0	Brown Sheet Vinyl Flooring Mastic NOT OBSERVED			Auditorium		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										

HA No

Material Description

Material

Units

Material

Quantity

Material Location

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Henry Clay Elementary School
Date: 12/10/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. CPS Website
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.