Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

John C Coonley Elementary School 22821 2880 School: **Oracle Unit: Building ID:** Address: 4046 N Leavitt Street Region: 01 Mail Room: Asbestos Surveyor: Suerth, Samuel **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 10/28/2024 Email Address: A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Other Posted on CPS websi Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar HA No Material Description Material Location Friable Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Type Category Quantity Type 12"x12" White w/Beige North and South Boys YES X NO 01 Streaks VFT - Not Play Room - 1902 Bldg Observed (Not Observed) 2022 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:

Oracle Unit: 22821

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
02	9"x9" Tan w/Brown Streaks VFT	500	SF	Room 008 - 1902 Bldg.		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2004 Ossiss O' Marth Ossas Na Obsassa
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	1'x1' Ceiling Tile			Gymnasium Stage Area - 1957 Bldg.							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Damaged
Comments:water damage
2023 Spring Six Month Survey: Damaged
Comments:water damage and 10 tiles missing
2024 Spring Six Month Survey: Damaged
Comments:water damage
2024 Fall Six Month Survey: Damaged
Comments:water damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
05	2'x2' Acoustic Ceiling Tile	2240	SF	Gymnasium - 1957 Bldg.		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch											
2023 Fall Six Comments:	Month Survey: No Ch	ange			- - -							
2023 Spring S	Six Month Survey: No	Change										
2024 Spring S	Six Month Survey: No	Change			- - -							
Comments:	Manth Common No Oh											
Comments:	Month Survey: No Ch	ange			_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	Spray-On Acoustical Plaster - ABATED SUMMER 2008			1st Floor Gymnasium Lobby - 1957 Bldg.		Surface		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

07	Hard Coat Plaster (Walls & Ceilings)		Gym Corridor, Gym Office, Gym outside Storeroom - 1957 Bldg.				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		7				
Comments:								
2023 Fall Six	Month Survey: No Ch	ange						
Comments:								
2023 Spring	Six Month Survey: No	Change		_				
Comments:	,							
2024 Spring	Six Month Survey: No	Change		1				
Comments:	•	•						
2024 Fall Six	Month Survey: No Cha	ange						
Comments:	•	-						
				_				

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" White w/Beige Streaks VFT Mastic - NOT OBSERVED	1200	SF	Room 204, North and South Boys and Girls Playrooms - 1902 Bldg - NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

09	9"x9" Tan w/Brown Streaks VFT Mastic	500	SF	Room 008 - 1902 Bldg.		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change												
Comments:	,	J										
2023 Fall Six	x Month Survey: No Ch	ange										
Comments:		g-										
2023 Spring	Six Month Survey: No	Change			_							
Comments:	-											
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	x Month Survey: No Ch	ange										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11	1'x1' Ceiling Tile Mastic			Gymnasium Stage Area -							YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Damaged
Comments:water damage
2023 Spring Six Month Survey: Damaged
Comments:water damage
2024 Spring Six Month Survey: Damaged
Comments:water damage
2024 Fall Six Month Survey: Damaged
Comments:water damage

HA No

Material Description

Material

Quantity

Material

Units

Material Location

1957 Bldg.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
12	9"x9" Tan w/Black Streaks VFT - ABATED			Boys and Girls Toilets By Gym, Corridor Outside Toilets- 1957 Bldg ABATED		Miscellaneous		None			YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:Not observed
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Tan w/Black Streaks VFT Mastic - ABATED			Boys and Girls Toilets By Gym, Corridor Outside Toilets- 1957 Bldg ABATED		Miscellaneous		None			YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9"x9" Tan w/Green Streaks VFT - NOT OBSERVED	600	SF	Room 107 - 1902 Bldg NOT OBSERVED (removed)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Spring Six Month Survey: No Change
Comments:Not observed
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	9"x9" Tan w/Green Streaks VFT Mastic - NOT OBSERVED	600	SF	Room 107 - 1902 Bldg NOT OBSERVED (removed)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:Not observed
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"x9" Light Tan w/White Streaks VFT - NOT OBSERVED	20	SF	Room 107 Wardrobe - 1902 Bldg NOT OBSERVED(removed)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Spring Six Month Survey: No Change
Comments:Not observed
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	9"x9" Light Tan w/White Streaks VFT Mastic - NOT OBSERVED	20	SF	Room 107 Wardrobe - 1902 Bldg NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:Not observed
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
16	12"x12" Off-White VFT	1000	SF	Room 101 and wardrobe - 1902 Bldg.		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Cha	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A	12"x12" Off-White VFT Mastic	1000	SF	Room 101 and wardrobe - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Yellow VFT - NOT OBSERVED	50	SF	Auditorium Stage South Stairwells - 1957 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	9"x9" Yellow VFT Mastic - NOT OBSERVED	50	SF	Auditorium Stage South Stairwells - 1957 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:	
2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	
2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Fall Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change	2024 Spring Six Month Survey: No Change
	Comments:
Comments:	2024 Fall Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" White w/Green Streaks VFT	400	SF	Office 300G and Office 300F - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	12"x12" White w/Green Streaks VFT Mastic	400	SF	Office 300G and Office 300F - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:	
2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	
2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Fall Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change	2024 Spring Six Month Survey: No Change
	Comments:
Comments:	2024 Fall Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
19	12"x12" Tan w/Brown & White Speckles VFT - ABATED	0	SF	Room 106 - 1902 Bldg ABATED		Miscellaneous		None			YES	X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	12"x12" Tan w/Brown & White Speckles VFT Mastic - ABATED	0	SF	Room 106 - 1902 Bldg ABATED		Miscellaneous		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Duct Wrap	1000	SF	Multipurpose Room 006 -1902 Bldg.		TSI	Yes	None	0		YES X NO
2022 Fall Six Month Survey: No Change Comments:											

2022 Fall Civ Month Company No Change
2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	White Canvas Wall Covering			Basement Girl's & Boy's Toilets - 1902 Bldg.							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	2'x4' Grooved Ceiling Tile	1900	SF	Room 203, 303 3rd floor library, 205 - 1902 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Carpet Mastic - REMOVED	0		Room 203 - REMOVED		Miscellaneous	No				YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:Not observed
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Blue w/Specks VFT	500	SF	2nd floor north book storage 200G, Room 004		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	12"x12" Blue w/Specks VFT Mastic	500	SF	2nd floor north book storage 200G, Room 004		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
25	12"x12" Yellow w/specks VFT	1900	SF	Multipurpose Room 006, Room 001 A & B - 1902 Bldg		Miscellaneous	No	None	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	12"x12" Yellow w/specks VFT Mastic	1900	SF	Multipurpose Room 006, Room 001 A & B - 1902 Bldg		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Fire doors	4	EA	Blast chamber, north and south		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	2'x2" White Ceiling Tiles	2000	SF	3rd floor corridor, Office 100A -1902 Bldg (2x4 new tile)		Miscellaneous	Yes	Loc	6		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	18"x18" Orange VFT (Linoleum)	3500	SF	3rd floor N. and S. ends of corridor; 2nd and 1st floor corridors, stair landings, elevator lobbies all floors, Room 202 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	18"x18" Orange VFT (Linoleum) Mastic	3500	SF	3rd floor N. and S. ends of corridor; 2nd and 1st floor corridors, stair landings, elevator lobbies all floors, Room 202 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 22821

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	18"x18" Tan VFT	2800	SF	3rd floor N. and S, ends of corridor; 2nd floor corridor, north and south stairwell landings, 1st floor corridor - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29A	18"x18" Tan VFT Mastic	2800	SF	3rd floor N. and S, ends of corridor; 2nd floor corridor, north and south stairwell landings, 1st floor corridor - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Beige linoleum flooring	800	SF	Room 303 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

30A	Beige linoleum flooring Mastic	800	SF	Room 303 - 1902 Bldg.		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:												
2023 Fall Six Month Survey: No Change												
Comments:												
2023 Spring	Six Month Survey: No	Change			_							
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:					_							
	Month Survey: No Ch	ange]							
Comments:					_							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

Material Location

31	Terrazzo	250	SF	2nd floor north book storage 200G, Door #1 Vestibule								
2022 Fall Six Month Survey: No Change												
Comments:												
2023 Fall Six Month Survey: No Change												
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Cha	ange										
Comments:	Comments:											

HA No

Material Description

Material

Quantity

Material

Units

YES

X NO

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32	12"x12" Pink VFT - NOT OBSERVED			Offices 100A and 100B - 1902 Bldg NOT OBSERVED		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		•]	•	•		•		•	

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Spring Six Month Survey: No Change
Comments:Not observed
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32A	12"x12" Pink VFT Mastic - NOT OBSERVED			Offices 100A and 100B - 1902 Bldg NOT OBSERVED		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:Not observed
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" Gray VFT	900	SF	Room 106 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	12"x12" Gray VFT Mastic	900	SF	Room 106 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Brown VFT - NOT OBSERVED	200	SF	Room 107 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34A	12"x12" Brown VFT Mastic - NOT OBSERVED	200	SF	Room 107 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Off-white w/specks VFT - NOT OBSERVED	700	SF	Room 107 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35A	12"x12" Off-white w/specks VFT Mastic - NOT OBSERVED	700	SF	Room 107 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Blue linoleum flooring (Not Observed)(18x18 tile)	1200	SF	Ground floor, Lunch Room 001 (Not Observed)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36A	Blue linoleum flooring Mastic (Not Observed) (18x18 tile)	1200	SF	Ground floor, Lunch Room 001 (Not Observed)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

White lenoleum flooring 800 SF Ground floor kitchen 001B, Storage 004C, 004D - 1902 Bldg. Miscellaneous No None 0 YES X NO	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
	37	White lenoleum flooring	800	SF	001B, Storage 004C,		Miscellaneous	No	None	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37A	White linoleum flooring, Mastic	800	SF	Ground floor kitchen 001B, Storage 004C, 004D - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Drywall, tape and compound	2000	SF	3rd floor boys and girls toilet, janitors closet, and 2nd floor, Gym Mezzanine -1902 Bldg		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12" x 12" White with black & gray specks VFT	600	SF	Room 204 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39A	12" x 12" White with black & gray specks VFT Mastic	600	SF	Room 204 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO
•											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12" x 12" Beige streaked VFT	350	SF	Room 204 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40A	12" x 12" Beige streaked VFT Mastic	350	SF	Room 204 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Canvas on N. and E. walls	200	SF	Room 204 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" Light tan with brown-and-white streaks VFT(tan/beige) (Not Observed)	1100	SF	Room 107 and wardrobe 107A (Under HA #50) - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

0200.10d)	
2022 Fall Six Month Survey: No Change	
Comments:not observed	
2023 Spring Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: No Change	
Comments:	
2024 Fall Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42A	12" x 12"(tan/beige) Light tan with brown-and-white streaks VFT Mastic (Not Observed)	1100	SF	Room 107 and wardrobe 107A (Under HA #50) - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Yellow streaked VFT	1800	SF	Ground floor-elevator lobby, storage room, corridor, unisex toilet, gym office, hall outside gym office - 1957 bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43A	12" x 12" Yellow streaked VFT Mastic	1800	SF	Ground floor-elevator lobby, storage room, corridor, unisex toilet, gym office, hall outside gym office - 1957 bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Blue streaked VFT	800	SF	Ground floor, Multipurpose Room 006 - 1902 bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44A	12" x 12" Blue streaked VFT mastic	800	SF	Ground floor, Multipurpose Room 006 - 1902 bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Off-white with tan streaks VFT	560	SF	Ground floor corridor by Storage Room 004C and 004D - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
2022 I ali Six Mortiri Survey. No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45A	12" x 12" Off-white with tan streaks VFT mastic	560	SF	Ground floor corridor by Storage Room 004C and 004D - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12" x 12" White with brown streaks VFT	1100	SF	Ground floor hall outside Rooms 005, 007 and 011 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

	Quantity	Units		Туре	Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
" x 12" White with brown reaks VFT Mastic	500	SF	Ground floor hall outside Rooms 005, 007 and 011 - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Terrazzo	1000	SF	Ground Floor Gym Lobby 014 and Vestibule - 1957 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Hard Coat Plaster	80000	SF	Throughout 1902 bldg.		Surface	No	None	0		YES X NO
2022 Fall Six	K Month Survey: No Ch	ange]						
Comments:	, ,										
2023 Fall Six Month Survey: No Change											
Commonte:											

ZOZZ T dil Cix Month Carvey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	18" x 18" Red with Black Specks VFT	400	SF	Corridor outside Room 100		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49A	18" x 18" Red with Black Specks VFT Mastic	400	SF	Corridor outside Room 100		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Tan Wood Laminate Flooring	1000	SF	Room 107, 100A, 100B		Miscellaneous	No	None	0		YES X NO

Page 39

2014A-01	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	2014A-01		9600	SF	3rd Floor Classrooms -		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2014A-01M	12" x 12" Blue Streaked VFT Mastic	9600	SF	Throughout 1st, 2nd and 3rd Floor Classrooms - 2014 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
2014A-02	12" x 12" Cream w/ Off White Streaks VFT	9600	SF	Throughout 1st, 2nd and 3rd Floor Classrooms - 2014 Annex		Miscellaneous	No	None	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2014A-02M	12" x 12" Cream w/ Off White Streaks VFT Mastic	9600	SF	Throughout 1st, 2nd and 3rd Floor Classrooms - 2014 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2014A-03	18" x 18" Light Green w/ Green and White Spots VFT	7500	SF	Throughout 1st, 2nd and 3rd Floor Corridors - 2014 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2014A-03M	18" x 18" Light Green w/ Green and White Spots VFT Msatic	7500	SF	Throughout 1st, 2nd and 3rd Floor Corridors - 2014 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2014A-04	18" x 18" Light Tan w/ Tan and White Spots VFT	10000	SF	Throughout 1st, 2nd and 3rd Floor Corridors, Lunchroom - 2014 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2014A-04M	18" x 18" Light Tan w/ Tan and White Spots VFT Mastic	10000	SF	Throughout 1st, 2nd and 3rd Floor Corridors, Lunchroom - 2014 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
2014A-05	2' x 2' Textured White Ceiling Tile	7500	SF	Throughout 1st, 2nd and 3rd Floor Corridors - 2014 Annex		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall Si	x Month Survey: No C	hange			1							
Comments:	•	· ·										
2023 Fall Si	x Month Survey: No C	hange			1							
Comments:]							
2023 Spring	Six Month Survey: No	c Change			-							
Comments:												
2024 Fall Si	x Month Survey: No C	hange			_							
Comments:	•	-										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2014A-06	2' x 4' Textured White Ceiling Tile	12000	SF	Throughout 1st, 2nd and 3rd Floor Offices and Classrooms - 2014 Annex		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

2024 Spring Six Month Survey: No Change

11/110	Material Besonption	Quantity	Units	Waterial Education	Туре	Category	THADIO	Туре	Quantity	Units	Change in Adde.	Someth Gategory
2014A-07	Vinyl Basboard Adhesive	15000	LF	Throughout 1st, 2nd and 3rd Floors - 2014 Annex		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	nange										
Comments:												
	Six Month Survey: No	Change										
Comments:												
	Month Survey: No Ch	nange										
Comments:												
	Month Survey: No Ch	nange										
Comments:												
	Six Month Survey: No	Change										
Comments:												
					_							

Asbestos

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2014A-08	18" x 18" Dark Brown VFT	2500	SF	Lunchroom - 2014 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2014A-08M	18" x 18" Dark Brown VFT Mastic	2500	SF	Lunchroom - 2014 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 22821

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Aircell Pipe Insulation	95	LF	Room 008, Multipurpose Room 006, Lunch Room 001, Boiler Room, Tank Room, Engine Room, Engineer's Storage Room - 1902 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A1	MJP E/F/V on Aircell Pipe Insulation	10	EA	Room 008, Multipurpose Rm 006, Lunch Rm 001, Boiler Room, Tank Room, Engine Room, Engineer's Storage Room - 1902 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP E/F/V on Fiberglass Pipe Insulation(good)	400	EA	(See Hatching Maps) Boiler Room, tank room, Basement girls and boys toilet pipe-chases - 1902 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Cardboard Pipe Insulation	1121	LF	Room 001(PTA), 003, 005, 007, Multipurpose Rm 006, Lunchroom 001, Fan & Boiler. Coal Room, tank Room Toilet, Tank Room Closet, Tank Room, Engineer's Storage Room Rooms - 1902 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	MJP E/F/V on Cardboard Pipe Insulation	128	EA	Room 001, 003, 005, 007, Multipurpose Room 006, Lunchroom 001, Fan & Boiler Rooms, Coal Room, Tank Room Toilet, Tank Room Closet, Tank Room, Engine Room, Engineer's Storage Room - 1902 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
G	Boiler Gasket (Rope) - ABATED (not observed)			Boiler Room - 1902 Bldg.		TSI	No	None			YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:no	ot observed											
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:	,											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Aircell Pipe Insulation - NOT OBSERVED	80	LF	Boys Toilet, Southwest Store Room, North Stage Stairwell, Gym mechanical rooms - 1957 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

H	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ı		MJP E/F/V on Aircell Pipe Insulation - NOT OBSERVED	16	EA	Boys Toilet, Southwest Store Room, North Stage Stairwell, Gym mechanical rooms - 1957 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Boiler Gasket(s) on New Boiler (not observed)	20	LF	Boiler Room - 1902 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:not observed
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Oracle Unit: 22821

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John C Coonley Elementary School
Date:10/28/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. Posted on CPS website
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.