Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Oracle Unit:

22931

Address: 7240 S. Wabash Region: 05 Mail Room: Asbestos Surveyor: Mayers, Reavon X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/14/2024 Email Address: rlmayers2@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 1953 Building- Lobby and YES 03 X NO 2'x2' Drop Ceiling Tile 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

Charles S Deneen Elementary School

School:

Oracle Unit: 22931

3010

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04	1'x1' Acoustical Ceiling Tiles			1953 Building- Lunchroom & Kitchen							YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange]							
Comments.												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:	_	_										
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2024 Spring	Six Month Survey: No	Change										
Comments:	· ·	-										
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	•	•										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	1'x1' Acoustical Ceiling Tiles	600	SF	1953 Building- Lobby		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06A	12x12 Blue Floor Tile	4675	SF	1962 Addition- Rooms 116, 117, 118, 119, 120, Teachers Lounge (115)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06B	12x12 White Floor Tile	2640	SF	1962 Addition- 1st & 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

09	Vinyl Mopboard			1953 Building- Classrooms & Lunchroom							YES	X NO
	·				7	·						
2022 Fall Six	Month Survey: No Ch	nange										
Comments:												
2023 Fall Six	Month Survey: No Ch	nange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	nange										
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

10	Vinyl Mopboard Mastic	Classrooms & Lunchroom			
2022 Fal	Il Six Month Survey: No Change				
Commer	nts:				
2023 Fal	Il Six Month Survey: No Change				
Commer	nts:				
2023 Sp	ring Six Month Survey: No Change				
Commer	nts:				
2024 Sp	ring Six Month Survey: No Change				
Commer	nts:				

1953 Building-

Material Location

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

Material Description

2024 Fall Six Month Survey: No Change

Comments:

Material

Quantity

Quantity

Units

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12	9x9 Tan Floor Tile	790	SF	1953 Building- Room 200		Miscellaneous	No	None	0		YES	X NO
2022 Fall S	Six Month Survey: No Cl	hange]							
Comments	:											
2023 Fall S	Six Month Survey: No Cl	hange										
Comments												
2023 Sprin	g Six Month Survey: No	Change										
Comments												
2024 Sprin	2024 Spring Six Month Survey: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9x9 Tan Floor Tile Mastic	900	SF	1953 Building- Room 200		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	12x12 Blue Floor Tile	11200	SF	1953 Building- School Offices, Rooms 103, 104, 105, 109, 202, 203, 204, 205, 206, 207, 208 & 209		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14B	12x12 White Floor Tile	5400	SF	1953 Building- 1st & 2nd Floor Corridors & Room 200		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	12x12 Blue Floor Tile Mastic	11200	SF	1953 Building- School Offices, Rooms 103, 104, 105, 109, 202, 203, 204, 205, 206, 207, 208 & 209		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15B	12x12 White Floor Tile Mastic	8825	SF	1953 Building- 1st & 2nd Floor Corridors and Rooms 106, 107 & 108		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18A	12x12 White Floor Tile	3850	SF	1958 Building- 1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No C	nange			1							
Comments:	-	_]							
2023 Spring	Six Month Survey: No	Change			-							
Comments:												
2023 Fall Six	Month Survey: No C	nange			-							
Comments:	-											
2024 Spring	Six Month Survey: No	Change			-							
Comments:												
2024 Fall Six	Month Survey: No C	nange										
Comments:	•]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18B	12x12 Blue Floor Tile	4660	SF	1958 Building- Rooms 112, 114, 210, 212 & 214		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Page 8

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	12x12 White Floor Tile Mastic	3850	SF	1958 Building- 1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19B	12x12 Blue Floor Tile Mastic	4660	SF	1958 Building- Rooms 112, 114, 210, 212, 214		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
22	Vibration Gasket			1953 Building- Fan Room							YES	X NO
2022 Fall Six	Month Survey: No Ch	nange										
Comments:												
2023 Fall Six	Month Survey: No Ch	nange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:	·											
2024 Fall Six	Month Survey: No Ch	nange										
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Wrap Around Duct Fiberglass	275	LF	Boiler Room		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category		Type	Quantity	Units		
24	Wrap Around Breeching Fiberglass	150	LF	Boiler Room		TSI	Yes	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange										
2023 Fall Six Comments:	Month Survey: No Cha	ange										
	Six Month Survey: No	Change										
Comments:												
	Six Month Survey: No	Change										
Comments:					-							

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Boiler Gasket ABATED			Boiler Room		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

2024 Fall Six Month Survey: No Change

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
26	Baseboard			1958 Building- Rooms 110, 112, 114, 210A, 210B, 212 & 214							YES	X NO
2022 Fall S	Six Month Survey: No C	hange			7							
Comments		J]							
2023 Fall S	Six Month Survey: No C	hange										
Comments	:											
2023 Sprin	g Six Month Survey: No	Change			-							
Comments	:											
2024 Sprin	g Six Month Survey: No	Change			1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Baseboard Mastic			1958 Building- Rooms 110, 112, 114, 210A, 210B & 212, 214							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

Comments:

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
28	Baseboard			1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219 & 220							YES	X NO
2022 Fall Comment	Six Month Survey: No C s:	hange					,					
2023 Fall Comment	Six Month Survey: No C s:	hange										
2023 Spri Comment	ng Six Month Survey: No s:	o Change										
2024 Spri	ng Six Month Survey: No	Change										

Comments:		

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Baseboard Mastic			1962 Building- Rooms 116, 117, 118, 119, 120, 216, 218, 219 & 220							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
32	Acoustic Ceiling			1958 Building- Corridors		Surface					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring S	Six Month Survey: No	Change			-							
	Six Month Survey: No	Change			-							
Comments:					- -							
2024 Fall Six Comments:	Month Survey: No Ch	ange			-							
Comments.]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Acoustic Plaster	5300	SF	1962 Building- Rooms 116, 117, 118, 119, 120, teachers lounge, 218, 220		Surface	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	Acoustic Plaster	1390	SF	1958 Building- Room 110		Surface	Yes	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch	ange										

2023 Spring Six Month Survey: No Change Comments:

2024 Spring Six Month Survey: No Change Comments:

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Brown Coat Plaster	7900	SF	1958 Building- Corridors/Ceiling		Surface	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

37	Acoustic Ceiling Plaster	1260	SF	1962 Building- 1st & 2nd Floor Corridors		Surface	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange									
Comments:											
2023 Fall Six	Month Survey: No Ch	ange									
Comments:											
2000 0 :	0: 14 (1 0 1)	01									
	Six Month Survey: No	Change									
Comments:											
2024 Spring	Six Month Survey: No	Change									
	Six Month Survey. No	Change									
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									
Comments:	•										
		•	•								

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38A	12x12 Blue Floor Tile Mastic	4755	SF	1962 Addition- Rooms 116, 117, 118, 119, 120, Teachers Lounge (115), Engineer's Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38B	12x12 White Floor Tile Mastic	2640	SF	1962 Addition- 1st & 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Brown Coat Plaster	1260	SF	1962 Addition- 1st & 2nd Floor Corridors		Surface	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	1'x1' Acoustical Ceiling Tile Mastic	2650	SF	1953 Building- Kitchen & Lunchroom		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	2'x4' Acoustical Ceiling Tiles	2400	SF	1953 Building- Lunchroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42A	12x12 Blue Floor Tile	4413	SF	1953 Building- Rooms 104, 106 & 108		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42B	12x12 Blue Floor Tile Mastic	4413	SF	1953 Building - Rooms 104, 106 & 108		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
43A	12x12 Blue Floor Tile	1471	SF	1958 Building- Room 110		Miscellaneous	No	None	0		YES	X NO
2022 Fall S	ix Month Survey: No C	hange]							
Comments:												
	ix Month Survey: No C	hange			1							
Comments:) 				-							
2023 Spring	g Six Month Survey: No	Change										
Comments:					1							
2024 Fall S	ix Month Survey: No C	hange										
Comments:					 -							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43B	12x12 Blue Floor Tile Mastic	1471	SF	1958 Building- Room 110		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
44	Blue/Gray Carpet Mastic	384	SF	Old Building- Room 102		Miscellaneous	No	None	0		YES	X NO
2022 Fall Si	x Month Survey: No Ch	ange										
Comments:	•	•										
2023 Fall Si	x Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change			_							
Comments:												
2024 Fall Si	x Month Survey: No Ch	ange			_							
Comments:												
2024 Spring	Six Month Survey: No	Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Brown Carpet Mastic	2000	SF	2007 Building- Main Office		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12x12 Light Green Vinyl Floor Tile	7892	SF	2007 Building- Cafeteria, Rooms 160, 201, 263, 252 & 256		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12x12 Light Green Vinyl Floor Tile Mastic	7892	SF	2007 Building- Cafeteria, Rooms 160, 201, 263, 252 & 256		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Tan Baseboard	312	LF	2007 Building- Cafeteria, Rooms 160, 201, 263, 252 & 256		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Tan Baseboard Mastic	312	LF	2007 Building- Cafeteria, Rooms 160, 201, 263, 252 & 256		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12x12 Yellow Vinyl Floor Tile	225	SF	2007 Building- Cafeteria, Rooms 160, 252, 261 & 263		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
Comments.
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12x12 Light Beige Vinyl Floor Tile	225	SF	2007 Building- Cafeteria, Rooms 160, 252, 261 & 263		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Mastic Associated with HA 50 and HA 51	450	SF	2007 Building- Cafeteria, Rooms 160, 261, 263, 252		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Green Baseboard	224	LF	2007 Building- Room 256 (Library)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

54	Green Baseboard Mastic	224	LF	2007 Building- Room 256 (Library)	Miscellaneous	No	None	0	YES	X NO
	Month Survey: No Cha	ange								
Comments:										
2023 Spring	Six Month Survey: No	Change								
Comments:										
2023 Fall Six	Month Survey: No Cha	ange								
Comments:										
2024 Fall Six	Month Survey: No Cha	ange								
Comments:										
	Six Month Survey: No	Change								
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Terrazzo Flooring	3500	SF	Stairs, Landings, Lobby & Corridors Throughout Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

56	Hard Plaster	200	SF	Basement & Tunnel	Surface	Yes	Loc	5	YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange								
2023 Spring S Comments:	Six Month Survey: No (Change								
2023 Fall Six Comments:	Month Survey: No Cha	ange								
2024 Fall Six Comments:	Month Survey: No Cha	ange								
2024 Spring S Comments:	Six Month Survey: No (Change								

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Aircell Pipe Insulation ABATED			1953 Building- Air Tunnel, Crawlspace (Abated)		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Categor
В	MJP Fittings ABATED			1953 Building- Air Tunnels, Crawlspace (Abated)		TSI		None			YES	X NO
2022 Fall Siz	x Month Survey: No C	hange	-	•			•	•	•	•	•	
Comments:	,	<u> </u>										
2023 Spring	Six Month Survey: No	o Change										
Comments:												
2023 Fall Siz	x Month Survey: No C	hange										
Comments:												
2024 Spring	Six Month Survey: No	o Change										
Comments:	·	<u> </u>		<u> </u>								
2024 Fall Siz	x Month Survey: No C	hange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Fittings on Fiberglass Runs ABATED		Fittings	1962 Building- Pipe Chases, Crawlspace (Abated)		TSI		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
Е	Aircell Pipe Insulation ABATED			1958 Addition- Crawlspace (Abated)		TSI		None			YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring S	Six Month Survey: No	Change										
	Month Survey: No Ch	ange			-							
Comments:		9-			-							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:]							
2024 Spring	Six Month Survey: No	Change										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Cardboard Pipe Insulation ABATED			1958 Addition- Crawlspace (Abated)		TSI		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-1	12x12 Green Speckled Floor Tile	250	SF	Room 200 & 100		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-2	12x12 Beige Floor Tile	85	SF	Room 217		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-1	12x12 Green Speckled Floor Tile Mastic	250	SF	Room 200 & 100		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Ch	ango									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-2	12x12 Beige Floor Tile Mastic	85	SF	Room 217		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

								,				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
G	Fttings on Fiberglass Runs ABATED			1958 Addition- (Abated)		TSI		None			YES	X NO
2022 Fall Six	Month Survey: No Ch]										
Comments:												
2023 Spring	Six Month Survey: No	Change			-							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange			_							
Comments:												
2024 Spring	Six Month Survey: No	Change			_							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Fittings on Fberglass Runs ABATED		Fittings	1962 Building- Crawlspace (Abated)		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
1	Aircell Pipe Fittings ABATED		Fittings	1953 Building- Air Tunnel, Crawlspace, Corridor (Abated)		TSI					YES	X NO
	•	•	•	•	-	•	-	•	•	•	•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
, , ,
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Cardboard Pipe Fittings ABATED		Fittings	1953 Building- Air Tunnels (Abated)		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
К	Aircell Pipe Joint ABATED		Fittings	1958 Building- Crawlspace (Abated)		TSI					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring S Comments:	Six Month Survey: No	Change										
2024 Fall Six Comments:	Month Survey: No Ch	ange										
	Six Month Survey: No	Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Cardboard Joint Fittings ABATED		Fittings	1958 Addition- Crawlspace (Abated)		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and after Renovations		Miscellaneous		Unknown			YES X NO

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Charles S Deneen Elementary School
Date: 11/14/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 22931

SCHOOL'S ASBESTOS MANAGEMENT PLAN.