Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Oracle Unit:

23301

Building ID: 5225 N Oak Park Avenue Address: Region: 01 Mail Room: Asbestos Surveyor: Quillen, Nathan X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/19/2024 Email Address: naquillen1@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other CPS Website Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type YES 03 SF X NO Acoustical Plaster 6000 Assembly Hall - 1951 Yes None 0 Surface 2022 Fall Six Month Survey: No Change Comments:No Change 2023 Spring Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

John W Garvy Elementary School

School:

3510

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Beige VFT	690	SF	Computer Room (207) - 1937		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change Comments:No Change											

2022 Fall Six Month Survey: No Change
Comments:No Change
_
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Dark Brown VFT	20	SF	Engineer's Bathroom - 1937		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Beige VFT Mastic	690	SF	Computer Room (207) - 1937		Miscellaneous	No	None	0		YES X NO
2022 Fall Civ	Month Cumasu No Cha										

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
0004 Fall O' Marth O are No Olarson
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	9"x9" Dark Brown VFT Mastic	20	SF	Engineer's Bathroom - 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Tan VFT	2430	SF	Rooms 101, 102, 103, and 104; Rooms 201, 202, 204, 206 and 105A (under existing VFT), Main Office - 1951		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Tan VFT Mastic	2430	SF	Rooms 101, 102, 103, and 104; Rooms 201, 202, 204, 206 and 105A (under existing VFT); Main Office (under carpet) - 1951		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	itegory
13	12"x12" Blue/Gray VFT	2430	SF	Rooms 101, 102, 103, 104, and 105; Rooms 201, 202, 204, 206 (under existing VFT); Main Office (under the carpet) - 1951		Miscellaneous	No	None	0		YES X N	0

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" White w/ Tan Speckles VFT	800	SF	Rooms 111 - 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
<u> </u>
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" White w/ Tan Specks VFT	1000	SF	Room 203 (under existing VFT) - 1951		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Brown VFT	1800	SF	Rooms 108 and 110; Cafeteria Office, Cafeteria Storage, Kitchen (under existing VFT in all three) - 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" White VFT	1800	SF	Rooms 108 and 110; Cafeteria Office, Cafeteria Storage, Kitchen (under existing VFT in all three) - 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Tan VFT - Abated			NE Gym Vestibule 1937 - Abated		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
19	12"x12" Blue/Gray VFT - Abated			NE Gym Vestibule 1937 - Abated		Miscellaneous				YES	X NO
	Month Survey: No Cha	ange									
Comments:No	o Change										
2023 Spring S	Six Month Survey: No	Change									
Comments:	,	J									
2023 Fall Six	Month Survey: No Cha	ange									
Comments:											
2024 Spring S	Six Month Survey: No	Change									
Comments:	•	=:									
2024 Fall Six	Month Survey: No Cha	ange									
Comments:	,										

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Off White VFT	150	SF	Engineer's Office - 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Blue/Gray VFT Mastic	2430	SF	Rooms 101, 102, 103, 104; Rooms 201, 202, 204, and 206 (under existing VFT, in all four rooms; Main Office - 1951		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" White w/ Tan Specks VFT Mastic	800	SF	Room 111 - 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" White w/ Tan Specks VFT Mastic	1000	SF	Room 203 (under existing VFT) - 1951		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Brown VFT Mastic	1800	SF	Rooms 108 and 110; Cafeteria Office, Cafeteria Storage, Kitchen (under existing VFT) - 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" White VFT Mastic	1800	SF	Rooms 108 and 110; Cafeteria Office, Cafeteria Storage, Kitchen (under existing VFT) - 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Tan VFT Mastic - Abated			NE Gym Vestibule 1937 - Abated		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
27	12"x12" Blue/Gray VFT Mastic - Abated			NE Gym Vestibule 1937 - Abated		Miscellaneous				YES	X NO
	Month Survey: No Cha	ange									
Comments:No	o Change										
2023 Fall Six	Month Survey: No Cha	ange									
Comments:											
2023 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Spring S	Six Month Survey: No	Change									
Comments:											
	Month Survey: No Cha	ange									
Comments:											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Off White VFT Mastic	150	SF	Engineer's Office - 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

Page 15

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" x 12" White w/Tan Specks VFT	4000	SF	Rooms 201, 202 & 204 (all under existing VFT); Teacher's Lounge - 1951		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29 A	12" x 12" White w/Tan Specks VFT Mastic	4000	SF	Rooms 201, 202 & 204 (all under existing VFT); Teacher's Lounge - 1951		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" White VFT	750	SF	Room 109 - 1937 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30 A	12" x 12" White VFT Mastic	750	SF	Room 109 - 1937 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" x 12" White w/Blue Gray Specks VFT	2500	SF	1st Floor Corridor (Some VFT, NOT reflected in the Material Quantity here, were abated in 2010)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31A	12" x 12" White w/Blue Gray Specks VFT Mastic	2500	SF	1st Floor Corridor (Some VFT, NOT reflected in the Material Quantity here, were abated in 2010)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
32	18" x 18" Carpet Squares Mastic	1500	SF	Main Office; Library 209		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	x Month Survey: No Ch No Change	ange										
2023 Spring Comments:	Six Month Survey: No	Change										
2023 Fall Six	x Month Survey: No Ch	ange										
	Six Month Survey: No	Change										
2024 Fall Six Comments:	x Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	12" x 12" Gray with Dark Streaks VFT	500	SF	Room 105A - 1951 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101 A	12" x 12" Gray with Dark Streaks VFT Mastic	500	SF	Room 105A - 1951 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	12" x 12" Off White w/ Tan Specks VFT			The 2000 Mobile Unit was demolished in 2010.		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:Does not exist
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
103	12" x 12" Off White w/ Tan Specks VFT Mastic			The 2000 Mobile Unit was demolished in 2010.		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:N	o Change											
2023 Fall Six	Month Survey: No Ch	ange										
Comments:D	oes not exist											
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	2' x 2' White Ceiling Tlle			The 2000 Mobile Unit was demolished in 2010.		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:Does not exist
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Change in Assessment Category

		Quantity	Units		Type	Category	Туре	Quantity	Units		
105	Drywall			The 2000 Mobile Unit was demolished in 2010.		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Cha	ange]						
Comments:No					1						
	Six Month Survey: No	Change			-						
Comments:					<u> </u>						
2023 Fall Six	Month Survey: No Cha	ange									
Comments:Do	oes not exist]						
	Six Month Survey: No	Change			-						
Comments:											
	Month Survey: No Cha	ange									
Comments:					-						
L					J						

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	Drywall Joint Compound			The 2000 Mobile Unit was demolished in 2010.		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:Does not exist
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Туре	Category	Type	Quantity	Units		
107	Vinyl Baseboard			The 2000 Mobile Unit was demolished in 2010.		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]						
Comments:N	o Change										
	Month Survey: No Ch	ange									
Comments:D	oes not exist				-						
2023 Spring S	Six Month Survey: No	Change									
Comments:					-						
2024 Fall Six	Month Survey: No Ch	ange									
Comments:					-						
	Six Month Survey: No	Change									
Comments:					-						
					J						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	Vinyl Baseboard Mastic			The 2000 Mobile Unit was demolished in 2010.		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:Does not exist
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

		Quantity	Units		Type	Category	Type	Quantity	Units		
109	Texture Drywall			The 2000 Mobile Unit was demolished in 2010.		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Cha	ange]						
Comments:No	o Change	-									
2023 Fall Six	Month Survey: No Cha	ange			_						
Comments:Do	oes not exist				=						
	Six Month Survey: No	Change									
Comments:					-						
	Six Month Survey: No	Change									
Comments:											
	Month Survey: No Cha	ange									
Comments:											
					1						

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Textured Drywall Joint Compound			The 2000 Mobile Unit was demolished in 2010.		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:Does not exist
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12"x12" White with Black Specs Floor Tile	1900	SF	1ST Floor: Corridor; 2ND Floor: Corridor and Storage Room 214 - Bldg 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change		
Comments:No Change		
_		
2023 Fall Six Month Survey: No Change		
Comments:		
2023 Spring Six Month Survey: No Change		
Comments:		
2024 Fall Six Month Survey: No Change		
Comments:		
2024 Spring Six Month Survey: No Change		
Comments:	· <u> </u>	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12"x12" White with Black Specs Floor Tile Mastic	1900	SF	1ST Floor: Corridor; 2ND Floor: Corridor and Storage Room 214 - Bldg 1937		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	2'x2' Smooth White Ceiling Tile	675	SF	1st Floor: Corridor and Vestibule 106; 2nd Floor Corridor by Rms 214, 214 Storage		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114	Beige Terrazzo	215	SF	1st Floor: Stairwell		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units		
115	Drywall	750	SF	2nd Floor: Corridor		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:N	o Change											
2023 Spring	Six Month Survey: No	Change										
Comments:					_							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					_							
	Six Month Survey: No	Change										
Comments:					_							
	Month Survey: No Ch	ange										
Comments:					_							
					_							

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	Drywall Joint Compound	750	SF	2nd Floor: Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	12" x 12" White w/black specs VFT	2500	SF	1st and 2nd floor corridors; Rm 105A - Bldg 1951 (Some VFT, NOT reflected in the Material Quantity here, were abated in 2010)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
118	12" x 12" White w/black specs VFT Mastic	2500	SF	1st and 2nd floor corridors; Rm 105A - Bldg 1951 (Some VFT, NOT reflected in the Material Quantity here, were abated in 2010)		Miscellaneous	No	None	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

119 Fire Door 7 EA Room 205 (Teacher's Lounge), Bookroom, Auditorium and Gymnasium Miscellaneous No None 0	YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	12" x 12" Red VFT	150	SF	1st and 2nd floor corridors; Rms 105A, 203; main office -1951 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121	12" x 12" Red VFT Mastic	150	SF	1st and 2nd floor corridors; Rms 105A, 203; main office -1951 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	12" x 12" Gray VFT	150	SF	1st and 2nd floor corridors; Rms 105A, 203; main office -1951 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123	12" x 12" Gray VFT Mastic	150	SF	1st and 2nd floor corridors; Rms 105A, 203; main office -1951 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

124 Curtain Wall 700 SF Gymnasium platform Miscellaneous No None 0	YES X NO
2022 Fall Six Month Survey: No Change Comments:No Change	
2023 Fall Six Month Survey: No Change Comments:	
2023 Spring Six Month Survey: No Change Comments:	
2024 Spring Six Month Survey: No Change Comments:	
2024 Fall Six Month Survey: No Change Comments:	

Material

Friable

Damage

Damage

HA No	Mate	aterial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
125		x 12" light beige with streaks VFT	2800	SF	Rooms 201, 202, 204, and 206 - 1951 Bldg		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
125A	12" x 12" light beige with tan streaks VFT Mastic	2800	SF	Rooms 201, 202, 204, and 206 - 1951 Bldg		Miscellaneous	No	None	0		YES		X NO
2022 Fall Six	Month Survey: No Ch	ange											
Comments:N	o Change]								
2023 Spring	Six Month Survey: No	Change											
Comments:													
2023 Fall Six	Month Survey: No Ch	ange			-								
Comments:													
2024 Fall Six	Month Survey: No Ch	ange			1								
Comments:	-	-]								
2024 Spring	Six Month Survey: No	Change			1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	2' x 4' Ceiling Tile	4900	SF	Rooms 107, 108, 109, 110, 111, and 112; 1st Floor Corridor - 1937 Bldg		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
127	2' x 4' Ceiling Tile	3500	SF	Rooms 101, 102, 103, and 104; 1st Floor Corridor - 1951 Bldg		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	12" x 12" Sand VFT	2600	SF	Assembly Hall - 1937 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

Page 35

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
128A	12" x 12" Sand VFT Mastic	2600	SF	Assembly Hall - 1937 Bldg.		Miscellaneous	No	None	0		YES	X NO
		•	•			•		•		•		

2022 Fall Six Month Survey: No Change
Comments:No Change
_
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
, , ,
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
129	Fire Brick - Electric Kiln Oven	30	SF	2nd Floor Storage / Former Bathroom by 203/206		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Cardboard Pipe Insulation	430	LF	All Unfinished Pipe Areas, Boiler Room, Engineer Storage, Janitor Room, Basement Corridors - 1937		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP E/F/V on Cardboard Pipe Insulation	41	FITTING	All Unfinished Pipe Areas, Boiler Room, Engineer Storage, Janitor Room, Basement Corridors - 1937		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	MJP E/F/V on Fiberglass Pipe Insulation	30	FITTING	Basement Storage Area by Electrical Room - 1937		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
<u> </u>
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Aircell Pipe Insulation	880	LF	All Unfinished Pipe Areas, Boiler Room, Janitor Room, Tunnel, Engineer Storage, Basement Corridors - 1937		TSI	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Aircell Pipe Insulation	136	FITTING	All Unfinished Pipe Areas, Boiler Room, Janitor Room, Tunnel, Engineer Storage, Basement Corridors - 1937		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

G	Aircell Duct Covering	2400	SF	Unexcavated Areas, Boiler Room - 1937		TSI	Yes	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ango]						
		ange									
Comments:No	o Change										
2023 Spring S	Six Month Survey: No	Change									
Comments:		•									
Commonto					1						
2023 Fall Six	Month Survey: No Ch	ange									
Comments:	·										
2024 Fall Six	Month Survey: No Ch	ange									
Comments:	,	<u> </u>									
2024 Spring S	Six Month Survey: No	Change									
Comments:		2									
			•]						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	Cardboard Pipe Insulation	450	LF	Pump Room, Fan Room, All Unfinished Areas, Basement Corridors - 1951		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	MJP E/F/V on Cardboard Pipe Insulation	45	FITTING	Pump Room, Fan Room, All Unfinished Areas, Basement Corridors - 1951		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
Comments.
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Aircell Pipe Insulation	635	LF	Pump Room, Fan Room, All Unfinished Areas, Basement Corridors - 1951		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	MJP E/F/V on Aircell Pipe Insulation	64	FITTING	Pump Room, Fan Room, All Unfinished Areas, Basement Corridors - 1951		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:No Change
•
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Mag Block Pipe Insulation	35	LF	Boiler Room - 1937		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change								
Comments:No Change								
2023 Spring Six Month Survey: No Change								
Comments:								
2023 Fall Six Month Survey: Abated								
Comments: Abated 10-23 due to pipe leak needing repair.								
2024 Fall Six Month Survey: No Change								
Comments:								
2024 Spring Six Month Survey: Abated								
Comments:Removed ACM from piping during pipe repair.								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	MJP E/F/V on Mag Block Pipe Insulation	8	FITTING	Boiler Room - 1937		TSI	Yes	None	0		YES X NO

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John W Garvy Elementary School
Date: 8/1/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. CPS Website
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.