Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Johann W von Goethe Elementary School 23341 3560 School: **Oracle Unit: Building ID:** Address: 2236 N. Rockwell Avenue Region: 02 Mail Room: Asbestos Surveyor: Soto, Mitchel X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2024 Email Address: A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other cps website Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type Throughout - 1885 YES 01 Hard Coat Plaster SF X NO 60000 No None 0 Miscellaneous Building 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments:N/A 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	2'x4' Ceiling Tile	500	SF	Room 106 - 1885 Building		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	12" x 12" beige specks floor tile	16700	SF	Rooms 205, 206, 207, 208, 203, 202, 201, 210, 2nd floor teachers lunchroom, 308, 307, 306, 305, 301, 108, 106, 105, 102, and 101 Throughout - 1885 Building		Miscellaneous	No	None	30		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: Other
Comments: Floor in 207 replaced with rubberized tile after flood damage in
september.
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

04	12"x12" Beige w/ Brown Spots VFT	2500	SF	Rooms 106 & 206 - 1st , 2nd floor corridors. 1885 Building		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange	<u> </u>	•	1		•	•	•	•	•	
	Month Survey. No Ci	iariye										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:N	/A											
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
					1							
2024 Spring	Six Month Survey: No	Change			1							
Comments:	•											
					1							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	•	-										

Asbestos

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" White VFT	1500	SF	First and Second Floor Hallways, Lunchroom Managers office, Kitchen, Room 001- 1885 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Brown w/ White Spots VFT	1500	SF	First and Second Floor Hallways, Lunchroom Managers office, Kitchen - 1885 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Air Cell Pipe Insulation	180	LF	Rooms 001, 002, 003, 004, Boiler Room, Coal Room- 1885 Building		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	MJP E/F/V on Aircell Pipe Insulation	35	LF	Rooms 001, 002, 003, 004, Boiler Room, Coal Room, Basement corridor's- 1885 Building		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
_

Oracle Unit: 23341

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Cardboard Pipe Insulation	320	LF	Storage room 004, 2nd floor boys washroom, room 003, basement boy washroom, pump room storage room next to room 001		TSI	Yes	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	MJP E/F/V on Cardboard Pipe Insulation	2	LF	Basement Boys washroom, pump room		TSI	Yes	None			X YES NO

2022 Fall Six Month Survey: Repaired	
Comments:Problem areas repaired last summer	
2023 Fall Six Month Survey: No Change	
Comments:N/A	
2023 Spring Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: No Change	
Comments:	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	MJP E/F/V on Fiberglass Pipe Insulation	124	LF	Fan Room #1, Hallway in front of room 003		TSI	Yes	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Aircell Duct Insulation	480	SF	Basement Corridor- 1885 Building		TSI	Yes	None	0		YES X NO
								<u>.</u>			

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
Comments.
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Brown VFT Mastic	18450	SF	Throughout - 1885 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

14	12"x12" Beige w/ Brown Spots VFT Mastic	1350	SF	Rooms 106 & 206- 1885 Building		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange									
Comments:											
2023 Fall Six Month Survey: No Change											
Comments:N/A											
	Six Month Survey: No	Change									
Comments:											
	Six Month Survey: No	Change									
Comments:											
	Month Survey: No Ch	ange									
Comments:											
<u> </u>					ı						

Asbestos

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" White VFT Mastic	2500	SF	First and Second Floor Hallways, Lunchroom, Managers office, Kitchen, RM 001 - 1885 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12" x12" Brown w/ White Spots VFT Mastic	2500	SF	First and Second Floor Corridors, Lunchroom Managers office, Kitchen, - 1885 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9" x 9" Brown w/ Streaks VFT	180	SF	Room 308 Wardrobe- 1885 Building (Possibly under flooring)		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Abated
Comments:Removed during elevator project
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:Removed during elevator capital project
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9" x 9" Brown w/ Streaks VFT Mastic	180	SF	Room 308 Wardrobe- 1885 Building (Possibly under flooring)		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Abated									
Comments:removed during elevator project									
2023 Fall Six Month Survey: No Change									
Comments:N/A									
2023 Spring Six Month Survey: Abated									
Comments:removed during elevator capital pr	oject								
2024 Spring Six Month Survey: No Change									
Comments:									
2024 Fall Six Month Survey: No Change									
Comments:									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12" x 12" White w/ Brown Specks VFT (NOT OBSERVED)	0		Room # 500 through # 503 - 1987 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12" x 12" White w/ Brown Specks VFT Mastic (NOT OBSERVED)	0		Room # 500 through # 503 - 1987 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12" x 12" Brown w/ Wht. & Black Specks VFT(NOT OBSERVED)	0		Throughout - 1987 Annex		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	12" x 12" Brown w/ Wht. & Black Specks VFT Mastic (ABATED)			Throughout (See Hatching Maps) - 1987 Annex		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12" x 12" Beige w/ Brown Specks VFT (ABATED)			Room 400, AP Room - 1987 Annex		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: Abated
Comments:Removed in 2022 Capital project, replaced with rubberized
loor
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" Beige w/ Brown Specks VFT Mastic (ABATED)			Room 400, AP Room - 1987 Annex		Miscellaneous					YES X NO

(18/1128)	
2022 Fall Six Month Survey: No Char	nge
Comments:	
2023 Fall Six Month Survey: No Char	nge
Comments:N/A	
2023 Spring Six Month Survey: Abate	ed
Comments:Removed in 2022 Capital	I project, replaced with rubberized
floor	
2024 Spring Six Month Survey: No Cl	hange
Comments:	
2024 Fall Six Month Survey: No Char	nge
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" x 12" White w/ Blue Specks VFT (NOT OBSERVED)			Room # 401 - 1987 Annex							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12" x 12" White w/ Blue Specks VFT Mastic (NOT OBSERVED)			Room # 401 - 1987 Annex							YES X NO
2022 Fall Si	y Month Survey: No Ch	ange]						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	1' x 1' White w/ Grooves Ceiling Tile	20000	SF	Throughout - 1987 Annex		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	1' x 1' White w/ Grooves Ceiling Tile Mastic	20000	SF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change Comments:											

2000 Fall Civ Month Company No Change
2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	1' x 1' White w/ Dots and Grooves Ceiling Tile	1200	SF	Room 400 - 1987 Annex		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	1' x 1' White w/ Dots & Grooves Clng. Tile Mastic	1200	SF	Room 400 - 1987 Annex		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
31	Vinyl Baseboard	3500	LF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessr	ment Category
32	Vinyl Baseboard Mastic	3500	LF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES		X NO
2022 Fall Six Month Survey: No Change Comments:													
2023 Fall Six Comments:N	Month Survey: No Ch	ange											
2023 Spring	Six Month Survey: No	Change											
Comments:	Six Month Survey: No.	Change											
2024 Spring Six Month Survey: No Change Comments:													
2024 Fall Six Month Survey: No Change Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Drywall	50000	SF	Room 400		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 19

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
34	Drywall Joint Compound	5000	LF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:												
2023 Spring	Six Month Survey: No	Change			-							
Comments:	-]							
2023 Fall Six	Month Survey: No Ch	ange			1							
Comments:N	/A											
2024 Spring	Six Month Survey: No	Change			1							
Comments:	,											
2024 Fall Six	Month Survey: No Ch	ange			-							
Comments:												
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12 x 12 White with Gray and Brown Specs Floor Tile (ABATED)			LunchroomREMOVED		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
36	12 x 12 White with Gray and Brown Specs Floor Tile (ABATED)			LunchroomREMOVED		Miscellaneous		None			YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12x12 White w/ tan specks floor tile	14000	SF	Rooms 403, 404, 501, 500, 502, 504, 504C, 506, and 507		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37M	12x12 White w/ tan specs VFT Mastic	14000	SF	1st fl classrooms (400 thru 405) + staff rooms #06-#09; 2nd fl classrooms(500 thru 507) 1987 annex bldg		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12x12 Green with Gray + Dark Green specs VFT	7800	SF	1st fl corridor (4000 SF); 2nd fl corridor (3800 SF) 1987 annex bldg		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38M	12x12 Green w/ gray + Dark green specs VFT Mastic	7800	SF	1st fl corridor (4000 SF); 2nd fl corridor (3800 SF)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
39	White Spray-On Under sink coating	3	SF	under sink in cabinet room #4021987 annex		Miscellaneous	No	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
40	1x1 White Ceiling Tile	2800	SF	3rd Floor Gym		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall S	Six Month Survey: No C	hange										
	g Six Month Survey: N	o Chango										
Comments	·	o Change										
2023 Fall S	Six Month Survey: No C	hange										

Comments:N/A

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
41	1x1 White Ceiling Tile Matic	2800	SF	3rd Floor Gym		Miscellaneous	No	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 24

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
42	Tank Insulation	40	SF	Boiler Room		TSI	Yes	None	0		YES X NO	
0000 Fall Civ	Marath Comment Na Ob											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
43	Under sink coating	36	SF	Room 306 and 2nd floor teachers lunch room		Miscellaneous	No	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
44	Under sink coating	6	SF	Room 402		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47 & 48	12 x 12 Off White VFT & Mastic			Room 304		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
49 & 50	12 x 12 Dark Gray VFT & Mastic			Room 304		Miscellaneous	No	None			YES	X NO
2022 Fall Siz	x Month Survey: No Cl	nange		•				•	•		•	
Comments:	,											
2023 Spring	Six Month Survey: No	Change										
Comments:												
2023 Fall Siz	x Month Survey: No Cl	nange										
Comments:N	N/A											
2024 Fall Siz	x Month Survey: No Cl	nange										
Comments:												
2024 Spring	Six Month Survey: No	Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA 45 & 46	12 x 12 Light Peach VFT & Mastic	400		Room 304		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:N/A
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Johann W von	Goethe Elementary School
Date: 8/1/2024	
the Asbestos Management	ordance with Illinois and Federal Asbestos Regulations, that a copy of t Plan is available at each school during school hours by appointment. bestos Management Plan must be made at least 24 hours in advance.
The last inspection was co	at CPS conducts asbestos inspections of all Schools every three years. Impleted in 2022. In conducted every six months.
CHECK ONE	
A copy of this notice	was sent home in each child's backpack.
A copy of this notice	was printed in the school's newsletter and sent home with each child
A copy of this notice	was printed in the school's calendar and sent home with each child
X Other. cps website	
A COPY OF THIS NO	TICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23341

SCHOOL'S ASBESTOS MANAGEMENT PLAN.