Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Oracle Unit:

23351

Address: 12450 S State Street Region: 06 Mail Room: Asbestos Surveyor: Jackson, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/30/2024 Email Address: majackson35@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 2' x 4' White Fissured SF YES X NO 01 42000 Yes 0 Throughout School Miscellaneous None Ceiling Tile 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

Jesse Owens Elementary Community Academy

School:

3470

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	2'x4' Lay-In Ceiling Panels	1200	SF	Offices		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 23351

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04A	12x12 Beige Floor Tile	19200	SF	Rooms:105-107, 109, 200, 203-207, 211-215, 219-222, 1st and 2nd Floor Cooridors, E & W Vestibules, Engineer's Office, Lunchroom, Teachers Lounge, Stairs, Library Storage, Vault, PE Faculty Toilet, Kitchen and Bathroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04B	12x12 Orange Floor Tile	3900	SF	Gymnasium		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 23351

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04C	12x12 Tan Mottled Floor Tile	1200	SF	Teachers' Lounge, Washroom, 1st Floor Washroom, Room 102 and Washroom, Office Washroom, 2nd Floor NW Washroom, all Teacher's Toilets & Room 108		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

04D	12x12 Beige Speckled Floor Tile	550	SF	Room 103, Main Office		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange									
Comments:	World Garvey. 140 Off	arigo									
2023 Fall Six	Month Survey: No Ch	ange									
Comments:		<u> </u>									
2023 Spring	Six Month Survey: No	Change									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									
Comments:											
L					J						

Asbestos

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Mopboard	1000	LF	1st and 2nd Floor Corrridors, Teachers' Lounge, 1st Floor SE Bathroom, 102 Bathroom, Office Bathroom, Kitchen		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07A	12x12 Beige Floor Tile Mastic	19200	SF	Rooms:105-107, 109, 200, 203-207, 211-215, 219-222, 1st and 2nd Floor Cooridors, E & W Vestibules, Engineer's Office, Lunchroom, Teachers Lounge, Stairs, Library Storage, Vault, PE Faculty & Toilet, Kitchen and Bathroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07B	12x12 Orange Floor Tile Mastic	3900	SF	Gym		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07C	12x12 Tan Mottled Floor Tile Mastic	1200	SF	Teachers Lounge, Washroom, 1st Floor Washroom, Room 102 and Washroom, Office Washroom, 2nd Floor NW Washroom, all Teacher's Toilet and Rm 108		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category		Type	Quantity	Units		
07D	12x12 Beige Speckled Floor Tile Mastic	550	SF	Room 103, Main Office, Room 101		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No C	hange]							
Comments:]							
2023 Fall Six	Month Survey: No C	hange										
Comments:		-										
2023 Spring	Six Month Survey: No	Change										
Comments:					_							
2024 Spring	Six Month Survey: No	Change										
Comments:					_							
2024 Fall Six	Month Survey: No C	hange			1							

Asbestos

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Mopboard Mastic	1000	LF	1st and 2nd Floor Corrridors, Teachers' Lounge, 1st Floor SE Bathroom, 102 Bathroom, Office Bathroom, Kitchen		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Material Description

Material

Material Location

HA No

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Drywall	4000	SF	Lunchroom, N Corridor, Between Gym and Receiving, Engineer's Office, NW Boys Toilet, W and E Vestibules, N Vestibule and Hallway, Room 215, NW Toilet and Closet		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Carpet Mastic	18500	SF	Library, Main Office, 103, 109, 200, 210, 218, 225, Faculty Planning, Teachers' Lounge & Principal's Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Civ Month Curvoy No Change
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Caulk	2500	LF	Throughout Interior Windows on 1st and 2nd Floors		Miscellaneous	No	None	0		YES X NO

12	24"x24" Red Grey & White Mix Floor Tile	1600	SF	Rooms 101 & 102		Miscellaneous	No	None	0		YES	X NO
2022 Fall Si	x Month Survey: No Ch	ange										
Comments:		g										
2023 Spring Six Month Survey: No Change												
Comments:		- · · · · · · · · · · · · · · · · · · ·										
2023 Fall Si	x Month Survey: No Ch	ange										
Comments:	,											
2024 Fall Si	x Month Survey: No Ch	ange										
Comments:	•											
2024 Spring	Six Month Survey: No	Change										
Comments:	•	<u> </u>										
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	Mastic associated with 24"	<u> </u>						1			,	

Asbestos

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

Rooms 101 & 102

1600

HA No

12A

Material Description

x24" Red Grey & White Mix

Floor Tile

Material

Quantity

Material

Units

SF

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	24"x24" Grey & White Mix Floor Tile	14500	SF	Rooms 105-108, 200, 204-207, 211-214 & 219- 222		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	Mastic associated with 24" x24" Grey & White Mix Floor Tile	14500	SF	Rooms 105-108, 200, 204-207, 211-214 & 219- 222		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
14	12"x12" Brown w/White Streaks Floor Tile	2000	SF	1st & 2nd Floor Hallways, Lunchroom & Room 215		Miscellaneous	No	None	0		YES	X NO
0000 F-II Ci-	Manth Comment Na Ob]							
2022 Fall Six	Month Survey: No Cha	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Cha	ange										
Comments:	•											
2024 Fall Six	Month Survey: No Cha	ange										
Comments:												

Material

Friable

Damage

Damage

Asbestos

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14A	Mastic associated with 12" x12" Brown w/White Streaks Floor Tile	2000	SF	1st & 2nd Floor Hallways, Lunchroom & Room 215		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

2024 Spring Six Month Survey: No Change

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
15	Hardcoat Plaster	1200	SF	Vestibule Ceiling and Stairwells, Washrooms		Surface	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Brown Ceramic Tile Grout	730	SF	1st and 2nd Floor Boys and Girls Washrooms		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Brown Ceramic Tile Adhesive	730	SF	1st and 2nd Floor Boys' and Girls' Washrooms		Miscellaneous	No	None	0		YES X NO
					1						_

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Aircell Pipe Insulation NOT OBSERVED	100	LF	Boiler Room		TSI			0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
В	Spray-On Insulation	15000	SF	Boiler Room, Throughout Building, above Ceiling Tiles		Surface	Yes	None	0		YES	X NO
2022 Fall Six	Month Survey: No Cha	ange	•	· · · · · · · · · · · · · · · · · · ·				•	-	. —		

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	MJP E/F/V on Fiberglass Pipe Insulation	75	LF	Boiler Room and Throughout School Chases		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations		Miscellaneous		Unknown	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _Jesse Owens Elementary Community Academy
Date: 9/2/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23351

SCHOOL'S ASBESTOS MANAGEMENT PLAN.