Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Friedrich L. Jahn Elementary of the Fine Arts 23921 School: **Oracle Unit: Building ID:** 4170 Address: 3149 N. Wolcott Avenue Region: 01 Mail Room: Asbestos Surveyor: Nowaczyk, Vincent X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/19/2024 Email Address: vnowaczyk@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material **Asbestos** Material Damage Damage Quantity Units Type Category Quantity Type (3rd Flr. Tchrs Toilet & X NO YES Lounge - under carpet), Rm 004, 108, (Main Off., 12"x12" White w/ Brown 01 2426 SF Tchrs Tlt Across from 109 Miscellaneous None 0 Streaks VFT - not observed). Lunchroom, Staff Lunchroom, Basement 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12"x12" Beige w/ White Streaks VFT - Not Observed	800	SF	Room 301 & Wardrobe - Not Observed		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	12"x12" Brown w/ Tan Streaks VFT - Not Observed	120	SF	Room 205 & Library Wardrobe (Under Carpet) Not Observed		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	9"x9" Gray w/ Black Streaks VFT - NOT OBSERVED	460	SF	Principal's Office & Vestibule (Under Wood Floor)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Beige w/ Brown Streaks VFT	450	SF	Auditorium Stage and Stage Stairs, Room 003		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category	Type	Quantity	Units		
06	Battleship Green Linoleum - NOT OBSERVED			Room 107 NOT OBSERVED		Miscellaneous				YES	X NO
2022 Fall Si	x Month Survey: No Ch	ange									
Comments:	,										
	x Month Survey: No Ch	ange									
Comments:											
2023 Spring	Six Month Survey: No	Change									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Si	x Month Survey: No Ch	ange									
Comments:	-										

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Light Green w/ Brown Streaks VFT - NOT OBSERVED	500	SF	Room 001		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9"x9" Red VFT	100	SF	Room 003		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	2'x4' White Wormy Ceiling Tile (Tectum)	33002	SF	Throughout 1st, 2nd, & 3rd FL; 3rd FL; 3rd FL; Rms 301,304,303,305,307,306,308,309, Teachers Lounge/Toilet, Corridor 2nd FL: Rms 202,201,203,204,205,207,209,208, Teachers Lounge/Toilet, Corridor 1st FL: Rms 102,101,104,103,108,109, Asst. Principal Office, Main Office, Principal Office, Corridor Basement: Kitchen Storage, Teacher Lunchroom		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" White w/ Brown Streaks VFT Mastic	1302	SF	(3rd Flr. Tchrs Toilet & Lounge - under carpet), Rm 004,, 108, (Main Off., Tchrs Tlt Across from 109 - not observed), Lunchroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Gray w/ Black Streaks VFT Mastic	420	SF	Principal's Office & Vestibule (under wood floor)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Battleship Green Linoleum Mastic (Not Observed)	750	SF	Room 107 (Not Observed)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Transite Wall Panel	640	SF	Kitchen Storage, Tank Room (Behind Drywall)		TSI	Yes	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	2"x18" Border Black VFT	25	SF	Room 003		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Brown w/ Red Streaks VFT - NOT OBSERVED	50	SF	Room 002 (Under Tile/Wood) NOT OBSERVED		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change						•	•	•	•	•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Green w/ White Streaks VFT - Not Observed	1000	SF	Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26) - Not Observed		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Beige w/ White Streaks VFT Mastic - Not Observed	800	SF	Room 301 & Wardrobe - Not Observed		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Green w/ White Streaks VFT Mastic ABATED (2013)			Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26) - NOT OBSERVED ABATED (2013)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Brown w/Tan Streaks VFT Mastic ABATED (2013)			Room 205 & Library Wardrobe ABATED (2013)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units	Ü	,
22	9"x9" Beige w/ Brown Streaks VFT Mastic	450	SF	Auditorium Stage and Stage Stairs, Room 003		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange]							
2023 Fall Six Comments:	Month Survey: No Ch	ange			-							
2023 Spring S	Six Month Survey: No	Change			-							
2024 Spring S	Six Month Survey: No	Change										
2024 Fall Six Comments:	Month Survey: No Ch	ange] - -							
					_							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	2"x18" Border Black VFT Mastic	25	SF	Room 003		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9"x9" Red VFT Mastic	750	SF	Room 003		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
, v
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9"x9" Brown w/ Red Streaks VFT Mastic (Under Wood) - NOT OBSERVED	50	SF	Room 002 NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Light Green w/ Brown Streaks VFT Mastic - NOT OBSERVED	500	SF	Room 002, 001 NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" Blue VFT	50	SF	Staff Toilet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Blue VFT Mastic	50	SF	Staff Toilet		Miscellaneous	No	None	0		YES X NO
0000 5 11 0:					i						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" x 12" Peach VFT - Not Observed	1500	SF	Lunchroom - Not Observed		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" Peach VFT Mastic - Not Observed	1500	SF	Lunchroom - Not Observed		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12 x 12 inch Light Blue w/White Specks VFT	650	SF	Room 002 (Duplicate of HA 45, 46)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

31A	12 x 12 inch Light Blue w/White Specks VFT Mastic	650	SF	Room 002 (Duplicate HA 45, 46)		Miscellaneous	No	None	0	YES	X NO
		·	•	•	1	•	•	•	•		
2022 Fall Six	Month Survey: No Ch	ange									
Comments:											
2023 Fall Six	Month Survey: No Ch	ange									
Comments:											
2023 Spring	Six Month Survey: No	Change									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									
Comments:	•	-									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Carpet Mastic	1000	SF	Main Office - not observed, Rooms 005, 205, 3rd FL Teacher's Lounge (over HA 01)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units	G	
33	12 x 12 Tan Floor Tile - Not Observed	750	SF	Room 108 - Not Observed		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange										
Comments.												
2023 Fall Six	Month Survey: No Cha	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change			-							
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
	Month Survey: No Cha	ange										
Comments:												

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12 x 12 Tan Floor Tile Mastic - Not Observed	750	SF	Room 108 - Not Observed		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12 x 12 Grey Floor Tile	2804	SF	Main Office, 1st and 2nd Floor Corridors, 301, 3rd FL Corridor, 3rd FL Stair Landings		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
0004 5 11 01 14 11 0 11 01
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12 x 12 Grey Floor Tile Mastic	2804	SF	Main Office, 1st and 2nd Floor Corridors, 301, 3rd FL Corridor, 3rd FL Stair Landings		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12 x 12 White Floor Tile	2500	SF	1st and 2nd Floor Corridors, 1st Boys and Girls Washrooms, 2nd FL Stair Landings, Basement Lunchroom, Main Office- Closet		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12 x 12 White Floor Tile Mastic	2500	SF	1st and 2nd Floor Corridors, 1st Boys and Girls Washrooms, 2nd FL Stair Landings, Basement Lunchroom, Main Office- Closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12 x 12 Yellow Floor Tile	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12 x 12 Yellow Floor Tile Mastic	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12 x 12 Blue Floor Tile	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12 x 12 Blue Floor Tile Mastic	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12 x 12 Green Floor Tile	250	SF	Teacher's Toilets across Room 109, 1st FL Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12 x 12 Green Floor Tile Mastic	250	SF	Teacher's Toilets across Room 109, 1st FL Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12 x 12 Light Blue Floor Tile (Duplicate HA 31, 31A)	1000	SF	Room 002, 301, 3rd FL Corridor, 3rd FL Stair Landing		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12 x 1 2 Light Floor Tile Mastic (Duplicate HA 31, 31A)	650	SF	Room 002. 301,3rd FL Corridor, 3rd FL Stair Landing		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12 x 12 Royal Blue Floor Tile	1720	SF	Lunchroom, 301, 3rd FL Corridor, 3rd FL Stair Landing		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12 x 12 Royal Blue Floor Tile Mastic	1720	SF	Lunchroom, 301, 3rd FL Corridor, 3rd FL Stair Landing		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
49	12 x 12 Off White Floor Tile	900	SF	Room 001		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Cha	ange										

Comments:

2023 Spring Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12 x 12 Off White Floor Tile Mastic	900	SF	Room 001		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Terrazzo	1800	SF	Room 005, vestibules, 1st Floor Toilet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
52	Ceramic Tile Grout	2140	SF	2nd Floor Restroom (206) and Basement Restroom, 3rd FL Teacher's Toilet, Rm 103-Toilet, 101- Toilet, 1st FL Boy's + Girl's Toilet, Main Office Toilet		Miscellaneous	Yes	None	0		YES	X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Ceramic Tile Adhesive	2140	SF	2nd Floor Restroom (206) and Basement Restroom, 3rd FL Teacher's Toilet, Rm 103-Toilet, 101- Toilet, 1st FL Boy's + Girl's Toilet, Main Office Toilet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Fire Door	11	EA	3rd FL Gym, 2nd FL Balcony of Assembly Hall, 1st FL Assembly Hall		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Drywall System (Drywall, Tape, Compound)	5000	SF	3rd FL: Teacher's Lounge-Toilet, 305, 303 2nd FL: 206, Boy's + Girl's Toilet, Teacher's Toilet 1st FL: Main Office Toilet, 103-Toilet, 101-Toilet Basement: Kitchen Storage, Girl's + Boy's Toilet, Teacher Lunchroom, BE Office, 001-Toilet		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	Vinyl Baseboard Mastic	2000	SF	2nd FL - Boy's and Girl's Toilet 1st FL - Teacher Toilet Basement - Kitchen Storage, Lunchroom, Teacher's Lunchroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
57	Hard Coat Plaster (walls and ceiling)	10000	SF	Throughout Building		Surface	No	None			YES	X NO
2022 Fall Six	Month Survey: No Ch											
Comments:	,	<u> </u>]							
2023 Spring	Six Month Survey: No	Change										
Comments:	•]							
2023 Fall Six	Month Survey: No Ch	nange										
Comments:	•											
2024 Fall Six	Month Survey: No Ch	nange										
Comments:	•	<u> </u>										
2024 Spring	Six Month Survey: No	Change			\dashv							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12x12 Orange Floor Tile	20	SF	1st FL Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Comments:

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	
58M	12x12 Orange Floor Tile Mastic	20	SF	1st FL Corridor		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									
Comments:											

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
0004 0 : 0: M (I 0 N 0)
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Mag Block Breeching ABATED (2016)			Boiler Room ABATED (2016)		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Aircell Pipe Insulation	150	LF	Passage by Rm. 003, Tank Room, Lunchroom/Kitchen, Main Office		TSI	Yes	None	0		YES X NO
					1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Aircell Pipe Insulation	40	LF	Passage by Rm. 003, Tank Room, Lunchroom/Kitchen		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Mag Block Insulation	40	LF	Tank Room, Kitchen/Lunchroom, Engine Room, Boiler Room		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

H MJP E/F/V on Mag Block Insulation 5 LF Tank Room, Kitchen/Lunchroom, Engine Room, Boiler Room	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	Н	0	5	LF	Kitchen/Lunchroom, Engine Room, Boiler		TSI	Yes	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Cardboard Pipe Insulation ABATED (2013)			Passage by Room 003, Girls Play Room, Tank Room, Boiler Room Toilets - ABATED (2013)		TSI		None			YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
J	MJP E/F/V on Cardboard Pipe Insulation	7	LF	Passage by Room 003, Girls Play Room, Tank Room, Boiler Room Toilets		TSI	Yes	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	MJP E/F/V on Fiberglass Pipe Insulation	68	LF	Throughout (See Hatching)		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

L	Aircell Duct Insulation	1200	SF	Lunchroom/Kitchen		TSI	Yes	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:]							
2023 Fall Six Month Survey: No Change												
Comments:					 							
	Six Month Survey: No	Change										
Comments:					-							
	Six Month Survey: No	Change			1							
Comments:					-							
2024 Fall Six Month Survey: No Change												
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Type

Damage

Units

Damage

Quantity

0

None

Change in Assessment Category

2022 Fall	Six Month 9	Survey: No Ch	ange		
Comment		<u> </u>	idiigo		
2022 Fall	Civ Month	Survey: No Ch	ongo		
Comment		Survey. NO Cr	iariye		
2222	0: 11		01		
2023 Spri		th Survey: No	Change		
Comment	5.				
		th Survey: No	Change		
Comment	S:				
2024 Fall	Six Month S	Survey: No Ch	nange		
Comment	s:				
I					

1070

HA No

М

Material Description

Mag Block Duct Insulation

Material

Quantity

Material

Units

SF

Boiler Room

Material Location

YES

X NO

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Friedrich L. Jahn Elementary of the Fine Arts
Date: 12/19/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23921

SCHOOL'S ASBESTOS MANAGEMENT PLAN.