Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Ellen Mitchell Elementary School 24511 School: **Oracle Unit: Building ID:** 4840 2233 W. Ohio Street Address: Region: 02 Mail Room: Asbestos Surveyor: Daly, Ryan **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 11/11/2024 Email Address: rdaly1@cps.k12.il.us A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other Posted to the CPS W Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Category Quantity Units Type Type X YES 02 NO Hard Coat Plaster Throughout - 1891 Bldg. 2022 Fall Six Month Survey: Deteriorated Comments:2 spots in the basment (ceiling) ive already created a EPA ticket for testing 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12" x 12" Brown w/Black & White Speckles Floor Tile	4500	SF	Lunchroom, Main Office (Not Observed), Rooms 206, 303, 306, 307 and 106 have carpet per engineer's Fall '11 survey. Rooms 308, 106 NOT OBSERVED - 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 24511

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
06A	12" x 12" Tan VFT	200	SF	Room 104A		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange										
2023 Spring S Comments:	Six Month Survey: No	Change										
	Manth Common No Ch											

2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

2024 Spring Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06B	12" x 12" Tan VFT Mastic	200	SF	Room 104A		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12" x 12" Brown w/Black & White Speckles Floor Tile Mastic	4500	SF	Lunchroom, Main Office (not observed), Rooms 206, 303, 306, 307 and 106 have carpet per engineer's Fall '11 survey. Rooms 308, 106 NOT OBSERVED - 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
08	Linoleum	500	SF	Gymnasium Stage - 1970 Bldg.		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Damaged
Comments:will be feathering over chipped areas when i receive the
compound
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:repaired w feathering concrete mix
2024 Fall Six Month Survey: Repaired
Comments:cracking/chipped areas filled in with concrete leveler

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Linoleum Mastic	500	SF	Gymnasium Stage - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
10	9" x 9" Black Floor Tile (Abated)			1891 Bldg: Under Carpet in Room 106 (Library)		Miscellaneous					YES	X NO
	x Month Survey: No Ch	nange										
Comments:												
2023 Fall Si	x Month Survey: No Ch	nange			_							
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:	,											
2024 Fall Si	x Month Survey: No Ch	nange										
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9" x 9" Black Floor Tile Mastic (Abated)			Under Carpet in Room 106 (Library) - 1891 Bldg.		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Blue Floor Tile	1500	SF	Kitchen, Room 101 Wardrobe & toilet. 101 & 304 encapsulated Aug. 2011 - 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:area near sink was dug up for plumbing issue, repaired by
nyself using same tile found in my shop
2024 Fall Six Month Survey: Repaired
Comments:section was removed to dig and fix a open drain. filled back and
new tile put down
•

Oracle Unit: 24511

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	12"x12" Blue Floor Tile Mastic	1500	SF	Kitchen, Rooms 101 wardrobe and toilet room & 304 - 1891 Bldg.		Miscellaneous	No	None	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Civ Month Company Denoised
2024 Fall Six Month Survey: Repaired
Comments:section was removed to dig and fix a open drain. filled back and
new tile/mastic put down

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" White Floor Tile	800	SF	Room 101 and Teacher's Toilet by Room 103 - 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" White Floor Tile Mastic	800	SF	Room 101 and Teacher's Toilet by Room 103 - 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Beige Floor Tile	800	SF	Principal's Office and Main Office - 1891 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
17	12"x12" Beige Floor Tile Mastic	800	SF	Principal's Office and Main Office- 1891 Bldg.		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0004.0 : 0: 14 .4 .0 14 .01
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Orange Floor Tile - (ABATED)			Boy's Lunchroom - 1891 Bldg.		Miscellaneous		None			YES X NO

Page 10

		Quantity	Units		Type	Category	Type	Quantity	Units		
19	12"x12" Orange Floor Tile Mastic- (ABATED)			Boy's Lunchroom - 1891 Bldg.		Miscellaneous				YES	X NO
0000 F II O'	M (1.0 N 0)				1						
2022 Fall Six	Month Survey: No Ch	ange									
Comments:											
2023 Fall Six	Month Survey: No Ch	ange									
Comments:	-										
2023 Spring	Six Month Survey: No	Change									
Comments:	•]						
2024 Spring	Six Month Survey: No	Change									
Comments:		-									
	·										
2024 Fall Six	Month Survey: No Ch	ange									
Comments:		·		-							

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Green Floor Tile - (ABATED)			Boy's Lunchroom- 1891 Bldg.		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Green Floor Tile Mastic - (ABATED)			Boy's Lunchroom - 1891 Bldg.		Miscellaneous					YES X NO
0000 F.II O'	Marth Oran Na Ol				1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Brown Floor Tile	750	SF	Gym East Hallway, Gym Office - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Abated
Comments:was abated in early 2022
2023 Spring Six Month Survey: Abated
Comments:removed in 21/22
2024 Spring Six Month Survey: Abated
Comments:in 2022
2024 Fall Six Month Survey: Abated
Comments:removed and replaced with new tile
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9"x9" Brown Floor Tile Mastic	750	SF	Gym East Hallway, Gym Office - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Abated
Comments:was abated in early 2022
·
2023 Spring Six Month Survey: Abated
Comments:removed in 21/22
2024 Spring Six Month Survey: Abated
Comments:in 2022
2024 Fall Six Month Survey: Abated
Comments:removed and replaced with new mastic

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9"x9" White Floor Tile	750	SF	Gym East Hallway, Gym Office - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

25	9"x9" White Floor Tile Mastic	750	SF	Gym East Hallway, Gym Office - 1970 Bldg.	Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange								
Comments:	Month Sarvey. No On	ungo								
2023 Fall Six	Month Survey: No Cha	ange								
Comments:	-									
2023 Spring 9	Six Month Survey: No	Change								
Comments:										
	Six Month Survey: No	Change								
Comments:										
	Month Survey: No Cha	ange								
Comments:										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Textured Plaster	1500	SF	Room 302. Ceilings in 103, 201, 202, 203, 204, 205, 207, 208 - 1891 Bldg.		Surface	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	2'x4' Ceiling Tile			Gymnasium Hallway - 1891 Bldg., Main office, 106 and closet, 105, 308 and wardrobe, 307 and wardrobe, 305, 306, corridor, 106 and closet, 105							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Beige w/Light Specks Floor Tile	1200	SF	Room 308		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28 A	12" x 12" Beige w/Light Specks Floor Tile Mastic	1200	SF	Room 308		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" x 12" Green w/Green Specks Floor Tile	100	SF	Room 106 Closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29 A	12" x 12" Green w/Green Specks Floor Tile Mastic	100	SF	Room 106 Closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments:
2023 Spring Six Month Survey: No Change Comments:
Comments:
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
30	12" x 12" Red Floor Tile (ABATED 2012)			Boy's Lunch Room-1891 Building		Miscellaneous	None			YES	X NO
2022 Fall Siv	Month Survey: No Ch	ange]						
Comments:	World Survey. No On	arige			1						
Commenter					1						
2023 Fall Six	Month Survey: No Ch	ange									
Comments:	•	•									
2023 Spring	Six Month Survey: No	Change									
Comments:	,										
2024 Fall Six	Month Survey: No Ch	ange			1						
Comments:	•				-						
2024 Spring	Six Month Survey: No	Change			_						
Comments:	•				1						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30 A	12" x 12" Red Floor Tile Mastic (ABATED 2012)			Boy's Lunch Room - 1891 Building		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Gold Carpet Mastic	150	SF	Room 101 - 1891 Building		Miscellaneous	No	None	0		YES X NO
0000 F II O	NA 41 0 NI 01				1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:doesnt exist
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Light Blue with Blue Streaks Vinyl Floor Tile	1000	SF	Boy Lunchroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Page 19

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32A	12" x 12" Light Blue with Blue Streaks Vinyl Floor Tile Mastic	10	SF	Boys Lunchroom		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change						•	•		•		•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	2' x 2' White w/ Pinholes Ceiling Tile	5000	SF	3rd Floor Corridor, Rooms 301, 302, 303, 304, 305, 306, 307, 308, (Including Wardrobe Closets)		Miscellaneous	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	MJP E/F/V on Aircell Pipe Insulation	286	FITTING	Basement Throughout, Hallways, Girl's Lunchroom - 1891 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Aircell Pipe Insulation	2813	LF	Basement Throughout, Hallways, Girl's Lunchroom - 1891 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:small section was abated due to pipe leak on steam line, and
others repaired due to cracking all in basement
2024 Fall Six Month Survey: Abated
Comments:partial section of piping was abated to fix a steam leak

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
С	Aircell Duct Insulation	800	SF	Basement Corridor and Boiler Room - 1891 Bldg.		TSI	Yes	None	0		YES X NO
2022 Fall Six	Month Survey: No Ch]									
Comments:	•	•									
2023 Fall Six	Month Survey: No Ch	ange									
Comments:					1						
2023 Spring S	Six Month Survey: No	Change			_						
Comments:											
2024 Fall Six	Month Survey: No Ch	ange			_						
Comments:					-						
2024 Spring S	Six Month Survey: No	Change			_						
Comments:					-						
					1						

HA No	Mater	rial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Paper	rwrap Pipe Insulation	400	LF	Boiler Room, Art Room & Hot Deck - 1891 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Е	MJP E/F/V on Paperwrap Pipe Insulation	150	EA	Basement: Boiler Room - 1891 Bldg.		TSI	Yes	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Pre-Formed Pipe Insulation	250	LF	Basement: Boiler Room - 1891 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
G	MJP E/F/V on Pre-Formed Pipe Insulation	75	FITTING	Basement: Boiler Room - 1891 Bldg.		TSI	Yes	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch											
2023 Fall Six Comments:	Month Survey: No Ch	ange										
	Six Month Survey: No	Change			-							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change			-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Paper Board			Boiler Room, Basement Corridor - 1891 Bldg.							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	MJP E/F/V on Fiberglass Pipe Insulation	100	LF	Room 307, boiler room, basement corridors, hot deck - 1891 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Green Carpet MASTIC	750	SF	106 Library		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ellen Mitchell Elementary School
Date: 8/1/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. Posted to the CPS Website
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.