Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

24781 Brian Piccolo Elementary Specialty School 5210 School: **Oracle Unit: Building ID:** Address: 1040 N. Keeler Avenue Region: 02 Mail Room: Asbestos Surveyor: Hernandez, Jimmie X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/18/2024 Email Address: jhernandez896@cps. A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other Material Description HA No Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Quantity Units Type Sprayon insulation above above ceiling tiles in X NO 1 SF YES 4000 Surface No None ceiling tiles Addition 1965 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

Oracle Unit: 24781

											II.
2022 Fall Six	Month Survey: No Ch	nange									
Comments:	•										
2023 Fall Six	2023 Fall Six Month Survey: No Change										
Comments:											
2024 Spring Six Month Survey: No Change											
Comments:											
	Month Survey: No Ch	nange									
Comments:											
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

80

Material

Units

SF

SF

Material

Quantity

80

Material Location

Room 110 Toilet

Room 110 Toilet

HA No

2

2A

Material Description

Tile & Mastic

12"x12" Blue Specks Floor

12" x12" Blue Specks Floor

Tile & Mastic

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

2022 Fall S	Six Month Survey: No C	hange									
Comments		U									
2023 Fall S	Six Month Survey: No C	hange									
Comments):										
2024 Fall S	Six Month Survey: No C	hange									
Comments	:										
2024 Sprin	ng Six Month Survey: No	Change									
Comments	S:										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Material

TSI

Category

Friable

No

Damage

Type

None

Damage

Quantity

Damage

Units

Material Location

Room 203 and 205

117	A NO	Material Description	Quantity	Units	Waterial Location	Type	Category	Filable	Type	Quantity	Units	Change in Asses	Smem Category
3/	4	12" x 12" Beige specks floor tile & mastic	1200		Room 203 and 205		Miscellaneous	No		0		YES	X NO
20	00 Fall Civ	Manth Coman Ala Cha				1							
20	122 Fall Six	Month Survey: No Cha	ange										
Co	omments:												
						1							
2023 Fall Six Month Survey: No Change													
20	2020 Fall Cix Month Carvey. No Onlinge												

Comments:

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change
Comments:

HA No

3

Material Description

12" x 12" Beige specks

floor tile & mastic

Material

Quantity

Material

Units

Change in Assessment Category

X NO

MJP on Aircell Pipe Insulation 15 LF Ist, 2nd, & 3rd Floor Janitor Closets, 2nd Floor Boys & Girls Tollets, Crawl Under Auditorium - 1918	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	015	•	15	LF	Janitor Closets, 2nd Floor Boys & Girls Toliets, Crawl Under Auditorium -		TSI	Yes	Loc	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
030	Sink Undercoat (Black)	20	SF	Rooms 214, 314 & 229,1918 Building 225 and 227 Lab - 1965 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

2022 Fall Si	x Month Survey: No C	hange									
Comments:		J									
2023 Fall Si	x Month Survey: No C	hange									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Si	x Month Survey: No C	hange									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

HA No

031

032

Material Description

Gray Coating on Sink Basin 4

Gray Coating on Sink Basin

Material

Units

SF

SF

Material

Quantity

Material Location

Kitchen - 1965 Building

125 - 1965 Bldg.

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
036	MJP on Fiberglass Pipe Insulation	105	LF	N&S Unexcavated Areas, Kitchen, Base Kitchen Store, Locker Room, Shower Room, Base Stairwell - 1965		TSI	Yes	None	0		YES	X NO
					_							

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
050	MJP on Fiberglass Pipe Insulation	193	LF	1st, 2nd, & 3rd Floor Boys & Girls Toliet Chases, 201, 202, 203, 204, 205, 206, 101, 102 - 1918 Bldg. Removed 2 ft and 5 ft in Rooms 101 and 202, respectively.		TSI	Yes	Loc	7		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 6

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
051	MJP on Cardboard Pipe Insulation	700	LF	1st, 2nd, & 3rd Floor JC's, Auditorium Toliet, Crawl Under Auditorium, Attic - 1918 Bldg.		TSI	Yes	None	0		YES	X NO
2022 Fall Si	2022 Fall Six Month Survey: No Change											
Comments:	Comments:											
2023 Fall Six Month Survey: No Change												

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Material

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
052	Air Cell Pipe Insulation	800	LF	1st, 2nd, & 3rd Floor N&S JC's, 2nd Floor Boys & Girls Toliets, Crawl Under Auditorium - 1918 Bldg.		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

O54 Cardboard Pipe Insulation 600 LF 1st, 2nd, & 3rd Floor JC's, Auditorium Toliet, Crawl Under Auditorium, Attic - 1918 Bldg.		HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	(054	Cardboard Pipe Insulation	600	LF	JC's, Auditorium Toliet, Crawl Under Auditorium,		TSI	Yes	None	0		

2022 Fall Six Month Survey: No Change
Comments:
0000 Fall Civ. Manth. Common No. Observe
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
055	Mortar	500	SF	Air Tunnel, Attic, Washrooms - 1918 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

	II.										
061	12"x12" Dark Brown VFT	950	SF	Room 208 ABATED - 1918 Bldg. 1st Floor Reading Room and Main Office remains.		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]						
Comments:	•										
2023 Fall Six	Month Survey: No Ch	ange			-						
Comments:											
2024 Spring S	Six Month Survey: No	Change									
Comments:					<u> </u>						
2024 Fall Six	Month Survey: No Ch	ange]						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
062	12"x12" Dark Brown VFT Mastic	950	SF	Room 208 ABATED - 1918 Bldg. 1st Floor Reading Room and Main Office remains.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

063	9"x9" Green VFT	1500	SF	1st Floor Store Room - 1918 Bldg.	Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Cl	nange								
Comments:										
	Month Survey: No Cl	nange								
Comments:										
2024 Fall Six	Month Survey: No Cl	nange								
Comments:										
	Six Month Survey: No	Change								
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
064	9"x9" Green VFT Mastic	1500	SF	1st Floor Store Room - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
065	12"x12" Pink VFT	60000	SF	Throughout - 1965 Bldg.		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
066	12"x12" Pink VFT Mastic	60000	SF	Throughout - 1965 Bldg.		Miscellaneous	No	None	0		X YES NO	

2022 Fall Six Month Survey: Abated
Comments:2nd fl. girls washroom,4 tiles were removed by Environmental
co. replaced with new VCT tile
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	67	9"x9" Green & 9"x9" Beige/Brown Checker Board Patterned Floor Tile	0	SF	1st Floor Lunchroom - 1965 Bldg. 2500 SF removed in 2012.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
068	9"x9" Green & 9"x9" Beige/Brown Checker Board Patterned Floor Tile Mastic	0	SF	1st Floor Lunchroom - 1965 Bldg. 2500 SF removed in 2012.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

	1										
2022 Fall Six	Month Survey: No Ch	ange]						
Comments:					1						
2023 Fall Six	Month Survey: No Ch	ange									
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									
Comments:											
2024 Spring S	Six Month Survey: No	Change			-						
Comments:					1						
					1						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

63000

HA No

069

070

Material Description

12"x12" Blue VFT Mastic

12"x12" Blue VFT

Material

Units

SF

SF

Material Location

Throughout - 1965 Bldg.

Throughout - 1965 Bldg.

Material

Quantity

63000

Change in Assessment Category

X NO

X NO

YES

071	2'x4' White Ceiling Tile	120000	SF	Throughout - 1965 Bldg.		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:	,	.										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:	,	.										
2024 Fall Six	Month Survey: No Ch	ange			1							
Comments:	•											
2024 Spring	Six Month Survey: No	Change			1							
Comments:	•											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Yes

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

2022 Fall Six Month Survey: No Change		
Comments:		
2023 Fall Six Month Survey: No Change		
Comments:		
2024 Spring Six Month Survey: No Change		
Comments:		
2024 Fall Six Month Survey: No Change		
Comments:		

5000

Material

Quantity

Material

Units

SF

Material Location

Throughout Hallways - 1918 Bldg.

HA No

072

Material Description

2'x4' White Ceiling Tile

YES

X NO

073	Hard Coat Plaster	100000	SF	Throughout 1918	Surface	Yes	None	0	YES	X NO
2022 Fall S	ix Month Survey: No	Change								
Oominichts.										
	ix Month Survey: No	Change								
Comments:										
2024 Spring	g Six Month Survey: I	No Change								
Comments:										
2024 Fall S	ix Month Survey: No	Change								
Comments:										

Type

Material

Category

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
074	12"x12" White Ceiling Tile	2000	SF	Upper Library, 2000 SF (1918 Bldg.) Removed/replaced but NOT ABATED. Classrooms throughout school were replaced with drop 2' X 4' ceiling tiles EXCEPT Upper Library and Student Dining Area.		Surface	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
075	12"x12" White VFT - NOT OBSERVED	2500	SF	1st Floor Store Room, Main Office, Reading Room (#208) - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
076	12"x12" White VFT Mastic - NOT OBSERVED	2500	SF	1st Floor Store Room, Main Office, Reading Room (208) - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

077	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	077		1500	SF	(principals's office), Offices #5, #6, #9, #10 & #11, Assistant Principal's		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
078	12"x12" White w/ Brown Streaks VFT Mastic	1500	SF	1st FI: Rm 109, Offices #5, #6, #9, #10 & #11, Assistant Principal's Office Area - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
079	12"x12" Brown w/ White & Black Streaks VFT	630	SF	(Room #204 - Closet Only) & Room #102 (NOT OBSERVED) -1918 Bldg.		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:												
2022 Fall Six	Month Survoy: No Ch	0000										

Material

Friable

Damage

Damage

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Material Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
080	12"x12" Brown w/ White & Black Streaks VFT Mastic	630	SF	Closet Only (Room 204) and room #102 (NOT OBSERVED) - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
081	12"x12" Beige w/ Brown Streaks VFT	1600	SF	Rooms 101, 103, 111 - 1918 Bldg. (A total of 1400 SF of tile/mastic were removed from Rooms 112 and 210 in 2012.)		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:]							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					 							
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
082	12"x12" Beige w/ Brown Streaks VFT Mastic	1600	SF	Rooms 101, 103, 111 - 1918 Bldg. (A total of 1400 SF of tile/mastic were removed from Rooms 112 and 210 in 2012.)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

083	12"x12" Brown Grain VFT	750	SF	Room 209 - 1918 Bldg.		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]						
Comments:		<u> </u>]						
2023 Fall Six	Month Survey: No Ch	ange									
Comments:					 						
	Six Month Survey: No	Change									
Comments:					1						
2024 Fall Six	Month Survey: No Ch	ange									
Comments:					-						
L					1						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
084	12"x12" Brown Grain VFT Mastic	750	SF	Room 209 - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

085	12"x12" Light Brown VFT	1500	SF	Rooms 204 (NOT OBSERVED), 304 & 305 - 1918 Bldg		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		<u> </u>]						
Comments:	,]						
2023 Fall Six	Month Survey: No Ch	ange			}						
Comments:											
	Six Month Survey: No	Change									
Comments:					1						
	Month Survey: No Ch	ange									
Comments:					-						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Rooms 204 (NOT

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
086	12"x12" Light Brown VFT Mastic	1500	SF	Rooms 204 (NOT OBSERVED), 304 & 305 - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

087	9"x9" White VFT (NOT OBSERVED)	0	SF	Room 314 - 1918 Bldg.		Miscellaneous					YES	X NO
2022 Fall	Civ Month Cumrous No C	hanga			7							
	Six Month Survey: No C	nange										
Comment	S:											
2023 Fall	Six Month Survey: No C	hange										
Comment	Comments:											
2024 Spri	ng Six Month Survey: No	o Change										
Comment	s:											
2024 Fall	Six Month Survey: No C	hange			-							
Comment	·	nango			+							
Comment	3.				+							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	· ·	Quantity	Units		Type	Category		Туре	Quantity	Units		0,
000	9"x9" White VFT Mastic		0.5	B 044 4040 BH								

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

0

HA No

880

Material Description

9"x9" White VFT (NOT

(NOT OBSERVED)

Material

Quantity

Material

Units

SF

Material Location

Room 314 - 1918 Blda.

YES

X NO

089	12"x12" Off White VFT	1500	SF	Rooms 304 & 305 - 1918 Bldg.	Miscellaneous	None	0	YES	X NO
2022 Fall Six	x Month Survey: No C	hange							
2023 Fall Six Comments:	x Month Survey: No C	hange							
2024 Spring Comments:	Six Month Survey: No	Change							
2024 Fall Six Comments:	x Month Survey: No C	hange							

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
090	12"x12" Off White VFT Mastic	1500	SF	Rooms 304 & 305 - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
091	12"x12" Off White w/ Beige Streaks VFT	2100	SF	Rooms 301, 303, 308, 309 - 1918 Bldg. (500 SF removed from Rm 202 in 2012.)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
092	12"x12" Off White w/ Beige Streaks VFT Mastic	2100	SF	Rooms 301, 303, 308, 309 - 1918 Bldg. (500 SF removed from Rm 202 in 2012)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

093	12"x12" White w/ Yellow Streaks VFT	800	SF	1st Floor Dean's Office - 1918 Bldg.		Miscellaneous	No	None	0		YES	X NO
2022 Fall	Six Month Survey: No Cl	hange			7							
Comments		larigo										
2023 Fall	Six Month Survey: No Cl	hange			_							
Comments	•	idiigo										
2024 Sprii	ng Six Month Survey: No	Change			_							
Comments	S:]							
2024 Fall	Six Month Survey: No Cl	hange										
Comments	S:											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

None

No

Damage

Quantity

Quantity

0

Damage

Units

Units

094	OBSERVED)	1000	5	1918 Bldg.
2022 Fall Six	Month Survey: No Ch	ange		
Comments:				
2023 Fall Six	Month Survey: No Ch	ange		
Comments:				
2024 Spring S	Six Month Survey: No	Change		
Comments:				
2024 Fall Six	Month Survey: No Ch	ange		
Comments:				

Quantity

1800

Units

SF

Material

Quantity

Material

Units

Material Location

1st Floor Dean's Office -

1918 Bldg.

HA No

094

Material Description

12"x12" White w/ Yellow

Streaks VFT Mastic (NOT

Change in Assessment Category

X NO

2022 Fall S	ix Month Survey: No C	hange									
Comments:											
2023 Fall S	ix Month Survey: No C	hange									
Comments:											
2024 Spring Six Month Survey: No Change											
Comments:											
2024 Fall S	ix Month Survey: No C	hange									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

900

Material

Quantity

900

Material

Units

SF

SF

Material Location

Room 310 - 1918 Bldg.

Room 310 - 1918 Bldg.

HA No

095

096

Material Description

12"x12" Peach VFT

12"x12" Peach VFT Mastic

Change in Assessment Category

X NO

X NO

YES

097	Streaks VFT (NOT OBSERVED)	0	SF	1918 Bldg.		Miscellaneous					YES	X NO
2022 Fall Six	x Month Survey: No C	hange			7							
Comments:	KINOHAI GAIVOY. IVO G	nango										
2023 Fall Six	x Month Survey: No C	hange										
Comments:	K Month Garvey. No G	nango										
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	x Month Survey: No C	hange										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

030	OBSERVED)	Ŭ	O.	1918 Bldg.
2022 Fall Six	Month Survey: No Ch	ange		
Comments:				
2023 Fall Six	Month Survey: No Ch	ange		
Comments:				
2024 Spring S	Six Month Survey: No	Change		
Comments:				
2024 Fall Six	Month Survey: No Ch	ange		
Comments:				

0

HA No

097

098

Material Description

9"x9" White w/ Black Streaks VFT (NOT

9"x9" White w/ Black

Streaks VFT Mastic (NOT

Material

Quantity

0

Material

Units

SF

SF

Material Location

Room 205 Wardrobe-

Room 205 Wardrobe -

1918 Bldg.

Change in Assessment Category

X NO

X NO

YES

099	Gray Fireproofing	60000	SF	Throughout - 1965 Bldg.		Surface		None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:	,	<u> </u>]							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:					 							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

100	9"x9" Spotted Brown VFT (Under New VFT)	1310	SF	Rooms 110, 1st floor storage - 1918 Bldg			
2022 Fall Six	Month Survey: No Cha	ange					
Comments:							
2023 Fall Six	Month Survey: No Cha	ange					
Comments:							
2024 Spring	Six Month Survey: No	Change					
Comments:							
2024 Fall Six Month Survey: No Change							
Comments:			•				
_	-						

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Change in Assessment Category

X NO

101	9"x9" Spotted Brown VFT Mastic (Under New VFT)	1310	SF	Rooms 110, 1st floor storage - 1918 Bldg		Miscellaneous	No	None	0		YES	X NO
2022 Fall	Six Month Survey: No Cl	2022			7							
		larige										
Comment	S:											
2023 Fall	Six Month Survey: No Cl	nange										
Comment												
Commone	· · · · · · · · · · · · · · · · · · ·				_							
2024 Spri	ng Six Month Survey: No	Change										
	•	Change			_							
Comment	S:											
2024 Fall	Six Month Survey: No Cl	nange										
Comment	s:											
					_							
	T	T		Tarana and a	1	T			т_		T	
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
				1st Floor Store Room and								

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

759

HA No

102

Material Description

9"x9" Beige VFT

Material

Units

SF

Material

Quantity

Material Location

303 MDF Closet, 3rd

Floor Janitors Closet -1918 Bldg.

Change in Assessment Category

X NO

YES

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	9"x9" Beige VFT Mastic	759	SF	1st Floor Store Room and 303 MDF Closet, 3rd Floor Janitors Closet - 1918 Bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	12"x12" Beige VFT	750	SF	Room 102; Storage (Room 104) - 1918 Bldg		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

105	12"x12" Beige VFT Mastic	750	SF	Room 102; Storage (Room 104) - 1918 Bldg		Miscellaneous	No	None	0		YES	X NO
2022 Fall	Six Month Survey: No Ch	nange			1							
Comments		larige			-							
Comments	o.				-							
2023 Fall	Six Month Survey: No Ch	nange										
Comments	S:											
2024 Sprir	ng Six Month Survey: No	Change			_							
Comments	<u> </u>											
2024 Fall :	Six Month Survey: No Ch	nange			_							
Comments	·	<u> </u>										
	_	_	_	1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
400	9"x9" Tan VFT -			Lunchroom - 1965 bldg.		N.C. II						V NO

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

(3000 SF removed in

2012)

Material

Units

Material

Quantity

HA No

106

Material Description

(REMOVED 2012)

Change in Assessment Category

X NO

107	9"x9" Tan VFT Mastic (REMOVED 2012)	Lunchroom - 1965 bldg. (3000 SF removed in 2012)	Miscellaneous			YES	X NO
2022 Fall Six	Month Survey: No Change]				
Comments:							
	Month Survey: No Change						
Comments:							
2024 Spring	Six Month Survey: No Char	nge					
Comments:							
2024 Fall Six	Month Survey: No Change						
Comments:							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
108	Terrazo	3000	SF	1st fl corridor and stair, landings - 1918 Bldg.		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange	<u> </u>									
0000 E-II 0:	Martin Orania Na Ob											

2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

Material

Quantity

Material

Units

Material Location

Lunchroom - 1965 bldg.

2024 Spring Six Month Survey: No Change

Material Description

Comments:

HA No

109	Brown Carpet Adhesive	1600	SF	Room 306/3071918 Building:		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	nange]						
Comments:	•	<u> </u>									
	Month Survey: No Ch	ange									
Comments:											
	Month Survey: No Ch	nange									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
					J						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Adobe Mosaic Ceramic Tile Grout	2300	SF	1918 Building: 1st, 2nd & 3rd Floor Girl's & Boy's Washrooms		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

111	Adobe Masaic Ceramic Tile Adhesive	2300	SF	1918 Building: 1st, 2nd & 3rd Floor Girl's & Boy's Washrooms	Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	·								
Comments:										
2023 Fall Six	Month Survey: No Ch	ange								
Comments:										
2024 Fall Six	Month Survey: No Ch	ange								
Comments:										
2024 Spring	Six Month Survey: No	Change								

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12"x12" Sand Colored Floor Tile	1090	SF	1918 Building: Room 205		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

113	12"x12" Sand Colored Floor Tile Adhesive	1090	SF	1918 Building: Room 205		Miscellaneous	No	None	0		YES	X NO
2022 Fall S	ix Month Survey: No Ch	ange]							
Comments:					- -							
2023 Fall S	ix Month Survey: No Ch	ange										
Comments:												
2024 Spring	g Six Month Survey: No	Change										
Comments:					=							
2024 Fall S	ix Month Survey: No Ch	ange										
Comments:					=							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

2022 Fall Six N	Month Survey: No Cha	ange		
Comments:				
2023 Fall Six N	Month Survey: No Cha	ange		
Comments:				
2024 Fall Six N	Month Survey: No Cha	ange		
Comments:				
2024 Spring S	ix Month Survey: No (Change		
Comments:			•	

930

Material

Quantity

Material

Units

SF

Material Location

1918 Building: Room 202

HA No

114

Material Description

12"x12" Gray Floor Tile

Change in Assessment Category

X NO

115	12"x12" Gray Floor Tile Adhesive	930	SF	1918 Building: Room 202		Miscellaneous	No	None	0	YES	X NO
2022 Fall Civ	Manth Cuman No Cl				Ī						
2022 Fall 51)	Month Survey: No Cl	nange									
Comments:											
2023 Fall Six	Month Survey: No Cl	nange									
Comments:											
2024 Fall Six	Month Survey: No Cl	nange									
Comments:	•										
2024 Spring	Six Month Survey: No	Change									
Comments:	•										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	12"x12" White w/Multi- Specks Floor Tile	1000	SF	1918 Building: Room 110		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

2022 Fall Si	x Month Survey: No C	hande									
Comments:	x Month Sarvey. No O	nange									
2023 Fall Si	x Month Survey: No C	hange									
Comments:											
2024 Spring Six Month Survey: No Change											
Comments:											
2024 Fall Six Month Survey: No Change											
Comments:	•										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

500

HA No

117

118

Comments:

Material Description

12"x12" White w/Multi-

12"x12" Blue Floor Tile

2022 Fall Six Month Survey: No Change

Specks Floor Tile Adhesive

Material

Units

SF

SF

Material

Quantity

1000

Material Location

1918 Building: Room 110

1918 Building: Room 110

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

119	12"x12" Blue Floor Tile Adhesive	500	SF	1918 Building: Room 110		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Cl	hange										
Comments:	Civional Carvey. 140 Of	lange										
2023 Fall Six	Month Survey: No Cl	hange										
Comments:												
2024 Spring	Six Month Survey: No	Change			_							
Comments:												
2024 Fall Six	Month Survey: No Cl	hange			_							
Comments:												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	smont Catagory
I I/A INO	Material Description	ivialellal	iviatellal	material Location	V20G2I02	iviaterial	i nable	Damaye	Damaye	Damaye	Change III Assess	sineni Calegory

Type

Material

Category

Category

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

Change in Assessment Category

X NO

120	Blue Carpet Adhesive	2000	SF	1918 Building: Assembly Hall NOT OBSERVED. Removed/covered in 2012 with 24" X 24" gray slip-free rubber flooring.		Miscellaneous	No	None	0	YES
2022 Fall S	ix Month Survey: No Ch	nange]					
	Comments:									
2023 Fall S	ix Month Survey: No Ch	nange								
Comments:										
					4					

Type

HA No

Material Description

Material

Units

Material

Quantity

Quantity

Units

Material Location

121	Red Terrazzo	2850	SF	1965 Addition: 2nd & 3rd Floor Stairways		Miscellaneous	No	None	0		YES	X NO
2022 Fall S	ix Month Survey: No C	hange			1							
Comments:												
2023 Fall S	ix Month Survey: No C	hange										
Comments:												
2024 Fall S	ix Month Survey: No C	hange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

122	Mosaic Ceramic Tile Grout	4170	SF	3rd Floor Giorl's & Boy's Washrooms
2022 Fall Six	Month Cumini No Ch	0000		
_	Month Survey: No Ch	ange		
Comments:				
2023 Fall Six	Month Survey: No Ch	ange		
Comments:				
2024 Spring S	Six Month Survey: No	Change		
Comments:				
2024 Fall Six	Month Survey: No Ch	ange		
Comments:				

HA No

Material Description

Material

Quantity

Material

Units

Material Location

1965 Addition: 1st, 2nd &

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
123	Mosaic Ceramic Tile Adhesive	4170	SF	1965 Addition: 1st, 2nd & 3rd Floor Giorl's & Boy's Washrooms		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]	•		•	•	•	•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	12"x12" White Floor Tile w/Tan Specks	1400	SF	1965 Addition: Room 129 & 122		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

		1									
125	12"x12" White Floor Tile w/Tan Specks Adhesuve	1400	SF	1965 Addition: Room 129 & 122		Miscellaneous	No	None	0	YES	X NO
					1						
2022 Fall Six	Month Survey: No Cha										
Comments:	-										
2023 Fall Six	Month Survey: No Cha	ange									
	Month Garvey. 140 On	arige									
Comments:											
2024 Fall Six	Month Survey: No Cha	ange									
Comments:		3 -									
Comments.											
2024 Spring Six Month Survey: No Change											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	12"x12" White Fissured Ceiling Tile	4500	SF	1965 Addition: Lunchroom		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

Page 41

127	12"x12" White Fissured Ceiling Tile Adhesive	4500	SF	1965 Addition: Lunchroom		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall S	Six Month Survey: No Ch	nange										
Comments		larigo										
2023 Fall S	Six Month Survey: No Ch	nange			_							
Comments	:				_							
2024 Sprin	g Six Month Survey: No	Change										
Comments):											
2024 Fall S	Six Month Survey: No Ch	nange										
Comments): :											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Type

Damage

Quantity

Damage

Units

128	12" X 12" tan with white streaks, VFT	1960	SF	Vauit Main Office (60 SF); Main Office Reception Area (1200 SF); Rm 104 (700 SF). All in 1918 Bldg.
2022 Fall	Six Month Survey: No Ch	2222		
		lariye		
Comments	S:			
2023 Fall	Six Month Survey: No Ch	nange		
Comments	S:			
2024 Sprii	ng Six Month Survey: No	Change		
Comments	s:			
2024 Fall	Six Month Survey: No Ch	nange		
Comments	S:			

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Vault Main Office (60

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
129	12" X 12" tan with white streaks, Mastic	1960	SF	Vault Main Office (60 SF); Main Office Reception Area (1200 SF); Rm 104 (700 SF). All in 1918 Bldg.		Miscellaneous	No	None	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
130	Transite hood	20	SF	Rm 305 Lab Work Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

131	Transite sink & counterop	215	SF	Lab Work Rooms in 303, 305, 306; Biology Lab in Rm 301.		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange	<u> </u>	•]						
Comments:	•				1						
2023 Fall Six	Month Survey: No Ch	ange			=						
Comments:											
2024 Spring	Six Month Survey: No	Change			=						
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
132	12x12 Beige w/ Streaks VFT - 1965 Bldg	9000	SF	Rooms 124, 126, 213, 214, 215, 218, 222, 224, Lunchroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Page 44

133	12x12 Beige w/Streaks VFT Mastic - 1965 Bldg	9000	SF	Rooms 124, 126, 213, 214, 215, 218, 222, 224, Lunchroom		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Cha	ange	•	•]	•	•	•	•	-	•	
Comments:	•	•										
2023 Fall Six	Month Survey: No Cha	ange			<u> </u>							
Comments:		J-										
2024 Fall Six	Month Survey: No Cha	ange										
Comments:	,											
2024 Spring S	Six Month Survey: No	Change										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
134	Carpet Mastic	600	SF	Room 228-1965 add		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Brian Piccolo Elementary Specialty School
Date: 12/23/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 24781

SCHOOL'S ASBESTOS MANAGEMENT PLAN.