Chicago Public Schools

6 Month Asbestos Surveillance

2024 Fall Six Month Survey

	School: Address:	Irma C Ruiz Elementary School 2410 S.Leavitt		Oracle Unit: Region:	24931 03	Building ID: Mail Room:	5390 37
X CHECK H	IERE IF I	NO CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date: Email Address:	Bobek, Taylor 10/18/2024 trbobek@cps.k12.il.us			
			2	1000000@003.012.11.03			

	A copy of the2022/20	23 notice to p	parents and	d staff regarding the asb	estos manag	jement plan not	ifications w	vas distribute	ed via:			
	Each child's backp	back	X Notice	printed in school's news	sletter	Notice prin	nted in sch	ool's calenda	ar Oi	ther		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
1	12" x 12"White w/Gray Floor Tile	14000	SF	Classrooms 203, 208, 209 213,301-314 and 316		Miscellaneous	No	None	0	SF	YES	XNO
2022 Fall S	Six Month Survey: No C	hange]							
Comments	3:											
2023 Fall S	Six Month Survey: Othe	r										
Comments	S:VCT located undernea	ith unit vent										
replaced wi	hen new unit ventilators	were insta	lled Sur	nmer of 2023	-							
2023 Sprin	ng Six Month Survey: No	c Change			-							
Comments	S:											
2024 Sprin	ng Six Month Survey: O	ther			-							
Comments	s:2 rows of floor tiles by assrooms during MEP p	exterior wa			-							
2024 Fall \$	Six Month Survey: No C	hange										
Comments:]							
L					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	12" x 12" White w/Gray Floor Tile Mastic	14000	SF	Classrooms 213,301-314 and 316		Miscellaneous	No	None	0	SF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:VCT located underneath unit ventilators was removed and
eplaced when new unit ventilators were installed Summer of 2023
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:2 rows of floor tiles by exterior walls were replaced in 2nd and
Brd floor classrooms during MEP project summer of 2023
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	12" x 12" Gray Mix Floor Tile	2000	SF	3rd Floor Corridor & Janitor's Closet		Miscellaneous	No	None	0	SF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12" x 12" Gray Mix Floor Tile Mastic	2000	SF	3rd Floor Corridor & Janitor's Closet		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	12" x 12" Pink Mix Floor Tile	2000	SF	2nd Floor Corridor & Storage and stairwells		Miscellaneous	No	None	0	SF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	12" x 12" Pink Mix Floor Tile Mastic	2000	SF	2nd Floor Corridor & Storage		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	12" x 12" Beige Mix Floor Tile	600	SF	Classrooms 201-212, 213 Closet, and 218		Miscellaneous	No	None	0	SF	YES XNO

2022 Fall Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: Other	
Comments:VCT located underneath unit ventilators was removed a	and
replaced when new unit ventilators were installed Summer of 202	23
2023 Spring Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: Other	
Comments:2 rows of floor tiles by exterior walls were replaced in 2	nd and
3rd floor classrooms during MEP project summer of 2023	
2024 Fall Six Marth Survey Na Change	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	12" x 12" Beige Mix Floor Tile Mastic	600	SF	Classrooms 201-212, 213 Closet, and 218		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: Other	
Comments:VCT located underneath unit ventilators was removed	d and
replaced when new unit ventilators were installed Summer of 2	023
2023 Spring Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: Other	
Comments:2 rows of floor tiles by exterior walls were replaced in	2nd and
3rd floor classrooms during MEP project summer of 2023	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	12" x 12" Brown Mix Floor Tile	2500	SF	1st Floor Corridor, Cafeteria, Janitor's Closet, Storage		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12" x 12" Brown Mix Floor Tile Mastic	2500	SF	1st Floor Corridor, Cafeteria, Janitor's Closet, Storage		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12" x 12" Light Brown w/Gray Floor Tile	2500	SF	102/104, 105, 110, 112, Demonstration room		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: Other
Comments:102 & 104 Pre-K Renovation Project, new flooring. Summer of
2022
2023 Fall Six Month Survey: Other
Comments:102 & 104 Pre-K Renovation Project, new flooring, Summer of
2022
2023 Spring Six Month Survey: Other
Comments:102 & 104 Pre-K Renovation Project, new flooring, Summer of
2022
2024 Spring Six Month Survey: Other
Comments: Rooms 102 & 104 have new floor tile. Pre-K renovation project
summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12" x 12" Light Brown w/Gray Floor Tile Mastic	2500	SF	102/104, 105, 110, 112, Demonstration Room		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: Other
Comments:102 & 104 Pre-K Renovation Project, new flooring. Summer of
2022
2023 Fall Six Month Survey: Other
Comments:102 & 104 Pre-K Renovation Project, new flooring, Summer of
2022
2023 Spring Six Month Survey: Other
Comments:102 & 104 Pre-K Renovation Project, new flooring, Summer of
2022
2024 Spring Six Month Survey: Other
Comments: Rooms 102 & 104 have new floor tile. Pre-K renovation project
summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12" x 12" Beige w/Brown Floor Tile	800	SF	Classroom 108		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Н	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	4	12" x 12" Beige w/Brown Floor Tile Mastic	800	SF	Classroom 108		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	White Undercoating on Sinks	10	SF	Classrooms 108, 110, 112, Demonstration Room		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	4" Gray vinyl baseboard	850	LF	Classrooms 213, 313, 314, 2nd & 3rd Floor Corridors		Miscellaneous	No	None	0	LF	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Baseboard for the exterior walls in classrooms on the 2nd and
3rd floor was replaced during MEP project summer of 2023
2024 Fall Six Month Survey: No Change
Comments:

VFT = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.* Oracle Unit: 24931 Page 11

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	4" Gray vinyl baseboard adhesive	800	LF	213, 313, 314, 2nd & 3rd Floor Corridors		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Baseboard for the exterior walls in classrooms on the 2nd and
3rd floor was replaced during MEP project summer of 2023
2024 Fall Six Month Survey: No Change
Comments:

HA	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	3	4" Brown vinyl baseboard	800	LF	Stairways, 106, 108, 313, Cafeteria, 1st Floor Corridor		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Baseboard for the exterior walls in classrooms on the 2nd and
3rd floor was replaced during MEP project summer of 2023
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	4" Brown vinyl baseboard adhesive	800	LF	Stairways, 106, 108, 313, Gym, Cafeteria, 1st Floor Corridor		Miscellaneous	No	None	0	LF	YES XNO

· · · · ·
2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:Baseboard for the exterior walls in classrooms on the 2nd and
3rd floor was replaced during MEP project summer of 2023
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	2' x 4' Lay In Ceiling Panels	48000	SF	Classrooms, Corridors, Library, Storage Rooms, Cafeteria, Demonstration Room		Miscellaneous	Yes	None	0	SF	

2022 Fall Six Month Survey: Other	
Comments: Changed multiple damaged ceiling tiles throughout 1st floo	or and
2nd floor classrooms and hallways.	
2023 Fall Six Month Survey: Other	
Comments: Changed multiple ceiling tiles throughout 1st floor and 2nd	l floor
classrooms and hallways	
2023 Spring Six Month Survey: Other	
Comments: Changed multiple ceiling tiles throughout 1st floor and 2nd	l floor
classrooms and hallways	
2024 Spring Six Month Survey: Other	
Comments: 102 & 104 now have 2 x 2 ceiling tiles, pre-k renovation pr	oject
summer of 2022	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	2' x 2' Lay In Ceiling Panels	1000	SF	Cafeteria and Demonstration Room		Miscellaneous	Yes	None	0	SF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments: Changed multiple ceiling tiles throughout 1st floor and 2nd floor
classrooms and hallways
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Duct sealant	80	LF	Third Floor Mechanical Room		Miscellaneous	No	None	0	LF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:Ductwork by mechanical room entrance had to be removed for
construction access, ductwork was reinstalled and resealed Summer
MEP Project 2023
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Vibration collars	20	LF	Third Floor Mechanical Room		Miscellaneous	No	None	0	LF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:Vibration collar in ductwork by mechanical room entrance was
replaced - Summer MEP Project 2023
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:New MEP equipment, MEP project summer of 2023
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Window caulk	18000	LF	Throughout Facility		Miscellaneous	No	None	0	LF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:205 & 305 windows were removed, reinstalled, and caulked -
Summer MEP Project 2023
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Drywall	50000	SF	Throughout Facility as Inside Walls Between Classroooms		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: Other
Comments:Drywall replacement for connecting wall between 102 & 104.
Summer of 2022
2023 Fall Six Month Survey: Other
Comments:Drywall replacement for connecting wall between 102 & 104.
Summer of 2022
2023 Spring Six Month Survey: Other
Comments:Drywall replacement for connecting wall between 102 & 104.
Summer of 2022
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Drywall compound	50000	SF	Throughout Facility as Inside Walls Between Classrooms		Miscellaneous	No	None	0	SF	X YES NO

2022 Fall Six Month Survey: Other
Comments:Drywall replacement for connecting wall between 102 & 104.
Summer of 2022
2022 Fell Six Month Survey Other
2023 Fall Six Month Survey: Other
Comments:Drywall replacement for connecting wall between 102 & 104.
Summer of 2022
2023 Spring Six Month Survey: Other
Comments:Drywall replacement for connecting wall between 102 & 104.
Summer of 2022
2024 Spring Six Month Survey: No Change
Comments:
2024 Fell Six Menth Survey No Change
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Blue carpet adhesive		SF	Classrooms 301-310, 312,201, 202, 211, 214, 102/104, 110, 112, Main Office, Library		Miscellaneous				SF	

2022 Fall Six Month Survey: Other	
Comments: Floor was redone, carpet removed. Library and main office	e still
nave carpet.	
2023 Fall Six Month Survey: Other	
Comments:Floor was redone, carpet removed. Library and main office	e still
nave carpet.	
2023 Spring Six Month Survey: Other	
Comments:Floor was redone, carpet removed. Library and main office	still
nave carpet.	
2024 Spring Six Month Survey: Other	
Comments:No carpet in classrooms	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Brown carpet adhesive			Classroom 213		Miscellaneous					X YES NO

2022 Fall Six Month Survey: Other
Comments:Floor was redone, carpet removed.
2023 Fall Six Month Survey: Other
Comments: Floor was redone, carpet removed. Library and main office still
have carpet.
2023 Spring Six Month Survey: Other
Comments: Floor was redone, carpet removed. Library and main office still
have carpet.
2024 Spring Six Month Survey: Other
Comments:No carpet in classrooms
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Lab Counter Tops and Sinks	90	SF	Classroom 311		Miscellaneous	No	None	0	SF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Lab table tops	90	SF	Classroom 311		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: Other
Comments:Lab tables in 311 were removed and replaced. Summer of
2022.
2023 Spring Six Month Survey: Other
Comments:Lab tables in 311 were removed and replaced. Summer of
2022.
2023 Fall Six Month Survey: Other
Comments:Lab tables in 311 were removed and replaced. Summer of
2022.
2024 Spring Six Month Survey: Other
Comments:Lab tables demolished and replaced summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Spray on InsuaLightion	48000	SF	Throughout First and Second Floors on Metal Ceilings		Surface	Yes	None	0	SF	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Chalk board/poster board adhesive	3400	SF	All Classrooms		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	4" White baseboard	90	LF	Classroom 213		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	4" White baseboard adhesive	90	LF	Classroom 213		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12" x 12" Blue w/White Floor Tile	500	SF	Room 103		Miscellaneous	No	None	0	SF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" Blue w/White Floor Tile Mastic	500	SF	Room 103		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12" x 12" Light Pink Mix Floor Tile	1500	SF	205, 206, 207		Miscellaneous	No	None	0	SF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:2 rows of floor tiles by exterior walls were replaced in 2nd and
3rd floor classrooms during MEP project summer of 2023
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12" x 12" Light Pink Mix Floor Tile Mastic	1500	SF	205, 206, 207		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:2 rows of floor tiles by exterior walls were replaced in 2nd and
3rd floor classrooms during MEP project summer of 2023
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12" x 12" White w/Gray Floor Tile	5000	SF	Modular Corridor, 115, 116, 117, 118, 119, 120		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: Other
Comments:Modular demolished summer of 2022.
2023 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2023 Fall Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12" x 12" White w/Gray Floor Tile Mastic	5000	SF	Modular Corridor, 115, 116, 117, 118, 119, 120		Miscellaneous	No	None	0	SF	X YES NO

2022 Fall Six Month Survey: Other
Comments: Modular demolished summer of 2022.
2023 Spring Six Month Survey: Other
Comments: Modular demolished summer of 2022
2023 Fall Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	2'x2' lay in ceiling tiles	5200	SF	Throughout Modular Unit		Miscellaneous	Yes	None	0	SF	

2022 Fall Six Month Survey: Other
Comments:Modular demolished summer of 2022.
2023 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2023 Fall Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	4" Tan vinyl baseboard	1000	LF	Modular corridor and classrooms		Miscellaneous	No	None	0	LF	

2022 Fall Six Month Survey: Other	
Comments:Modular demolished summer of 2022.	
2023 Spring Six Month Survey: Other	
Comments:Modular demolished summer of 2022	
2023 Fall Six Month Survey: Other	
Comments:Modular demolished summer of 2022	
2024 Spring Six Month Survey: Other	
Comments:Modular demolished summer of 2022	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	4" Tan vinyl baseboard adhesive	1000	LF	Modular corridor and classrooms		Miscellaneous	No	None	0	LF	

2022 Fall Six Month Survey: Other
Comments: Modular demolished summer of 2022.
2023 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2023 Fall Six Month Survey: Other
Comments: Modular demolished summer of 2022
2024 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Drywall	5200	SF	Throughout Modular Unit		Miscellaneous	No	None	0	SF	X YES NO

2022 Fall Six Month Survey: Other	
Comments:Modular demolished summer of 2022.	
2023 Spring Six Month Survey: Other	
Comments:Modular demolished summer of 2022	
2023 Fall Six Month Survey: Other	
Comments:Modular demolished summer of 2022	
2024 Spring Six Month Survey: Other	
Comments: Modular demolished summer of 2022	
2024 Fall Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Fire door insulation	160	SF	Entrances of Modular Unit		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: Other
Comments: Modular demolished summer of 2022.
2023 Spring Six Month Survey: Other
Comments: Modular demolished summer of 2022
2023 Fall Six Month Survey: Other
Comments: Modular demolished summer of 2022
2024 Spring Six Month Survey: Other
Comments: Modular demolished summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Drywall joint compound	1500	LF	Throughout Modular		Miscellaneous	No	None	0	LF	

2022 Fall Six Month Survey: Other	
Comments:Modular demolished summer of 2022.	
2023 Spring Six Month Survey: Other	
Comments:Modular demolished summer of 2022	
2023 Fall Six Month Survey: Other	
Comments:Modular demolished summer of 2022	
2024 Spring Six Month Survey: Other	
Comments:Modular demolished summer of 2022	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Beige vinyl flooring	200	SF	Men's and Women's Bathrooms in Modular		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: Other
Comments:Modular demolished summer of 2022.
2023 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2023 Fall Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Beige vinyl flooring mastic	200	SF	Men's and Women's Bathrooms in Modular		Miscellaneous	No	None	0	SF	X YES NO

2022 Fall Six Month Survey: Other	
Comments: Modular demolished summer of 2022.	
2023 Spring Six Month Survey: Other	
Comments: Modular demolished summer of 2022	
2023 Fall Six Month Survey: Other	
Comments:Modular demolished summer of 2022	
2024 Spring Six Month Survey: Other	
Comments: Modular demolished summer of 2022	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Drywall joint tape	1000	LF	Throughout Modular		Miscellaneous	No	None	0	LF	

2022 Fall Six Month Survey: Other
Comments:Modular demolished summer of 2022.
2023 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2023 Fall Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Spring Six Month Survey: Other
Comments:Modular demolished summer of 2022
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12" x 12" Brown & White Floor Tile	14000	SF	Room 301- 310,312,201,202,211,214 ,102/104,110,112, Main Office, Library		Miscellaneous	No	None	0	SF	YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Other
Comments:VCT located underneath unit ventilators was removed and
replaced when new unit ventilators were installed Summer of 2023
2024 Spring Six Month Survey: Other
Comments:2 rows of floor tiles by exterior walls were replaced in 2nd and
3rd floor classrooms during MEP project summer of 2023
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" x 12" Brown & White Floor Tile Mastic	14000	SF	Room 301- 310,312,201,202,211,214 ,102/104,110,112, Main Office, Library		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: No Change	
Comments:	
2023 Spring Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: Other	
Comments:VCT located underneath unit ventilators was removed and	
replaced when new unit ventilators were installed Summer of 2023	
2024 Spring Six Month Survey: Other	
Comments:2 rows of floor tiles by exterior walls were replaced in 2nd a	nd
3rd floor classrooms during MEP project summer of 2023	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" x 12" Brown & White Floor Tile	800	SF	Room 313		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Mont	n Survey: No Change
	Touvey. No Change
Comments:	
2023 Fall Six Mont	n Survey: Other
Comments:VCT loc	cated underneath unit ventilators was removed and
	unit ventilators were installed Summer of 2023
2023 Spring Six Mo	onth Survey: No Change
Comments:	· · · · · · · · · · · · · · · · · · ·
2024 Spring Six Mo	onth Survey: Other
Comments:2 rows	of floor tiles by exterior walls were replaced in 2nd and
	s during MEP project summer of 2023
2024 Fall Six Mont	n Survey: No Change
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" x 12" Brown & White Floor Tile Mastic	800	SF	Room 313		Miscellaneous	No	None	0	SF	YES XNO

Comments:
2022 Fall City Marsth Currenty Other
2023 Fall Six Month Survey: Other
Comments:VCT located underneath unit ventilators was removed and
replaced when new unit ventilators were installed Summer of 2023
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Other
Comments:2 rows of floor tiles by exterior walls were replaced in 2nd and
3rd floor classrooms during MEP project summer of 2023
2024 Fall Six Month Survey: No Change
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Rubber flooring material	1500	SF	Gym		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Rubber flooring material mastic	1500	SF	Gym		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	Blue ceramic tile	700	SF	3rd Floor Boy's/girl'/Teacher's Bathroom		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Blue ceramic grout	700	SF	3rd Floor Boy's/girl'/Teacher's Bathroom		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Tan ceramic tile	700	SF	2nd Floor Boy's/girl'/Teacher's Bathroom		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Tan ceramic grout	700	SF	2nd Floor Boy's/girl'/Teacher's Bathroom		Miscellaneous	No	None	0	SF	

022 Fall Six Month Survey: No Change
Comments:
023 Spring Six Month Survey: No Change
Comments:
023 Fall Six Month Survey: No Change
Comments:
024 Spring Six Month Survey: No Change
Comments:
024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Gray ceramic tile	700	SF	1st Floor Boy's/girl'/Teacher's Bathroom		Miscellaneous	No	None	0	SF	

· · ·
2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Gray ceramic grout	700	SF	1st Floor Boy's/girl'/Teacher's Bathroom		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Dark brown ceramic tile	1100	SF	Kitchen/Service area		Miscellaneous	No	None	0	SF	YES XNO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
63	Dark brown ceramic grout	1100	SF	Kitchen/Serving Area		Miscellaneous	No	None	0	SF	YES XNO	

2022 Fall Six Month Survey: No Change	
Comments:	
2023 Spring Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: Other	
Comments:Walk-in coolers were removed, where the walk-in coolers wer located, the ceramic tile underneath was replaced - Summer 2023	e
2024 Fall Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: Other	
Comments:Old walk-in coolers were demolished, new ceramic tile was	
installed before the new walk-in freezer. MEP project summer of 2023	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
MB-6	Orange sheet flooring adhesive	160	SF	Girl's Bathroom		Miscellaneous	No	None	0	SF	YES XNO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Irma C Ruiz Elementary School
---------	-------------------------------

Date: 10/15/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.

Asbestos surveillances are conducted every six months.

CHECK ONE

X A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.