Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

William H Ray Elementary School 25071 5560 School: **Oracle Unit: Building ID:** Address: 5631 S. Kimbark Region: Mail Room: Asbestos Surveyor: Mayo, Thomas X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/21/2024 Email Address: A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's calendar Notice printed in school's newsletter Each child's backpack Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Throughout 1893 01 SF 2 YES X NO Hard plaster 40000 No SF Surface Loc Construction 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
02A	12" x 12" Beige w/tan Streaks Floor Tile	1550	SF	basement art room		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02B	12" x 12" black Floor Tile	300	SF	room 306		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
02C	12" x 12" White Floor Tile	300	SF	room 306		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02D	12" x 12" Beige streaked Floor Tile	430	SF	1st, 2nd, 3rd floor corridors (patches), 310 (patches)		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Quantity	Units		Туре	Category		Type	Quantity	Units	
02E 12" x 12" Orange Floor Tile 75	SF	1st floor corridor - outside boys toilet, as patches in room 313, 311, 310, 303, 211		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02F	12" x 12" tan Floor Tile	4770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office 211		Miscellaneous	No	Loc	10	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

03A	9" x 9" black Floor Tile			main office - principal's office, bathroom, vault		Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No C	nange			7							
Comments:	•	- U			1							
2023 Spring	Six Month Survey: Ot	her			_							
Comments:												
2023 Fall Si	x Month Survey: No C	nange			_							
Comments:												
2024 Spring	Six Month Survey: No	Change			-							
Comments:	•				1							
2024 Fall Si	x Month Survey: No C	nange			-							
Comments:					1							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
03B	9" x 9" White Floor Tile			main office - principal's office, bathroom & vault		Miscellaneous					YES	X NO

Material

Category

Asbestos

Type

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

2022 Fall Six Month Survey: No Change

Material

Quantity

Material

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
03C	9" x 9" Green Floor Tile			Engineer's Bathroom		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No C	hange			7							
Comments:	•											
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2023 Fall Six	Month Survey: No C	hange										
Comments:												
2024 Fall Six	Month Survey: No C	hange										
Comments:												
2024 Spring	Six Month Survey: No	Change			-							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Linoleum			basement ladie's room		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
08	12" x 12" Floor Tile- ABATED			1955 building (demolished)		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	nange										
	Month Survey: No Ch	nange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six Comments:	Month Survey: No Ch	nange										
Comments.					-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	9" x 9" Floor Tile- ABATED			1955 building (demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Wallboard	450	SF	basement art room, fire pump room		Miscellaneous	No	None	0	SF	YES X NO
2022 Fall Six Month Survey: No Change Comments:											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
, ,
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
11A	12" x 12" Beige w/tan Streaks Floor Tile Mastic	1550	SF	basement - art room		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
11B	12" x 12" black Floor Tile Mastic	1000	SF	room 306		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring Six Month Survey: No Change												
Comments:												
					_							

2023 Fall Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11C	12" x 12" White Floor Tile Mastic			room 306		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11D	12" x 12" Beige streaked Floor Tile Mastic	150	SF	1st, 2nd, 3rd floor corridors (patches), 310 (patches)		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11E	12" x 12" Orange Floor Tile Mastic	75	SF	1st floor corridor - outside boys toilet, Room 313, 311, 310 (patches), 303		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11F	12" x 12" tan Floor Tile Mastic	4770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102,105,107, engineer'sn office, 211		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	9" x 9" black Floor Tile Mastic (Abated)			main office - principal's office, washroom, vault		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

12B	9" x 9" White Floor Tile Mastic (Abated)		main office - principal's office, bathroom & vault		Miscellaneous			YES	X NO
0000 F-II O'	Martin Orana Na Ob			1					
	Month Survey: No Cha	ange							
Comments:									
				1					
2023 Spring	Six Month Survey: No	Change							
Comments:	•			1					
				1					
2023 Fall Six	Month Survey: No Cha	ange							
Comments:		-							
2024 Fall Six	Month Survey: No Cha	ange		1					
Comments:	,								
2024 Spring S	Six Month Survey: No	Change							
Comments:	on monar burvey. He								

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12C	9" x 9" Green Floor Tile Mastic			engineer's toilet		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
13	Linoleum mastic			basement ladie's room		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Cha	ange									
Comments:											
2023 Fall Six	Month Survey: No Cha	ange									
Comments:											
	Six Month Survey: No	Change									
Comments:											
	Six Month Survey: No	Change									
Comments:											
	Month Survey: No Cha	ange									
Comments:											
					J						

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12" x 12" Floor Tile Mastic- ABATED			1955 building- (building demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
15	9" x 9" Floor Tile Mastic- ABATED			1955 building- (building demolished)		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	nange			1							
Comments:		<u> </u>										
2023 Fall Six	Month Survey: No Ch	nange										
Comments:												
2023 Spring Six Month Survey: No Change												
Comments:												
2024 Spring	Six Month Survey: No	Change										

2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Brown vinyl baseboard	200	LF	basement art room		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Brown vinyl baseboard Mastic	200	LF	basement art room		Miscellaneous	No	None	0	LF	YES X NO
2022 Fall Six Month Survey: No Change Comments:											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Drywall compound	200	SF	basement art room		Surface	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	12" x 12" Green Floor Tile	800	SF	Staff lounge - kitchen		Miscellaneous	No	None	0	SF	YES X NO
2022 Fall Six	2022 Fall Six Month Survey: No Change										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19B	12" x 12" Green Floor Tile Mastic	800	SF	Staff lounge - kitchen		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
20	Hard plaster			Auditorium		Surface					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:		ge										
2023 Spring	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					_							
2024 Spring	Six Month Survey: No	Change										
Comments:					_							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:		•										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Ceiling plaster	10160	SF	Throughout basement and classrooms		Miscellaneous	No	Dist	40	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Page 17

22 12" x 12" Light Blue Vinyl Floor Tile 6700 SF Basement Storage, Boys Bathroom, Lunchroom, Corridor, Girls Playroom, Room 312, Miscellaneous No None 0 SF YES X NO	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	22	· ·	6700	SF	Bathroom, Lunchroom, Corridor, Girls Playroom,		Miscellaneous	No	None	0	SF	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12" x 12" Light Blue Vinyl Floor Tile Mastic	6700	SF	Basement Storage, Boys Bathroom, Lunchroom, Corridor,Girls Playroom, Room 312,		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" Dark Blue Vinyl Floor Tile	2400	SF	Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change	
Comments:	
2023 Spring Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: No Change	
Comments:	
2024 Fall Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: No Change	
Comments:	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" x 12" Dark Blue Vinyl Floor Tile Mastic	2400	SF	Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
26	Lab table tops	432	SF	Room 309		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
Confinents.
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" Light Green Vinyl Floor Tile	3200	SF	1st Floor Corridor, Storage Room, Principles Office.		Miscellaneous	No	Loc	2	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Light Green Vinyl Floor Tile Mastic	3200	SF	1st Floor Corridor, Storage Room, Principles Office.		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" x 12" Dark Green Vinyl Floor Tile	3200	SF	1st Floor Corridor and Office		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" Dark Green Vinyl Floor Tile Mastic	3200	SF	1st Floor Corridor and Office		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Oracle Unit: 25071

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Tongue and groove wooden floor	600	SF	Rooms 315, 314, 309, 307, 304, 302, 301, 215, 214, 213, 212, 210, 209, 207, 204, 202, 201, 104, gym track, gym, 106, 112, 113, 114, 115		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Repaired
Comments:repaired floor
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" Light Brown w/ White Specks Floor Tile	20	SF	Patches in Room 308, 305		Miscellaneous	No	Loc	4	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" Light Brown w/ White Specks Floor Tile Mastic	20	SF	Patches in Room 308, 305		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12" x 12" White w/ Light Green/ gray Specks Floor Tile	3500	SF	1st Fl Corridor, main Office, 1st floor teacher's storage		Miscellaneous	No	Loc	4	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" White w/ Light Green/ gray Specks Floor Tile Mastic	3500	SF	1st FI Corridor, main Office, 1st floor teacher's storage		Miscellaneous	No	Loc	4	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
	А	Mag block boiler insulation- ABATED			boiler room- material abated and boiler removed in 1994		Miscellaneous					YES	X NO
2022 Fall Six Month Survey: No Change					1	•	•	•	•	•			

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Cardboard pipe covering	40	SF	attic - tank		TSI	Yes	None	0	SF	X YES NO

2022 Fall Six Month Survey: Abated
Comments:pipe repair
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
F	Cardboard pipe fittings	3	LF	attic - tank		TSI	Yes	None	0	LF	YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2004 Ossiss O' Mostle Ossas No Obsessor
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Aircell pipe insulation			original (1893) building air chamber		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category		Type	Quantity	Units		
Н	Aircell pipe joints	6	FITTING	basement teachers lounge		TSI	Yes	None	0	FITTING	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	•	<u> </u>										
2023 Spring S	Six Month Survey: No											
Comments:	-											
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change										

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Preform pipe covering- ABATED			1893 building		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Material Location

Page 28

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
К	Water meter packing	5	FITTING	basement fire pump room, Basement Teacher's Lounge		TSI	Yes	None	0	FITTING	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		· · · · · · · · · · · · · · · · · · ·	· · ·							

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Cardboard pipe covering- ABATED			1955 addition- (building demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Р	Cardboard pipe joint- ABATED			1955 addition- (building demolished)		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	-											
2023 Fall Six	Month Survey: No Ch	ange			_							
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	_											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Aircell pipe insulation- ABATED			1955 building addition- (building demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA NO	Material Description	Quantity	Units	iviaterial Location	Type	Category	Friable	Type	Quantity	Units	Change in Assess	sment Category
R	Aircell pipe joints- ABATED			1955 addition- (building demolished)		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:												
2023 Spring	Six Month Survey: No	Change			}							
Comments:					<u> </u>							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					1							
2024 Spring	Six Month Survey: No	Change										
Comments:					 							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Cementious pipe fittings	10	LF	Girls and Boys bathrooms - pipe chases		TSI	Yes	None	0	LF	YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Т	Pipe insulation	30	LF	Girls and Boys bathrooms - pipe chases		TSI	Yes	None	0	LF	YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	Incinerator brick			boiler room		TSI					X YES NO

2022 Fall Six Month Survey: Abated
Comments:boiler room upgrade
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
V	Cementitous pipe fittings			Engineer's Storage and Fire Pump Room		TSI					YES	X NO
2022 Fall Si	x Month Survey: No Ch	ange										
Comments:					_							
2023 Fall Si	x Month Survey: No Ch	ange										
Comments:					_							
2023 Spring	Six Month Survey: No	Change										
Comments:												

2024 Fall Six Month Survey: No Change Comments:

2024 Spring Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
W	Pipe insulation	100	LF	Engineer's Storage and Fire Pump Room		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Х	Material behind metal ceiling and walls			Auditorium Fan Room		Surface					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 25071

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William H Ray Elementary School
Date:10/21/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
X A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 25071

SCHOOL'S ASBESTOS MANAGEMENT PLAN.