

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2024 Fall Six Month Survey

**School:** Paul Revere Elementary School  
**Address:** 1010 E. 72nd St.

**Oracle Unit:** 25121  
**Region:** 05

**Building ID:** 5610  
**Mail Room:** 46

☐ **CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Smith, Jimmie  
**Survey Date:** 11/6/2024  
**Email Address:** jsmith340@cps.edu

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ *Each child's backpack* ☒ *Notice printed in school's newsletter* ☐ *Notice printed in school's calendar* ☐ *Other* |

| HA No | Material Description  | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 01    | 9x9 Floor Tile ABATED |                   |                | 1961 Building- Material Removed |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 25121

Page 1

| HA No | Material Description   | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02    | 12x12 Beige Floor Tile | 15000             | SF             | 1961 Building- Classroom/Storage Rooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 03    | Carpeting ABATED     |                   |                | 1961 Building- Material Removed |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04    | Hardcoat Plaster     | 40000             | SF             | 1961 Building     |               | Surface           | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05    | Old Spray-On Insulation<br>ABATED |                   |                | 1961 Building     |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06    | New Spray-On Ceiling Insulation |                   |                | 1961 Building     |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07    | Hardcoat Plaster     |                   |                | 1938 Building- Gym |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08    | 9x9 Brown Floor Tile and Mastic | 390               | SF             | 1902 Building- Classroom 200 (formerly Teachers' Room) |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description   | Material Quantity | Material Units | Material Location                                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09    | 12x12 Beige Floor Tile | 10000             | SF             | 1902 Building- Throughout Classrooms, & Room 201 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10    | Hardcoat Plaster     | 49000             | SF             | 1902 Building     |               | Miscellaneous     | No      |             | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description           | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 11    | Canvas Wall Covering<br>ABATED |                   |                | 1902 Building- Material<br>Removed |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 12    | 2x4 Ceiling Tile     | 7000              | SF             | 1902 Building- Kitchen, and Throughout 1961 Building |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 13    | Fire Doors           | 8                 | EA             | 1938 Building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 14    | Fire Doors           | 6                 | EA             | 1902 Building     |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description         | Material Quantity | Material Units | Material Location                              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15    | Light Grey Floor Tile Mastic |                   |                | 1961 Building-<br>Classrooms, Storage<br>Rooms |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | 12x12 Grey Floor Tile | 1700              | SF             | 1961 Building- Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description            | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | 12x12 Grey Floor Tile<br>Mastic |                   |                | 1961 Building- Corridors |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18    | 12x12 Purple Floor Tile | 360               | SF             | 1961 Building- Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description              | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19    | 12x12 Purple Floor Tile<br>Mastic | 360               | SF             | 1961 Building- Corridors |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | 12x12 Pink Floor Tile | 600               | SF             | 1961 Building-Classrooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description         | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21    | 12x12 Pink Floor Tile Mastic |                   |                | 1961 Building-Classrooms |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23    | 12x12 Beige Floor Tile Mastic | 10000             | SF             | 1902 Building- Throughout Classrooms |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24    | 12x12 Tan Floor Tile | 3500              | SF             | 1938 Building- Auditorium |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | 12x12 Tan Floor Tile Mastic |                   |                | 1938 Building- Auditorium |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description  | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26    | 12x12 Grey Floor Tile | 2200              | SF             | 1961 Building- Main Corridor |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27    | 12x12 Grey Floor Tile Mastic |                   |                | 1938 Building- Main Corridors |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28    | 9x9 Brown Floor Tile | 150               | SF             | 1938 Building- Gym Storage Room |               | Miscellaneous     | No      | Loc         | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29    | 9x9 Brown Floor Tile Mastic | 150               | SF             | 1938 Building- Gym Storage Room |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30    | Brown Carpet Mastic  |                   |                | 1961 Building- Main Office Area, Room 219 & Room 221D |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31    | Purple Carpet Mastic |                   |                | 1961 Building- 1st Floor Classrooms |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|  |
|--|
| 2022 Fall Six Month Survey: No Change  |
| Comments:  |
|  |
| 2023 Fall Six Month Survey: No Change  |
| Comments:  |
|  |
| 2023 Spring Six Month Survey: No Change  |
| Comments:  |
|  |
| 2024 Spring Six Month Survey: No Change  |
| Comments:  |
|  |
| 2024 Fall Six Month Survey: Other  |
| Comments:I can not find any room that have purple carpet. It must have been Abated |
|  |

| HA No | Material Description | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32    | Drywall              |                   |                | 1902 Building- Pump Room and Corridors |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33    | Drywall Compound     |                   |                | 1902 Building- Pump Room |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 34    | Drywall              |                   |                | 1938 Building- Main Corridor |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36    | Stucco Ceiling Plaster |                   |                | Main Corridor     |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description   | Material Quantity | Material Units | Material Location                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37    | Stucco Ceiling Plaster |                   |                | 1902 Building- Corridors & Classrooms |               | Surface           |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38    | Transite Table Tops  |                   |                | 1902 Building- Classroom 203 |               | Miscellaneous     |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39    | Ceramic Flooring     |                   |                | 1961 Building- Student Bathrooms and Entry Vestibule by Gym |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40    | Beige Terrazzo       | 800               | SF             | 1961 Building- Stairwells, Gym Entry/Foyer |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41    | Beige Terrazzo       | 500               | SF             | 1902 Building- Basement Serving Area, Lunchroom Manager's Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                        | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42    | 12x12 Beige w/Streaks Floor Tile and Mastic | 180               | SF             | 1902 Building- Basement Engineer's Office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43    | Pipe Fitting         | 10                | LF             | Basement Room B30 Equipment Room |               | TSI               | Yes     | Loc         | 5               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A     | Fiberglass Duct Wrap |                   |                | 1961 Building-Mechanical Room |               | TSI               |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B     | Duct Expansion Joint |                   |                | 1961 Building-Mechanical Room |               | TSI               |         | None        |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C     | Fiberglass Insulation |                   |                |                   |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E     | Univents             | 38                | EA             | 1961 Building     |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F     | Concealed Boiler Insulation under Metal Jackets and Gaskets | 600               | SF             | 1902 Building- Boiler Room |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|  |
|--|
| 2022 Fall Six Month Survey: No Change  |
| Comments:  |
|  |
| 2023 Fall Six Month Survey: No Change  |
| Comments:  |
|  |
| 2023 Spring Six Month Survey: No Change  |
| Comments:  |
|  |
| 2024 Fall Six Month Survey: Deteriorated   |
| Comments: Metal jacket rusted and hanging underneath boiler # 2 Exposed insulation |
|  |
| 2024 Spring Six Month Survey: No Change  |
| Comments:  |
|  |
|  |

| HA No | Material Description   | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G     | Tank Insulation ABATED |                   |                | 1902 Building- Pump Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H     | Aircell Pipe Insulation | 100               | LF             | 1902 Building- Fan Room |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description  | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I     | Fiberglass Insulation |                   |                | 1902 Building- Pump Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J     | Fiberglass Fittings  | 50                | JOINTS         | 1902 Building- Basement B20 Fan Room |               | TSI               | Yes     |             | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description        | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K     | Cardboard Insulation ABATED |                   |                | 1902 Building- Boiler Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L     | Cardboard Joint Insulation ABATED |                   |                | 1902 Building     |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description    | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| M     | Aircell Duct Insulation | 150               | SF             | 1902 Building- Fan Room |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| N     | Hot Water Tank Insulation ABATED |                   |                | 1902 Building- Tank Room |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description        | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| NEW   | Newly Installed Suspect ACM |                   |                | Installed After Implementation of Management Plan and After Renovations |               | Miscellaneous     |         | Unknown     |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| O     | Duct Expansion Joint | 300               | SF             | 1902 Building- Fan Room |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| P     | Pre-Form Pipe Insulation | 75                | LF             | Coal Room- 02     |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| Q     | Duct Insulation Jacket | 300               | LF             | Crawlspace below Auditorium Stage |               | TSI               | No      | Loc         | 2               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

| HA No | Material Description     | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| R     | Aircell Joint Insulation | 7                 | LF             | 1902 Building-Boiler/Pump Room |               | TSI               | Yes     |             | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| S     | Preform Pipe Joint Insulation | 10                | LF             | 1902 Building- Coal Room |               | TSI               | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |

| HA No | Material Description    | Material Quantity | Material Units | Material Location                                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| T     | Aircell Pipe Insulation | 40                | LF             | 1902 Building - Pump Room, B19B Storage, Basement Hall |               | TSI               | Yes     | Loc         | 15              |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|   |
|---|
| 2022 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|   |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|   |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

A handwritten signature in black ink, appearing to read 'Richard J. Schleyer', written in a cursive style.

---

Richard J. Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Paul Revere Elementary School

Date: 11/6/2024

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.

**CHECK ONE**

- ☐ A copy of this notice was sent home in each child's backpack.
- ☒ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☐ Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***