Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

A.N. Pritzker School 25871 6460 School: **Oracle Unit:** Building ID: Address: 2009 W. Schiller Street Region: Mail Room: Marquez, Alexander Asbestos Surveyor:

X CHEC	CK HERE IF NO CH	IANGE TO	O ASBE		rvey Date: nail Address:	10/29/2 amarqu	024 lez81@cps.ed	du				
	A copy of the2022/20	,		0 0	· ·							
	Each child's backp	oack	Notice	printed in school's	s newsletter	sletter Notice printed in school's calendar X Other cps website						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
01	Plaster	80000	SF	Throughout		Surface	No	None	0		YES	X NO
2022 Fall \$	Six Month Survey: No C	hange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 25871

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	Acoustic Spray-on	15065	SF	1st, 2nd & 3rd Floors, Breezeway Hallway		Surface	Yes	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	1'x1' White Grooved Ceiling Tile	50000	SF	Throughout		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04	9"x9" Sand Floor Tile	150	SF	Engineers Office		Miscellaneous	No	None	0		YES	X NO
	Month Survey: No Ch	ange]							
Comments:												
2023 Fall Six Month Survey: No Change												
Comments:												

2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" Off-white floor tile	8530	SF	Lunch Room, Room 304, Room 117, Room 112		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9"x9" Sand Floor Tile Mastic	150	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO
					1						_

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Off-white Floor Tile Mastic	8530	SF	Lunch Room, Room 304, Room 117, Room 112		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9"x9" Brown Floor Tile	4100	SF	Room 301, 203, 101, 102, 103, 104, 105, 106, 107, 108, 109, 111, Library, Library Office, MDF Room, Gym Stage, Gym Office		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Abated
Comments:Room 109 New floor tiles installed
2023 Fall Six Month Survey: Abated
Comments:Room 109 abated and new floor tiles installed
2023 Spring Six Month Survey: Abated
Comments:room 109 new floor tiles
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
09	9"x9" Brown Floor Tile Mastic	4100	SF	Room 301, 203, 101, 102, 103, 104, 105, 106, 107, 108, 109, 111, Library, Library Office (not observed), MDF Room, Gym Stage		Miscellaneous	No	None	0		XYES	NO

2022 Fall Six Month Survey: Abated
Comments:Room 109 New floor tiles installed
2023 Fall Six Month Survey: Abated
Comments:Room 109 abated and new floor tiles installed
2023 Spring Six Month Survey: Abated
Comments:rom 109 new floor tiles
2024 Spring Six Month Survey: Abated
Comments:room 109 floor tiles replaced
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category	Туре	Quantity	Units		
10	9"x9" Orange Floor Tile (ABATED)			1st, 2nd, 3rd Floor Corridors		Miscellaneous				YES	X NO
2022 Fall Six	« Month Survey: No Cł	nange									
Comments:											
2023 Fall Six	Month Survey: No Ch	nange									
Comments:											
2023 Spring	Six Month Survey: No	Change									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Ch	nango			\dashv						

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9"x9" Orange Floor Tile Mastic (ABATED)			1st, 2nd, 3rd Floor Corridors		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12	12"x12" Tan Floor Tile (Not Observed)		SF	1st Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Tan Floor Tile Mastic (Not Observed)		SF	1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
14	9"x9" Grey Floor Tile	1100	SF	Teachers Lounge, Office Hallway, Auditorium Storage Room		Miscellaneous	No	None	3		YES	X NO
2022 Fall S	ix Month Survey: No C	hange			1							
Comments:		<u> </u>										
2023 Fall Six Month Survey: No Change]							
Comments:	:											
2022 Spring	a Civ Month Cumrour N	o Changa			-							

2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"x9" Grey Floor Tile Mastic	1100	SF	Teachers Lounge, Office Hallway, Gym Storage Room, Gym Office, Auditorium Storage Room		Miscellaneous	No	None	3		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	9"x9" Dark Brown Floor Tile	11550	SF	Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302 (not observed), 306, 308, 309, 311 Gym Storage, Gym Office, and 2nd Floor Storage Room		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Abated
Comments:Room 109/311 New floor tiles installed
2023 Fall Six Month Survey: Abated
Comments:Rooms 109,311 abated and new floor tiles installed
2023 Spring Six Month Survey: Abated
Comments:room109 and 311 new floor tile
2024 Spring Six Month Survey: Abated
Comments:rooms 109 and 311 floor tiles replaced
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Dark Brown Floor Tile Mastic	11550	SF	Rooms 101-109, 111, 201-204, 206, 207, 209, 301, 302, 306 (not observed) ,308, 309, and 2nd Floor Storage Room		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Abated
Comments:Room 109/311 New floor tiles installed
2023 Fall Six Month Survey: Abated
Comments:Rooms 109 and 311 abated and new floor tiles installed
2023 Spring Six Month Survey: Abated
Comments:room 109 and 311 new floor tiles
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Beige Floor Tile (NOT OBSERVED)	50	SF	Corridor by Room 104, Breezeway		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

10	Mastic (NOT OBSERVED)		0.	Breezeway		·····oconariocao		110.10	ŭ			<u> </u>
2022 Fall S	Six Month Survey: No C	hange			7							
Comments	•											
2023 Fall Six Month Survey: No Change												
Comments	:				_							
2023 Sprin	g Six Month Survey: No	Change										
Comments	:				_							
2024 Sprin	g Six Month Survey: No	Change										
Comments	:				_							
2024 Fall S	Six Month Survey: No C	hange										
Comments	:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category

Type

Material

Category

Miscellaneous

Miscellaneous

No

None

0

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

Material Location

Corridor by Room 104,

2000

LF

Throughout

Material Description

9"x9" Beige Floor Tile

Exterior Window Caulk

2022 Fall Six Month Survey: No Change

Material

Quantity

80

Material

Units

SF

HA No

19

20

Change in Assessment Category

X NO

X NO

YES

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12" x 12" Green with Dark Streaks Floor Tile	800	SF	Room 307, 205 Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21 A	12" x 12" Green with Dark Streaks Floor Tile Mastic	800	SF	Room 307		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" Blue Gray Floor Tile	150	SF	Libraray Office and Closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22 A	12" x 12" Blue Gray Floor Tile Mastic	150	SF	Libraray Office and Closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Spray Applied Acoustical Plaster (Patch)	15000	SF	1st, 2nd & 3rd Floors, Breezeway Hallway		Surface	Yes	None	0		YES X NO
					1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Carpet Adhesive	4500	SF	Rooms 110, 113, 115, 205, 200 and Counselors Office.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Green with Dark Green Streaks Floor Tile	99	SF	Vault, Store Room		Miscellaneous	No	None	0		YES X NO
2022 Fall Civ	Month Cumiou No Chi	20.00									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	Green with Dark Green Streaks Floor Tile Mastic	99	SF	Vault, Store Room		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Lab Table Tops	248	SF	Science Room (Room 302)		Miscellaneous	No	None	0		YES X NO
					-						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0004 0 1 0 1 0 1 0
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" White and Blue Floor Tile	2340	SF	Rooms 208, 302 and 306		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	12" x 12" White and Blue Floor Tile Mastic	2340	SF	Rooms 208, 302 and 306		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Green Streaked Floor Tile	165	SF	2nd Floor Store Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	12" x 12" Green Streaked Floor Tile Mastic	165	SF	2nd Floor Store Room		Miscellaneous	No	None	0		YES X NO
0000 Fall Civ	Manth Common Na Oba										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Terrazzo	1500	SF	All Entries		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" Grey w/White and Dark Grey Floor Tile	3300	SF	Auditorium, and Main Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30A	12" x 12" Grey w/White and Dark Grey Floor Tile Mastic	3300	SF	Auditorium. and Main Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Fume Hood Lining	60	SF	Science Room (Room 302)- (not observed).		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Light Blue w/ Blue specs VFT	1200	SF	Auditorium, and 1st Floor Corridor outside Auditorium.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Abated
Comments:3ft x 7ft area abated by door entrance #16
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
33	12" x 12" Light Blue w/ Blue specs VFT Mastic	1200	SF	Auditorium		Miscellaneous	No	None	0		X YES	NO
2022 Fall S	ix Month Survey: Abated	t										
Comments:	area by door entrance #	16 aprox	8'x3'6"									
	ix Month Survey: Abated											
Comments:	3ftx 7ft area abated by o	door entra	nce #16									
2023 Spring	g Six Month Survey: Aba	ited										
Comments:	small area by door 16 re	eplaced da	amaged ti	les								
2024 Spring	g Six Month Survey: No	Change										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" Light Gray w/ Gray Specks VFT	900	SF	Main office, principals office, conference room in office, Foyer outside auditorium		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

2024 Fall Six Month Survey: No Change

Change in Assessment Category

HA No Mat		Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	" x 12" Light Gray w/ ay specks VFT Mastic	900	SF	Main office, principals office, conference room in office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" Pink Streaked VFT	2240	SF	1st, 2nd, 3rd Floor Classrooms under the Univents		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12" x 12" Pink Streaked VFT Mastic	2240	SF	1st, 2nd, 3rd Floor Classrooms Under the Univents		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Dry Wall Soffit	120	SF	Rooms 101 and 108		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Black Painted Accoustic Ceiling	3250	SF	Auditorium		Surface	Yes	None	0		YES X NO
2022 Fall Six	2022 Fall Six Month Survey: No Change										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	2'x2' White Ceiling Tile	560	SF	1st Floor faculty Lounge, Main Office, Counselors Office, and Nurses Office.		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
41	Unfinished Drywall Ceiling	2000	SF	Mezzanine above First Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:	-											
2023 Fall Six Comments:	Month Survey: No Ch	ange			- - -							
	Six Month Survey: No	Change										
Comments:					_							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Drywall	20000	SF	Above ceiling tiles in classrooms, 1st Floor Electrical Vault, and Gym Office.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
43	Black tar-like Fireproofing	20000	SF	Above ceiling tile in classrooms		Miscellaneous	No	None	0		YES	X NO
2022 Fall S Comments:	ix Month Survey: No Ch	nange										
2023 Fall S Comments:	ix Month Survey: No Ch	nange			_							
2023 Spring	g Six Month Survey: No	Change										
	g Six Month Survey: No	Change			_							
Comments:	, , , , , , , , , , , , , , , , , , , ,	2										
2024 Fall S	ix Month Survey: No Ch	nange										
Comments.					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Boiler Lag (Abated)			Boiler Room (Abated)		Miscellaneous					YES X NO

Page 27

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
В	Water Tank Insulation (Abated)			Boiler Room (Abated)		TSI					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:		<u>gc</u>			= =							
2023 Spring S	Six Month Survey: No	Change			-							
Comments:					1							
2023 Fall Six	Month Survey: No Ch	ange			_							
Comments:					-							
2024 Spring S	Six Month Survey: No	Change										
Comments:					-							
2024 Fall Six	Month Survey: No Ch	ange			-							
Comments:					1							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	MJP on Fiberglass Pipe Insulation	192	FITTING	Boiler Room, Crawl Space, First Floor Storage Room Next To Office, Gym Storage Room on Second Level		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category	Type	Quantity	Units		
G	Storage Tank Insulation (Abated)			Boiler Room (Abated)		TSI				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange									
Comments:											
2023 Spring	Six Month Survey: No	Change									
Comments:					_						
2023 Fall Six	Month Survey: No Ch	ange									
Comments:					_						
	Six Month Survey: No	Change									
Comments:											
	Month Survey: No Ch	ange									
Comments:											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	12" x 12" Tan with Specks VFT	2400	SF	Rooms 303, 305, 112A, 206		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material Material Location

Damage Change in Assessment Category

		Quantity	Units		Type	Category		Type	Quantity	Units		
1	12" x 12" Tan with Specks Mastic	2400	SF	Rooms 303 & 305, 112A, 206		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change												
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Cha	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												

Material

Damage

Damage

Friable

НА	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J		12" x 12" Light Blue with Dark Blue Streaks Floor Tile	8640	SF	1st, 2nd, and 3rd Floor Corridors and Stairwells		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

2024 Fall Six Month Survey: No Change

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
K	12" x 12" Lt Blue w/ Dk Blue Strks Floor Tile Mastic	8640	SF	1st, 2nd & 3rd floor Corridors and Stairwells		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Grey Speck Carpet Mastic	1824	SF	Engineer's Office, 2nd Floor Faculty Lounge(rm 200), Library		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
М	2' x 4' Ceiling Tile	500	SF	Kitchen		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	1'x1' Fissured Ceiling Tile	110	SF	Dishwashing Room- (not observed).		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	Vinyl Baseboard Mastic	600	LF	Throughout 1961 Addition		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Ch	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	9" x 9" Multicolor VFT	100	SF	3rd floor hall to nurses office, Electrical Vault.		Miscellaneous	No	Loc	50		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Damaged
Comments:Broken floor tiles in electrical closet by 102
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
QM	9" x 9" Multicolor VFT Mastic	140	SF	3rd Floor Hall to Nurses Office-(not observed), 1st Floor Janitor's Closet by Room 102 and Electrical room, Electrical Vault.		Miscellaneous	No	Loc	50		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: Damaged
Comments:Broken floor tiles in electrical closet by room 102
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 25871

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: A.N. Pritzker School
Date: 8/1/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. cps website
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 25871