## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2024 Fall Six Month Survey

**Oracle Unit:** 

26191

Address: 8505 S Ingleside Avenue Region: 06 Mail Room: Asbestos Surveyor: Barrett, Lester X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/25/2024 Email Address: Ilbarrett4@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Category Quantity Type Type Over Trophy Case on 1st 04 SF YES X NO 1'x1' Ceiling Tiles 425 Miscellaneous Yes None 0 Floor (next to stairs) 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

Arthur R Ashe Elementary School

School:

6900

**Building ID:** 

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Brown Floor Tile	3000	SF	Rooms 300 and 309 (Aqua), 3rd Floor Corridor and 3rd Floor Teachers' Washroom		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	2022 Fall Six Month Survey: No Change										

2022 Fall Civ Month Curvey No Change
2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Brown Floor Tile Mastic	3000	SF	Rooms 300 and 309, South End of 3rd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Encapsulated Spray-On	80000	SF	Throughout Building		Surface	Yes	None	0		YES X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange									
2023 Fall Six	2023 Fall Six Month Survey: No Change										

Comments:

Comments:

Comments:

Comments:

2023 Spring Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" Aqua Floor Tile	55000	SF	Rooms 101-111, 201- 211, 301-310, 2nd Floor Teachers' Lounge (next to boys' washroom) and 3rd Floor Janitor's Closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 26191

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Aqua Floor Tile Mastic	55000	SF	1st, 2nd and 3rd Corridors, Rooms 101- 111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom), 3rd Floor Janitor's Closet		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
11	Baseboard	500	LF	Office Area and Lunchroom		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	2022 Fall Six Month Survey: No Change Comments:											
2023 Fall Six	2023 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Baseboard Mastic	500	LF	Office Area and Lunchroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Asses	sment Category
15	Vibration Damper	5	SF	Fan Room		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												

2023 Fall Six Month Survey: No Change
Comments:

2023 Spring Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Gray Vinyl Floor Tile	350	SF	Engineer's Office/Washroom and Locker Room/Washroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16A	12"x12" Gray Vinyl Floor Tile Mastic	350	SF	Engineer's Office/Washroom and Locker Office/Washroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16B	TSI	872	LF	Small Boiler in Boiler Room near Engineer's Doorway		TSI	Yes	Loc	25		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Gray Vinyl Floor Tile	80	SF	Engineer's Office/Washroom		Miscellaneous	No	None	0		YES X NO
2222 5 11 21					1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	12"x12" Gray Vinyl Floor Tile Mastic	80	SF	Engineer's Office/Washroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Peach Vinyl Floor Tile	120	SF	Patchwork in Kitchen		Miscellaneous	No	None	0		YES X NO
_					i						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	12"X12" Peach Vinyl Floor Tile Mastic	120	SF	Patchwork in Kitchen		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Light Blue Vinyl Floor Tile	100	SF	Patchwork in Kitchen		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Chr	ango									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19A	12"x12" Light Blue Vinyl Floor Tile Mastic	100	SF	Patchwork in Kitchen		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change Comments:  2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:	
2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	Comments:
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	
2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	Comments:
Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Fall Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change	2024 Spring Six Month Survey: No Change
	Comments:
Comments:	2024 Fall Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Textured Plaster Ceiling	700	SF	Fan Room		Surface	Yes	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	MJP on Fiberglass Pipe Insulation	250	EA	Fan Room and Crawlspace		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Blue Carpet Mastic	1800	SF	Main Office and Library (Room 104)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Pipe Insulation	300	LF	Pipe Chases - hidden behind walls		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

24	Pipe Fittings	90	LF	Pipe Chases - hidden behind walls		TSI	Yes	None	0	YES	X NO
0000 Fall Civ	Marath Commercia Na Ob				Ī						
	Month Survey: No Cha	ange									
Comments:											
2023 Spring S	Six Month Survey: No	Change									
Comments:											
2023 Fall Six	Month Survey: No Cha	ange									
Comments:											
2024 Fall Six	Month Survey: No Cha	ange									
Comments:											
2024 Spring Six Month Survey: No Change											
Comments:	•										

Asbestos

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CM1	Carpet Mastic			West/North/West Center Wall in Room 302 (NOT OBSERVED)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
CM2	Carpet Mastic			West/South/West Center Walls in Library		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	•	<u> </u>										
2023 Spring S	Six Month Survey: No	Change										
Comments:	_											
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange			-							
Comments:												
2024 Spring S	Six Month Survey: No	Change			-							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT1	12"x12" Dark Blue Floor Tile	3500	SF	Teachers' Dining Area, Sink Room in Cafeteria Area		Miscellaneous	No	Dist	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT2	12"x12" Light Blue Floor Tile	3500	SF	Gym Area		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Ch	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM1	12"x12" Dark Blue Floor Tile Mastic	3500	SF	Teacher's Dining Room and Sink Room in Cafeteria Area		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
FTM2	12"x12" Light Blue Floor Tile Mastic	3500	SF	Gym Area		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												
2023 Spring Six Month Survey: No Change Comments:												
2023 Fall Six	2023 Fall Six Month Survey: No Change											

Comments:

2024 Fall Six Month Survey: No Change Comments:

2024 Spring Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
MF1	Beige & Green Terrazzo	5000	SF	Stairs and Landings		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations		Miscellaneous		Unknown			YES	X NO
2022 Fall Si	x Month Survey: No C	hange										
Comments:		J -										
2023 Spring	Six Month Survey: No	Change			_							
Comments:	,											
2023 Fall Si	x Month Survey: No C	hange										
Comments:	<b>,</b>	J										
2024 Spring Six Month Survey: No Change												
Comments:												
2024 Fall Si	x Month Survey: No C	hange			+							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
SP1	Plaster	34000	SF	Ceilings Throughout Facility		Surface					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Arthur R Ashe Elementary School
Date: 10/25/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Oracle Unit: 26191 Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.