Chicago Public Schools 6 Month Asbestos Surveillance

2024 Fall Six Month Survey

School:	William E B Dubois Elementary School		Oracle Unit:	26601	Building ID:	8010
Address:	330 E. 133rd Street		Region:	06	Mail Room:	48
	IO CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date: Email Address:	Zavala, Jason 10/31/2024 jzavala82@cps.k12.il.us			

	A copy of the2022/20	23 notice to	parents and	staff regarding the as	sbestos manag	ement plan no	otifications w	as distribute	ed via:			
	Each child's backp	back	X Notice	printed in school's ne	wsletter	Notice p	rinted in sch	ool's calenda	ar Ot	her		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
02	Stucco Ceiling	3600	SF	1968 Building- All- Purpose Room		Surface	Yes	None	0		YES	X NO
2022 Fall S Comments	Six Month Survey: No C :	hange										
2023 Fall S Comments	Six Month Survey: No C	hange			_							
2023 Sprin Comments	g Six Month Survey: No :	o Change										
2024 Sprin Comments	g Six Month Survey: No :Same	o Change			_							
2024 Fall S Comments	Six Month Survey: No C :	hange										
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	9"x9" Beige Floor Tile	11100	SF	1st Floor Rooms 103, 109, 111 & 112, 111, 109 and Rooms 210, 212, 214, 2nd Floor MDF Room		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" Beige Floor Tile	5700	SF	1st and 2nd Floor Corridors and Lunchroom, Main Office Waiting Area, Faculty Lunchroom, and Room 103		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	12"x12" Beige Floor Tile Mastic	5700	SF	1st and 2nd Floor Corridors and Lunchroom, Main office and waiting area, Faculty lunchroom, and Room 103		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:new
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9"x9" Beige Floor Tile Mastic	11100	SF	1st Floor Rooms 103, 109, 111 & 112, and Rooms 210, 212, 214, 2nd Floor MDF Room		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: No Change	
Comments:	
2023 Spring Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: No Change	
Comments:Same	
2024 Fall Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Hardcoat Plaster	6000	SF	Throughout 1937 Building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	2'x4' Ceiling Tile	5440	SF	Throughout 1937 Building		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9"x9" Brown Floor Tile	150	SF	Room 101, 9x9 Pink and 9x9 Beige		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9"x9" Floor Tile Mastic	150	SF	1968 Building- Room 101		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	9"x9" Green Floor Tile	3500	SF	1st Floor Classrooms, Rooms 103, 108, 113		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Green Floor Tile Mastic	3500	SF	1st Floor Classrooms, Rooms 103, 108, 113		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9"x9" Green Floor Tile	80	SF	1937 Building- Basement Engineer's Office		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:scheduled for demo
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9"x9" Green Floor Tile Mastic	80	SF	1937 Building- Basement Engineer's Office		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:sfd
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
16	9"x9" Gray Floor Tile	1450	SF	1968 Building- Counsellor's Room, 1st Floor Offices, 1st and 2nd Floor Storage Rooms, Vault and Lunchroom Storage Room		Miscellaneous	No	None	0		YES	XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
17	9"x9" Gray Floor Tile Mastic	1450	SF	1968 Building- Counselor's Room, 1st Floor Offices, 1st and 2nd Floor Storage Rooms, Vault and Lunchroom Storage Room		Miscellaneous	No	None	0		YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Pink Floor Tile	1050	SF	1st Floor Stage Storage Room, Room 101		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Pink Floor Tile Mastic	1050	SF	1st Floor Storage Room, Room 101		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: Other
Comments:new tile
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Tan Floor Tile	1200	SF	1968 Building- Rooms 103, 208, 213, Engineer's Office 156, Locker Room 157, Closet 158 and All Gender Bathroom		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Tan Floor Tile Mastic	600	SF	1968 Building- Rooms 103, 208, 213, Engineer's Office 156, Locker Room 157, Closet 158 and All Gender Bathroom		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Beige Floor Tile- DUPLICATE of HA 05	5670	SF	1st and 2nd Floor Corridors and Lunchroom		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

VFT = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Beige Floor Tile Mastic- DUPLICATE of HA 06	5670	SF	1st and 2nd Floor Corridors and Lunchroom		Miscellaneous	No	None	0		

2022 Fall Circ Manth Currier No Change
2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Black Floor Tile	3515	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:blue and beige speckle
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12"Black Floor Tile Mastic	3515	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:blue and beige speckle
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Black Vinyl Baseboard	320	LF	School Offices		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

ſ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	27	Black Vinyl Baseboard Mastic	320	LF	School Offices		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Blue Carpet Mastic	1000	SF	School Offices and Library (Carpet removed in Room 209 and 211)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change							
Comments:							
2023 Fall Six Month Survey: No Change							
Comments:							
2023 Spring Six Month Survey: No Change							
Comments:							
2024 Spring Six Month Survey: No Change							
Comments:Same							
2024 Fall Six Month Survey: No Change							
Comments:							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Brown Carpet Mastic	700	SF	Main Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:blue and beige speckle
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Insulation in Fire Rated Doors	2	EA	1937 Building- Boiler Room		TSI	No	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:SFD
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" White w/Blue, Red & Yellow Specks Floor Tile	1700	SF	1968 Building- Room 209, 211		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change							
Comments:							
2023 Spring Six Month Survey: No Change							
Comments:							
2023 Fall Six Month Survey: No Change							
Comments:							
2024 Spring Six Month Survey: No Change							
Comments:Same							
2024 Fall Six Month Survey: No Change							
Comments:							

HA No	0	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31M		12"x12" White w/Blue, Red & Yellow Specks Floor Tile Mastic	1700	SF	1968 Building- Room 209, 211		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey No Change
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	White with Black Terrazzo	900	SF	1968 Building- NE and SE Stairwells, Lobby		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33		Green Mosaic Ceramic Tile Grout ABATED			1968 Building- 1st and 2nd Floor Boys and Girls Washrooms		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Green Mosaic Ceramic Tile Adhesive ABATED			1968 Building- 1st and 2nd Floor Boys and Girls Washrooms		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:grey tile

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Yellow Mosaic Ceramic Tile Grout	170	SF	1968 Building- 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:grey tile
2024 Fall Six Month Survey: No Change
Comments:

VFT = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.* Oracle Unit: 26601 Page 21

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Yellow Mosaic Ceramic Tile Adhesive	170	SF	1968 Building- 1st and 2nd Floor Teachers Washrooms, Office Restroom, 101 and 103 Restrooms		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:grey tile
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Plaster Ceiling	1800	SF	Boiler Room, All Washrooms, 1st and 2nd Floor Storage Rooms		Surface	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2004 October O', Marth Oraca, Databat
2024 Spring Six Month Survey: Repaired
Comments:drywall ceiling
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Brown Mosaic Ceramic Tile Grout	230	SF	1968 Building- North, South and East Vestibules		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:grey tile
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Brown Mosaic Ceramic Tile Adhesive	230	SF	1968 Building- North, South & East Vestibules		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:grey tile
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" Light Brown Floor Tile	6800	SF	1937 Building- Throughout 1st Floor		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey Other
2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:Scheduled for Demo
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40M	12"x12" Light Brown Floor Tile Mastic	6800	SF	1937 Building- Throughout 1st Floor		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Spring Six Month Survey: Other
Comments:SFD
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Brown Mosaic Ceramic Tile Grout	800	SF	1937 Building- 1st Floor Vestibules, Boys and Girls Washrooms		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:SFD
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Brown Mosaic Ceramic Tile Adhesive	800	SF	1937 Building- 1st Floor Vestibules, Boys and Girls Washrooms		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:SFD
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Mag Pipe Insulation	30	LF	1937 Building- Boiler Room		TSI	Yes	None	0		

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:SFD
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Hard Fittings on Fiberglass	30	LF	1937 Building- Boiler Room		TSI	Yes	None	0		

2020 E-II Oin Marth Outran Other
2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:SFD
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	0	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45		2'x4' White Fissured Ceiling Tile	45000	SF	1968 Building- Throughout		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
Comments.
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

Н	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	46	9"x9" Blue Vinyl Floor Tile	25	SF	1968 Building- 2nd Floor Janitor's Closet		Miscellaneous	No	Loc	1		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47		9"x9" Blue Vinyl Floor Tile Mastic	25	SF	1968 Building- 2nd Floor Janitor's Closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	2'x4' White Ceiling Tile	3500	SF	1968 Building- Lunchroom, Faculty Lunchroom, Room 103		Miscellaneous	Yes	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Repaired
Comments:serving line floor is has now have blue tile
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12"x12" Beige w/Tan Specks Vinyl Floor Tile	400	SF	1968 Building- Room 134		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12"x12" Beige w/Tan Specks Vinyl Floor Tile Mastic	400	SF	1968 Building- Room 134		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Yellow Rubber Tile Mastic	350	SF	1968 Building- Room 101 Kindergarten		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:new rubber tile
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Aircell Pipe Insulation NOT OBSERVED	200	LF	1937 Building Basement		TSI	Yes	Dist	10		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:SFD
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

H	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
в	3	MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED	25	LF	Building 1937- Basement		TSI	Yes	None	0		

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Spring Six Month Survey: Other
Comments:SFD
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Manth Survey No Change
2024 Fall Six Month Survey: No Change
Comments:

ſ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	D	MJP E/F/V on Fiberglass Pipe Insulation ABATED			2nd Floor Boiler Room, 1st Floor Fan Room		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е		MJP E/F/V on Fiberglass Pipe Insulation - Duplicate	345	LF	1st Floor Storage Room, 1st Floor Pipe Chases for Boy's and Girl's Bathrooms		TSI	Yes	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Cardboard Pipe Insulation NOT OBSERVED	200	LF	Building 1937- Tunnel Area		TSI	Yes	Loc	0		

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:SFD
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned

ſ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	I	Cementitous Duct Insulation NOT OBSERVED	150	SF	Building 1937- Basement		TSI	Yes	None	0		

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Spring Six Month Survey: Other
Comments:SFD
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Vibration Dampener NOT OBSERVED	10	LF	Fan Room, Pipe Chase, 2nd Floor Boiler Room		TSI	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	Furnace Gasket Insulation NOT OBSERVED	5	LF	Building 1937- Basement		TSI	Yes	None	0		X YES NO

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Other
Comments:SFD
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

ŀ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	-	MJP E/F/V on Paperwrap Pipe Insulation NOT OBSERVED	15	LF	Building 1937- Basement		TSI	Yes	None	0		

2022 Fall Six Month Survey: Other
Comments:soon to be demo
2023 Spring Six Month Survey: Other
Comments:SFD
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Inaccessible
Comments:abandoned
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Pipe Joints NOT OBSERVED	20	LF	Primary Building- 2nd Floor Boiler Room and Fan Room		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Ν	Duct Wrap	150	SF	Primary Building- 2nd Floor Boiler Room and Fan Unit		TSI	Yes	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations		Miscellaneous		Unknown			YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: Abated
Comments:NEW CONSTRUCTION
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:Same
2024 Fall Six Month Survey: No Change
Comments:
I

VFT = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.* ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	William E B Dubois Elementary School
Date:	10/31/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.

Asbestos surveillances are conducted every six months.

CHECK ONE

X A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.