Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Edison Park Elementary School 28081 2220 School: **Oracle Unit: Building ID:** Address: 6220 Olcott Region: 01 Mail Room: Asbestos Surveyor: Baez, Esteban X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/27/2024 Email Address: A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other Website Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type YES 01 Hard Coat Plaster 0 X NO Throughout 1948 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

03	9"x9" Brown w/ Orange Streaks VFT	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Cha	ange]						
Comments:	Month Garvey. 140 Gil	arigo									
2023 Fall Six Month Survey: No Change											
Comments:	Monar Carvey. No Cris	arigo			-						
2023 Spring	Six Month Survey: No	Change			_						
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Cha	ange									
Comments:	•	-]						
]						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Beige w/ Brown Specks VFT	3500	SF	Main Office (under existing flooring), 1st & 2nd Floor Corridors, Rooms 103, 206 - 1948 building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

05	2'x2' Acoustic Ceiling Tile	0		Room 102, 104, 1948 Removed							YES	X NO
2022 Fall S	ix Month Survey: No Ch	ange										
Comments												
	ix Month Survey: No Ch	ange										
Comments					_							
	g Six Month Survey: No	Change										
Comments					_							
	g Six Month Survey: No	Change										
Comments					_							
	ix Month Survey: No Ch	ange										
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

TIANO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Туре	Quantity	Units	Onlange in Asses	Silletti Oatogory
07	9"x9" Brown w/ Orange Streaks VFT Mastic	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES	X NO
2022 Fall	Six Month Survey: No Ch	ange]							
Commen	Comments:]							
2023 Fall Six Month Survey: No Change]								
Commen	Comments:											

2023 Spring Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Beige w/ Brown Specks VFT Mastic	3500	SF	Main Office (under existing flooring), 1st & 2nd Floor Corridors, Room 103, 206 - 1948 building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Beige w/ Brown Specks VFT	900	SF	1st & 2nd Floor Corridors, 1954		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

11	12"x12" Beige w/ Brown Specks VFT Mastic	900	SF	1st & 2nd Floor Corridors, 1954		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	nange]							
Comments:					1							
2023 Fall Six	Month Survey: No Ch	nange			_							
Comments:					-							
2023 Spring	Six Month Survey: No	Change										
Comments:					-							
	Six Month Survey: No	Change										
Comments:					-							
	Month Survey: No Ch	nange										
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

None

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

2022 Fall Six	Month Survey: No Cha	ange	
Comments:			
2023 Fall Six	Month Survey: No Cha	ange	
Comments:			
2023 Spring S	Six Month Survey: No (Change	
Comments:			
2024 Spring S	Six Month Survey: No (Change	
Comments:			
2024 Fall Six	Month Survey: No Cha	ange	
Comments:			

700

SF

HA No

12

Material Description

Linoleum Under 12"x12"

Gray VFT

Material

Quantity

Material

Units

Material Location

Room 107, 1954

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
14	Hard Coat Plaster	0		Throughout 1954							YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
	Month Survey: No Ch	ange										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Duct Vibration Isolators	8	SF	Fan Room, 1948		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	nent Category
16	2'x2' Tectum Ceiling Tile			Gym, 1948							YES		X NO
2022 Fall Six	Month Survey: No Ch	ange											
Comments:													
2023 Fall Six	Month Survey: No Ch	ange											
Comments:	_												
2023 Spring S	Six Month Survey: No	Change											
Comments:													
2024 Spring S	Six Month Survey: No	Change											
Comments:													
2024 Fall Six Comments:	Month Survey: No Ch	ange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Orange w/ Beige Streaks VFT	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:	
2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	
2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Fall Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change	2024 Spring Six Month Survey: No Change
	Comments:
Comments:	2024 Fall Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Orange w/ Beige Streaks VFT Mastic	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	1'x2' Black VFT	20	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	1'x2' Black VFT Mastic	20	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES X NO
2022 Fall Civ	Month Curron No Ch										

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" White w/ Beige Specks VFT	2250	SF	Main Office & Rooms 202, 200A & 200B, Room 103 1948		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
22	12"x12" White w/ Beige Specks VFT Mastic	2250	SF	Main Office & Rooms 202, 200A & 200B, Room 103 1948 Bldg.		Miscellaneous	No	None	0		YES	X NO
	-	•		•	•	•	-	•	•			

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Gray w/ White & Gray Specks VFT	1800	SF	1st floor corridor near Room 107 (replacement), Rm 107 (under existing flooring), 109 - 1954 building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Gray w/ White & Gray Specks VFT	1800	SF	1st floor corridor near Room 107 (replacement), Rm 107 (under existing flooring), 109 - 1954 building.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Tan w/ Brown Specks VFT	60	SF	Teacher's Toilet, 1954		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Tan w/ Brown Specks VFT Mastic	60	SF	Room 107 Toilet & Teacher's Toilet, 1954		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:	
2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	
2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Fall Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change	2024 Spring Six Month Survey: No Change
	Comments:
Comments:	2024 Fall Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
27	12"x12" Dark Brown w/ Cream Streaks VFT - Removed			107 Store Room, 1954 - Removed		Miscellaneous	No				YES	X NO
2022 Fall S	ix Month Survey: No C	hange		•		•			•	•		
Comments												
2023 Fall S	ix Month Survey: No C	hange										
Comments												
2023 Sprin	g Six Month Survey: No	Change			-							
Comments												
2024 Sprin	g Six Month Survey: No	Change			_							
Comments												
					I							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Dark Brown w/ Cream Streaks VFT Mastic - removed			107 Storeroom, 1954 - removed		Miscellaneous	No				YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Beige w/ Cream & Brown Streaks VFT	2750	SF	Rooms 211, & 209, Rm 109 (under exisring floor tile)1954		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Beige w/ Cream & Brown Streaks VFT Mastic	2750	SF	Rooms 109 (under existing floor tile), 211, & 209, 1954		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
31	12"x12" White VFT	20	SF	Room 111 Countertop, 1954-		Miscellaneous	No	None			YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" White VFT Mastic	20	SF	Room 111 Countertop - 1954 Building		Miscellaneous		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

		Quantity	Units		Type	Category		Туре	Quantity	Units		
33	2'x4' Speckled Ceiling Tile			Throughout 1948			Yes				YES	X NO
	Month Survey: No Cha	ange										
Comments:					_							
2023 Fall Six	Month Survey: No Cha	ange]							
Comments:												
2023 Spring S	ix Month Survey: No (Change			-							
Comments:												
2024 Spring S	ix Month Survey: No (Change										
Comments:												
2024 Fall Six	Month Survey: No Cha	ange			-							
Comments:												

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	2'x4' Speckled Ceiling Tile	9000	SF	Throughout 1954		Miscellaneous	Yes	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
35	Light Gray w/ Black Streaks Linoleum - Removed	0		Room 211 Countertop, 1954 Removed		Miscellaneous					YES	X NO
2022 Fall Six I	Month Survey: No Cha	ange										
	Month Survey: No Cha	ange										
Comments:												
2023 Spring S	Six Month Survey: No (Change										
Comments:												

2024 Spring Six Month Survey: No Change

Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Light Gray w/ Black Streaks Linoleum Mastic - Removed			Room 211 Countertop, 1954 Removed		Miscellaneous	No				YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
37	Exterior Window Caulk - Removed			Throughout 1948 - Removed		Miscellaneous	Yes	None			YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
- Commonico.
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" White w/ Tan Spots VFT	1400	SF	Room 109; 111 (under HA#47) - 1954 Building		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" White w/ Tan Spots VFT Mastic	1400	SF	Room 109; 111 (under HA#47), 1954		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" White w/ Black & Grey Streaks VFT	50	SF	MDF Room (In Library Room 207), 1954		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" White w/ Black & Grey Streaks VFT Mastic	50	SF	MDF Room (In Library Room 207), 1954		Miscellaneous	No	None	0		YES X NO
											_

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Gray & Tan VFT	50	SF	1st and 2nd floors near elevator, 1948		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Gray & Tan VFT Mastic	50	SF	1st and 2nd floors near elevator, 1948		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0004 0 1 0 1 0 1 0
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12"x12" Tan w/Cream Streaks VFT	50	SF	First and Second Floor Near Elevator, 1948		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" Tan VFT w/cream Stks Mastic	50	SF	1st and 2nd Floors Near Elevator, 1948		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12"X 12" Lt. Beige Floor Tile	850	SF	Room 111, 1954		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12"X 12" Lt. Beige Floor Tile MASTIC	850	SF	Room 111, 1954		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Carpet Mastic	1500	SF	Rms 207, 208 (1954 Bldg)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Drywall, Tape, and Compounds	1000	SF	Rms 207, 208 (1954 Bldg)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Vinyl Baseboard Mastic	150	LF	Rms 207, 208, 107 (1954 Bldg)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
52	Terrazzo	1200	SF	Stairwells (1948 Bldg)		Miscellaneous	No	None	0		YES	X NO
2022 Fall S	ix Month Survey: No C	hange										
	g Six Month Survey: No	Change										
Comments:	:											
2023 Fall S	ix Month Survey: No C	hange										

Comments:

2024 Spring Six Month Survey: No Change Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Terrazzo	600	SF	Stairwells (1954 Bldg)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Carpet Mastic	200	SF	Principal's Office (1948 Bldg)		Miscellaneous	No	None	0		YES X NO
					i						_

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12"x12" brown and white VFT	800	SF	Room 206 (under existing flooring) - 1948 building		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55A	12"x12" brown and white VFT MASTIC	800	SF	Room 206 (under existing flooring) - 1948 building		Miscellaneous	No	None	0		YES X NO
				1	1						<u>.</u>

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	2' x 2' White Textured Ceiling Tile	1400	SF	Rms. 102 and 104		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

57	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	57		750		Northwest connecting corridor hallway to new		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Н	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	57A	12" x 12" Orange splotched VFT /w Mastic	750	SF	Classrooms #102, 104 + Northwest connecting corridor hallway to new Annex building		Miscellaneous	No	None			YES X NO

Classroom #102, 104 + Northwest hallway to new Miscellaneous No None		
58 12 x 12 Yellow splotched 750 SF Northwest hallway to new Miscellaneous No None None	one YES	X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2004 Fall Cir. Manth Common No Observe
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58A	12" x 12" Yellow splotched VFT /w Mastic	750	SF	Classrooms #102, 104 + Northwest connecting hallway to new annex building		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Black tape pipe wrap insulation - Removed			#105 Classroom + Bathroom #106, Basement 1948 Bldg Removed		TSI	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	1' x 1' White ceiling tile	600	SF	#207 MDF room inside #207 library *above 2' x 4' white ceiling tile grid - 1954 Annex bldg.		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Glue puck Associated with new HA#60 - 1' x 1' Ceiling Tile	600	SF	MDF Room or #207 Library *Above 2' x 4' White C.T. Grid - 1954 Annex bldg.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

62	Sink undercoating - Sprayed on (black)	6	SF	Room #211 1954 Bldg.		Miscellaneous	No	None			YES	X NO
2022 Fall S	ix Month Survey: No C	hange			7							
Comments:		-]							
2023 Spring	g Six Month Survey: No	Change			-							
Comments:					1							
2023 Fall S	ix Month Survey: No C	hange										
Comments:		-										
2024 Spring	g Six Month Survey: No	Change										
Comments:												
2024 Fall S	ix Month Survey: No C	hange										
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
63	Cloth electricla wire insulation (Inside wall	100	LF	1st + 2nd floor mens (Boys) + ladies (Girls) Bathrooms, inside wall		Miscellaneous	No	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

	heater)			heat units 1954 Bldg.							
0000 5-11 0	Martin Orana Na Ob										
2022 Fall Six Month Survey: No Change											
Comments:	Comments:										
2023 Spring \$	2023 Spring Six Month Survey: No Change										
Comments:											
2023 Fall Six	Month Survey: No Cha	ange									
Comments:											
2024 Spring S	Six Month Survey: No (Change									
Comments:											
2024 Fall Six	Month Survey: No Cha	ange									
Comments:											

HA No

Material Description

Material

Units

Material

Quantity

Material Location

64	12 x 12 Sand VFT	1200	SF	Rm 107, storage closet & toilet - 1954 Addition		Miscellaneous	No	None			YES	X NO
2022 Fall \$	Six Month Survey: No Cl	nange										
	Comments:											
2023 Fall \$	Six Month Survey: No Cl	nange										
Comments		•										
2023 Sprir	ng Six Month Survey: No	Change										
Comments	S:											
2024 Fall S	Six Month Survey: No Cl	nange										
Comments	S:	_										
2024 Sprir	ng Six Month Survey: No	Change										
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
C4A	40 · 40 C 1 VET M+-	4000	0.5	Rm 107, storage closet &		Minnellandon	NI-	Nana				Ty. I. a

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

Material Location

toilet - 1954 Addition

Rm 107, storage closet &

1200

SF

HA No

64A

Material Description

12 x 12 Sand VFT Mastic

Material

Quantity

Material

Units

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12 x 12 Sand VFT	150	SF	1st floor corridor by Rm 104, 1st Floor boy's & girl's restrooms (entry vestibules) - 1948 Building		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65A	12 x 12 Sand VFT Mastic	150	SF	1st floor corridor by Rm 104, 1st Floor boy's & girl's restrooms (entry vestibules) - 1948 Building		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Paperwrap Pipe Insulation	2	LF	1st & 2nd Floor Boys Toilet Pipe Chases, 1948		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units	3	
D	MJP E/F/V on Paperwrap Pipe Insulation	17	LF	1st & 2nd Floor Boys Toilet Pipe Chases, 1948		TSI	Yes	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:		J										
2023 Spring	Six Month Survey: No	Change			-							
Comments:					1							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:	•				1							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Aircell Pipe Insulation	20	LF	1st & 2nd Floor Boy's Toilet Pipe Chases, 1948		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
L	Blown-In Insulation	0		Attic, 1948							YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	•	•										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	·			·								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	2" Fiberglass Insulation	0		Attic, 1948							YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Edison Park Elementary School
Date: 11/27/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. Website
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 28081

SCHOOL'S ASBESTOS MANAGEMENT PLAN.