Chicago Public Schools

6 Month Asbestos Surveillance

2024 Fall Six Month Survey

| | School: Address: | Gerald Delgado Kanoon Elementary Magnet So 2233 S. Kedzie | chool | Oracle Unit: Region: | 29071 03 | Building ID: Mail Room: | |
|-----------|---------------------|--|---------------------------|--------------------------------|----------------|----------------------------|--|
| | | | Asbestos Surveyor: | Jafar, Mohammad | | | |
| X CHECK I | HERE IF I | NO CHANGE TO ASBESTOS | Survey Date: | 10/15/2024 | | | |
| | | | Email Address: | msjafar@cps.k12.il.us | | | |
| | | | | | | | |
| Γ | A copy of t | he2022/2023 notice to parents and staff regard | ling the asbestos managen | nent plan notifications was di | stributed via: | | |

| | Each child's backpa | ck | Notice | printed in school's new | sletter | X Notice prin | nted in scho | ool's calendai | . Oth | er | | |
|----------------------------|---------------------------------------|----------------------|-------------------|-------------------------|------------------|----------------------|--------------|----------------|--------------------|-----------------|---------------|------------------|
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Ass | essment Category |
| 1 | 2' x 4' Ceiling tile | | | Throughout building | | Miscellaneous | | | | | YES | X NO |
| 2022 Fall Six | Month Survey: No Ch | ange | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2023 Fall Six | 2023 Fall Six Month Survey: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2023 Spring | Six Month Survey: No | Change | | | _ | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| 2024 Spring | Six Month Survey: No | Change | | | _ | | | | | | | |
| Comments: | <u> </u> | 0 | | | | | | | | | | |
| 2024 Fall Six Comments: | Month Survey: No Ch | ange | | | - | | | | | | | |
| | | | | | _ | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 2 | Spray-on fire proofing | | | Throughout school | | Surface | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2004 Fall Ois Marth Osmann Na Ohan sa |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 3 | 12" x 12" Beige w/ Brown Specks Floor Tile | 30000 | SF | Throughout building in all classrooms and hallways except washrooms | | Miscellaneous | No | Loc | 2 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 4 | 12" x 12" Beige w/Brown Specks Floor Tile Mastic | 30000 | SF | Throughout building | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|---------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 5 | Baseboard | | | Throughout building | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|---------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 6 | Baseboard mastic | | | Throughout building | | Miscellaneous | | | | | |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| , o |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 7 | Vault door insulation | 60 | SF | Main Office (Room 100D/Storage), Room 218 | | TSI | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 8 | Transite counter top | 150 | SF | Science Lab (Room 201) | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 9 | Vibration Collar (isolation cloth) | 100 | LF | Ductwork throughout building - mechanical areas | | Miscellaneous | No | None | 0 | LF | |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 10 | Hard plaster on walls & ceiling | | | Small Gym (Handball Court) | | Surface | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey No Change |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 11 | 2' x 4' Metal covered ceiling tile | | | Throughout classrooms on the 1st & 2nd floors | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 12 | Duct interior lining | | | Mechanical/Fan Rooms | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 13 | Folding doors cloth cover | | | Rooms 120 &122 | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| ſ | HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---|-------|-----------------------|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| | 14 | Black pipe insulation | | | Mechanical/Fan Rooms | | TSI | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|---------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 15 | Duct exterior insulation | | | Mechanical/Fan Room | | TSI | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 16 | Interior window caulk | | | Throughout school | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2004 Fall Ois Marth Osmann Na Ohan sa |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 17 | Exterior window caulk - Non-AHERA | | | Exterior of building | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 18 | Exterior window glaze - Non-AHERA | | | Exterior of building | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 19 | Lower Roof Field - Non- AHERA | | | Lower roof | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 20 | Lower Roof Flashing - Non- AHERA | | | Lower roof | | Miscellaneous | | | | | YES X NO |

| - |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 21 | Upper Roof Field - Non- AHERA | | | Upper roof | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 22 | Upper Roof Flashing - Non- AHERA | | | Upper roof | | Miscellaneous | | | | | YES X NO |

| - |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 23 | Stage lights electrical insulation | 20 | LF | Auditorium | | TSI | No | None | 0 | LF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| ſ | HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| | 24 | Carpet mastic | | | | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 25 | Sink coating | 135 | SF | 200, 201, 202, 204, 206, 208, 210, 212, 205, 214, 218, 220, 222,223, 224, 226,105,108, 110, 112, 114, 116, 118,120,122 | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.* Oracle Unit: 29071 Page 13

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 26 | 12" x 12" White w/Blue Specks Floor Tile | 2400 | SF | Room 105,112,118 | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 27 | 12" x 12" White w/Blue Specks Floor Tile Mastic | 2400 | SF | Room 105, 112, 118 | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| · · · · |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|----------------------|-------------------|-----------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 28 | 12" x 12" Blue Speckled Floor Tile | | | Room 105, 112, 118, and 212 | | Miscellaneous | | | | | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-----------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 29 | 12" x 12" Blue Speckled Floor Tile Mastic | | | Room 105, 112, 118, and 212 | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 30 | Beige ceramic floor tile grout | 4000 | SF | All 1st and 2nd Floor Bathrooms, 1st Floor Janitors Closets, and Kitchen Area | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2023 Fall Six Month Survey: Other |
| Comments:remodeled,2023 |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 31 | Brown ceramic baseboard grout | 600 | LF | All 1st and 2nd Floor Bathrooms, 1st Floor Janitors Closets, and Kitchen Area | | Miscellaneous | No | None | 0 | LF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2023 Fall Six Month Survey: Other |
| Comments:remodeled,2023 |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

VFT = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.* Oracle Unit: 29071 Page 16

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|--------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 32 | Interior door caulk | 1280 | LF | All door on 1st and 2nd floors | | Miscellaneous | No | None | 0 | LF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: Other |
| Comments:remodeled,2023 |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 33 | Burgandy carpet mastic | 4600 | SF | Main Office, Conf Room, Faculty Lounge, Asst Prin Office, Rooms 106C and D, Student Services, | | Miscellaneous | No | None | 0 | SF | |

| Comments: 2023 Spring Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: Other Comments:remodeled,2023 | |
|---|---|
| 2023 Spring Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: Other Comments:remodeled,2023 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change | 2022 Fall Six Month Survey: No Change |
| Comments: 2023 Fall Six Month Survey: Other Comments:remodeled,2023 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change | Comments: |
| Comments: 2023 Fall Six Month Survey: Other Comments:remodeled,2023 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change | |
| 2023 Fall Six Month Survey: Other Comments:remodeled,2023 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change | 2023 Spring Six Month Survey: No Change |
| Comments:remodeled,2023 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change | Comments: |
| Comments:remodeled,2023 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change | |
| 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change | 2023 Fall Six Month Survey: Other |
| Comments: 2024 Fall Six Month Survey: No Change | Comments:remodeled,2023 |
| Comments: 2024 Fall Six Month Survey: No Change | |
| 2024 Fall Six Month Survey: No Change | 2024 Spring Six Month Survey: No Change |
| | Comments: |
| | |
| Comments: | 2024 Fall Six Month Survey: No Change |
| | Comments: |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 34 | 4" Black vinyl baseboard | 600 | LF | Assembly Hall, 1st and 2nd Floor Corridors | | Miscellaneous | No | None | 0 | LF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 35 | 4" Black vinyl baseboard adhesive | 600 | LF | Assembly Hall, 1st and 2nd Floor Corridors | | Miscellaneous | No | None | 0 | LF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Manth Survey No Change |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 36 | Wall expansion joint caulk | 300 | LF | Assembly Hall | | Miscellaneous | No | None | 0 | LF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 37 | Drywall ceiling | 400 | SF | Room 221 | | Miscellaneous | Yes | None | 0 | SF | YES X NO |

| 2022 Fall Six Marth Survey No Change |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 38 | Drywall ceiling joint compound | 50 | SF | Room 221 | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 39 | Drywall ceiling joint tape | 32 | LF | Room 221 | | Miscellaneous | No | None | 0 | LF | YES X NO |

| 2022 Fall Six Marth Survey No Change |
|---|
| 2022 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 40 | 12" x 12" beige speckled floor tile (patch) | | | 2nd Floor Hall outside room 234 and Stairs | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| I | HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---|-------|---|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| | 41 | 12" x 12" beige speckled floor tile (patch) | | | 2nd Floor Hall outside room 234 and Stairs | | Miscellaneous | | | | | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 42 | Gray skid pad covering adhesive | 25 | SF | Elevator | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 43 | Ceramic wall tile grout | 20 | SF | Janitors Closets | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| Comments. |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 44 | Ceramic wall tile adhesive | 20 | SF | Janitor's Closets | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 45 | Gray carpet adhesive | 4000 | SF | Assembly Hall | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| Comments. |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HAN | 10 | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-----|----|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 46 | | 12" x 12" Gray w/Dark Gray Streaks Vinyl Floor Tile | 3300 | SF | Rooms 116,120,122 | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 47 | 12" x 12" Gray w/Dark Gray Streaks Vinyl Floor Tile Mastic | 3300 | SF | Rooms 116,120,122 | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 48 | 12" x 12" Beige w/White Streaks Vinyl Floor Tile | 2740 | SF | Room 208, 210, 212, 214, 226 | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 49 | 12" x 12" Beige w/White Streaks Vinyl Floor Tile Mastic | 740 | SF | Room 208, 210, 212, 214, 226 | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 50 | 12" x 12" Red Vinyl Floor Tile | 30 | SF | Room 212 | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HAI | No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-----|----|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 51 | | 12" x 12" Red Vinyl Floor Tile Mastic | 30 | SF | Room 212 | | Miscellaneous | No | Loc | 2 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 52 | Gray patterned carpet mastic | 1430 | SF | Room 225(Library) | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| ŀ | HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---|-------|--|----------------------|-------------------|-------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 5 | 53 | 12" x 12" White w/ Gray Specks Floor Tile | 500 | SF | Room 222, 220, 200, 234 | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 54 | Mastic for 12" x 12" White w/ Gray Specks Floor Tile | 500 | SF | Room 222, 220, 200, 234 | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 55 | 12" x 12" White w/ Brown Specks Floor Tile | 200 | SF | Room 221B, 2nd floor corridor, 201, 104 (principal office, 1st floor corridor, | | Miscellaneous | No | None | 0 | SF | |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 56 | Mastic for 12" x 12" White w/ Brown Specks Floor Tile | 200 | SF | Room 221B, 2nd floor corridor, 201, 104 (principal office), 1st floor corridor | | Miscellaneous | No | None | 0 | SF | |

| 2022 Fall Six Month Survey: No Change | |
|---|--|
| Comments: | |
| | |
| 2023 Spring Six Month Survey: No Change | |
| Comments: | |
| 2023 Fall Six Month Survey: No Change | |
| Comments: | |
| 2024 Fall Six Month Survey: No Change | |
| Comments: | |
| 2024 Spring Six Month Survey: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 57 | 12" x 12" Light Gray w/ Dark Gray & White Specks Floor Tile | 2000 | SF | Rooms 106, 100 | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 58 | Mastic for 12" x 12" Light Gray w/ Dark Gray & White Specks Floor Tile | 2000 | SF | Rooms 106, 100 | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change | |
|---|--|
| Comments: | |
| | |
| 2023 Fall Six Month Survey: No Change | |
| Comments: | |
| 2023 Spring Six Month Survey: No Change | |
| Comments: | |
| 2024 Fall Six Month Survey: No Change | |
| Comments: | |
| 2024 Spring Six Month Survey: No Change | |
| Comments: | |

| HA | A No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----|------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 59 | 9 | 12" x 12" Tan w/ Dark Gray & Brown Floor Tile | 55 | SF | Lunchroom | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 60 | Mastic for 12" x 12" Tan w/ Dark Gray & Brown Floor Tile | 55 | SF | Lunchroom | | Miscellaneous | No | None | 0 | SF | YES XNO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 61 | Tongue and groove wooden floor | 1000 | SF | Gymnasium, small gym | | Miscellaneous | No | None | 0 | SF | YES X NO |

| 2022 Fall Six Month Survey: No Change |
|---|
| Comments: |
| |
| 2023 Fall Six Month Survey: No Change |
| Comments: |
| 2023 Spring Six Month Survey: No Change |
| Comments: |
| |
| 2024 Fall Six Month Survey: No Change |
| Comments: |
| |
| 2024 Spring Six Month Survey: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| В | Hard Joint Compound on Fiberglass Pipe Runs | | | Throughout school (above ceiling tiles) | | Miscellaneous | | | | | YES XNO |

| 2022 Fall Six Month Survey: No Change | | | | |
|---|--|--|--|--|
| Comments: | | | | |
| | | | | |
| 2023 Fall Six Month Survey: No Change | | | | |
| Comments: | | | | |
| | | | | |
| 2023 Spring Six Month Survey: No Change | | | | |
| Comments: | | | | |
| | | | | |
| 2024 Spring Six Month Survey: No Change | | | | |
| Comments: | | | | |
| | | | | |
| 2024 Fall Six Month Survey: No Change | | | | |
| Comments: | | | | |
| | | | | |

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

| School: | Gerald Delgado Kanoon Elementary Magnet School |
|---------|--|
| Date: | 10/15/2024 |

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.

Asbestos surveillances are conducted every six months.

CHECK ONE

| opy of this notice was sent home in each child's backpack. |
|--|
|--|

A copy of this notice was printed in the school's newsletter and sent home with each child

X A copy of this notice was printed in the school's calendar and sent home with each child

Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.