Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Oracle Unit:

31121

Address: 4316 S. Princeton Region: Mail Room: Asbestos Surveyor: Casa, Anthony X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/3/2024 Email Address: apcasa@cps.k12.il.us A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other Email Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Category Quantity Type Type 12" x 12" Beige (Tan) Floor Lunchroom, lunchroom YES X NO Miscellaneous 2022 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

Thomas A Hendricks Elementary Community Academy

School:

3930

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
1M	12" x 12" Beige (Tan) Floor Tile Mastic			Lunchroom and lunchroom storage		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:	•	<u> </u>										
2023 Fall Six	Month Survey: No Ch	ange			1							
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	•											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	Cove base black			Lunchroom		Miscellaneous					YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	1' x 1' Ceiling Tile	3250	SF	Lunchroom		Miscellaneous	Yes	None	0	SF	YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3M	1' x 1' Ceiling Tile Mastic	3250	SF	Lunchroom; 1srt, 2nd, 3rd floor corridors		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12" x 12" Tan Floor Tile	15000	SF	102,104,106,108,110,202 , 206,208,212,302,304,308 ,312,310,main office, assembly hall, 2nd & 3rd floor corridors		Miscellaneous	No	Loc	16	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4M	12" x 12" Tan Floor Tile Mastic	21600	SF	102,104,106,108,110,202 ,206,208,212,302,304, 308,312,310,main office, assembly hall, 2nd & 3rd floor corridors		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Plaster	25000	SF	Throughout		Surface	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	12" x 12" Dark Gray Floor Tile	21000	SF	2nd fl women's washroom, 101, 103, 105, 107, 201, 203, 205, 207, 307 311		Miscellaneous	No	Loc	7	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 31121

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6M	12" x 12" Dark Gray Floor Tile Mastic	21000	SF	2nd fl women's washroom, 101, 103, 105, 107, 201, 203, 205, 207, 307, 311		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	12" x 12" Beige Floor Tile	390	SF	Doorways of Rooms 101, 103, and 104		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

7M	12" x 12" Beige Floor Tile Mastic	390	SF	Doorways of Rooms 101, 103, and 104		Miscellaneous	No	None	0	SF	YES	X NO
					1							
2022 Fall Six	Month Survey: No Cha	ange										
Comments:	•											
2023 Fall Six	Month Survey: No Cha	ange										
Comments:	•											
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Cha	ange										
Comments:	•	-										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	2' x 4' Hanging Ceiling			Gym		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category	Type	Quantity	Units		
9	1' x 1' Ceiling Tile			Library		Miscellaneous				YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange									
2023 Fall Six Comments:	Month Survey: No Ch	ange									
	Six Month Survey: No	Change									
Comments:					_						
2024 Spring S	Six Month Survey: No	Change			-						
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									
Comments:		•									

Material

Damage

Damage

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	1' x 1' Ceiling Tile	2100	SF	Auditorium		Miscellaneous	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12" x 12" Brown Floor Tile	450	SF	1st, 2nd, 3rd Floor Corridor Perimeter		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11M	6" x 12" Brown Floor Tile Mastic	450	SF	1st, 2nd, 3rd floor Corridor Perimeter		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	TSI on Pipe w/ Metal Cover	80	LF	Girl's 2nd Floor and Girl's and Boy's 1st Floor Bathrooms		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	TSI on Valve Coupler/20" Pipe	54	SF	Boiler Room		TSI	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

14	TSI on <4" Valves	5	LF	Boiler Room		TSI	Yes	None	0	LF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
	Month Survey: No Ch	ange										
Comments:												
	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
	Month Survey: No Ch	ange										
Comments:												

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Tsi pipe cover (12" pipe)	450	LF	Hall/Passageway Fan Room, air tunnel, basement storage rooms, boiler room		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Tsi 12" pipe elbows/fittings	46	LF	Hall/Passageway Fan Room, air tunnel, basement storage rooms, boiler room		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	TSI Cardboard insulationSmall Pipe Elbows/Fittings	30	LF	Boiler Room and Passageway		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

10/110	Waterial Bescription	Quantity	Units	Waterial Eddalon	Type	Category	THADIO	Type	Quantity	Units	Change in 7,55cc	omoni Galogory
18	Tsi cardboard insulation	375	LF	Boiler Room and Passageway		TSI	Yes	None	0	LF	YES	X NO
2022 Fall S	Six Month Survey: No C	hange										
Comments	S:											
2023 Fall S	Six Month Survey: No C	hange										
Comments	S:											
2023 Sprin	ng Six Month Survey: No	Change										
Comments	S:											
2024 Sprin	ng Six Month Survey: No	Change										
Comments	S:											
2024 Fall S	Six Month Survey: No C	hange										
Comments	S:											

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Tsi 4" valves	10	LF	Boiler and Air Tunnel		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Tsi small pipe/covers	400	LF	Air Tunnel		TSI	Yes	None	0	LF	YES X NO
					-						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Tsi cardboard insulation	300	LF	Air Tunnel		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	TSI on Small Pipes	28	LF	Air Tunnel		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0004 0 1 0 1 0 1 0
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Tsi boiler coverings	2000	SF	Boiler Room		TSI	Yes	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
24	TSI In Boiler by Doors			Boiler Room		TSI					YES	X NO
2022 Fall S Comments:	x Month Survey: No C	nange										
2023 Fall Si Comments:	x Month Survey: No C	hange										
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall S Comments:	x Month Survey: No C	hange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Boiler gasket			Boiler Room		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
26	Refractory brick			Boiler Room		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	nange			7							
Comments:	•				1							
2023 Fall Six	Month Survey: No Ch	nange										
Comments:	•	_										
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Roof flashing - Non-AHERA			Roof		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
28	Exterior brick - Non-AHERA			Building Exterior		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Cha	ange										
Comments:	•	<u> </u>										
2023 Fall Six	Month Survey: No Cha	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
	Month Survey: No Cha	ange										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Exterior mortar - Non- AHERA			Building Exterior		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Chalk board/poster board adhesive	300	SF	All classrooms		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
31	12" x 12" Tan w/White Specks Floor Tile	775	SF	Room 301		Miscellaneous	No	Loc	7	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Tan w/White Specks Floor Tile Mastic	775	SF	Room 301		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
33	12" x 12" Dark Green w/Tan Floor Tile	1000	SF	Room 204		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
34	12" x 12" Dark Green w/Tan Floor Tile Mastic	1000	SF	Room 204		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change												
Comments:					<u> </u>							

2023 Spring Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Interior Material of Incinerator			Boiler Room		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36	Vault door	28	SF	Office		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Month Survey: No Change												
Comments:												
2023 Fall Si	x Month Survey: No C	hange										
Comments:												
2023 Spring Six Month Survey: No Change												
Comments:												

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	9" x 9" Beige w/ Brown Streaks Floor Tile			Hallway outside 314 and 302, 311-312		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
38	9" x 9" Beige w/ Brown straks Floor Tile Mastic	20	SF	Hallway outside 311 and 312.		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2000 Fall O' Marth O and No Observe
2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0000 F II 0' M (I 0 N O
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Sink under coating			Room 312		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
40	Aircell pipe insulation			Room 204 under lab sinks.		TSI				YES	X NO
2022 Fall Six	Month Survey: No Ch	nange									
Comments:											
2023 Fall Six	Month Survey: No Ch	nange									
Comments:											
2023 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Ch	ange			1						

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Vibration dampers	6	LF	2nd floor mechanical space (fan Room #2) and fan room in lunchroom		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

42	Cork board wall panels adhesive	300	SF	2nd floor mechanical space		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
<u> </u>					J							

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Blue Floor Tile	1500	SF	Hallyway by 311, elevator vestibules, stage vestibule, 104 washroom, basm't passage, 211		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Blue Floor Tile Mastic	1500	SF	Hallyway by 311, elevator vestibules, stage vestibule, 104 washroom, basm't passage, 211		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	4" Dark Blue baseboard	270	LF	Hallyway by 311, elevator vestibules, stage vestibule, 104 washroom, basm't passage		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	4" Dark Blue baseboard Mastic	270	LF	Hallyway by 311, elevator vestibules, stage vestibule, 104 washroom, basm't passage		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Mag pipe insulation	70	LF	2nd floor mechanical room		TSI	Yes	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

TIANO	Waterial Description	Quantity	Units	Material Location	Type	Category	Thable	Type	Quantity	Units	Change in Asses	Sameric Category
48	Fittings on Mag pipe insulation	30	LF	2nd floor mechanical room		TSI	Yes	None	0	LF	YES	X NO
2022 Fall S Comments:	ix Month Survey: No Cl	nange										
2023 Fall S Comments:	ix Month Survey: No Cl	nange										
2023 Spring Comments:	g Six Month Survey: No	Change										
2024 Spring Comments:	g Six Month Survey: No	Change										
2024 Fall S Comments:	ix Month Survey: No Cl	nange										
L												

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Gray W/Black Dot linoleum	3600	SF	Room 305, 306, 303		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Page 29

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49M	Gray W/Black Dot linoleum Mastic	3600	SF	Room 305, 306, 303		Miscellaneous	No	None	0	SF	YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
, v
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Blue carpet mastic	2100	SF	Library		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	3' x 3' rubber floor white w/black	1625	SF	Lunchroom and lunchroom Storage		Miscellaneous	No	None	0	SF	YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51M	3' x 3' rubber floor adhesive	3250	SF	Lunchroom and lunchroom storage		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
52	3' x 3' rubber floor blue w/white	1925	SF	Lunchroom, lunchroom storage, and lunchroom manager office		Miscellaneous	No	None	0	SF	YES	X NO
		•	•				•	•	•	•		

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0000 F # 01 H
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52M	3' x 3' rubber floor blue w/white adhesive	3250	SF	Lunchroom, lunchroom storage, and lunchroom manager office		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" x 12" Cream W/Tan Floor Tile	4214	SF	Main office, principal office, washroom, 1st floor hallway, and hallway by the gym		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
Comments.
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53M	12" x 12" Cream W/tan Floor Tile Mastic	4214	SF	Main office, principal office, washroom, 1st floor hallway, and hallway by the gym		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
54	Terrazo	900	SF	Stairs and Landings		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange				·				•		
Comments:												
2023 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring Comments:	Six Month Survey: No	Change										
	Six Month Survey: No	Change										
Comments:												
2024 Fall Six Comments:	Month Survey: No Ch	ange										

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	2' x 2' Off-White w/ Specks Floor Tile	200	SF	Room 104, 102		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Page 34

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	2' x 2' Light Blue w/ Specks Floor Tile	200	SF	Room 104, 102		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0004 0 1 0 1 0 1 0
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	2' x 2' Light Gray w/ Specks Floor Tile	600	SF	Room 104, 102		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	2' x 2' Off-White, Light Blue, and Light Gray w/ Specks Floor Tile Mastic	1000	SF	Room 104, 102		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Tongue and Groove Wood Floor	1000	SF	Auditorium Stage, Gym		Surface	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Thomas A Hendricks Elementary Community Academy
Date: 12/3/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. Email
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 31121

SCHOOL'S ASBESTOS MANAGEMENT PLAN.