

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2024 Fall Six Month Survey

**School:** Charles Kozminski Elementary Community Academy  
**Address:** 936 E. 54th St.

**Oracle Unit:** 31151  
**Region:** 04

**Building ID:** 4390  
**Mail Room:** 46

☐ **CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Durham, Dwayne  
**Survey Date:** 11/6/2024  
**Email Address:** ddurham7@cps.edu

A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

☐ *Each child's backpack* ☐ *Notice printed in school's newsletter* ☐ *Notice printed in school's calendar* ☒ *Other* | **EMAIL**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                                       |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------------------------------------------------------------|
| 001 A | Plaster Walls and Ceilings |                   |                | 1896 Building     |               | Surface           |         |             |                 |              | <input checked="" type="checkbox"/> <b>YES</b>   <input type="checkbox"/> <b>NO</b> |

|                                             |
|---------------------------------------------|
| 2022 Fall Six Month Survey: Other           |
| Comments: NEW FLOOR TILE                    |
|                                             |
| 2023 Spring Six Month Survey: Other         |
| Comments: Elevator in rm 002, 102, 202, 302 |
|                                             |
| 2023 Fall Six Month Survey: Damaged         |
| Comments: OUTSIDE RM 307                    |
|                                             |
| 2024 Spring Six Month Survey: No Change     |
| Comments:                                   |
|                                             |
| 2024 Fall Six Month Survey: No Change       |
| Comments:                                   |
|                                             |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 31151

Page 1

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 001 B | Plaster Walls and Ceilings |                   |                | 1927 Building     |               | Surface           |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location                                                                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|-------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 A | 12" x 12" White Floor Tile w/ Gray Streaks | 34500             | SF             | Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways |               | Miscellaneous     | No      | Loc         | 3               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Other       |
| Comments:REPLACED FLOOR TILE IN 302     |
|                                         |
| 2023 Spring Six Month Survey: Other     |
| Comments:Elevator in rm 002,102,202,302 |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Repaired    |
| Comments:SOME FLOOR REPLACED            |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 B | 12" x 12" Brown Floor Tile | 20                | SF             | Closet Across from 303 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 C | Tile Beneath 12" x 12" Brown Floor Tile | 20                | SF             | Closet Across from 303 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 D | 12" x 12" Multi-Brown Floor Tile | 1738              | SF             | Rooms 106 and 208 |               | Miscellaneous     | No      | Dist        | 50              | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 E | 12" x 12" Black Floor Tile | 1440              | SF             | Auditorium        |               | Miscellaneous     | No      | Loc         | 50              | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 F | 12" x 12" Brown Floor Tile | 1440              | SF             | Auditorium        |               | Miscellaneous     | No      | Loc         | 100             | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 G | 12" x 12" Black Floor Tile w/White Streaks | 1400              | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLE FLOOR TILE                 |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 H | 12" x 12" White Floor Tile | 800               | SF             | Room 311          |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 I | 12" x 12" Light Brown Floor Tile | 80                | SF             | Engineer's Office |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 003 J | 12" x 12" White Floor Tile | 80                | SF             | Engineer's Office |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description                             | Material Quantity | Material Units | Material Location                                                                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------------|-------------------|----------------|-------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 004   | 12" x 12" White Floor Tile w/Gray Streaks Mastic | 34500             | SF             | Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways |               | Miscellaneous     | No      | Loc         | 20              | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Other       |
| Comments:REPLACED FLOOR TILE IN 202     |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: Other     |
| Comments:Elevator in rm 002,102,202,302 |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 005   | 12" x 12" Brown Floor Tile Mastic | 20                | SF             | Closet Across from 303 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 006   | Floor Tile Mastic For Tile Beneath 12" x 12" Brown | 20                | SF             | Custodial Closet Across From 303 |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Other       |
| Comments:REPLACED FLOOR TILE            |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 007   | 12" x 12" Multi-Brown Floor Tile Mastic | 1738              | SF             | Rooms 208 and 106 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 008   | 12" x 12" Black Floor Tile Mastic | 620               | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 008 B | 12" x 12" Tan Floor Tile | 100               | SF             | 2nd Floor Lobby   |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 008 C | 12" x 12" Tan Floor Tile<br>Mastic | 100               | SF             | 2nd Floor Lobby   |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 009   | 12" x 12" Brown Floor Tile Mastic | 1440              | SF             | Auditorium        |               | Miscellaneous     | No      | Loc         | 20              | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Fall Six Month Survey: Damaged     |
| Comments:needs replacing                |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD MASTIC                     |
|                                         |

| HA No | Material Description                              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 010   | 12" x 12" Black Floor Tile w/White Streaks Mastic | 620               | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Fall Six Month Survey: Damaged     |
| Comments:needs replacing                |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 011   | 12" x 12" White Floor Tile Mastic |                   |                | Room 311          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |

| HA No | Material Description                    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 012   | 12" x 12" Light Brown Floor Tile Mastic |                   |                | Engineer's Office |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 013   | 12" x 12" White Floor Tile Mastic |                   |                | Engineer's Office |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 014   | Cementitious Patches on Walls |                   |                | Boiler Room       |               | Surface           |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 015   | Large stone mortar   |                   |                | Boiler Room and Coal Room |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: No Change    |
| Comments:NO CHANGE                       |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

| HA No | Material Description     | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 016   | 6" Black vinyl baseboard |                   |                | Throughout Facility |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 017   | 6" Black vinyl baseboard mastic |                   |                | Throughout Facility |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

| HA No | Material Description | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 018   | 4" Black baseboard   |                   |                | Throughout Classrooms |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 019   | 4" Black baseboard mastic |                   |                | Throughout Classrooms |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 020   | 4" Gray vinyl baseboard |                   |                | Room 311          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: No Change    |
| Comments:NO CHANGE                       |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 021   | 4" Gray vinyl baseboard mastic |                   |                | Room 311          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: No Change    |
| Comments:NO CHANGE                       |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 022   | Interior brick       |                   |                | Basement          |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:NO CHANGE                       |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 023   | Interior brick mortar |                   |                | Basement          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: No Change    |
| Comments:NO CHANGE                       |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 024   | Cinder block mortar  |                   |                | Basement          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: No Change    |
| Comments:NO CHANGE                       |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 025   | Window glazing       |                   |                | Throughout 1896 Construction |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 026   | Window glazing       |                   | LF             | Throughout 1928 Construction |               | Miscellaneous     |         |             |                 | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 027   | Material Beneath 12"x12" Floor Tile | 725               | SF             | Room 004 (Parents Room) |               | Miscellaneous     | No      | Loc         | 20              |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                            |
|--------------------------------------------|
| 2022 Fall Six Month Survey: Damaged        |
| Comments:DAMAGED                           |
|                                            |
| 2023 Fall Six Month Survey: No Change      |
| Comments:                                  |
|                                            |
| 2023 Spring Six Month Survey: Deteriorated |
| Comments:Floor tile                        |
|                                            |
| 2024 Fall Six Month Survey: Damaged        |
| Comments:OLD FLOOR TILE                    |
|                                            |
| 2024 Spring Six Month Survey: No Change    |
| Comments:                                  |
|                                            |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 27    | Material Beneath 12" x 12" Floor Tile | 725               | SF             | Room 004 (Parents Room) |               | Miscellaneous     | No      | Loc         | 15              | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                            |
|--------------------------------------------|
| 2022 Fall Six Month Survey: Damaged        |
| Comments:DAMAGED                           |
|                                            |
| 2023 Spring Six Month Survey: Deteriorated |
| Comments:Floor tile                        |
|                                            |
| 2023 Fall Six Month Survey: Damaged        |
| Comments:needs replacing                   |
|                                            |
| 2024 Spring Six Month Survey: No Change    |
| Comments:                                  |
|                                            |
| 2024 Fall Six Month Survey: Damaged        |
| Comments:OLD FLOOR TILE                    |
|                                            |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 028   | Material beneath floor tile |                   |                | Room 106          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: Damaged     |
| Comments:needs replacing                |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 029   | Orange floor leveler |                   |                | Auditorium        |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 030   | 2' x 4' Ceiling Panels |                   |                | Room 311          |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 031   | 1' x 1' Ceiling Tiles | 800               | SF             | Room 310          |               | Miscellaneous     | Yes     | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:BROKEN                         |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 032   | Terrazzo wall panels |                   |                | Bathrooms Throughout Facility |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description  | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 033   | Finished brick mortar |                   |                | Throughout Facility |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 034   | Tan ceramic tile grout |                   |                | Bathrooms and Rear Exit |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:BROKEN                          |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description           | Material Quantity | Material Units | Material Location                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 035   | Tan & brown ceramic tile grout | 400               | SF             | Bathrooms & Hall by Student Lunchroom |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 036   | Terrazzo             |                   |                | 1928 Stairways & Corridors |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 037   | Brown & tan terrazzo |                   |                | Auditorium Entry & Stairs |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 038   | Green terrazzo       |                   |                | Auditorium and Vestibule |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:OLD FLOOR TILE                 |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description                  | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 039   | Insulation over fiberglass insulation | 10                | LF             | Boiler Room on Wall by Sink |               | TSI               | Yes     | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:OLD FLOOR TILE                 |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                               | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 040   | Wrap on Insulation Over Fiberglass Pipe Insulation | 4                 | LF             | Boiler Room on Wall by Sink |               | TSI               | Yes     | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:LOOSE                          |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 041   | Drywall              |                   |                | Room 210 and 211  |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:BROKEN                         |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                         | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 042   | Gray window caulk    |                   |                | Throughout Building as Patches on Windows |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 043   | Brown chalkboard     |                   |                | Classroom 310     |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                                                                           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------|-------------------|----------------|---------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 044   | Black slate material behind marker board | 210               | SF             | Classrooms Under Beneath Various Marker Boards Including Those in Rooms 104, 106, 108 & 109 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 045   | Asphalight flooring  |                   |                | 1896 Stairs and Landings |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 046   | Brown carpet mastic  |                   |                | Kitchen Office    |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: Other       |
| Comments:replaced                       |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 46    | Brown carpet mastic  |                   |                | Kitchen Office    |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: Other       |
| Comments:replaced                       |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 047   | Brown carpet mastic  | 100               | SF             | Office            |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 048   | Purple carpet mastic | 500               | SF             | Room 103          |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 049   | 2" Square ceramic tile grout | 160               | SF             | Boy's Bathrooms Under Urinals |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 050   | Fire Brick in Incinerator | 150               | SF             | Boiler Room       |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Other       |
| Comments:Down,not in use                |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 051   | Fire door insulation | 408               | SF             | Entrances, Exits, Boiler Room |               | TSI               | Yes     | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: Damaged     |
| Comments:NOT IN USE                     |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 052   | Exterior brick mortar - Non-AHERA |                   |                | 1896 Building     |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 053   | Exterior brick - Non-AHERA |                   |                | 1896 Building     |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 054   | Exterior brick mortar - Non-AHERA |                   |                | 1928 Building     |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:LOOSE                           |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 055   | Exterior brick - Non-AHERA |                   |                | 1928 Building     |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:LOOSE                           |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 056   | Exterior window caulk - Non-AHERA |                   |                | 1928 Building     |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:LOOSE                           |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 057   | Flashings on Roof B - Non-AHERA |                   |                | Third Elevation Roof |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description          | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 058   | Flashing on Roof C- Non-AHERA |                   |                | Third Elevation Roof |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 059   | Roof a core - Non-AHERA |                   |                | Third Elevation Roof |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description  | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 060   | Roof core - Non-AHERA |                   |                | Second Elevation Roof |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 061   | Roof flashing - Non-AHERA |                   |                | Second Elevation Roof B |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description      | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 062   | Roof flashing - Non-AHERA |                   |                | Second Elevation Roof C |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 063   | Roof core - Non-AHERA |                   |                | Second Elevation Roof C |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description  | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 064   | Roof core - Non-AHERA |                   |                | Second Elevation Roof D |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 065   | Roof flashing - Non-AHERA |                   |                | Second Elevation Roof D |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:DAMAGED                         |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 066   | Roof sealant - Non-AHERA |                   |                | 1896 Building     |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:NEEDS REPLACING                 |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 067   | Roof sealant- Non-AHERA |                   |                | 1928 Building     |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments:NEEDS REPLACING                 |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description      | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 068   | Roof flashing - Non-AHERA |                   |                | First Elevation Roof F |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Deteriorated |
| Comments: NEEDS RELACING                 |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 069   | Roof core - Non-AHERA |                   |                | First Elevation Roof F |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description      | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 070   | Roof flashing - Non-AHERA |                   |                | First Elevation Roof E |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 071   | Roof tile - Non-AHERA |                   |                | First Elevation Roof E |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description     | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 072   | Roof sealant - Non-AHERA |                   |                | First Elevation Roof |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 073   | Roof tile - Non-AHERA |                   |                | Roof B            |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 074   | Roof tile - Non-AHERA |                   |                | Roof D            |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description  | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 075   | Roof tile - Non-AHERA |                   |                | Roof 7            |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 076   | Exterior window caulk - Non-AHERA |                   |                | 1896 Building     |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:DETERIORATED                    |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                        | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 080   | 12" x 12" Beige Floor Tile w/ White Streaks | 500               | SF             | Rooms 202, 301, and 308 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: Other     |
| Comments:Elevator in rm 002,102,202,302 |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 081   | 12" x 12" Beige Floor Tile w/ White Streaks Mastic | 150               | SF             | Rooms 202, 301, and 308 |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: Other     |
| Comments:Elevator in rm o2,1o2,2o2,302  |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 082   | Lab Counter and Sink | 50                | SF             | Room 303          |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description        | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-----------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 083   | 1' x 1' Ceiling Tile Mastic | 50                | SF             | Music Room (Room 310) |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 084   | 12" x 12" Black w/Gray Specks Floor Tile (Patch) | 55                | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 085   | 12" x 12" Black w/Gray Specks Floor Tile Mastic | 55                | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 086   | 2"x1' black border tile | 170               | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DAMAGED                        |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 087   | 2"x1' black border tile mastic | 170               | SF             | Auditorium        |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Damaged     |
| Comments:DA,MAGED                       |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location                   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 088   | Blackboards          | 5000              | SF             | 006, 008, 101-104, 106-109, 201-210 |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description          | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 089   | 12" x 12" Gray Mix Floor Tile |                   |                | Material Not Present |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:OLD FLOOR TILE                  |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                 | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 090   | 12" x 12" Gray Mix Floor Tile Mastic |                   |                | Material Not Present |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:OLD FLOOR TILE                  |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description                       | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 091   | 12" x 12" Beige w/Gray Speckles Floor Tile |                   |                | Material Not Present |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:OLD FLOOR TILE                  |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                              | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 092   | 12" x 12" Beige w/Gray Speckles Floor Tile Mastic |                   |                | Material Not Present |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                          |
|------------------------------------------|
| 2022 Fall Six Month Survey: Deteriorated |
| Comments:OLD                             |
|                                          |
| 2023 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |
| 2023 Fall Six Month Survey: No Change    |
| Comments:                                |
|                                          |
| 2024 Fall Six Month Survey: Damaged      |
| Comments:OLD FLOOR TILE                  |
|                                          |
| 2024 Spring Six Month Survey: No Change  |
| Comments:                                |
|                                          |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 093   | Sink undercoating    | 15                | SF             | Room 006          |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Other       |
| Comments:REPLACED                       |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 094   | 12" x 12" White/Gray Mix Floor Tile | 900               | SF             | Room 202          |               | Miscellaneous     | No      | None        | 0               | SF           | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Other       |
| Comments:ABATED/REPLACED                |
|                                         |
| 2023 Spring Six Month Survey: Other     |
| Comments:Elevator in rm 002,102,202,302 |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 095   | 12"x12" White/Gray Mix Floor Tile Mastic | 900               | SF             | Room 202          |               | Miscellaneous     | No      | Loc         | 100             |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Other       |
| Comments:ABATED/REPLACED                |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: Other     |
| Comments:Elevator in rm 002,102,202,303 |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                       | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|--------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 95    | 12" x 12" White/Gray Mix Floor Tile Mastic |                   |                | Room 202          |               | Miscellaneous     |         |             |                 |              | <input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: Other       |
| Comments:ABATED/REPLACED                |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: Other     |
| Comments:Elevator in rm 002,102,202,302 |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description                     | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 096   | 12" x 12" Beige w/Red Streaks Floor Tile | 535               | SF             | Room 301, South Door Vestibule |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                            | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 097   | 12" x 12" Beige w/Red Streaks Floor Tile Mastic | 535               | SF             | Room 301, South Door Vestibule |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 098   | Blue carpet adhesive | 200               | SF             | Main Office       |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                 | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 099   | 12" x 12" Gray w/ Dark Gray/White Streaks Floor Tile | 150               | SF             | Kitchen office    |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description                                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 100   | Mastic w/ 12" x 12" Gray w/ Dark Gray/White Streaks Floor Tile | 150               | SF             | Kitchen Office    |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 101   | Blackboard adhesive  | 5000              | SF             | Classrooms        |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 102   | Gray carpet adhesive | 500               | SF             | Room 310          |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                   | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 103   | 9" x 9" Tan w/ Black Specks Floor Tile | 87                | SF             | Vault in Main Office |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description                                        | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 104   | Mastic Associated w/ 9" x 9" Tan w/ Black Specks Floor Tile | 87                | SF             | Vault in Main Office |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| 105   | Wood flooring        | 800               | SF             | Room 104          |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description       | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| A     | Fiberglass pipe insulation |                   |                | Throughout Building |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                            | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| B     | Joint Insulation off Fiberglass Pipe Insulation | 240               | LF             | 1896 Construction, 1927 Building |               | TSI               | Yes     | Loc         | 7               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

| HA No | Material Description      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|---------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| C     | Cardboard pipe insulation | 160               | LF             | Basement Tank Room |               | TSI               | Yes     | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                           | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|------------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| D     | Joint Insulation off Cardboard Pipe Insulation | 20                | LF             | Tank Room         |               | TSI               | Yes     | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description    | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| E     | Aircell pipe insulation | 1500              | LF             | Basement          |               | TSI               | Yes     | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                         | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| F     | Joint Insulation off Aircell Pipe Insulation | 100               | LF             | Basement          |               | TSI               | Yes     | None        | 0               | LF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description | Material Quantity | Material Units | Material Location           | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|-----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| G 1   | Boiler insulation    |                   |                | Boiler Room by Outside Door |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|----------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| G 2   | Boiler insulation    |                   |                | Boiler Room by Inside Door |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

| HA No | Material Description    | Material Quantity | Material Units | Material Location                                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category                                         |
|-------|-------------------------|-------------------|----------------|--------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-----------------------------------------------------------------------|
| K     | Glue under rubber floor | 3000              | SF             | Kitchen, Lunchroom, West Lunchroom Entrance Hall |               | Miscellaneous     | No      | None        | 0               | SF           | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                                         |
|-----------------------------------------|
| 2022 Fall Six Month Survey: No Change   |
| Comments:NO CHANGE                      |
|                                         |
| 2023 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |
| 2023 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Fall Six Month Survey: No Change   |
| Comments:                               |
|                                         |
| 2024 Spring Six Month Survey: No Change |
| Comments:                               |
|                                         |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

A handwritten signature in black ink, appearing to read "Richard J. Schleyer", written in a cursive style.

---

Richard J. Schleyer

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Charles Kozminski Elementary Community Academy

Date: 12/6/2024

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.  
Asbestos surveillances are conducted every six months.

CHECK ONE

- ☐ A copy of this notice was sent home in each child's backpack.
- ☐ A copy of this notice was printed in the school's newsletter and sent home with each child
- ☐ A copy of this notice was printed in the school's calendar and sent home with each child
- ☒ Other. EMAIL
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***