Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

	Address: 4320 W.		1 & Science	Community Acad ES			egion:	03	21	Buildir Mail Re	
X CHEC	CK HERE IF NO CH	ANGE TO	O ASBE	STOS Survey	os Surveyor: Date: ddress:			_			
	A copy of the2022/202	23 notice to	parents and	staff regarding the asl	bestos manag	ement plan no	tifications w	as distribute	d via:		
	Each child's backpa	ack	Notice	orinted in school's new	sletter	Notice pri	inted in sch	ool's calenda	r Ot	her	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
001.1	Wall/ceiling plaster			Throughout the 1890 building		Surface					YES X NO
2022 Fall S	Six Month Survey: No Cl	nange									
Comments):										
2023 Sprin Comments	ng Six Month Survey: No s:	Change									
2023 Fall S	Six Month Survey: No Cl	nange									
Comments		90									
	ng Six Month Survey: No	Change									
Comments	S:				=						

001.2	Wall/ceiling plaster			Throughout the 1912 building		Surface					YES	X NO
2022 Fall (Civ. Month Cuminus No. C	h a m m a			_							
	Six Month Survey: No C	nange										
Comments	S:											
2023 Sprir	ng Six Month Survey: No	Change										
Comments	S:											
2023 Fall \$	Six Month Survey: No C	hange										
Comments	3:											
2024 Sprir	ng Six Month Survey: No	Change										
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
000.4				Lunch Room.1890								

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Throughout the 1912

Building

Material

Quantity

Material

Units

HA No

002.1

Material Description

1' x 1' Ceiling Tile

YES

X NO

002A.1	1' x 1' Acoustic Ceiling Tile			Lunch Room, 1890 Building		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No Ch	ange			1							
Comments:]							
2023 Spring	g Six Month Survey: No	Change										
Comments:					_							
2023 Fall S	ix Month Survey: No Ch	ange										
Comments:					_							
2024 Spring	g Six Month Survey: No	Change										
Comments:					_							
L					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
			1									

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

013.1

Material Description

2' x 4' Acoustic Ceiling Tiles

2022 Fall Six Month Survey: No Change

Material

Units

Material Quantity Material Location

Lunch Room, 1890

Room 334, 1890 Building

Change in Assessment Category

X NO

YES

YES

	1110										
2022 Fall \$	Six Month Survey: No C	hange]						
Comments		<u> </u>									
2023 Sprir	ng Six Month Survey: No	Change									
Comments	3:										
2023 Fall \$	Six Month Survey: No C	hange									
Comments	3:										
2024 Sprir	ng Six Month Survey: No	Change									
Comments	3:										
					<u> </u>						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
016.1	Window caulk groop			Teacher's Lounge, Room		Miscollangous					Tyre I Tylio

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Yes

Damage

Туре

None

Damage

Quantity

0

Damage

Units

SF

HA No

013.2

016.1

Material Description

2' x 4' Acoustical Ceiling

Window caulk, green

Material

Quantity

750

Material

Units

SF

Material Location

131, 1890 Building

Room 335, 1912 Building

Change in Assessment Category

X NO

X NO

YES

YES

016.2	Window caulk			Building		Miscellaneous					YES	X NO
2022 Fall	Six Month Survey: No C	hange			1							
Comments	,				1							
2023 Sprir	ng Six Month Survey: No	o Change										
Comments	3:											
2023 Fall	Six Month Survey: No C	hange			<u> </u>							
Comments	S:				_							
	ng Six Month Survey: No	o Change										
Comments	S:				-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
017.1	Masonry brick			Tank Room, Boiler		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2022 Fall Six Month Survey: No Change

Material

Quantity

Material

Units

Material Location

Throughout Interior 1912

Room, 1912 Building

017.2	Masonry brick mortar			Engine Room, 1912 Building		Miscellaneous					YES	X NO
2022 Fall :	Six Month Survey: No C	hange			\neg							
Comments	•											
2023 Sprir	ng Six Month Survey: No	c Change										
Comments	S:											
2023 Fall	Six Month Survey: No C	hange										
Comments	S:											
2024 Sprir	ng Six Month Survey: No	o Change										
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
018.1	Masonry mortar			Tank Room, Boiler Room, 1890 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Room, 1890 Building

Material

Units

Material Quantity

HA No

Material Description

018.2	Masonry brick wall			Engine Room, 1912 Building		Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No C	nange			7							
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
	x Month Survey: No C	nange]							
Comments:					1							
2024 Spring	Six Month Survey: No	Change]							
Comments:					_							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
019.1	Wood wall board			Basement Stairwell, 1890		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Building

Material

Units

Material Quantity

HA No

Material Description

019.2	Wood wall board			Room 124, 1912 Building		Miscellaneous					YES X NO	
2022 Fall S	Six Month Survey: No C	hange			1							
Comments	:											
	g Six Month Survey: No	o Change										
Comments	:				-							
	Six Month Survey: No C	hange										
Comments	:				-							
2024 Sprin	g Six Month Survey: No	o Change										
Comments	:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	/
020.1	Cinder block			Tank Room, Boiler		Miscellaneous					YES X NO	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

Room, 1890 Building

HA No

Material Description

020.2	Cinder block			Store Room Across From Assembly Hall, 1912 Building		Miscellaneous					YES	X NO
2022 Fall 9	Six Month Survey: No C	hange			1							
Comments		rialigo			Ī							
	ng Six Month Survey: N	o Change			_							
Comments	3:				_							
	Six Month Survey: No C	hange]							
Comments	S:											
2024 Sprin	ng Six Month Survey: No	o Change			-							
Comments	5:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
021.1	Cinder block morter			Tank Room, Boiler		Missellaneous					Dyro I	V NO

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Description

Cinder block mortar

Material

Quantity

Material

Units

Material Location

Room, 1890 Building

Store Room Across From

HA No

021.1

YES

X NO

021.2	Cinder block mortar			Storeroom Across From Assembly Hall, 1912 Building		Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No C	hongo		·	· 7							
	x Month Survey. No C	nange			_							
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:	-											
					1							
2023 Fall Si	x Month Survey: No C	hange										
Comments:	Transfer Carrey 110 C	90			†							
Comments.					-							
2024 Caring	Six Month Survey: No	Change			+							
	Six Month Survey. No	Change										
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		3. 7
				Teacher's Lounge, 1st								

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

HA No

022.1

Comments:

Comments:

Comments:

Comments:

Drywall

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material Description

Material

Units

Material

Quantity

Material Location

Floor Slop Sink, 1890

Building

YES

X NO

Change in Assessment Category

Damage

Units

022.2	Drywall			Room 120 and 223, 1912 Building		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No Ch	ange			1							
Comments:		ange			-							
2023 Spring	g Six Month Survey: No	Change										
Comments:												
2023 Fall S	ix Month Survey: No Ch	ange			_							
Comments:	·]							
2024 Spring	g Six Month Survey: No	Change			_							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
023.1	12" x 12" Light Gray w/Brown and White Streaks			Lunch Room, 1890		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

Floor Tile 2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Comments:

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

Building

Change in Assessment Category

Damage

Units

		Quantity	Units		Туре	Category		Type	Quantity	Units		
023.3	12" x 12" Brown Floor Tile w/Dark Brown & White Streaks	800	SF	Room 137, 1890 Building		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall S	ix Month Survey: No Ch	ange	•	•]		•	•	•	•	•	
Comments:	-	arige										
2023 Spring	g Six Month Survey: No	Change										
Comments												

Material

Friable

Damage

Damage

Damage

Comments:

2023 Fall Six Month Survey: No Change
Comments:

Material

Material Location

2024 Spring Six Month Survey: No Change

Material Description

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
023.4	12" x 12" Beige w/White & Brown Floor Tile	15000	SF	1st, 2nd & 3rd Floor Corridors, 1912 Building		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

023.5	12"x 12" Cream Flecks w/ Tan Specks Floor Tile	200	SF	Engineer's Office, 1890 Building		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:	•	J			- -							
2023 Spring	Six Month Survey: No	Change			_							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange			_							
Comments:					-							
2024 Spring	Six Month Survey: No	Change										
Comments:					-							
					J							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
024.1	12" x 12" Light Gray w/Brown & White Floor Tile Mastic			Lunch Room, 1890 Building		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	024.2	Mastic assoc. W/ 12" x 12" Tan Flecks Floor Tile	700	SF	Room 221, 1912 Building		Miscellaneous	No	None	0	SF	YES X NO
2	2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
0004.0 ' 0' 14 4 0 14 0
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
024.3	12"x12: Brown w/Dark Brown Floor Tile Mastic	800	SF	Room 137, 1890 Building		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

024.4	Mastic assoc. W/12" x 12" Cream Flks w/Tan Spks Vinyl Floor Tile	200	SF	Engineer's Office, 1890 Building		Miscellaneous	No	None	0	SF	YES	X NO
	•	•	•		-			-	-			
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
024.5	12" x 12" Beige w/White & Brown Floor Tile Mastic	15000	SF	1st, 2nd & 3rd Floor Corridors, 1912 Building, 024		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

2024 Spring Six Month Survey: No Change

Material

Quantity

Material

Units

Material Location

025.1	Brown vinyl baseboard			Lunch Room,1890 Building		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No C	hange										
Comments:	-											
2023 Spring	g Six Month Survey: No	Change										
Comments:												
2023 Fall S	ix Month Survey: No C	hange										
Comments:					_							
2024 Spring	g Six Month Survey: No	Change										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
025.2	Light brown vinyl			Teacher's Lounge		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

baseboard

Comments:

Comments:

Comments:

Comments:

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Quantity

Material

Units

Material Location

026.1	Brown vinyl baseboard adhesive		Lunch Room, 1890 Building		Miscellaneous			YES	X NO
				1					
2022 Fall Six	Month Survey: No Ch	ange							
Comments:									
2023 Spring S	Six Month Survey: No	Change							
Comments:	-	_							
2023 Fall Six	Month Survey: No Ch	ango							
	Month Survey. No Ch	arige							
Comments:									
2024 Spring S	Six Month Survey: No	Change							
Comments:	•								

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
026.2	Light brown vinyl baseboard adhesive	80	LF	Teacher's Lounge		Miscellaneous	No	None	0	LF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

027.1	12" x 12" Vinyl Floor Tile, Tan Flecks w/Brown and White Specks	1576	SF	Lunchroom kitchen, 1890 Building		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		<u> </u>								
Comments:		J-										
2023 Spring 9	Six Month Survey: No	Change										
Comments:	Six Month Survey. 140	Orlange										
2022 Fall Six	Month Survey: No Ch	ango										
Comments:	Month Survey. No Ch	ange										
	O' Marth O a Ala	01										
Comments:	Six Month Survey: No	Change										
Comments.												
					1							

Type

Asbestos

Type

Material

Material

Category

Miscellaneous

Category

Friable

Friable

Damage

Damage

Type

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

VIIIIVITIOOTTIIC		
2022 Fall Six Month Survey: No Ch	ange	
Comments:		
2023 Spring Six Month Survey: No	Change	
Comments:		
2023 Fall Six Month Survey: No Ch	ange	
Comments:		
2024 Spring Six Month Survey: No	Change	
Comments:		

Material

Quantity

HA No

HA No

027.1M

Material Description

Material Description

Vinyl Floor Tile

Mastic assoc. W/ 12" x 12"

Tan Flks w/Brown & White

Material

Material

Units

Units

Material

Quantity

Material Location

Material Location

Lunchroom, Kitchen,

1890 Building

Change in Assessment Category

Change in Assessment Category

YES

X NO

027.2	Mastic assoc. W/12" x 12" Tan Flecks w/Brown & White Vinyl Floor Tile	Assembly Hall, Gym, 1912 Building	M	liscellaneous					YES	X NO
2022 Fall 5	Six Month Survey: No Change									
Comments										
2023 Sprir	ng Six Month Survey: No Change									
Comments	<u> </u>									
2023 Fall \$	Six Month Survey: No Change									
Comments	5:									
2024 Sprir	ng Six Month Survey: No Change									
Comments	S:									
			_							
HA No	Material Description Material	Material Material Location	Asbestos M	/laterial	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
027.2M	Mastic assoc. W/ 12" x 12" Tan Flks w/Brown & White Vinyl Floor Tile			Assembly Hall, Gym, 1912 Building		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:					-							
2022 Fall Civ	Month Currous No Ch	0000			1							

2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change

HA No

Comments:

Material Description

Mastic assoc. W/12" x 12"

Material

Units

Material Quantity Material Location

028.1	12" x 12" Vinyl Floor Tile, Beige Flecks w/Brown and White Specks	332	SF	Room 133, 1890 Building		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		<u> </u>]							
Comments:	monar carrey. Ne cri	arigo										
2023 Spring S	Six Month Survey: No	Change										
Comments:	Oix Monar Carvey: 140	Onlango										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:	•											
2024 Spring	Six Month Survey: No	Change										
Comments:												
					J							
	1			I and a state of					-			

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
028.1M	Mastic assoc. W/12" x 12" Beige Flecks w/Brown & White Vinyl Floor Tile			Room 133, 1890 Building		Miscellaneous					YES X NO
2022 Fall Six	x Month Survey: No Ch	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

028.2	12" x 12" Vinyl Floor TileMastic, Beige Flecks w/Brown & White Specks			2nd Floor Corridor, 1912 Building		Miscellaneous					YES	X NO
2022 Fall	Six Month Survey: No C	hange		<u>* </u>	, 						·	
Comment		90										
2023 Spri	ng Six Month Survey: No	Change			-							
Comment	s:											
2023 Fall	Six Month Survey: No C	hange										
Comment	S:											
2024 Spri	ng Six Month Survey: No	Change			=							
Comment	S:				=							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
028.21	Mastic assoc. W/12" x 12" Mastic assoc. W/12" x 12" Beige Flecks w/Brown & White Vinyl Floor Tile			2nd Floor Corridor, 1912 Building		Miscellaneous					YES	X NO
2022 F	Fall Six Month Survey: No C	hange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

12" x 12" Vinyl Floor TileMastic, Beige Flecks

Material

Quantity

Material

Units

Change in Assessment Category

029.1	Vinyl floor tile molding, brown			Room 133, 1890 Building		Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No C	hange										
Comments:	-	y -										
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2023 Fall Si	x Month Survey: No C	hange										
Comments:					_							
2024 Spring	Six Month Survey: No	Change										
Comments:												
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
029.2	Vinyl floor tile molding,			Assembly Hall, 1912		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

brown

Comments:

Comments:

Comments:

Comments:

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Units

Material

Quantity

Material Location

Building

Change in Assessment Category

Damage

Units

030.1	12" x 12" Vinyl Floor Tile, Brown w/Dark Brown and White Streaks			Room 137, 1890 Building, 234		Miscellaneous					YES	X NO
2022 Fall Six	K Month Survey: No Cl	nange	•	•	7	•	•	•	•	•	•	
Comments:	C MONITO COLVEY. NO CI	larige										
Commenter												
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2023 Fall Six	k Month Survey: No Ch	nange										
Comments:												
	Six Month Survey: No	Change										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

031.1	Beige w/Brown and White Streaks		1st Floor Corridor
2022 Fall Si	x Month Survey: No Ch	ange	
Comments:	•		
2023 Spring Comments:	Six Month Survey: No	Change	
2023 Fall Si	x Month Survey: No Ch	ange	
Comments:			
	Six Month Survey: No	Change	
Comments:			

Material

Units

Material

Quantity

Material Location

HA No

Material Description

12" x 12" Vinyl Floor Tile,

031.1M	Mastic assoc. W/ 12" x 12" Beige w/ Brown & White Vinyl Floor Tile			1st Floor Corridor		Miscellaneous					YES	X NO
2022 Fall Civ	· Manth Cumara Ala Ch		•]	•	•	•	•	•	•	
	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
LIA NI-	Material December	NA-C-2-1	Material	Material Land Con	A - I 1	Markani al	Establis	D	D	D	Observation Assessed	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
032.1	12" x 12" Vinyl Floor Tile, Light Beige w/Brown and White Streaks		SF	Room 233, 1890 Building		Miscellaneous				SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										

Comments:

2023 Spring Six Month Survey: No Change
Comments:

2023 Fall Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Units

Material Quantity

Material Location

032.1M	Mastic assoc. W/ 12" x 12" Light Beige w/Brown & White Vinyl Floor Tile			Room 223, 1890 Building		Miscellaneous					YES	X NO
2022 Fall Six	x Month Survey: No C	hange										
Comments:		90										
2023 Spring	Six Month Survey: No	Change										
Comments:	CIX WORLT CUIVEY. 140	, onange			1							
2023 Fall Siz	x Month Survey: No C	hange			_							
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:	,											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

033.1	Beige Flecks w/Brown and White Specks		2nd Floor Corridor, 1890 Building
2022 Fall	Six Month Survey: No Ch	ongo	
		ange	
Comments	S:		
2023 Fall	Six Month Survey: No Ch	ange	
Comments	S:		
2023 Sprir	ng Six Month Survey: No	Change	
Comments	S:		
2024 Sprir	ng Six Month Survey: No	Change	
Comments	S:		

HA No

Material Description

Mastic assoc. W/ 12" x 12"

12" x 12" Vinyl Floor Tile,

Material

Quantity

Material

Units

Material Location

2nd Floor Corridor, 1890

YES

X NO

033.1M	Mastic assoc. W/12" x 12" Beige Flks w/Brown & White Vinyl Floor Tile			2nd Floor Corridor, 1890 Building		Miscellaneous					YES	X NO
			•	•	7	•	•	•	•	· ·	•	
2022 Fall S	Six Month Survey: No C	hange										
Comments	•											
2023 Fall S	Six Month Survey: No C	hange			-							
Comments	·	nango			1							
	-											
2023 Sprin	g Six Month Survey: No	Change										
Comments												
0004.0	· O' Mardi O · · · Ni	01			4							
	g Six Month Survey: No	Change										
Comments	• •											
LIA NI-	Material December	Maradal	I Maradal	I Maradalla anda	A - I 1	I Marradal	Leadin			I B	Observation Assess	
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

YES

Material Location

1st, 2nd & 3rd Floor

Corridors, 1912 Building

2nd Floor Corridor, 1890

01100	110			
2022 Fall Six Mont	h Survey: No Ch	ange		
Comments:				
2023 Fall Six Mont	h Survey: No Ch	ange		
Comments:				
2023 Spring Six M	onth Survey: No	Change		
Comments:				
2024 Spring Six M	onth Survey: No	Change		
Comments:				

Quantity

Units

HA No

033.2

Material Description

Mastic assoc. W/12" x 12"

12" x 12" Vinyl Floor Tile,

Beige w/Brown and White

Streaks

Material

Quantity

Material

Units

Change in Assessment Category

X NO

33.2	Beige w/Brown and White Streaks		Corridors, 1912 Building		Miscellaneous					YES	X NO
2022 Fall	Six Month Survey: No Chang	ie .	•	1	•	•	•	•	•		
Comment											
2023 Fall	Six Month Survey: No Chang	ge		1							
Comment											
	ng Six Month Survey: No Cha	ange									
Comment	s:										
	ng Six Month Survey: No Cha	ange									
Comment	S:			1							
				1							
HA No	Material Description M	laterial Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

1st, 2nd & 3rd Floor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
034.1	Black vinyl molding			1st and 2nd Floor Corridors, 1890 Building		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange										

2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments:

HA No

33.2

Material Description

12" x 12" Vinyl Floor Tile, Beige w/Brown and White

Material

Quantity

Material

Units

2024 Spring Six Month Survey: No Change Comments:

Change in Assessment Category

X NO

YES

034.2	black			Room 220, 1912 Building		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No C	hange			1							
Comments												
2023 Fall S	Six Month Survey: No C	hange										
Comments	S:											
2023 Sprin	ng Six Month Survey: No	Change										
Comments	3:											
2024 Sprin	ng Six Month Survey: No	Change										
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34.1	Black vinyl molding			1st and 2nd Floor Corridors, 1890 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

Vinyl floor tile molding

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Units

Material

Quantity

Material Location

Corridors, 1890 Building

035.1	Light Brown Mastic for Black Vinyl Molding			1st and 2nd Floor Corridors, 1890 Building		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No C	hange										
Comments	-	.										
2023 Fall S	Six Month Survey: No C	hange			-							
Comments		-										
2023 Sprin	g Six Month Survey: No	Change										
Comments	:											
2024 Sprin	g Six Month Survey: No	Change										
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
035.2	Vinyl floor tile molding			Assembly Hall, 1912		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Building

Material

Units

Material Quantity

HA No

Material Description

mastic (light brown)

036.1	12" x 12" Vinyl Floor Tile, Beige w/Blue, Gray, and Rust Streaks	1156	SF	Room 332, 1890 Building		Miscellaneous	No	None	0	SF	YES X NO
		-	•		7	•	•	•	•	•	
2022 Fall Si	x Month Survey: No Ch	nange									
Comments:											
2023 Fall Si	x Month Survey: No Ch	nange									
Comments:											
					-						
2023 Spring	Six Month Survey: No	Change									
Comments:											
					1						
2024 Spring	Six Month Survey: No	Change									
Comments:	•										
					•						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Category

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

YES

X NO

036.1M	Mastic Assoc.w/12" x 12" Beige ,Blue, Gry & Rust Vinyl Floor Tile		Room 332, 18	90 Building	Miscellaneous	
2022 Fall S	Six Month Survey: No Cha	ange				
Comments						
2023 Fall S	Six Month Survey: No Cha	ange				
Comments	:					
2023 Sprin	g Six Month Survey: No (Change				
Comments	:					
2024 Sprin	g Six Month Survey: No (Change				

Units

Material

Units

Material

Quantity

Quantity

Material Location

HA No

Comments:

Material Description

037.1	12" x 12" Vinyl Floor Tile, Cream Flecks w/Tan Specks	200	SF	Engineer's Office, 1890 Building	Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange									
2023 Fall Six Comments:	Month Survey: No Cha	ange									
2023 Spring S Comments:	Six Month Survey: No	Change									
2024 Spring S	Six Month Survey: No	Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
038.1	Incinerator brick			Tank Room, 1890 Building		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

038A.1	Incinerator brick mortar			Tank Room, 1890 Building		Miscellaneous					YES	X NO
2022 Fall Si	ix Month Survey: No C	hange			7							
Comments:												
2023 Fall Si	ix Month Survey: No C	hange										
Comments:					-							
	g Six Month Survey: No	Change										
Comments:					_							
	g Six Month Survey: No	Change										
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
039.1	Brick			Exterior, 1890 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

039.2	Brick			Exterior, 1912 Building		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No C	hange										
Comments		<u></u>										
2023 Fall S	Six Month Survey: No C	hange										
Comments	:											
2023 Sprin	ng Six Month Survey: No	o Change										
Comments	S:											
	ng Six Month Survey: No	o Change										
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
040.1	Brick mortar			Exterior, 1890 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

040.2	Brick mortar			Exterior, 1912 Building		Miscellaneous					YES	X NO
2022 Fall Si	ix Month Survey: No C	hange										
Comments:	•	<u> </u>										
2023 Spring	g Six Month Survey: No	Change										
Comments:												
	ix Month Survey: No C	hange										
Comments:												
	Six Month Survey: No	Change										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
042.2	Glazed brick			Assembly Hall, 1912		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Units

Material

Quantity

Material Location

Building

043.2	Glazed brick mortar			Assembly Hall, 1912 Building		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No Ch	ange										
Comments	•	ango										
2023 Sprin	g Six Month Survey: No	Change										
Comments												
2023 Fall S	Six Month Survey: No Ch	ange			1							
Comments	:											
2024 Sprin	g Six Month Survey: No	Change										
Comments	:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
044.2	12" x 12" Vinyl Floor Tile, Beige w/Blue, Pink, Gray, &			Room 120 121, and 220,		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Brown

Material Description

Material

Units

Material

Quantity

Material Location

1912 Building

Change in Assessment Category

Damage

Units

044.2M	Mastic assoc. W/12" x 12" Vinyl Floor Tile, Beige, Blue, Pink			Rooms 120, 121, and 220, 1912 Building		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange	<u> </u>		7							
	Month Survey. No Ci	larige			+							
Comments:												
2023 Fall Six	Month Survey: No Ch	nange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:	,											
Commonic					-							
2024 Spring	Six Month Survey: No	Change										
Comments:	,											
22					\dashv							
L												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Type

Damage

Quantity

Quantity

Damage

Units

Units

YES

045.2	Tan w/Blue, Gray, Brown, Orange & Beige		Room 321, 1912 Building
2022 Fall Six	Month Survey: No Ch	ange	
Comments:	•		
2023 Fall Six	Month Survey: No Ch	ange	
Comments:			
2023 Spring S	Six Month Survey: No	Change	
Comments:			
2024 Spring S	Six Month Survey: No	Change	
Comments:		·	

Quantity

Units

HA No

Material Description

Mastic assoc. W/12" x 12"

12" x 12" Vinyl Floor Tile,

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

X NO

045.2M	12" x 12" Tan, Bl, Gray, Brown, Or & Gray Vinyl Floor Tile Mastic			Room 321, 1912 Building		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No C	hango		·	7							
		nange			4							
Comments:												
2023 Spring	g Six Month Survey: No	Change										
Comments:												
					1							
2023 Fall S	ix Month Survey: No C	hange										
Comments:												
2024 Spring	g Six Month Survey: No	Change										
Comments:												
					1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

046.2

Material Description

12" x 12" Tan, Bl, Gray,

Gray vinyl baseboard

Material

Units

Material

Quantity

Material Location

Assembly Hall, 1912

Building

YES

X NO

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
047.1	Boiler brick	1200	SF	Boiler Room, 1890 Building		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
048.1	Boiler brick mortar	750	SF	Boiler Room, 1890 Building		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

2022 Fall Six	Month Survey: No Ch	ange									
Comments:	Monar Garray. No Gr	arigo									
2023 Spring	Six Month Survey: No	Change									
Comments:											
2023 Fall Six	Month Survey: No Ch	ange									
	Werter Carvey: 140 Cit	arigo									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:	on monar carrey. He	Onango									
Comments.											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Domogo	Change in Assessment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Fliable	Damage Type	Quantity	Damage Units	Change in Assessment Category
		+	-		* *		-		-		

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

SF

Material

Units

SF

Material Location

Throughout Stairwell

Areas, 1912 Building

Exterior, 1890 Building

Material

Quantity

300

HA No

049.2

050.1

Comments:

Comments:

Comments:

Comments:

Material Description

Roof (Non-AHERA)

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Fire doors

Change in Assessment Category

X NO

X NO

YES

050.2	Roof (Non-AHERA)			Exterior, 1912 Building		Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No Ch	ange			7							
Comments:					1							
2023 Spring	Six Month Survey: No	Change										
Comments:												
	x Month Survey: No Ch	ange										
Comments:					4							
	Six Month Survey: No	Change										
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
051.1	Roof flashing (Non-AHERA)			Exterior, 1890 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Units

Material

Quantity

Material Location

051.2	Roof flashing (Non-AHERA)			Exterior, 1912 Building		Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No Ch	ange			7							
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:					-							
	x Month Survey: No Ch	ange										
Comments:					-							
	Six Month Survey: No	Change										
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
053.1	Door caulk (Non-AHERA)			Exterior, 1890 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

2022 Fall Six Month Survey: No Change

Material

Units

Material

Quantity

Material Location

053.2	Door caulk (Non-AHERA)			Exterior, 1912 Building		Miscellaneous					YES	X NO
2022 Fall \$	Six Month Survey: No C	hange			7							
Comments	-	J -										
2023 Sprir	ng Six Month Survey: No	o Change										
Comments	S:											
2023 Fall \$	Six Month Survey: No C	hange										
Comments	S:				_							
2024 Sprir	ng Six Month Survey: No	o Change										
Comments	S:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
054.1	Window caulk (Non-			Exterior, 1890 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

AHERA)

Comments:

Comments:

Comments:

Comments:

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

Damage

Units

054.2	Window caulk (Non- AHERA)			Exterior, 1912 Building		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No Ch	nange			1							
Comments:	•											
2023 Spring	g Six Month Survey: No	Change										
Comments:					1							
	ix Month Survey: No Ch	nange										
Comments:												
2024 Spring	g Six Month Survey: No	Change										
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
055.1	Blue mixed carpet mastic			Room 235, 1890 Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

Change in Assessment Category

055.2	Blue mixed carpet mastic			Room 024		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No Ch	nange			7							
Comments:	-	<u> </u>			1							
2023 Spring	g Six Month Survey: No	Change			_							
Comments:					_							
2023 Fall S	ix Month Survey: No Ch	nange										
Comments:												
2024 Spring	g Six Month Survey: No	Change										
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
056.1	Pink mixed carpet mastic			Room 235 Closet, 1890		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Material

Units

Material

Quantity

Material Location

Building

HA No

Material Description

Change in Assessment Category

Damage

Units

056.2	Pink mixed carpet mastic			Rooms 020, 125, Teacher's Lounge 1912 Building		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No Ch	ange			7							
Comments		ange .										
2023 Sprin	ng Six Month Survey: No	Change			_							
					-							
	Six Month Survey: No Ch	ange										
Comments	5:				-							
2024 Sprin	ng Six Month Survey: No	Change			=							
Comments	5:	_										
HA No	Material Description		Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
057.4	Description description			Main Office, 1890		Missellessess						Tv. luc

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Rooms 020, 125,

Building

HA No

057.1

Comments:

Comments:

Comments:

Comments:

Material Description

Brown mixed carpet mastic

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Quantity

Material

Units

YES

X NO

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12" x 12" Tan w/ black and White Floor Tile	325	SF	Rooms 122, Teacher's Lounge - 1912 Building		Miscellaneous	No	None	6	SF	YES X NO
					1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Mastic for 12" x 12" Tan w/ black and White Floor Tile	325	SF	Rooms 122, Teachers Lounge		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
60	12" x 12" Tan w/ Blue and red Floor Tile	250	SF	1912 Building Rooms 124, 221 and 1890 Building		Miscellaneous	No	Loc	8	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange	•	•]	•	•	•	•	•		

2022 Fall Six Month Survey: No Change
2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Mastic for 12" x 12" tan w/ Blue and red Floor Tile	250	SF	1912 Building Rooms Room 124, and 221 and 1890 Building room 332		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	12" x 12" Light gray w/ White and black Floor Tile	1750	SF	1890 Building Rooms 231, 335		Miscellaneous	No	None	0	SF	YES X NO
					1						_

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Mastic for 12" x 12" Light gray w/ White and black Floor Tile	1750	SF	1890 Building Rooms 231, 335		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Page 48

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
64		Black Chalk board Adhesive	4000	SF	1890 and 1912 Building classrooms		Miscellaneous	No	None	0	SF	YES	X NO
202	22 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
0004.0 ' 0' 14 4 0 14 0
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
65	Green chalk board adhesive	4000	SF	1966 Building Classrooms		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12" x 12" Tan Floor Tile	10000	SF	1966 Building Lunch Room 101 (offices), 102, faculty washroom, 103- 107, 109-111, 114-116, PC Lab, 1st floor hallway		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change	
Comments:	
2023 Spring Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Mastic for 12" x 12" Tan Floor Tile	10000	SF	1966 Building Lunch Room 101 (offices), 102, faculty washroom, 103- 107, 109-111, 114-116, PC Lab, 1st floor hallway		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
68	12" x 12" Blue/Green /Purple Floor Tile	800	SF	1966 Building Room 112		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six Month Survey: No Change												
Comments:												
2023 Spring Six Month Survey: No Change												
Comments:												

2023 Fall Six Month Survey: No Change Comments:

2024 Spring Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
69	Mastic for 12" x 12" Blue/Gree/Purple Floor Tile	800	SF	1966 Building Room 112		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
70	12" x 12" Red Floor Tile	400	SF	1966 Building lunch room		Miscellaneous	No	None	0	SF	YES	NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
71	Mastic for 12" x 12" Red Floor Tile	400	SF	1966 Building Lunch Room		Miscellaneous	No	None	0	SF	YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmen	t Category
72		Green terrazzo	3000	SF	1966 Building Entrance and stairwells		Surface	No	None	0	SF	YES	NO
202	2 Fall Six	Month Survey: No Ch	ange										

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12" x 12' Beige w/ White Specks Floor Tile	2110	SF	Lunchroom		Miscellaneous	No	Loc	100	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Page 53

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
74	12" x 12' Red w/ White Specks Floor Tile	1710	SF	Lunchroom		Miscellaneous	No	None	0	SF	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange]							

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	12" x 12' Floor Tile Mastic	3820	SF	Lunchroom		Miscellaneous	No	None	0	SF	YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

A.1	Cardboard pipe insulation			Building		Miscellaneous					YES	X NO
2022 Fall :	Six Month Survey: No Ch	ange			7							
Comments		3 -										
2023 Sprir	ng Six Month Survey: No	Change										
Comments:												
2023 Fall 3	Six Month Survey: No Ch	ange										
Comments	S:				_							
2024 Sprir	ng Six Month Survey: No	Change										
Comments	S:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
B.1	Joint Insulation on			Main Entrance, 1890		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Material

Units

Material

Quantity

Material Location

Main Entrance 1890

Building

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

Cardboard Insulated Piping

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Change in Assessment Category

Damage

Units

				ŭ .							
2022 Fall S	Six Month Survey: No Ch	nange									
Comments											
2023 Fall S	Six Month Survey: No Ch										
Comments	:										
2023 Spring Six Month Survey: No Change											
Comments:											
2024 Spring Six Month Survey: No Change											
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0.0	Manufalanian in colorian			Engine Room, 1912		TOL					

Type

Material

TSI

TSI

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Main Entrance, 1890

Building

Material

Units

Material Quantity

HA No

C.1

C.2

Material Description

Mag block pipe insulation

Mag-block pipe insulation

Change in Assessment Category

X NO

X NO

YES

D.1	Block Insulated Piping			Building		151					YES	X NO
2022 Fall 5	Six Month Survey: No C	hange										
Comments												
2023 Fall \$	Six Month Survey: No C	hange										
Comments	5:	_										
2023 Sprir	ng Six Month Survey: No											
Comments:												
2024 Spring Six Month Survey: No Change												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
	0 "			Filter Room, 1890							l — і	

Type

Material

TSI

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material Quantity Material Location

Main Entrance, 1890

Building

HA No

D.1

1.1

Material Description

Joint Insulation on Mag

Cardboard duct wrap

Change in Assessment Category

X NO

X NO

YES

2022 Fall Si	ix Month Survey: No C	hange									
Comments:											
2023 Fall Six Month Survey: No Change											
Comments:	•										
2023 Spring Six Month Survey: No Change											
Comments:											
2024 Spring Six Month Survey: No Change											
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

TSI

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Engine Room, 1912

2nd and 3rd Floor Janitor

Closets, 1890 Building

Building

Material

Quantity

Material

Units

HA No

J.2

K.1

Material Description

Joint Insulation on Mag

Block Insulated Piping

Joint Insulation on

Fiberglass Insulated Piping

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K.2	Joint Insulation on Fiberglass Insulated Piping			1st and 2nd Floor Girl's Bathrooms and 1st Floor Boy's Bathroom, 1912 building		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
2022 I all SIX Mortin Survey. No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Charles Sumner Math & Science Community Acad ES
Date:
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.