## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Gwendolyn Brooks College Preparatory Academy HS 47051 1500 School: **Oracle Unit: Building ID:** Address: 250 E. 111th St. Region: Mail Room: Asbestos Surveyor: Sachen, Justin X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/6/2024 Email Address: A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other Posted to the CPS we Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type Main Building- Hot Water YES 002 X NO Aircell Jacket ABATED TSI Tank in Boiler Room 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

		Quantity	Units		Туре	Category	Type	Quantity	Units		
004	Cardboard Pipe Insulation ABATED			Main Building- Boiler Room East		TSI				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]						
Comments:											
2023 Fall Six	Month Survey: No Ch	ange									
Comments:					 						
	Six Month Survey: No	Change			-						
Comments:					1						
2024 Spring	Six Month Survey: No	Change									
Comments:					<u> </u>						
2024 Fall Six	Month Survey: No Ch	ange			]						
Comments:											

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
005	Mag. Jacket Boilers 1&2 ABATED			Main Building- Boiler Room		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

007	Cardboard Pipe Insulation ABATED			Main Building- Boiler Room, East Perimeter		TSI			YES	X NO
2000 = 11 01					1					
	2022 Fall Six Month Survey: No Change									
Comments:										
2023 Fall Six Month Survey: No Change										
Comments:										
2023 Spring S	Six Month Survey: No	Change								
Comments:										
2024 Spring S	Six Month Survey: No	Change								
Comments:										
2024 Fall Six Month Survey: No Change										
Comments:	Comments:									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

	Quantity	Units		Туре	Category	Туре	Quantity	Units	
Joint Comp Cardboard ABATED	ound on Pipe Insulation		Main Building- Boiler Room Hot Water Pipe		TSI				YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
009	Joint Compound on Aircell Pipe Insulation ABATED			Main Building- Boiler Room on East Wall		TSI					YES	X NO
2022 Fall Six	Month Survey: No Ch											
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring Six Month Survey: No Change												
Comments:	-											

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
010	Aircell Pipe Insulation	300	LF	Main Building- Attic (Abated) and Tunnels (Still Present)		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
TIANO	Material Description	Quantity	Units	Waterial Location	Type	Category	Thable	Type	Quantity	Units	Change in Asse	SSITIETI Category
011	Mag Block Pipe Insulation	800	LF	Main Building- Tunnel		TSI	Yes	None	0		YES	X NO
2022 Fall Six Month Survey: No Change												
Comments:												
2023 Fall S	2023 Fall Six Month Survey: No Change											
Comments	Comments:											
2023 Spring Six Month Survey: No Change												
Comments:												
2024 Spring Six Month Survey: No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
012	Cardboard Pipe Insulation	500	LF	Main Building- Tunnels		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

Comments:

Comments:

2024 Fall Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
013(F18)	9x9 Brown Speckled Floor Tile ABATED			Main Building- West Wind Coaches' Offices		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	-											
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
014(C12)	2'x4' Ceiling Tile ABATED			Main Building- West Wing Coach's Office		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

014A Red, Black, Brown, Tan Linoleum Pattern ABATED	1st Floor, 2nd Floor Foyer	Miscellaneous		YES	X NO
2022 Fall Six Month Survey: No Change					
Comments:					
2023 Fall Six Month Survey: No Change					
Comments:					
2023 Spring Six Month Survey: No Change					
Comments:					
2024 Spring Six Month Survey: No Change					
Comments:					
2024 Fall Six Month Survey: No Change					
Comments:					

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
015(C9)	1'x1' Glued on Ceiling ABATED			Main Building- Men's Bathroom		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

016	Plaster ABATED		Main Building- Throughout West Wing of Building	Surface			YES	X NO
2022 Fall Six	Month Survey: No (	Change						
Comments:								
	Month Survey: No (	Change						
Comments:								
2023 Spring	Six Month Survey: N	lo Change						
Comments:								
2024 Spring	Six Month Survey: N	lo Change						
Comments:								
2024 Fall Six	Month Survey: No (	Change						
Comments:								

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
017(F1)	9x9 White Floor Tile ABATED			Main Building- East Wing Rooms 15, 19, and 306		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Page 8

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
018	9x9 Pink Floor Tile ABATED			Main Building- West Wing Foyer		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No C	hange			]							
Comments:	•	<u> </u>			- -							
2023 Spring	Six Month Survey: No	c Change			-							
Comments:		•										
2023 Fall Six	Month Survey: No C	hange										
Comments:												
2024 Spring	Six Month Survey: No	Change			=							
Comments:												
2024 Fall Six	Month Survey: No C	hange										
Comments:	•	•			=							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
018(F15)	9x9 Pink Floor Tile Mastic ABATED			Main Building- West Wing 1st & 2nd Floor Foyer and Lounge		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
019	Beige Terrazzo	30000	SF	Main Building- 1st, 2nd, 3rd & 4th Floor Hallways, Bathrooms, Lunchroom, Rooms 307, 321B, 325, 403 & 407		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
020	12x12 Yellow Floor Tile	9000	SF	Rooms 100 (Hallway), 106, 114, 115, 205, 211, 216, 228A & 316		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12x12 Yellow Floor Tile Mastic	9000	SF	Rooms 100 (Hallway), 106, 114, 115, 205, 211, 216, 228A & 316		Miscellaneous	No	None	0		YES X NO

2000 Fell Civ Manth Common Na Channa
2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Brown Carpet Mastic	6000	SF	Library, Assistant Principal's, Nurse Office, Side Office, 102, 103, 111, 117, and Office Hall		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

023	Light Beige Linoleum ABATED			Main Building- Gym (Room 251), Room 253		Miscellaneous					YES	X NO
2022 Fall Six	x Month Survey: No Cl	hange			]							
Comments:	-	-			1							
	Six Month Survey: No	Change			-							
Comments:												
	x Month Survey: No Cl	hange										
Comments:												
	Six Month Survey: No	Change										
Comments:					-							
	x Month Survey: No Cl	hange										
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
023(F2)	9x9 Black Floor Tile ABATED			Main Building- East Wing 2nd & 3rd Floor Rooms 15, 19, 306		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Description

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
024(F4)	9x9 Maroon Floor Tile ABATED			Main Building- East Wing 2nd Floor, Library, and Guidance Office		Miscellaneous					YES	X NO
2022 Fall Six	2022 Fall Six Month Survey: No Change											
Comments:												
2023 Fall Six Month Survey: No Change												
Comments:												

	2023 Spring Six Month Survey: No Change
	Comments:
	2024 Spring Six Month Survey: No Change
	Comments:
- [	

2024 Fall Six Month Survey: No Change

12x12 Gray Floor Tile

Comments:

025

ļ												
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Miscellaneous

No

None

0

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

800

SF

Rooms 321A & 329A

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12x12 Gray Floor Tile Mastic	800	SF	Rooms 321A & 329A		Miscellaneous	No	None	0		YES X NO
					i						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0004 0 1 0 1 0 1 0
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	2x4 Lay-in Panels- NOT OBSERVED	1000	SF	Kitchen		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Spray-on Insulation	3000	SF	Gymnasium		TSI	Yes	None	0		YES X NO
2022 Fall Six	Month Survey: No Ch	ongo									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	2x2 Lay-in Ceiling Panels	20000	SF	Hallways		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Black Counter Tops	26	SF	Rooms 307, 307A, 310, 325 & 400		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12x12 Yellow/Grey Mix Floor Tile	21500	SF	Rooms 107, 109, 110, 112, 113, 116, 129, 207, 208, 209, 212, 214, 221, 223, 227, 233, 300, 301, 304, 305, 308, 309, 312, 323 & 327		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31A	Mastic associated with 12x12 Yellow/Grey Mix Floor Tile	21500	SF	Rooms 107, 109, 110, 112, 113, 116, 129, 207, 208, 209, 212, 214, 221, 223, 227, 233, 300, 301, 304, 305, 308, 309, 312, 323 & 327		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 47051

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12x12 Grey Yellow & Blue Mix Floor Tile	1600	SF	Room 321		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Cha	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32A	Mastic associated with 12x12 Grey Yellow & Blue Mix Floor Tile	1600	SF	Room 321		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Lab Tables	500	SF	Rooms 319, 325 & 400		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12x12 Blue, Dark Blue & White Mix Floor Tile	800	SF	Room 229		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34A	Mastic associated with 12x12 Blue, Dark Blue & White Mix Floor Tile	800	SF	Room 229		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12x12 Grey & Light Grey w/Specks Floor Tile	4000	SF	Rooms 131, 133, 135, 137 & 139		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35A	Mastic associated with 12x12 Grey & Light Grey w/Specks Floor Tile	4000	SF	Rooms 131, 133, 135, 137 & 139		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
036 (C13)	2x4 Lay-In Ceiling Tile ABATED			Main Building- Music Room		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Mastic associated with Wood Pattern Linoleum	500	SF	Principal's Office (Room 235)		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
37	12x12 White, Blue, Green, Olive & Beige Mix Floor Tile	1000	SF	Rooms 237C & 239		Miscellaneous	No	None	0		YES X NO	

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
37A	Mastic associated with 12x12 White, Blue, Green, Olive & Beige Mix Floor Tile	1000	SF	Rooms 237A & 239		Miscellaneous	No	None	0		YES	X NO
	·	•	•	•	•	•	•	•	•	•	•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
040(F9)	9x9 Gray Floor Tile ABATED			Main Building- Guidance and Xerox Offices		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
041(F3)	9"x9" Red Floor Tile ABATED			Main Building- Room 306 and Xerox Room		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
	Six Month Survey: No	Change										
Comments:												
	Month Survey: No Ch	ange										
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
043(F11)	9x9 White Floor Tile ABATED			Main Building- Office		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
045 (F16)	9x9 Grey Floor Tile ABATED			Main Building- West Wing 2nd Floor Lounge		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	•	<u> </u>										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
046(F20)	9x9 Green Floor Tile ABATED			Main Building- Gym & Cafeteria		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

		Quantity	Units		Type	Category	Type	Quantity	Units		
047(F19)	9x9 Tan Floor Tile ABATED			Main Building- Gym, Cafeteria Building		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Cha	ange			7						
Comments:		<u> </u>									
2023 Fall Six	Month Survey: No Cha	ange									
Comments:											
	Six Month Survey: No (	Change									
Comments:					_						
2024 Spring S	Six Month Survey: No (	Change									
Comments:					4						
	Month Survey: No Cha	ange									
Comments:					4						
					_						

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
049 (F5)	9x9 Tan Floor Tile ABATED			Main Building- Guidance Office, East Wing Room 29 & Library		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
051 (F12)	9x9 Green & White Floor Tile ABATED			Main Building- East Wing 2nd & 3rd Floor Hallways & Room 31		Miscellaneous					YES	X NO
		•	•	•	1	•	•	•	•	•		
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
		<u> </u>										
2023 Spring 8	Six Month Survey: No	Change										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	World Sarvey. NO On	arigo			-							
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
052 (F17)	9x9 Green & Tan Floor Tile ABATED			Annex- Office & Storage 156A & 156B		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
052 (F21)	9x9 Blue Floor Tile ABATED			Annex- Room 151		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring Six Month Survey: No Change												
Comments:	•	<b>-</b>										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					_							
2024 Spring S	Six Month Survey: No	Change			_							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
					┙							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
052(F8)	Blue and White Linoleum ABATED			Main Building- 2nd Floor Teachers' Lounge Kitchen		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
053 (F13)	12x12 Tan Floor Tile ABATED			Annex- Boys' & Girls' Toilets & Corridors		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:					 							
2024 Spring S	Six Month Survey: No	Change										
Comments:					-							
	Month Survey: No Ch	ange										
Comments:					-							
L					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
054	2x4 Ceiling Tile ABATED			Annex- Chemistry Lab Room 252		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
055	Aircell ABATED			Annex- Chemistry Lab		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange			1							
Comments:	•	•										
2023 Spring S	Six Month Survey: No	Change			_							
Comments:												
2024 Spring S	Six Month Survey: No	Change			-							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange			-							
Comments:	•	-			]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
059	Trim Mastic on Tan Baseboard ABATED			Annex- Foyer/Corridor		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment C	Category
060	Trim Tan Baseboard ABATED			Annex- Foyer/Corridor		Miscellaneous					YES X	NO
2022 Fall Six	Month Survey: No Cl	hange			7							
Comments:												
2023 Fall Six	Month Survey: No Cl	hange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:					_							
	Six Month Survey: No	Change										
Comments:					_							
	Month Survey: No Cl	hange										
Comments:												
L					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
070 (F13)	12x12 Tan Floor Tile Mastic ABATED			Annex- Boys' & Girls' Toilets & Corridors		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

		Quantity	Units		Туре	Category	Type	Quantity	Units		
070 (F17)	9x9 Green Floor Tile Mastic ABATED			Annex- Room 151		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Cha	ange			7						
Comments:					1						
2023 Spring S	Six Month Survey: No	Change			_						
Comments:											
2023 Fall Six	Month Survey: No Cha	ange									
Comments:											
2024 Fall Six	Month Survey: No Cha	ange			-						
Comments:											
2024 Spring S	Six Month Survey: No	Change			-						
Comments:											
					J						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
070 (F21)	9x9 Blue Floor Tile Mastic ABATED			Annex- Room 151		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
072	Paneling Mastic ABATED			Annex- Annex Corridor		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:		<b>J</b> -										
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:	•											
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2024 Spring	Six Month Survey: No	Change			_							
Comments:	•											
2024 Fall Six	Month Survey: No Ch	ange			_							
Comments:	•	120			]							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
073 (C14)	12x12 Ceiling Tile Mastic ABATED			Annex- Rooms 155 A-D		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
078	Aircell Pipe Insulation	3000	LF	Crawlspace Tunnels, Tunnel connecting Main Building and Monastery (Monastery no longer exists)		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
079	Hard Fittings on Aircell Pipe Insulation	200	LF	Crawlspace Tunnels, Tunnel connecting Main Building with Monastery (Monastery no longer exists)		TSI	Yes	None	0		YES X NO

OOOO Fall O' March O are No Olarses
2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
080 (F25)	12x12 Black Floor Tile			Monastery- 2nd Floor Fireplace (Building Demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

080 (F26)	12x12 Red Floor Tile			Monastery- 1st, 2nd & 3rd Floor Stairways (Building Demolished)		Miscellaneous					YES	X NO
2022 Fall Siv	Month Survey: No Ch	ango			٦							
	Month Survey. No Ci	iange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Ch	nange										
Comments:	•											
2024 Fall Six	Month Survey: No Ch	nange										
Comments:	•											
					=							
2024 Spring	Six Month Survey: No	Change										
Comments:												
Commonto.												
					_							
	T	T		T	T	T			T =		I a	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Monastery- 2nd & 3rd Floor (Building Demolished)

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

080 (F27)

Material Description

12x12 Orange/Brown Floor Tile

Material

Quantity

Material

Units

YES

X NO

081 (F25)	12x12 Black Floor Tile Mastic			Monastery- 2nd Floor Fireplace (Building Demolished)		Miscellaneous					YES	X NO
	•	•	•	•	- -	•	=	•	•	•		
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:	,											
2024 Spring	Six Month Survey: No	Change										
Comments:	-	-										
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	•											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

Material Location

Monastery- 1st, 2nd &

081 (F26)	12x12 Red Floor Tile Mastic		3rd Floor Stairways (Building Demolished)
			1 1 3 1 1 1 1 1
2022 Fall Six	Month Survey: No C	Change	
Comments:			
2023 Spring S	Six Month Survey: N	o Change	
Comments:			
2023 Fall Six	Month Survey: No C	Change	
Comments:			
2024 Fall Six	Month Survey: No C	Change	
Comments:			
2024 Spring S	Six Month Survey: N	o Change	
Comments:			

Quantity

Units

HA No

Material Description

12x12 Red Floor Tile

Material

Quantity

Material

Units

081 (F27)	12x12 Orange/Brown Floor Tile Mastic			Monastery- 2nd & 3rd Floors (Building Demolished)		Miscellaneous					YES	X NO
2022 Fall Six	x Month Survey: No Ch	ange			7							
Comments:	k Month Carvey. 140 On	arigo			1							
Comments					1							
2023 Spring	Six Month Survey: No	Change										
Comments:												
0000 F II 0	NA (1.0 N. O)				4							
	x Month Survey: No Cha	ange										
Comments:					_							
2024 Fall Six	x Month Survey: No Ch	ango			-							
	k Month Survey. No Ch	ange			-							
Comments:					4							
2024 Spring	Six Month Survey: No	Change			1							
Comments:	,				1							
					]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

		Quantity	Units		Type	Category	Туре	Quantity	Units		
082 (F31)	Brown Vinyl Baseboard			Monastery- 2nd Floor Community Room (Building Demolished)		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange									
Comments:	Civionar Garvey. 140 On	unge									
2023 Spring	Six Month Survey: No	Change			1						

Comments:

2023 Fall Six Month Survey: No Change

Comments:

2024 Spring Six Month Survey: No Change

Comments:

2024 Fall Six Month Survey: No Change

Comments:

HA No

Material Description

Material

Quantity

Material

Units

**Material Location** 

082(F32)	Black Vinyl Baseboard		3rd Floor Stairwells, 315 (Building Demolished)	Miscellaneous		YES	X NO
2022 Fall Six	K Month Survey: No Ch	ange					
Comments:	t monar ourroy. No on	larigo					
2023 Spring	Six Month Survey: No	Change					
Comments:							
2023 Fall Six	Month Survey: No Ch	ange					
Comments:							
2024 Spring	Six Month Survey: No	Change					
Comments:							
2024 Fall Six	K Month Survey: No Ch	ange					
Comments:	•	-					

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
082(F33)	Woodgrain Baseboard Mastic			Monastery- Room 210 (Building Demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

083 (F31)	Mastic under Baseboard	Monastery- 2nd Floor Community Room (Building Demolished)	Miscellaneous			YES	X NO
2022 Fall Six	Month Survey: No Chang		7				
Comments:	Month Garvey. No Onang	<u>jc</u>	1				
2023 Fall Six	Month Survey: No Chang	ge					
Comments:							
2023 Spring	Six Month Survey: No Cha	ange	-				
Comments:			- -				
2024 Spring	Six Month Survey: No Cha	ange	-				
Comments:							
2024 Fall Six	Month Survey: No Chang	ge	-				
Comments:	•						
			<u> </u>				

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
083 (F33)	Woodgrain Baseboard			Monastery- Room 210 (Building Demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

083(F32)	Black Vinyl Baseboard Mastic			Monastery- 1st, 2nd & 3rd Floor Stairwells, 315 (Building Demolished)		Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No C	hange			1						•	
Comments:	x monar carvey. No ci	larigo										
2023 Fall Si	x Month Survey: No C	hande			_							
Comments:	x Month Garvey. No O	narige										
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Siz	x Month Survey: No C	hange			-							
Comments:					]							
2024 Spring	Six Month Survey: No	Change										
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
084 (CM 45)	Orange Carpet Mastic			Monastery- 2nd Floor Corridor, Room 204 & 210 (Building Demolished)		Miscellaneous					YES	X NO
2022 Fall Siz	x Month Survey: No C	hange			]							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

Comments:

Comments:

2023 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material Description

Material

Units

Material

Quantity

Material Location

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		0 ,
084 (CM53)	Brown Tweed Carpet Mastic			Monastery- Room 306 (Building Demolished)		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Fall Six	2023 Fall Six Month Survey: No Change											
Comments:	•	_										
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2024 Spring	Six Month Survey: No	Change										
Comments:	•	120										
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
084(42)	Orange/Brown Carpet Mastic			Monastery- 1st Floor Northwest Corner (Building Demolished)		Miscellaneous					YES	X NO

Material

Friable

Damage

Damage

Damage

HA No

Material Description

Material

Material

Material Location

084(43)	Rust Carpet Mastic		Northwest Corridor (Building Demolished)	Miscellaneous			YES	X NO
2022 Fall Siz	Month Cumiou No Che	2022						
	x Month Survey: No Cha	ange						
Comments:								
2023 Fall Six	x Month Survey: No Cha	ange						
Comments:	,							
2023 Spring	Six Month Survey: No 0	Change						
Comments:								
2024 Fall Six	x Month Survey: No Cha	ange						
Comments:		_						
2024 Spring	Six Month Survey: No 0	Change						
Comments:	,	J						
						1		

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
084(CM41)	Brown/Tweed Carpet Mastic			Monastery- 1st Floor NW Corridor (Building Demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

085(F28)	9x9 Red/Black Border Floor Tile	Monastery- 1st, 2nd & 3rd Floor Stairwells (Building Demolished)	Miscellaneous		YES	X NO
2022 Fall Six	x Month Survey: No Change					
Comments:	i i i i i i i i i i i i i i i i i i i					
2023 Spring	Six Month Survey: No Change					
Comments:	, J					
2023 Fall Six	x Month Survey: No Change					
Comments:	,					
2024 Fall Six	x Month Survey: No Change					
Comments:						
2024 Spring	Six Month Survey: No Change					
Comments:	•					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
085(F29)	9x9 Grey/Red Trim Floor Tile			Monastery- 1st Floor (Building Demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

086(F28)	9x9 Red/Black Border Floor Tile Mastic	Monastery- Stairwells 1st, 2nd & 3rd Floor (Building Demolished)	Miscellaneous		YES	X NO
2022 Fall Six	Month Survey: No Chang	ge				
Comments:	t month out of the onen	90				
2023 Spring Comments:	Six Month Survey: No Ch	ange				
	Month Survey: No Chang	ge				
Comments:						
2024 Fall Six	Month Survey: No Chang	ge				
Comments:						
2024 Spring	Six Month Survey: No Ch	ange				
Comments:	•					

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
086(F29)	9x9 Grey/Red Trim Floor Tile Mastic			Monastery- 1st Floor (Building Demolished)		Miscellaneous					YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

087	12x12 Ceiling Tile			Monastery- 2nd & 3rd Floor (Building Demolished)		Miscellaneous					YES	X NO
	· · · · · · · · · · · · · · · · · · ·	_	-	•	7	•	•	•	•	•		
2022 Fall Si	ix Month Survey: No C	hange										
Comments:												
2023 Spring	g Six Month Survey: N	o Change										
Comments:												
					1							
2023 Fall Si	ix Month Survey: No C	hange										
Comments:	•											
2024 Fall Si	ix Month Survey: No C	hange										
Comments:	•				1							
2024 Spring	Six Month Survey: N	o Change										
Comments:	<u> </u>				1							
					<b>_</b>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

		_		İ
088	12x12 Ceiling Tile Mastic		Monastery- 2nd & 3rd Floor (Building Demolished)	
2022 Fall Six	Month Survey: No Cha	ange		
Comments:				
2023 Fall Six	Month Survey: No Cha	ange		
Comments:				
2023 Spring S	Six Month Survey: No	Change		
Comments:				
2024 Spring S	Six Month Survey: No	Change		
Comments:				
2024 Fall Six	Month Survey: No Cha	ange		
Comments:				

Quantity

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

089	Plaster NOT OBSERVED	Monastery- Throughout 1st, 2nd & 3rd Floors- (Building Demolished)	Surface		YES X NO
0000 F-II O:	. Manth Common No Observe				
	x Month Survey: No Change				
Comments:					
2023 Fall Si	x Month Survey: No Change				
Comments:					
2023 Spring	Six Month Survey: No Change				
Comments:					
2024 Fall Si	x Month Survey: No Change				
Comments:	·				
2024 Spring	Six Month Survey: No Change				
Comments:					

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
090 (F23)	12x12 White Floor Tile Mastic			Annex- Physics Lab (Building Demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Type	Category	Туре	Quantity	Units		
090M(F23)	12x12 White Floor Tile			Annex- Physics Lab (Building Demolished)		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]						
Comments:		<b>.</b>									
2023 Fall Six	Month Survey: No Ch	ange			]						
Comments:					1						
	Six Month Survey: No	Change			]						
Comments:					1						
	Month Survey: No Ch	ange									
Comments:					_						
	Six Month Survey: No	Change									
Comments:					_						
L					1						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
091	12x12 Off-White Floor Tile NOT OBSERVED			Gym		Miscellaneous	No	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
092	12x12 Off-White Floor Tile Mastic NOT OBSERVED			Gym		Miscellaneous	No				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	_											
	Six Month Survey: No	Change										
Comments:					-							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:	•											
					┙							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
093	Aircell Pipe Insulation NOT OBSERVED			Gym- Throughout Building, Locker Rooms & Showers		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

094	Hard Fittings on Aircell Pipe Insulation NOT OBSERVED	Gym- Throughout Building, Locker Rooms & Showers	TSI			YES	X NO
2022 Fall	Six Month Survey: No Change						
	, , , , , , , , , , , , , , , , , , , ,						
Comment	S:						
2023 Spri	ng Six Month Survey: No Change						
Comment	S:						
2023 Fall	Six Month Survey: No Change						
Comment	S:						
2024 Spri	ng Six Month Survey: No Change						
Comment	S:						
2024 Fall	Six Month Survey: No Change						
Common	·c·						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	1'x1' Ceiling Tile Mastic NOT OBSERVED			Monastery- Confessionals (Building Demolished)		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
101 (F61)	12x12 Light Gray Floor Tile ABATED			Main Building- West Wing Far West Corridor		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange									
Comments:		ge									
2023 Fall Six	Month Survey: No Ch	ange									
Comments:	•										
2023 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									
Comments:											
					I						

Material

Friable

Damage

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101 (F62)	12x12 Dark Brown w/White/Black Specks Floor Tile ABATED			Main Building- West Wing, Northwest Corner		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

101(F60)	12x12 Off-White Floor Tile ABATED	Main Building- West Wing 3rd Floor, Northwest Corner, West & East Wing, North Portion	Miscellaneous			YES	X NO
2022 Fall Six	Month Survey: No Change						
Comments:	monar carrey. No change						
2023 Spring	Six Month Survey: No Change	)					
Comments:							
	Month Survey: No Change						
Comments:							
	Month Survey: No Change						
Comments:							
	Six Month Survey: No Change						
Comments:							
-							

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102 (F61)	12x12 Light Grey Floor Tile Mastic ABATED			Main Building- West Wing, Far West Corridor		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
102(F60)	12x12 Off-White Floor Tile Mastic ABATED			Main Building- West Wing 3rd floor, Northwest Corner, West & East Wing, North Portion		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	· monar carray. No on	arigo										
2023 Spring	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102(F62)	12x12 Dark Brown w/White/Black Specks Floor tile ABATED			Main Building- West Wing, Northwest Corner		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
103(F63)	9x9 Light Green Floor Tile ABATED			Main Building- West Wing Corridor, 2nd & 3rd Floor East & West Wing Patches		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring S	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103(F64)	9x9 Light Brown Floor Tile ABATED			Main Building- West Wing 1st, 2nd & 3rd Corridor Patches & East End		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

103(F65)	9x9 Medium Brown Floor Tile ABATED	1st & 3rd Floor Corridor Patches & East Wing	Miscellaneous		YES	X NO
2022 Fall Six	Month Survey: No Change					
Comments:						
2023 Spring	Six Month Survey: No Change					
Comments:						
2023 Fall Six	Month Survey: No Change					
Comments:						
2024 Fall Six	Month Survey: No Change					
Comments:						
2024 Spring	Six Month Survey: No Change					
Comments:						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103(F66)	9x9 Yellow Floor Tile ABATED			Main Building- 1st Floor Corridor Patches		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103(F7)	9x9 Clay Floor Tile ABATED			Main Building- 1st Floor Corridor West Wing		Miscellaneous					YES X NO
2022 Fall Six	Month Survey: No C	hange			]						
Comments:	,	<u> </u>									
2023 Fall Six	Month Survey: No C	hange			<u></u>						
Comments:	<b>,</b>	J -									
2023 Spring	Six Month Survey: No	o Change									
Comments:	•										
2024 Fall Six	Month Survey: No C	hange									
Comments:	•										
2024 Spring	Six Month Survey: No	Change									
Comments:	,										
					_						
HA No	Material Description	Material	Material	Material Location	Achaetae	Material	Eriable	Damaga	Damago	Domogo	Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104 (F63)	9x9 Light Green Floor Tile Mastic ABATED			Main Building- West Wind Corridor, 2nd & 3rd Floor East & West Wing Patches		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
104 (F7)	9x9 Clay Floor Tile Mastic ABATED			Main Building- 1st Floor Corridor West Wing		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:		<b>J</b> -										
2023 Spring S	Six Month Survey: No	Change			-							
Comments:												
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104(F1)	9x9 White Floor Tile Mastic ABATED			Main Building- East Wing Rooms 15 & 19 & West Wing Music Room		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
104(F2)	9x9 Black Floor Tile Mastic ABATED			Main Building- East Wing Rooms 15 & 19		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	•											
2023 Spring S	Six Month Survey: No	Change										
Comments:	-											
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104(F3)	9x9 Pink Floor Tile Mastic ABATED			Main Building- West Wing 1st & 2nd Floor Foyer		Miscellaneous					YES X NO

Comments:  2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	
2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	Comments:
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	
2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	Comments:
Comments:  2024 Spring Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Fall Six Month Survey: No Change	Comments:
Comments: 2024 Fall Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change	2024 Spring Six Month Survey: No Change
	Comments:
Comments:	2024 Fall Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
104(F4)	9x9 Maroon Floor Tile Mastic ABATED			Main Building: 1st & 2nd Floor West Wing, 1st Floor Throughout, 2nd Floor West Rooms		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No C	hange			1							
Comments:	•				]							
2023 Fall Six	Month Survey: No C	hange			-							
Comments:												
2023 Spring	Six Month Survey: No	Change			-							
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No C	hange			_							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104(F5)	9x9 Tan Floor Tile Mastic ABATED			Main Building- Library, East Wing Throughout		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

104(F64)	9x9 Light Brown Floor Tile Mastic ABATED		Main Building- West Wing, 1st, 2nd & 3rd Corridor Patches & East End		Miscellaneous			YES	X NO
0000 E !! O'	M (1.0 N O)			1					
	Month Survey: No Cha	ange							
Comments:									
2023 Fall Six	Month Survey: No Cha	ange							
Comments:									
				1					
2023 Spring S	Six Month Survey: No (	Change							
Comments:									
				1					
2024 Spring S	Six Month Survey: No (	Change		1					
Comments:	,			1					
2024 Fall Six	Month Survey: No Cha	ange		1					
Comments:		<u> </u>		1					
Commonto.				1					
				J					

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

Damage

Type

Damage

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

Material Location

Material Location

Main Building- West Wing

104(F65)	9x9 Medium Brown Floor Tile Mastic ABATED		1st & 3rd Floor Corridor Patches & East Wing
	•	•	
2022 Fall Six	Month Survey: No Ch	nange	
Comments:			
2023 Fall Six	Month Survey: No Ch	nange	
Comments:			
2023 Spring	Six Month Survey: No	Change	
Comments:			
2024 Fall Six	Month Survey: No Ch	nange	
Comments:			
2024 Spring	Six Month Survey: No	Change	
Comments:			
			_

Material

Quantity

Material

Units

HA No

HA No

Material Description

Material Description

9x9 Medium Brown Floor

Material

Quantity

Material

Units

Change in Assessment Category

Change in Assessment Category

X NO

YES

104(F66)	9x9 Yellow Floor Tile Mastic ABATED			Main Building- 1st Floor Corridor Patches		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:												
2023 Spring Six Month Survey: No Change												
Comments:					-							
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:					-							
	Month Survey: No Ch	ange			-							
Comments:												
	Six Month Survey: No	Change										
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
104(F67)	9x9 Green Floor Tile Mastic ABATED			Main Building- 1st Floor Stairwell, East Wing, and 2nd & 3rd Floor Hallways		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

105 (F68)	Various Sizes of Brown Speckled Floor Tile ABATED		Main Building- 1st, 2nd & 3rd Floor Patches in East & West Wings	Miscellaneous			YES	X NO
0000 F-II O'	Maril O a a Na Ola							
2022 Fall SIX	Month Survey: No Char	nge						
Comments:								
2023 Spring	Six Month Survey: No C	hange						
Comments:								
2023 Fall Six	Month Survey: No Chai	nge						
Comments:								
2024 Fall Six	Month Survey: No Char	nge						
Comments:								
2024 Spring	Six Month Survey: No C	hange						
Comments:	-							

Type

Material

Category

Material Location

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106(F68)	Various Sizes of Brown Speckled Floor Tile Mastic ABATED			Main Building- 1st, 2nd & 3rd Floor Patches in East & West Wings		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

107(CM70)	Carpet Mastic under Multicolored ABATED			Main Building- 2nd Floor West Wing, far West Wing		Miscellaneous					YES	X NO
2222 = 11.21				•	1	·	•					
	Month Survey: No Ch	ange										
Comments:												
	<del></del>											
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

Material Location

Main Building 2nd Floor

Office, 1st Floor West

2022 Fall Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: No Change	
Comments:	
2023 Spring Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: No Change	
Comments:	
2024 Fall Six Month Survey: No Change	
Comments:	

Quantity

Units

HA No

107(CM71)

Material Description

Grey Carpet Mastic ABATED

Material

Quantity

Material

Units

108	Grey Vinyl Stair Treads ABATED		Main Building- 1st, 2nd & 3rd Floors, East & West Wings	Miscellaneous			YES	X NO
2022 Fall Si	x Month Survey: No Ch	ango						
	•	lariye						
Comments:								
2023 Spring	Six Month Survey: No	Change						
Comments:								
2023 Fall Si	x Month Survey: No Ch	ange						
Comments:	•							
2024 Fall Si	x Month Survey: No Ch	ange						
Comments:	•							
2024 Spring	Six Month Survey: No	Change						
Comments:		Ŭ						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
109	Vinyl Stair Tread Mastic ABATED			Main Building- 1st, 2nd & 3rd Floors, East & West Wings		Miscellaneous					YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

Comments:

2023 Spring Six Month Survey: No Change
Comments:

2023 Fall Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Units

Material

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110 (F75)	4" Brown Vinyl Baseboard ABATED			Main Building- 1st Floor Corridor leading to West Wing, 3rd Floor Northwest Corner		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110 (F76)	4" Black Baseboard ABATED			Main Building- 1st, 2nd & 3rd Floor Throughout East Wing & Corridor- East Wing 1st Floor Northeast Corner West Wing		Miscellaneous					YES X NO
2022 Fall Six Comments:	Month Survey: No Ch	nange									

2022 Fall Six Month Survey: No Change Comments:  2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:
2023 Spring Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments:
Comments:  2023 Fall Six Month Survey: No Change Comments:
Comments:  2023 Fall Six Month Survey: No Change Comments:
2023 Fall Six Month Survey: No Change Comments:
Comments:
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

110 (F77)	4" Tan Baseboard ABATED			Main Building- 1st, 2nd Floor, Northeast & Northwest Portions		Miscellaneous					YES	X NO
2022 Fall Siv	Month Survey: No Ch	ange		·	7						·	
Comments:	Month Survey. No Ch	ange										
Comments.												
2023 Fall Six	Month Survey: No Ch	ange										
Comments:	•	•										
2023 Spring	Six Month Survey: No	Change										
Comments:	SIX MONUT Survey. NO	Change										
	Six Month Survey: No											
Comments:												
2024 Fall Six	Month Survey: No Ch	ongo										
Comments:	Month Survey. No Ch	ange			_							
Comments.												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
111(F75)	4" Brown Vinyl Baseboard Mastic ABATED			Main Building- 1st Floor Corridor leading to West Wing, 3rd Floor Northwest Corner		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

2023 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Comments:

Comments:

Comments:

Comments:

Material

Units

Material

Quantity

Material Location

111(F76)	4" Black Baseboard ABATED			Main Building- 1st, 2nd & 3rd Floors Throughout		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	•	•										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					  -							
2023 Spring	Six Month Survey: No	Change										
Comments:					-							
	Six Month Survey: No	Change										
Comments:					-							
	Month Survey: No Ch	ange										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
111(F77)	4" Tan Baseboard Mastic ABATED			Main Building- 1st & 2nd Floors, Northeast &		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Northwest portions

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
112 (F80)	6" Black Vinyl Baseboard ABATED			Main Building- 2nd Floor, Southeast Corner		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange									
Comments:	World Garvey. No on	arigo									
2023 Spring S	Six Month Survey: No	Change									
Comments:	,	<u> </u>									
2023 Fall Six	Month Survey: No Ch	ange			-						
Comments:		-									
2024 Fall Six	Month Survey: No Ch	ange			-						
Comments:											
2024 Spring S	Six Month Survey: No	Change			-						
Comments:											
					J						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113 (F80)	6" Black Vinyl Baseboard Mastic (ABATED)			Main Building- 2nd Floor Southeast Corner		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material

		Quantity	Units		Type	Category	Type	Quantity	Units		
114 (CT1)	12x12 Ceiling Tile ABATED			Main Building- 1st Floor West Wing near Northwest Corner		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Cha	ange		•	7	•		·		•	
	Month Survey. No Ch	arige			4						
Comments:											
2023 Fall Six	Month Survey: No Cha	ange									
Comments:											
2023 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Cha	ange									
Comments:	-				1						
22					1						
2024 Spring	Six Month Survey: No	Change									
Comments:	•				1						

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
114 (CTM1)	12x12 Ceiling Tile Mastic ABATED			Main Building- 1st Floor West Wing near Northwest Corner		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
116	12x12 Cork Tile ABATED			Main Building- 2nd Floor West Wing Room Northeast Corner of Building		Miscellaneous					YES	X NO
2022 Fall S	2022 Fall Six Month Survey: No Change											
	Comments:											
2023 Sprin	2023 Spring Six Month Survey: No Change											
	Comments:											
2023 Fall S	2023 Fall Six Month Survey: No Change											
Comments:												
2024 Fall S	2024 Fall Six Month Survey: No Change											
Comments:												
2024 Sprin	2024 Spring Six Month Survey: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
151	12X12 Grey/Dark Brown Floor Tile (Replacement)	50000	SF	1st, 2nd & 3rd Floor Hallways		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

152	Baseboard Mastic	50000	SF	1st, 2nd & 3rd Floors Throughout Building		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange									
Comments:	Month Garvey. 140 On	ange									
2022 Caring (	Civ Month Curvoy No.	Changa			-						
Comments:	Six Month Survey: No	Change									
Comments.											
2023 Fall Six	Month Survey: No Ch	ange									
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									
Comments:		-									
2024 Spring S	Six Month Survey: No	Change			_						
Comments:	,										
					J						

Asbestos

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
153	2'x4' Speckled Pattern Ceiling Tile (w/ 2'x2' Sections)	1350	SF	1st Floor: West Wing - Dining Room: 4th Floor: Center Building - Room 402 and 405		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
154	4" Grey Vinyl Baseboard	5000	LF	Throughout Classrooms & Offices		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										

2000 Fall O' Marth O and No Observe
2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
0000 F II 0' M (I 0 N O
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
155	Mastic Associated with 4" Grey Vinyl Baseboard	5000	LF	Throughout Classrooms & Offices		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
156	12x12 White with Grey Specks Floor Tile	5350	SF	1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
0004.0 : 0: 14 .4 .0 14 .0
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
157	12x12 White with Grey Specs Floor Tile Mastic	5350	SF	1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
158	2'x2' Smooth Pattern Ceiling Tile	7375	SF	1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139, and North/South Corridor		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
159	Interior Window Caulk	400	LF	1st Floor: East Wing - Room 131, 133, 135, 137, and 139; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
160	Terrazzo Floor	2025	SF	1st Floor: East Wing - North/South Corridor		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
161	12x12 Grey Speckled Floor Tile	2600	SF	1st Floor: Room 116, 116A, 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, 405 & Engineer's Office		Miscellaneous	No	None	0		YES	X NO

Comments:  2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	Comments:
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	Comments:
Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Spring Six Month Survey: No Change	Comments:
Comments: 2024 Spring Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change	2024 Fall Six Month Survey: No Change
	Comments:
Comments:	2024 Spring Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate
162	12x12 Grey Speckled Floor Tile Mastic	2600	SF	1st Floor: Room 116, 116A; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, 405 & Engineer's Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
163	Black Sink Undercoat	1	EA	4th Floor: Center Building - Room 400		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange	_		]							

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
164	Black Counter Top	200	SF	4th Floor: Center Building - Room 400 and 400A		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
165	Drywall	4600	SF	4th Floor: Center Building - Room 400, 400A, and 404		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange				•						
2023 Spring S	Six Month Survey: No	Change										

2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

2024 Spring Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
166	Drywall Joint Compound	4600	SF	4th Floor: Center Building - Room 400, 400A, and 404		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
167	Sheet Flooring - Brown Multi-Color Pattern	1350	SF	1st Floor: West Wing - Dining Room		Miscellaneous	No	None	0		YES X NO
					-						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
168	Sheet Flooring - Brown Multi-Color Pattern Mastic	1350	SF	1st Floor: West Wing - Dining Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change Comments:  2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:	
2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	Comments:
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	Comments:
Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Spring Six Month Survey: No Change	Comments:
Comments: 2024 Spring Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change	2024 Fall Six Month Survey: No Change
<u> </u>	Comments:
<u> </u>	
Comments:	2024 Spring Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessr	ment Category
169	White Sink Undercoating	1	EA	4th Floor: Center Building - Room 404		Miscellaneous	No	None	0		YES		X NO
	Month Survey: No Ch	ange											
Comments:													
2023 Spring S	Six Month Survey: No	Change											
Comments:													
2023 Fall Six	Month Survey: No Ch	ange											
Comments:													
2024 Fall Six	Month Survey: No Ch	ange			-								
Comments:	Monar Carvey. 140 On	ungo			-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
170	Brown Carpet Mastic	2200	SF	Rooms 100 A, 100 C, 100 E, 100 F, 105, 111, 116A and 116B		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change

Comments:

Page 84

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
171	Carpet Mastic Blue w/White Streaks	1500	SF	Rooms 201, 201A, 201C and 201D		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	•											
2023 Spring	Six Month Survey: No	Change			1							
Comments:	•	<u> </u>			]							
2023 Fall Six	Month Survey: No Ch	ange			1							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	,				]							
2024 Spring	Six Month Survey: No	Change			1							
Comments:	•											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
172	Carpet Mastic Brown w/Blue and Orange Streaks	10300	SF	Rooms 147, 153A, 153C, 153D, 153E, 153F, 153F2, 235, 237A, 237D and Library		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan or After Renovations		Miscellaneous		Unknown			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Gwendolyn Brooks College Preparatory Academy HS
Date: 11/6/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. Posted to the CPS website.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.