## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Chicago High School for the Arts (ChiArts) 63051 4400 School: **Oracle Unit:** Building ID: 2714 W. Augusta Blvd. Address: Region: 02 Mail Room: Asbestos Surveyor: Bermejo, Rolando X CHECK HERE IF NO CHANGE TO ASBESTOS 10/31/2024 Survey Date: Email Address

				Elliali At	uuress.	rbermej	04@cps.eau					
	A copy of the2022/20	23 notice to p	parents and	I staff regarding the asb	estos manag	ement plan no	otifications w	vas distribute	d via:			
	Each child's backp	ack	Notice	printed in school's new	sletter	Notice p	rinted in sch	ool's calenda	r X Otl	ner posted	to CPS websit	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Catego
01	Aircell pipe insulation	800	LF	Boiler room corridor by the warm air chamber across from play room 7		TSI	Yes	Loc	5		X YES	NO
2022 Fall S	Six Month Survey: Repa	aired			7							
Comments	repaired in deck 1											
2023 Fall S	Six Month Survey: No C	hange										
Comments	:											
2023 Sprin	2023 Spring Six Month Survey: No Change											
Comments	:											
2024 Spring Six Month Survey: No Change												
Comments	:	•										

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
02	Hard Coat Plaster			Throughout 1892 Building		Surface					YES	X NO
2022 Fall Six	Month Survey: No Cl	hange										
Comments:												
2023 Fall Six	Month Survey: No Cl	hange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
	Month Survey: No Cl	hange										
Comments:												
<u> </u>					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	1'x1' Ceiling Tile (ABATED)	0		Rooms 207, 208, 210, 211, and 305- 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	2'x2' Ceiling Tile (ABATED)	0		1st & 2nd Floor Corridors, 1st Floor Teachers Toilet - 1892		Miscellaneous					YES X NO
2022 Fall Six	Month Survey: No Ch	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Paperwrap Pipe Insulation	900	LF	Basement Corridor, Engine Room - 1892		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	MJP E/F/V on Aircell Pipe Insulation	80	LF	Boiler & Engine Rooms, Bsmt Cor, 007, 006 -1892		TSI	Yes	None	0		X YES NO

2022 Fall Six Month Survey: Repaired
Comments:repaired in deck 3
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	MJP E/F/V on Paperwrap Pipe Insulation	30	LF	Room 107, 108, 007, Basement Corridor, Engine Room - 1892		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Air Cell Duct Insulation	250	LF	Room 002 (Playroom), 1st and 2nd floor Janitor's Closet, 2nd Girl's and Boys Toilet, and 1st floor Girl's Toilet - 1921		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Hard Coat Plaster			Throughout 1921		Surface	Yes	None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Paperwrap Pipe Insulation	400	LF	Engine Room, 021, Basement Corridor, 1st & 3rd Floor Janitors Closet - 1921		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Mag Block Pipe Insulation	300	LF	Boiler Room - 1892		TSI	Yes	Loc	4		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2004 Christia Circ Month Coming No Change
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units	G	,
20	ACM Rope	10	LF	Boiler Room - 1892		TSI	Yes	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring Comments:	Six Month Survey: No	Change										
2024 Spring Comments:	Six Month Survey: No	Change			-							
	Month Survey: No Ch	ange			- - - -							
					_							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Plaster	150000	SF	Throughout 1921 Building		Surface	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
22	Boiler Gaskets	10	SF	Boiler #1 in Boiler Room - 1892		Miscellaneous	Yes	None	0		YES	X NO
2022 Fall Si Comments:	ix Month Survey: No C	hange										
2023 Fall S Comments:	ix Month Survey: No C	hange										
2023 Spring Comments:	g Six Month Survey: No	o Change										
2024 Spring Comments:	g Six Month Survey: No	o Change										
	ix Month Survey: No C	hange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Boiler Gasket (ABATED)	0		Boiler #2 in Boiler Room -1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	MJP E/F/V on Paperwrap Pipe Insulation	50	LF	Engine Room, 021, Basement Corridor - 1921		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	MJP E/F/V on Magblock Pipe Insulation	60	LF	Boiler Room - 1892		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

26	9x9 Green Off-White w/ Black Streaks Floor Tile (ABATED)	0	Rooms 307 & 309 - 1892		Miscellaneous	None		YES	X NO
0000 5-11 0	Martin Orana Na Ob			1					
	Month Survey: No Ch	ange							
Comments:									
2023 Fall Six	Month Survey: No Ch	ange							
Comments:	-								
2023 Spring S	Six Month Survey: No	Change							
Comments:	•								
2024 Spring S	Six Month Survey: No	Change							
Comments:	-	, <u></u> -							
2024 Fall Six	Month Survey: No Ch	ange							
Comments:	•								
				•					

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

Damage

Туре

Damage

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

27	12"x12" Brown w/ Speckles Floor Tile (ABATED)	0	206, 105, 106, 109, 107 (Main Office),108 and Staff Lounge - 1892
2022 Fall Six	Month Survey: No Cha	ange	
Comments:			
2023 Fall Six	Month Survey: No Cha	ange	
Comments:			
2023 Spring S	Six Month Survey: No	Change	
Comments:			
2024 Spring S	Six Month Survey: No	Change	
Comments:			
2024 Fall Six	Month Survey: No Cha	ange	
Comments:			
		•	

Material

Quantity

Material

Units

HA No

HA No

Material Description

Material Description

Material

Units

Material

Quantity

Material Location

**Material Location** 

1st & 3rd Floor Corridors,

Change in Assessment Category

Change in Assessment Category

X NO

YES

28	Black Linoleum NOT OBSERVED			Auditorium - 1921		Miscellaneous	No				YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	•	Ŭ										
2023 Fall Six	Month Survey: No Ch	ange			1							
Comments:	•	Ŭ										
2023 Spring Comments:	Six Month Survey: No	Change										
	Six Month Survey: No	Change			-							
Comments:												
	Month Survey: No Ch	ange			=							
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
29	9"x9" Off White w/ Black Streaks Floor Tile Mastic (ABATED)	0		Rooms 307 & 309 - 1892		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
30	12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)	0		1st & 3rd Floor Corridors, 206, 105, 106,196, 109, 107 (Main Office),108 and Staff Lounge - 1892		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Cha	ange			Ī							

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Brown Linoleum (ABATED)	0		Auditorium Balcony - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

32	9"x9" Brown Floor Tile (ABATED)	0		3rd Floor Teacher's Toilet - 1921		Miscellaneous			YES	X NO
2022 Fall Civ	Manth Cumini No Chi									
	Month Survey: No Cha	ange								
Comments:										
2023 Fall Six	Month Survey: No Cha	ange								
Comments:	•									
2023 Spring S	Six Month Survey: No	Change								
Comments:										
2024 Spring S	Six Month Survey: No	Change								
Comments:										
2024 Fall Six Month Survey: No Change										
Comments:	•									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" Green w/ White Streaks Floor Tile (ABATED)	0		1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	9"x9" Brown Floor Tile Mastic (ABATED)	0		3rd Floor Teacher's Toilet - 1921		Miscellaneous					YES X NO
					1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Oracle Unit: 63051

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Green w/ White Streaks Floor Tile Mastic (ABATED)	0		1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Aircell Pipe Insulation	21	LF	Basement Corridor, Fan Rooms, All Janitors Closets - 1921		TSI	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	MJP E/F/V on Aircell Pipe Insulation	10	LF	Basement Corridor, Fan Rooms, All Janitors Closets - 1921		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Mag Block Pipe Insulation	14	LF	Room 002 - 1921		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	MJP E/F/V on Mag Block Pipe Insulation	7	LF	Room 002 - 1921		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	MJP E/F/V on Fiberglass Pipe Insulation	7	LF	Coal room, Boiler room, Basement Corridor, Fan Rooms 1 and 3 - 1892		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	MJP E/F/V on Fiberglass Pipe Insulation	50	SF	Boys and Girls Playrooms, Assembly Hall - 1921		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" Coffee Brown Floor Tile (ABATED)	0		Room 306, 2nd & 3rd Floor Corridors - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Page 18

		Quantity	Units		Type	Category	Туре	Quantity	Units		
42A	12"x12" Coffee Brown Floor Tile Mastic (ABATED)	0		Room 306, 2nd & 3rd Floor Corridors - 1892		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Cha	ange			1						
Comments:		<u>g</u> c			]						
2023 Fall Six	Month Survey: No Cha	ange			1						
Comments:	-				]						
2023 Spring S	Six Month Survey: No	Change									
Comments:											
2024 Spring S	Six Month Survey: No	Change			-						
Comments:											
2024 Fall Six	Month Survey: No Cha	ange			-						

Material

Friable

Damage

Damage

Asbestos

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Green w/ White Streaks Floor Tile (ABATED)	0		1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317, mens lounge& 319, 007 - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43A	12"x12" Green w/ White Streaks Floor Tile (ABATED)	0		1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317,mens lounge & 319, 007 - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)	0		Rooms 005, 213, 312, 311, 305 (under carpet), 313-315, 317, 319 & 3rd Floor Corridor - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44A	12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED)	0		Rooms 005, 213, 312, 311, 305, (under carpet) 313-315, & 3rd Floor Corridor - 1892		Miscellaneous					YES X NO

HA No Ma	aterial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1 /15	2"x12" White w/ Specks oor Tile (ABATED)	0		Rooms 308, 208, 211, 215, 110, 113, 115, 117, & 119 - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	9"x9" Dark Brown w/ White Streaks Floor Tile (ABATED)	0		Room 001,002, 003 - 1921		Miscellaneous					YES X NO

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	46A	9"x9" Dark Brown w/ Streaks Floor Tile Mastic (ABATED)	0		Room 001,002,003 - 1921		Miscellaneous					YES	X NO
-				•		1							

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	9"x9" Gray w/ White Streaks Floor Tile (under carpet) (ABATED)	0		Engineer's Office (Under Carpet) - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

47A	9"x9" Gray w/ White Streaks Floor Tile Mastic (ABATED)	0		Engineer's Office (Under Carpet) - 1892		Miscellaneous					YES	X NO
2022 Fall \$	Six Month Survey: No Ch	ange			]							
Comments	•	<u> </u>										
2023 Fall S	Six Month Survey: No Ch	ange										
Comments	:											
2023 Sprin	g Six Month Survey: No	Change										
Comments	:											
2024 Sprin	g Six Month Survey: No	Change			_							
Comments	:											
2024 Fall S	Six Month Survey: No Ch	ange										
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
48	9"x9" Black VFT (ABATED)	0		1st Floor Teacher's Toilet, & Engineer's Office (Under Carpet) -		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

2022 Fall Six Month Survey: No Change

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Comments:

Comments:

Comments:

Comments:

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48A	9"x9" Black Floor Tile Mastic (ABATED)	0		1st Floor Teacher's Toilet, & Engineer's Office (Under Carpet) - 1892		Miscellaneous					YES X NO
2022 Fall Six	x Month Survey: No C	hange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	9"x9" Light Beige w/ Light Brown Streaks Floor Tile (ABATED)	0		Room 209 - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49A	9"x9" Light Beige w/ Lt Brown Streaks Floor Tile Mastic (ABATED)	0		Room 209 - 1892		Miscellaneous					YES X NO
2022 Fall Six	Month Survey: No Ch	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2004 Chaina Civ Month Cuning Alo Change
2024 Spring Six Month Survey: No Change
Comments:
0004 5 11 01 14 11 0
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12"x12" Dark Brown w/ White Speck Floor Tile (ABATED)	0		Room 106, & 111 - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
50A	12"x12" Dark Brown w/ White Specks Floor Tile Mastic (ABATED)	0		Room 106, & 111 - 1892		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange		•							•	

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12"x12" Peach Floor Tile (ABATED)	0		Main Office Toilet - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
51A	12"x12" Peach Floor Tile Mastic (ABATED)	0		Main Office Toilet - 1892		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:	,				]							
2023 Fall Six	Month Survey: No Ch	ange			-							
Comments:					]							
2023 Spring S	Six Month Survey: No	Change			]							
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:					_							
2024 Spring S	Six Month Survey: No	Change										
Comments:	·				_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12"x12" Light Green Floor Tile (ABATED)	0		Room 112 - 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change Comments:  2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change Comments:	
2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	Comments:
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	Comments:
Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Spring Six Month Survey: No Change	Comments:
Comments: 2024 Spring Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change	2024 Fall Six Month Survey: No Change
<u> </u>	Comments:
<u> </u>	
Comments:	2024 Spring Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
52A	12"x12" Light Green Floor Tile Mastic (ABATED)	0		Room 112 - 1892		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Fall Six Comments:	Month Survey: No Ch											
2023 Spring S	Six Month Survey: No	Change			-							
	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)	0		Rooms 002, 302, 326 - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53A	12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED)	0		Rooms 002, 302, 326 - 1921		Miscellaneous					YES X NO
	•	•	•	•	1	•	•		•		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	9"x9" Black Floor Tile (ABATED)	0		3rd Floor Teacher's Toilet - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
54A	9"x9" Black Floor Tile Mastic (ABATED)	0		3rd Floor Teacher's Toilet - 1921		Miscellaneous					YES	X NO
2022 Fall S	Six Month Survey: No C	hange			]							
Comments	S:	<u> </u>			1							
2023 Sprin	ng Six Month Survey: No	o Change										
Comments	S:											
2023 Fall \$	Six Month Survey: No C	hange			_							
Comments	S:											
2024 Fall S	Six Month Survey: No C	hange			-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12"x18" Black Floor Tile (ABATED)	0		3rd Floor Teacher's Toilet - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

Comments:

2024 Spring Six Month Survey: No Change

		Quantity	Units		Type	Category	Type	Quantity	Units		
55A	12"x18" Black Floor Tile Mastic (ABATED)	0		3rd Floor Teacher's Toilet - 1921		Miscellaneous				YES	X NO
2022 Fall Six	Month Survey: No Ch	nange			]						
Comments:					1						
2023 Spring S	Six Month Survey: No	Change			_						
Comments:					]						
2023 Fall Six	Month Survey: No Ch	nange									
Comments:					 						
2024 Fall Six	Month Survey: No Ch	nange									
Comments:					 						
2024 Spring S	Six Month Survey: No	Change									
Comments:	·			·							

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	9"x9" Light Brown w/ Dark Floor Tile (ABATED)	0		Library (221/223) - 1921		Miscellaneous		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
56A	9"x9" Light Brown w/ Dark Floor Tile Mastic (ABATED)	0		Library (221/223) - 1921		Miscellaneous		None			YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange			]							
Comments.												
2023 Spring S	Six Month Survey: No	Change										
Comments:	-	_										
2023 Fall Six	Month Survey: No Cha	ange			-							
Comments:	•											
2024 Fall Six	Month Survey: No Cha	ange			-							
Comments:	•	_			1							
2024 Spring S	Six Month Survey: No	Change			1							
Comments:	,	<u> </u>										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12"x12" White Specks Floor Tile (ABATED)	0		Room 321, 218 - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
57A	12"x12" White Specks Floor Tile Mastic (ABATED)	0		Room 321, 218 - 1921		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
2023 Spring Comments:	Six Month Survey: No	Change			] - -							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring Comments:	Six Month Survey: No	Change			-  - -							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12"x12" Brown w/ Speckles Floor Tile (ABATED)	0		2nd Floor Corridor -1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
58A	12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)	0		2nd Floor Corridor -1921		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:												
2023 Spring S	Six Month Survey: No	Change			_							
Comments:					]							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					_							
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring S	Six Month Survey: No	Change										
Comments:				·	_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	12"x12" Brown Floor Tile (ABATED)	0		Room 021, 023, 025, Nurses Office - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

59A	12"x12" Brown Floor Tile Mastic (ABATED)	0		Room 021, 023, 025, Nurses Office - 1921		Miscellaneous			YES	X NO
2022 Fall Siv	Month Survey: No Cha	ange			1					
Comments:	Month Survey. No One	arige								
Comments.					-					
2023 Spring Six Month Survey: No Change										
Comments:		•								
					]					
2023 Fall Six	Month Survey: No Cha	ange								
Comments:										
2224 5 11 21										
	Month Survey: No Cha	ange								
Comments:										
	Six Month Survey: No	Change								
Comments:										
	·	·		<u> </u>						

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	9"x9" Beige w/ Brown Streaks Floor Tile (ABATED)	0		Assembly Hall - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
60A	9"x9" Beige w/ Brown Streaks Floor Tile Mastic (ABATED)	0		Assembly Hall - 1921		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	- 	•	•	•	•	•	•				
Comments:												
2023 Spring	Six Month Survey: No	+										
Comments:												
2023 Fall Six	Month Survey: No Ch	nange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:		4										
2024 Spring Six Month Survey: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	9"x9" Brown w/ Beige Streaks Floor Tile (ABATED)	0		Assembly Hall - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
61A	9"x9" Brown w/ Beige Streaks Floor Tile Mastic (ABATED)	0		Assembly Hall - 1921		Miscellaneous					YES	X NO
2022 Fall	Six Month Survey: No C	hange	•	~		•	•	•	•	•	•	
Comment	s:											
2023 Fall Six Month Survey: No Change												
Comment	s:											
2023 Sprii	ng Six Month Survey: No	Change										
Comment	s:											
2024 Fall	Six Month Survey: No C	hange										
Comment	·	<u> </u>										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	12"x12" Off White w/ Brown Specks Floor Tile (ABATED)	0		Room 001, Teachers Toilet - 1921		Miscellaneous		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

2024 Spring Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
62A	12"x12" Off White w/ Brown Specks Floor Tile Mastic (ABATED)	0		Room 001 and teacher's lounge- 1921		Miscellaneous		None			YES		X NO
2022 Fall Six	x Month Survey: No Ch	ange		•	1	•	•	•	•	•	•		
Comments:		<b>y</b> -											
2023 Spring	Six Month Survey: No	Change											
Comments:													
2023 Fall Six	x Month Survey: No Ch	ange											
Comments:													
2024 Fall Six	x Month Survey: No Ch	ange											
Comments:													
2024 Spring	Six Month Survey: No	Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12"x12" Dark Brown w/ White Specks Floor Tile (ABATED)	0		Assembly Hall - 1921		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

63A	White Specks Floor Tile Mastic (ABATED)	0	Assembly Hall - 1921	Miscellaneous			YES	X NO
[ · ·				٦				
2022 Fall Si	x Month Survey: No Cl	nange						
Comments:								
2023 Spring	Six Month Survey: No	Change						
Comments:								
2023 Fall Si	x Month Survey: No Cl	nange						
Comments:								
2024 Fall Si	x Month Survey: No Cl	nange						
Comments:	•							
				1				
2024 Spring	Six Month Survey: No	Change		1				
Comments:	•			1				

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12"x12" Red/Orange w/ Yellow Specks Floor Tile (ABATED)	0		Kitchen & Room 15		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
64A	12"x12" Red/Orange w/ Yellow Specks Floor Tile Mastic (ABATED)	0		Kitchen & Room 15		Miscellaneous					YES	X NO
2022 Fall S	ix Month Survey: No C	hange	•	~		•	•	•	•	•	•	
Comments:		<u> </u>										
2023 Spring	Six Month Survey: No	Change										
Comments:												
2023 Fall S	ix Month Survey: No C	hange										
Comments:												
2024 Fall S	ix Month Survey: No C	hange										
Comments:												
2024 Spring	g Six Month Survey: No	Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Brown Carpet Adhesive (ABATED)	0		Basement Eng. Office		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
66	12 x 12 Light Blue Mix Floor Tile (ABATED)	0		Rooms 213, 219, 313, and 315		Miscellaneous					YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12 x 12 Light Blue Mix Floor Tile Adhesive (ABATED)	0		Rooms 213, 219, 313, and 315		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
·

68	12"x12" Bright Blue Mix Floor Tile (ABATED)	0	Rooms 309 and 317		Miscellaneous			YES	X NO
2022 Fall Six	Month Survey: No Cha	ange							
Comments:	-								
2023 Spring S	Six Month Survey: No	Change							
Comments:	-								
2023 Fall Six	Month Survey: No Cha	ange							
Comments:	-								
2024 Fall Six	Month Survey: No Cha	ange							
Comments:	-								
2024 Spring S	Six Month Survey: No	Change							
Comments:									
L				1					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12"x12" Bright Blue Mix Floor Tile Adhesive (ABATED)	0		Rooms 309 and 317		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
70	12"x12" Medium Blue Mix Floor Tile (ABATED)	0		Room 217-1892	1777	Miscellaneous		1775			YES	X NO
2022 Fall Si	x Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2023 Fall Si	x Month Survey: No Ch	ange										
Comments:												
2024 Fall Si	x Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12"x12" Medium Blue Mix VFT Adhesive (ABATED)	0		Room 217-1892		Miscellaneous					YES X NO

Comments:

	Pattern) (ABATED)										
2022 Fall S	ix Month Survey: No C	hange									
Comments:	•	9									
2023 Sprine	g Six Month Survey: No	Change									
Comments											
2023 Fall S	ix Month Survey: No C	hange									
Comments:											
2024 Fall S	ix Month Survey: No C	hange									
Comments:											
2024 Spring	g Six Month Survey: No	Change									
Comments											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	12"v12" Reige Floor Tile				715.5	2 222 3017		71. "			

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

0

HA No

72

73

Material Description

12"x12" Beige Floor Tile (As part of Checkerboard

Mastic (As part of Checkerboard Pattern) (ABATED) Material

Quantity

Material

Units

Material Location

Main Office

Main Office

Change in Assessment Category

X NO

X NO

YES

YES

74	12x12 Dark Gray Specks VFT (ABATED)	0		225-1921 Bldg		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			1							
Comments:		<u> </u>										
2023 Spring	Six Month Survey: No	Change										
Comments:												
2023 Fall Six Month Survey: No Change												
Comments:												
2024 Fall Six	Month Survey: No Ch	ange			-							
Comments:	,											
2024 Spring	Six Month Survey: No	Change			1							
Comments:	,											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
75	12x12 Dark Gray W/ Specks VFT Mastic (ABATED)	0		225 - 1921 Bldg		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
76	12x12 Light Blue w/ Speckles VFT (ABATED)	0		019, 213, 215, 219- 1892 Bldg		Miscellaneous					YES	X NO
2022 Fall Siz Comments:	x Month Survey: No Ch	ange										
2023 Spring Comments:	Six Month Survey: No	Change										
2023 Fall Siz	x Month Survey: No Ch	ange										
2024 Fall Si	x Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	12x12 Light Blue w/ Speckles VFT Mastic (ABATED)	0		019, 213, 215, 219-Bldg 1892		Miscellaneous					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

Comments:

2024 Spring Six Month Survey: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	12x12 Light Blue w/ Speckles VFT	1500	SF	001(Lunchroom), 002		Miscellaneous	No	None	0		YES X NO
2022 Fall Civ	Month Cumrous No Ch				1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	12x12 Light Blue w/ Speckles VFT Mastic	1500	SF	001(Lunchroom), 002		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
80	Carpet Mastic(Tile Carpet) (ABATED)	0		Library		Miscellaneous					YES	X NO
2022 Fall Si	x Month Survey: No Ch	nange		•					•	•		
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:	-											
2023 Fall Si	x Month Survey: No Ch	nange										
Comments:												
2024 Fall Si	x Month Survey: No Ch	nange										
Comments:												
2024 Spring	Six Month Survey: No	Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	2'x4' White Ceiling Tile	3000	SF	Room 001, Room 002, Library (2nd Floor)		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	Dry Wall Soffit	200	SF	Room 001, Room 002		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	24"x24" Beige VFT	30000	SF	Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108, 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320. 1st, 2nd, and 3rd floor corridors.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	24"x24" Beige VFT Mastic	30000	SF	Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108, 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320, 1st, 2nd, and 3rd floor corridors.		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	24"x24" light blue VFT	2500	SF	Rooms 003, 005, 013, 318, 320		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	24"x24" light blue VFT Mastic	2500	SF	Rooms 003, 005, 013, 318, 320		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	24"x24" gray VFT	8000	SF	Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	24"x24" gray VFT Mastic	8000	SF	Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	24"x24" dark brown VFT	3000	SF	Rms 005 and 013; Lunchroom manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

Comments:  2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2023 Spring Six Month Survey: No Change Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	2022 Fall Six Month Survey: No Change
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	Comments:
Comments:  2023 Fall Six Month Survey: No Change Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2023 Spring Six Month Survey: No Change
Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	Comments:
Comments:  2024 Fall Six Month Survey: No Change Comments:  2024 Spring Six Month Survey: No Change	
2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change	2023 Fall Six Month Survey: No Change
Comments: 2024 Spring Six Month Survey: No Change	Comments:
Comments: 2024 Spring Six Month Survey: No Change	
2024 Spring Six Month Survey: No Change	2024 Fall Six Month Survey: No Change
	Comments:
Comments:	2024 Spring Six Month Survey: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	24"x24" dark brown VFT Mastic	3000	SF	Rms 005 and 013; Lunchroom Manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	24"x24" Black VFT	3000	SF	Rm 025 and Auditorium		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units	· ·	
94	24"x24" Black VFT Mastic	3000	SF	Rm 025 and Auditorium		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:					1							
2023 Spring S	Six Month Survey: No	Change			_							
Comments:					-							
	Month Survey: No Ch	ange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:					=							
	Six Month Survey: No	Change										
Comments:					=							
					1							
						T		_	_	_		 

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	Carpet Mastic	2500	SF	Rm 011, Auditorium		Miscellaneous	No	None	0		YES X NO
0000 E # 0:					1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
96	Decorative Plaster	300	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]							
Comments:	•	•										
2023 Spring	Six Month Survey: No	Change			1							
Comments:	•	<u> </u>										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					]							
2024 Fall Six	Month Survey: No Ch	ange			_							
Comments:	•				]							
2024 Spring	Six Month Survey: No	Change			-							
Comments:	•				]							
					╛							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	2'x2' White Ceiling Tile	12000	SF	Rooms 105A, 106, 107, 108, 109, 110, 205, 206, 207, 208, 210, 218A, 324, and 326		Miscellaneous	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	24"x24" Orange VFT	2000	SF	Rms 205, 206, 207, 208, 210, and 221		Miscellaneous	No	None	0		YES X NO
					1						

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	24"x24" Orange VFT Mastic	2000	SF	Rms 205, 206, 207, 208, 210, and 221		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
100	24"x24" Green VFT	1500	SF	Rms 112, 115, and 117		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six Month Survey: No Change Comments:												

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	24"x24" Green VFT Mastic	1500	SF	Rms 112, 115, and 117		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	frame hood panel	12	SF	Room 208		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Month Survey: No Change											

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Science Lab Tables	180	SF	Rooms 206, 208, 207, 210 and 317		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
104	Spray On Insulation	3000	SF	Attic In addition 1892		Surface	Yes	None	0		YES	X NO
2022 Fall Six Comments:	x Month Survey: No Cl											
2023 Fall Six Comments:	x Month Survey: No Cl	nange										
2023 Spring Six Month Survey: No Change Comments:												
2024 Fall Six Month Survey: No Change Comments:												
2024 Spring Six Month Survey: No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Spray on Insulation	4000	SF	Attic in Addition 1921		Surface	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
106	Carpet Mastic	900	SF	Auditorium and balcony isles		Miscellaneous	No	None	0		YES	X NO
2022 Fall Si	x Month Survey: No C	]										
Comments:	•	<b>V</b>										
2023 Fall Si	x Month Survey: No C	hange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six Month Survey: No Change												
Comments:												
2024 Spring Six Month Survey: No Change												

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Drywall System	250	SF	3rd, 2nd, 1st, basement corridor for elevator door room 311		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Chicago High School for the Arts (ChiArts)
Date: 8/1/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. posted to CPS website
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 63051