## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Excel Englewood HS 63142 7050 School: **Oracle Unit: Building ID:** Address: 7141 S. Morgan Region: 05 Mail Room: Asbestos Surveyor: Hamp, Alexander X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/20/2024 Email Address: A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Library, Lunchroom, YES 02 12x12 Ceiling Tiles SF X NO 10000 Miscellaneous Yes Dist 20 Corridors 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

2022 Fall S	Six Month Survey: No C	hange			$\neg$						
Comments	,										
2023 Fall S	Six Month Survey: No C	hange									
Comments											
2024 Spring	g Six Month Survey: No	Change									
Comments	:										
	Six Month Survey: No C	hange									
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Surface

Surface

Category

Friable

No

No

Damage

Туре

None

Loc

Damage

Quantity

0

20

Damage

Units

60000

Material

Units

SF

SF

Material Quantity

1500

Material Location

**Boiler Room Ceiling** 

Throughout

HA No

03A

03B

Material Description

Hard Plaster White Coat

Hard Plaster

Change in Assessment Category

X NO

X NO

YES

04	9x9 VAT	200	SF	2nd Floor Storage, 2nd Floor Teachers' Restroom, Room 209		Miscellaneous	No	Dist	45	YES	X NO
	Month Survey: N	o Change			]						
Comments:											
2023 Fall Siz	Month Survey: N	o Change									
Comments:											
2024 Spring	Six Month Survey	: No Change									
Comments:											
2024 Fall Six	k Month Survey: N	o Change									
Comments:											
					<u></u>						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	12x12 Taupe VAT	7000	SF	Janitors Closet at North Hall Corridor, Corridors & Classrooms, Main Office, Server Room and Cafeteria		Miscellaneous	No	None	0		YES X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange									

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

05B	12x12 Crème VAT	7000	SF	Janitor's Closet at North Hall Corridor, Corridors & Classrooms, Main Office		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No C	Change			]						
Comments:		ge			<u> </u>						
2023 Fall Six	Month Survey: No C	hange			_						
Comments:	Ţ				1						
2024 Spring	Six Month Survey: N	o Change									
Comments:	•										
2024 Fall Six	Month Survey: No C	Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05C	12x12 Pink VAT	600	SF	State Pre-K Room 116		Miscellaneous	No	None	0		YES X NO
2022 Fall Six	Month Survey: No Ch	ange			]						

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

2022 Fall Si	x Month Survey: No C	hange									
Comments:	•	<u> </u>									
2023 Fall Si	x Month Survey: No C	hange									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Si	x Month Survey: No C	hange									
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

2250

HA No

05D

05E

Material Description

12x12 White VAT

12x12 Beige VAT

Material

Units

SF

SF

Material

Quantity

600

Material Location

State Pre-K Room 116

2nd Floor Corridor

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

	I .		1								
2022 Fall Six	Month Survey: No Cl	nange									
Comments:	•	<u> </u>									
2023 Fall Six	Month Survey: No Cl	nange									
Comments:	Comments:										
2024 Fall Six	Month Survey: No Cl	nange									
Comments:	,										
2024 Spring S	Six Month Survey: No	Change									
Comments:	•	-									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Surface

Asbestos

Type

Material

Category

Miscellaneous

Friable

No

Yes

Damage

Туре

None

None

Damage

Quantity

0

10

Damage

Units

18900

Material

Quantity

450

Material

Units

SF

SF

Material Location

Classrooms throughout

Building, Gym

Kitchen

HA No

05F

07

Material Description

12x12 Pink Speckled VAT

Spray-On Acoustic Plaster

Change in Assessment Category

X NO

X NO

YES

09	Vinyl Baseboard Mastic- NOT OBSERVED	2000	LF	Throughout Building (No Baseboard or Mastic was Observed)		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	x Month Survey: No Cl	nange			1							
Comments:		90			<b>=</b> <b>-</b>							
2023 Fall Six	x Month Survey: No Cl	nange			-							
Comments:					1							
2024 Spring	Six Month Survey: No	Change										
Comments:					-							
2024 Fall Six	x Month Survey: No Cl	nange										
Comments:					=							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

YES

X NO

			,	
2022 Fall Six Mor	nth Survey: No Ch	ange		
Comments:				
2023 Fall Six Mor	nth Survey: No Ch	ange		
Comments:				
				,
2024 Spring Six N	Month Survey: No	Change		
Comments:				
2024 Fall Six Mor	nth Survey: No Ch	ange		
Comments:				

Material

Quantity

Material

Units

Material Location

Boiler Room- Incinerator

(Incinerator Disabled)

HA No

10

Material Description

Firebrick-NOT OBSERVED

2022 Fall S	ix Month Survey: No C	hange			$\neg$						
Comments:		J									
2023 Fall S	ix Month Survey: No C	hange									
Comments:											
	g Six Month Survey: No										
Comments:											
	ix Month Survey: No C	hange									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
<del></del>			+			+		+	+	+	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

640

HA No

11

12

Material Description

Fire Doors

Drywall

Material

Quantity

4

Material

Units

EΑ

SF

Material Location

Throughout Building

Library & Kitchen

Page 8

Change in Assessment Category

X NO

X NO

YES

2022 Fall Six	k Month Survey: No Ch	nange									
Comments:											
2023 Fall Six	Month Survey: No Ch	nange									
Comments:					_						
2024 Spring	Six Month Survey: No	Change									
Comments:											
	k Month Survey: No Ch	nange									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

HA No

13

14

Comments:

Comments:

Comments:

Comments:

Material Description

Vibration Isolators

**Drywall Compound** 

2022 Fall Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

Material

Quantity

10

640

Material

Units

SF

SF

Material Location

Lunchroom & Kitchen

Gym Fan Room

Change in Assessment Category

X NO

X NO

YES

15A	12x12 Taupe VAT Mastic	7000	SF	Main Office, Server Room, Cafeteria		Miscellaneous	No	None	0	YES	X NO
0000 Fall Ci-	· Mandle Ormani Na Ol			<u> </u>	1						
2022 Fall 51)	Month Survey: No Ch	iange									
Comments:											
					_						
2023 Fall Six	Month Survey: No Ch	ange									
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

Corridors & Classrooms,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15B	12x12 Crème VAT Mastic	7000	SF	Corridors & Classrooms, Main Office		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

2022 Fall S	Six Month Survey: No C	hange									
Comments											
2023 Fall S	Six Month Survey: No C	hange									
Comments	:										
	g Six Month Survey: No	Change									
Comments	:				_						
2024 Fall S	Six Month Survey: No C	hange									
Comments	:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2022 Fall Six Month Survey: No Change		
Comments:		
2023 Fall Six Month Survey: No Change		
Comments:		
2024 Spring Six Month Survey: No Change		
Comments:		
2024 Fall Six Month Survey: No Change		
Comments:	 	

600

Material

Quantity

600

Material

Units

SF

SF

Material Location

State Pre-K Room 116

State Pre-K, Room 116

HA No

15C

15D

Material Description

12x12 Pink VAT Mastic

12x12 White VAT Mastic

Change in Assessment Category

X NO

X NO

YES

2022 Fall Six	Month Survey: No Ch	nange									
Comments:	•										
	Month Survey: No Ch	nange									
Comments:											
	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Ch	nange									
Comments:					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

450

HA No

15E

15F

Material Description

12x12 Beige VAT Mastic

12x12 Pink Speckled VAT

Material

Units

SF

SF

Kitchen

Material

Quantity

2250

Material Location

2nd Floor Corridor

Change in Assessment Category

X NO

X NO

YES

16	12x12 Acoustic Ceiling Tile Mastic	10000	SF	Library, Lunch Room, Corridors		Miscellaneous	No	None	0		YES	X NO
2022 Fall	Six Month Survey: No Ch	ange			7							
Commen		<u> </u>										
2023 Fall	Six Month Survey: No Ch	ange										
Commen	ts:				4							
	ing Six Month Survey: No	Change										
Commen	ts:				4							
2024 Fall	Six Month Survey: No Ch	ange										
Commen	ts:				4							
					_							
LIA NI=	Material Description	Matarial	Matarial	Metarial Lagation	A =  - = + = =	Matarial	Falable	D	D	Damas	Change in Assess	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA NO	Material Description	Material Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units Units	Change in Assess	sment Category
17	Vault Door Lining	24	SF	School Office		TSI	No	None	0		YES	X NO
2022 Fall Six Comments:	Month Survey: No Cha	ange										

2023 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No

Material Description

12x12 Acoustic Ceiling Tile

Material

Units

Material

Quantity

Material Location

Library, Lunch Room,

18	Linoleum	5200	SF	Gym, Library, and Electrical Room		Miscellaneous	No	None	0		YES	X NO
2022 Fall Six	Month Survey: No Cl	nange										
Comments:	•	•										
2023 Fall Six	Month Survey: No Cl	nange										
Comments:												
2024 Spring	Six Month Survey: No	Change			_							
Comments:												
2024 Fall Six	Month Survey: No Cl	nange										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

2022 Fall Six	Month Survey: No Cha	ange		
Comments:				
2023 Fall Six	Month Survey: No Cha	ange		
Comments:				
2024 Spring S	Six Month Survey: No (	Change		
Comments:				
2024 Fall Six	Month Survey: No Cha	ange		
Comments:				

5200

Material

Quantity

Material

Units

SF

Material Location

Gym, Library, and Electrical Room

HA No

19

Material Description

Linoleum Mastic

Change in Assessment Category

X NO

	iviastic		& 222						
0000 F-II O'	Marillo a a Ni	01		1	·	•	•	•	
	Month Survey: No	Change							
Comments:									
2023 Fall Six	Month Survey: No	Change							
	Month Survey. N	Change							
Comments:									
2024 Fall Six	Month Survey: No	Change							
Comments:									
2024 Spring S	Six Month Survey:	No Change							
Comments:									
		•							

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
47	Ceiling Tile - NOT OBSERVED			Basement (Music Room)		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	ange										
	Month Survey: No Ch	ange			-							

Comments:

2024 Fall Six Month Survey: No Change
Comments:

HA No

33

Material Description

12x12 Beige Floor Tile

Material

Quantity

4050

Material

Units

SF

Material Location

1959- Classroom 124,

Music Room, Rooms 220

2024 Spring Six Month Survey: No Change Comments: Change in Assessment Category

X NO

48	12x12 White w/Light Brown Floor Tile	75	SF	Janitors Closet by Boiler Room		Miscellaneous	No	None	0	YES	X NO
2022 Fall Six	Month Survey: No Ch	ange			]						
Comments:		<b>J</b> -									
2023 Fall Six	Month Survey: No Ch	ange									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:					-						
2024 Fall Six	Month Survey: No Ch	ange			-						
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48M	12x12 White w/Light Brown Floor Tile Mastic	75	SF	Janitors Closet by Boiler Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

49	Red and Tan Terrazzo	1200	SF	Entrance and Stairways, Stage stairs		Miscellaneous	No	None	0		YES	X NO
2022 Fall Si	x Month Survey: No C	hango			1							
	A MOHIT Survey. NO C	lialige										
Comments:												
2023 Fall Siz	x Month Survey: No C	hange										
Comments:	-											
					1							
2024 Fall Siz	x Month Survey: No C	hange										
Comments:	•				1							
					1							
2024 Spring	Six Month Survey: No	Change										
Comments:	-				]							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

2022 Fall Six	Month Survey: No Cha	ange		
Comments:				
2023 Fall Six	Month Survey: No Cha	ange		
Comments:				
2024 Spring S	Six Month Survey: No (	Change		
Comments:				
2024 Fall Six	Month Survey: No Cha	ange		
Comments:				

1051

Material

Quantity

Material

Units

SF

Material Location

Lunch Room

Entrance and Stairways,

Material Description

12x12 Light Gray w/ Specks Floor Tile

HA No

50

YES

X NO

											<u> </u>
2022 Fall Six	Month Survey: No Ch	nange									
Comments:	-										
2023 Fall Six	Month Survey: No Ch	nange									
Comments:	-										
2024 Spring	Six Month Survey: No	Change			_						
Comments:											
2024 Fall Six	Month Survey: No Ch	nange									
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

Damage

Units

2051

Material

Units

SF

SF

Material

Quantity

1000

Material Location

Lunch Room

Lunch Room

HA No

51

52

Material Description

Floor Tile

12x12 Dark Gray w/Specks

Light and Dark Gray w/Specks Floor Tile Mastic

Page 18

Change in Assessment Category

X NO

X NO

YES

CM-1	Brown Carpet Mastic	570	SF	Principal's Office, Corridor, Main Office		Miscellaneous	No	None	0	YES	X NO
					7						
2022 Fall Six	Month Survey: No C	hange									
Comments:											
2023 Fall Six	Month Survey: No C	hange									
Comments:					_						
2024 Spring	Six Month Survey: No	Change									
Comments:	,										
2024 Fall Six	Month Survey: No C	hange									
Comments:		•									

Type

Material

Category

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D-1	Heat Exchanger Tank Insulation	45	SF	Boiler Room		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

D-2	Hot Water Holding Tank Insulation	145	SF	Boiler Room		TSI	Yes	None	0	YES	X NO
2022 Fall S	Six Month Survey: No Ch	nange									
Comments		·ugu									
2023 Fall 9	Six Month Survey: No Ch	nange			1						
Comments		iarigo									
2024 Fall S	Six Month Survey: No Ch	nange									
Comments	· · · · · · · · · · · · · · · · · · ·										
2024 Sprin	g Six Month Survey: No	Change			1						
Comments	:	-									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-1	12x12 Black Floor Tile	250	SF	2nd Floor Ladies' Toilet, Room 116 Toilet, 1st Floor Staff Toilet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

FTM-1	12x12 Black Floor Tile Mastic	250	SF	2nd Floor Ladies Toilet, Room 116 Toilet, 1st Floor Staff Toilet	Miscellaneous	No	None	0	YES	X NO
		•	•	•	•	•	•	•		
2022 Fall Six	Month Survey: No Ch	ange								
Comments:										
2023 Fall Six Month Survey: No Change										
Comments:										
2024 Spring Six Month Survey: No Change										
Comments:										

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-2	9x9 Taupe VT Mastic	45	SF	Vault, Room 116 closet		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

2024 Fall Six Month Survey: No Change

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Fiberglass Joints & Elbows	85	LF	Boiler Room & Crawlspace		TSI	Yes	Loc	2		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Excel Englewood HS
Date: 11/20/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 63142