## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2024 Fall Six Month Survey

**Oracle Unit:** 

65016

Address: 3100 Belmont Region: Mail Room: Asbestos Surveyor: McCormick, Douglas X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/15/2024 Email Address: A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Change in Assessment Category Material Asbestos Material Damage Damage Damage Quantity Units Type Category Quantity Type 1st and 2nd Floor YES X NO Drywall Miscellaneous Throughout 2024 Spring Six Month Survey: No Change Comments: HA No Material Description **Material Location** Change in Assessment Category Material Material **Asbestos** Material Friable Damage Damage Damage Quantity Units Type Category Type Quantity Units Drywall joint compound -1st & 2nd Floor 2 X NO Miscellaneous YES Throughout 2024 Spring Six Month Survey: No Change Comments:

Pathways in Education- Avondale

School:

Oracle Unit: 65016

55035

**Building ID:** 

Guantity Units    Surface   Type   Quantity   Units   Type   Category   Type   Quantity   Units   Quantity   Units   Type   Quantity   Units   Quantity   Units   Type   Quant														
Surface   Surf	HA No	Material Description			Material Location			Friable				Change in A	ssessi	ment Category
HA No Material Description Material Material Location Units Material Location Type Category Friable Damage Type Damage Quantity Units Change in Assessment Category Type Quantity Units Production Throughout Miscellaneous Damage Type Damage Quantity Units Throughout Quantity Units Throughout Throughout Throughout Damage Type Damage Quantity Units Throughout Throughout Damage Change in Assessment Category Type Category Type Quantity Units Damage Type Quantity Units Change Category Type Quantity Units Change In Assessment Category Units Damage Type Quantity Units Change In Assessment Category Type Quantity Units Change In Assessment Category In Institute In Institute In Institute In Institute Institut	3	Gray spray-on fireproofing					Surface					YES	I	X NO
HA No Material Description Material Material Location Dunits Material Location Type Category Type Damage Damage Damage Change in Assessment Category Units Press No Change Comments:  HA No Material Description Material Material Material Location Dunits Material Location Dunits Material Description Material Description Assessment Category Type Damage Damage Damage Change in Assessment Category Type Category Type Damage D	2024 Spring	Six Month Survey: No.	Chango			1								
HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Type Quantity Units Change in Assessment Category Units Change in Assessment Category Units Textured w Gouges Type Quantity Units Material Description Material Quantity Units Material Location Type Category Friable Damage Quantity Units Change Comments:  HA No Material Description Material Quantity Units Spaces Type Category Friable Damage Quantity Units Change in Assessment Category Units Change In Assessment Category Type Quantity Units Change in Assessment Category Units Change In Assessment Category Units Introduction Classrooms Assessment Category Introduction Classrooms Introduction Introduction Classrooms Introduction International Introduction Internation Introduction Introduction Introduction Introduction Inte		Six Month Survey. No	Change			1								
Quantity Units Type Category Type Quantity Units    Type Category Type Quantity Units   Type Quantity Units   Type   Quantity Units   Type   Quantity Units   Type   Quantity   Units   Type   Quantity   Units   Type   Quantity   Units   Type   Quantity   Units   Type   Quantity   Units   Type   Quantity   Quantity   Quantity   Quantity   Type   Quantity   Quanti	Commonto.													
Quantity Units Type Category Type Quantity Units    Type Category Type Quantity Units   Type Quantity Units   Type   Quantity Units   Type   Quantity Units   Type   Quantity   Units   Type   Quantity   Units   Type   Quantity   Units   Type   Quantity   Units   Type   Quantity   Units   Type   Quantity   Quantity   Quantity   Quantity   Type   Quantity   Quanti														
Throughout Miscellaneous   Light No.   Lig	HA No	Material Description			Material Location			Friable				Change in A	ssessi	ment Category
Comments:  HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Type Quantity Units Damage Quantity Units Damage Type Quantity Units Damage Type Quantity Units Damage Quantity Units Damage Type Quantity Units Damage Quantity Units Damage Quantity Units Damage Type Quantity Units Damage Quantity Units Damage Quantity Units No None 0 SF YES X NO Miscellaneous No None 0 SF YES X NO Material Description Material Description Material Material Location Assessment Category Category Type Damage Quantity Units Damage Quantity Unit	4	2' x 2' Ceiling Tile - Textured w/ Gouges					Miscellaneous					YES	1	X NO
Comments:  HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Type Quantity Units Damage Quantity Units Damage Type Quantity Units Damage Type Quantity Units Damage Quantity Units Damage Type Quantity Units Damage Quantity Units Damage Quantity Units Damage Type Quantity Units Damage Quantity Units Damage Quantity Units No None 0 SF YES X NO Miscellaneous No None 0 SF YES X NO Material Description Material Description Material Material Location Assessment Category Category Type Damage Quantity Units Damage Quantity Unit	2024 Spring	Six Month Survey: No.	Change			1								
HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Type Quantity Units Change in Assessment Category  5 Carpet mastic 4500 SF Throughout Classrooms and Office Spaces  2024 Spring Six Month Survey: No Change Comments:  HA No Material Description Material Quantity Units Material Quantity Units Material Category Type Category Friable Damage Quantity Damage Change in Assessment Category  Asbestos Material Friable Damage Damage Quantity Units Change Change in Assessment Category  Type Category Friable Damage Damage Quantity Units Change Change in Assessment Category  Category Type Damage Quantity Units Change Change in Assessment Category		OIX WORLD CUIVEY. 140	Onlange			-								
Quantity Units Type Category Type Quantity Units  Carpet mastic 4500 SF Throughout Classrooms and Office Spaces  Miscellaneous No None 0 SF Type X NO  2024 Spring Six Month Survey: No Change  Comments:  HA No Material Description Material Quantity Units Material Location Asbestos Type Category Friable Damage Quantity Units Change Change in Assessment Category Units														
Quantity Units Type Category Type Quantity Units  Carpet mastic 4500 SF Throughout Classrooms and Office Spaces  Miscellaneous No None 0 SF Type X NO  2024 Spring Six Month Survey: No Change  Comments:  HA No Material Description Material Quantity Units Material Location Asbestos Type Category Friable Damage Quantity Units Change Change in Assessment Category Units														
SF Throughout Classrooms and Office Spaces  Miscellaneous No None 0 SF YES X NO  2024 Spring Six Month Survey: No Change  Comments:  HA No Material Description Material Quantity Units Material Location Asbestos Type Category Friable Type Quantity Units Change Damage Quantity Units Change in Assessment Category	HA No	Material Description			Material Location			Friable				Change in A	ssessi	ment Category
HA No Material Description Material Quantity Units Material Location Asbestos Type Category Friable Damage Quantity Units Damage Quantity Units Category	5	Carpet mastic	4500	SF	Throughout Classrooms		Miscellaneous	No	None	0	SF	YES	1	X NO
HA No Material Description Material Quantity Units Material Location Asbestos Type Asbestos Type Category Friable Damage Quantity Units Damage Quantity Units Change in Assessment Category	2024 Spring	Six Month Survey: No.	Change			1								
HA No Material Description Material Quantity Units Material Location Type Asbestos Type Material Damage Quantity Units Damage Quantity Units Damage Quantity Units Category		OIX WORLD CUIVEY. 140	Onlange			-								
Quantity Units Type Category Type Quantity Units														
Quantity Units Type Category Type Quantity Units														
6 Ceramic tile adhesive 500 SF Vestibule and Bathrooms Miscellaneous No None 0 SF YES X NO	HA No	Material Description			Material Location			Friable		Damage Quantity		Change in A	ssessi	ment Category
	6	Ceramic tile adhesive	500	SF	Vestibule and Bathrooms		Miscellaneous	No	None	0	SF	YES	I	X NO
2024 Spring Six Month Survey: No Change	2024 Spring	Six Month Survey: No.	Change			 1								
	Comments:	OIX MOUTHET OUTVEY. INO	Change			-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
7	Red firestop	7	EA	1st & 2nd Floor Throughout (Above Suspended Drop Ceiling)		Miscellaneous	No	None	0	EA	YES	X NO
2024 Sprin	ng Six Month Survey: No	Change		•	1							
Comments		Onlange										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
8	Gray duct sealant	10	EA	1st & 2nd Floor Throughout (Above Suspected Drop Ceiling)		Miscellaneous	No	None	0	EA	YES	X NO
2024 Sprin	ng Six Month Survey: No	Change	•	•	7		•	•	•	•	•	
Comments		Change										
	1		T	T	1		1					
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
9	Drywall joint compound (yellow)			1st & 2nd Floor Throughout		Miscellaneous					YES	X NO
2024 Sprin	ng Six Month Survey: No	Change										
Comments		o mango										
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
10	12" x 12" Gray Mottled Floor Tile	1200	SF	SGI Room, 2nd floor staff lounge		Miscellaneous	No	None	0	SF	YES	X NO
2024 Sprin	ng Six Month Survey: No	Change	•		1	•	•	•	•	•	•	
Comments		Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
11	12" x 12" Gray Mottled Floor Tile Mastic	1200	SF	SGI Room, 2nd floor staff lounge		Miscellaneous	No	None	0	SF	YES	X NO
2024 Spring	Six Month Survey: No	Change			]							
Comments:	•	•			- -							
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
12	Tan textured wall fovering adhesive	600	SF	1st and 2nd Floor Restrooms		Surface	No	None	0	SF	YES	X NO
2024 Spring	Six Month Survey: No	Change			]							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
13	12" x 12" Red Floor Tile w/ White Streaks	500	SF	2nd Floor Stair Landing and Hallway		Miscellaneous	No	None	0	SF	YES	X NO
2024 Spring	Six Month Survey: No	Change			1							
Comments:	,											
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
14	12" x 12" Red Floor Tile w/ White Streaks Mastic	500	SF	2nd Floor Stair Landing and Hallway		Miscellaneous	No	None	0	SF	YES	X NO
2024 Spring	Six Month Survey: No	Change			]							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
15	12" x 12" Yellow Floor Tile w/ Red Streaks	20	SF	2nd Floor Stair Landing and Hallway		Miscellaneous	No	None	0	SF	YES	X NO
2024 Sprin	g Six Month Survey: No	Change										
Comments	:				-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
16	12" x 12" Yellow Floor Tile w/ Red Streaks Mastic	20	SF	2nd Floor Stair Landing and Hallway		Miscellaneous	No	None	0	SF	YES	X NO
2024 Sprin	g Six Month Survey: No	Change			]							
Comments	:				-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
17	4" Beige baseboard	1500	SF	2nd Floor Stair Landing and near restrooms		Miscellaneous	No	None	0	SF	YES	X NO
2024 Sprin	g Six Month Survey: No	Change			7							
Comments	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
18	4" Beige baseboard adhesive	1500	SF	2nd Floor Stair Landing and near restrooms		Miscellaneous	No	None	0	SF	YES	X NO
2024 Sprin	g Six Month Survey: No	Change										

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	White sink undercoating	5	SF	2nd Floor Staff Lounge		Miscellaneous	No	None	0	SF	YES X NO

2024 Spring Six Month Survey: No Change	
Comments:	

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 65016

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

	thways in Education- Avondale
Date: 8/26	/2024
the Asbestos M	you in accordance with Illinois and Federal Asbestos Regulations, that a copy of Management Plan is available at each school during school hours by appointment. view the Asbestos Management Plan must be made at least 24 hours in advance.
The last inspec	advised that CPS conducts asbestos inspections of all Schools every three years. etion was completed in 2022. eillances are conducted every six months.
CHECK ONE	
A copy o	of this notice was sent home in each child's backpack.
X A copy o	of this notice was printed in the school's newsletter and sent home with each child
A copy o	of this notice was printed in the school's calendar and sent home with each child
Other.	
4 CODY OF	THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 65016

SCHOOL'S ASBESTOS MANAGEMENT PLAN.