## **Chicago Public Schools**

### 6 Month Asbestos Surveillance

#### 2024 Fall Six Month Survey

Scho Addr		Noble - John and Eunice Johnson College Prep 6350 Stewart		Oracle Unit: Region:	66148	Building ID: Mail Room:	6870 45
CHECK HERE	E IF N	O CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date:	Marrero, Elizabeth 11/14/2024			
			Email Address:	emarrero5@cps.k12.il. us			

	A copy of the2022/202	3 notice to p	parents and	I staff regarding the asb	estos manag	ement plan not	ifications w	as distribute	d via:				
	Each child's backpa	Each child's backpack Notice printed in school's newsl				sletter Notice printed in school's calendar X Other Posted to the CPS W							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
03	12x12 White Floor Tile in Checkerboard Pattern (with HA04)	21000	SF	1st, 2nd & 3rd Floor Corridors, Custodial Break Room, Engineer's Office, Classrooms 201, 307, 309, 308, 314		Miscellaneous	No	None	0				
2022 Fall S	ix Month Survey: Abated	t											
Comments:	Removal of flooring in 3:	rd floor co	rridors		_								
2023 Fall S	Six Month Survey: No Ch	ange			-								
Comments:													
2023 Sprind	g Six Month Survey: No	Change			-								
Comments:	0 /	0											
2024 Sprine	g Six Month Survey: Aba	ated											
	2nd & 3rd floors corrido												
	ix Month Survey: Abated				-								
Comments:	2nd & 3rd floor corridors	3			4								
<u> </u>					L								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12x12 Brown Floor Tile in Checkerbaord Pattern (with HA3)	23000	SF	1st, 2nd & 3rd Floor Corridors & Custodial Break Room, Engineer's Office, Class rooms 101, 103, 201, 307, 309, 308, 314		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Abated
Comments:Removal of flooring in 3rd floor corridors
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:2nd & 3rd floors corridors
2024 Fall Six Month Survey: Abated
Comments:2nd & 3rd floor corridors

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12x12 Rust Floor Tile	1500	SF	1st Floor Kitchen		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	12x12 Off-White Floor Tile	23000	SF	Classrooms, 1st, 2nd & 3rd Floors		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:2nd & 3rd floors
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9x9 Tan Floor Tile	2900	SF	Room 301, 305, 317, Boiler Room, Storage Room		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: Abated
Comments:Removal of flooring in storage rom
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:boiler room
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Acoustical Plaster	30000	SF	1st floor SW Corridor, & 2nd Floor Corridor, Classrooms & Lunchroom		Surface	Yes	None	0		YES XNO

2022 Fall Six Month Survey: No Change
· · · · · · · · · · · · · · · · · · ·
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2022 Carries Six Month Survey No Change
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:2nd floor corridor
2024 Fall Six Month Survey: Abated
Comments:2nd floor corridors

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	1'x1' Ceiling Tile	500	SF	SE Lobby		Miscellaneous	Yes	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	12x12 White Floor Tile Mastic	21000	SF	1st, 2nd & 3rd Floor Corridors, Rooms 201 & 314		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: Abated
Comments:Removal of flooring in 3rd floor corridors
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:2nd & 3rd floors
2024 Fall Six Month Survey: Abated
Comments:2nd & 3rd floor corridors

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13B	12x12 Brown Floor Tile Mastic	23000	SF	1st, 2nd & 3rd Floor Corridors, Rooms 101, 103, 201, 314		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: Abated
Comments:Removal of flooring in 3rd floor corridors
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:2nd & 3rd floors
2024 Fall Six Month Survey: Abated
Comments:2nd & 3rd floor corridors

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13C	12x12 Rust Floor Tile Mastic	1500	SF	1st Floor Kitchen		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13D	12x12 Off-White Floor Tile Mastic	21200	SF	1st, 2nd & 3rd Floor Classrooms		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ſ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	14	9x9 Tan Floor Tile Mastic	2880	SF	Rooms 301, 305 & Boiler Room Storage		Miscellaneous	No	None	0		X YES NO

2022 Fall Six Month Survey: Abated
Comments:Removal of flooring in storage rom
Confinents. Removal of hoofing in storage form
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:Boiler room abated
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	1'x1' Ceiling Tile Mastic	500	SF	Southeast Lobby		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Interior Window Glaze	416	EA	All Interior Windows		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18E	Burgundy Carpet Mastic	1300	SF	Room 126		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Insulation	150	SF	Incinerator		TSI	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Vibration Isolator	40	LF	Fan Room		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12x12 Brown Mottle Floor Tile	750	SF	Room 303		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey No Change
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12x12 Brown Mottle Floor Tile Mastic	750	SF	Room 303		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change								
Comments:								
2023 Fall Six Month Survey: No Change								
Comments:								
2023 Spring Six Month Survey: No Change								
Comments:								
2024 Spring Six Month Survey: No Change								
Comments:								
2024 Fall Six Month Survey: No Change								
Comments:								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12x12 White w/Gray Mottle Floor Tile	16650	SF	2nd Floor Classrooms, Rooms 105, 106, 108, 109, 110 & Gym		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12x12 White w/Gray Mottle Floor Tile Mastic	16650	SF	2nd Floor Classrooms, Rooms 105, 106, 108, 109, 110 & Gym		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HAN	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25		Sink Insulation	15	SF	Art Room, 109		Surface	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

H	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26		12x12 Yellow Floor Tile w/Blue Flecks ABATED			Room 112		Miscellaneous		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Mat	aterial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27		x12 Off-White Floor Tile Brown Flecks ABATED			Room 112		Miscellaneous		None			YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12x12 Yellow FT w/Blue Flecks Mastic, 12x12 Off- White FT w/Brown Mastic ABATED			Room 112		Miscellaneous		None			YES XNO

022 Fall Six Month Survey: No Change
Comments:
onnents.
023 Fall Six Month Survey: No Change
comments:
023 Spring Six Month Survey: No Change
comments:
024 Fall Six Month Survey: No Change
comments:
024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" White w/Blue and Red Specks Vinyl Floor Tile	5000	SF	Rooms 107, 108, 109, 110, 111, 112, 300, 304, 306, 310, 311, 312, 313, 314 3rd Unisex Bathroom, Elevator Area, Lunchroom		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29A	12"x12" White w/Blue and Red Specks Vinyl Floor Tile Mastic	1400	SF	Rooms 107, 108, 109, 110, 111, 112, 300, 304, 306, 310, 311, 312, 313, 314 3rd Unisex Bathroom, Elevator Area, Lunchroom		Miscellaneous	No	None	0		YES X NO

0000 Fall O' Marth O and Ne Observe
2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Blue w/Streaks Vinyl Floor Tile	680	SF	Lunchroom, 3rd Floor Water Fountain Area, Elevator Area, Room 310		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30A	12"x12" Blue w/Streaks Vinyl Floor Tile Mastic	680	SF	Lunchroom, 3rd Floor Water Fountain Area, Elevator Area, Room 310, Unisex Bathroom		Miscellaneous	No	None	0		

2000 Fall Circ Marshe Constant Na Changes
2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2004 Opting City Marth Concern No. Ober pro
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Red w/Streaks Vinyl Floor Tile	480	SF	Lunchroom, 2nd & 3rd Floor Water Fountain & Elevator Area		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31A	12"x12" Red w/Streaks Vinyl Floor Tile Mastic	680	SF	Lunchroom, 3rd Floor Water Fountain Area & Elevator Area		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Carpet Mastic	650	SF	Main Office & Room 100		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Hardcoat Plaster	28417	SF	Ceilings Throughout		Surface	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
Comments.
2024 Fall Six Month Survey: No Change
Comments:
2024 Chrise Cir Month Currey No Change
2024 Spring Six Month Survey: No Change
Comments:

ſ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	34	Green Sheet Floor	750	SF	Dance Studio- Room 200		Miscellaneous	No	None	0		YES XNO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Green Sheet Floor Mastic	750	SF	Dance Studio - Room 200		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2022 Fall Six Marth Survey No Change
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" White w/Brown Specks Floor Tile	3860	SF	Rooms 201, 202, 203, 205-213, 226, and MDF Room		Miscellaneous	No	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" White w/Brown Specks Floor Tile Mastic	3860	SF	Rooms 201, 202, 203, 205-213, 226, and MDF Room		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Terrazzo Flooring	1500	SF	1st Floor Main Entrance, North Entrance and Stairwells		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Breeching	600	SF	Boiler Room		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
Commente.
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:Boiler room abated
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Heat Exchange Cover	270	SF	Boiler Room		TSI	Yes	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
ooninents.
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:Boiler room abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Feed Water Tank (formerly known as Condensate Return Tank)	24	SF	Boiler Room		TSI	No	None	0		

2022 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: Abated
Comments:Boiler room abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Pipe Fitting Insulation	100	LF	Pipe Chases, Boiler Room, Fan Room & Crawlspace		TSI	Yes	None	1		

2022 Fall Six Month Survey: Abated
Comments:sampling conducted following the glove bag removal of
asbestos
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations		Miscellaneous		Unknown			YES XNO

2022 Fall Six Month Survey: No Change	
Comments:	
2023 Fall Six Month Survey: No Change	
Comments:	
2023 Spring Six Month Survey: No Change	
Comments:	
2024 Fall Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Noble - John and Eunice Johnson College Prep Date: 8/1/2024

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

A copy of this notice was sent home in each child's backpack.

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

X Other. Posted to the CPS Website

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.