Chicago Public Schools

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Oracle Unit:

66151

Building ID: Address: 3141 W. Jackson Region: 02 Mail Room: Asbestos Surveyor: VCFOSTER1 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/6/2024 Email Address: vcfoster1@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type Throughout 1910 001 SF YES X NO Plaster Walls and Ceilings 25000 Yes None 0 SF Surface Construction 2023 Spring Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:

Alain Locke Charter School

School:

4730

002	Plaster Walls and Ceilings	25000	SF	Throughout 1938 Construction		Surface	Yes	None	0	SF	YES	X NO
2023 Spring	Six Month Survey: No	Change			1							
Comments:	on monar carray. He	Onlango										
2023 Fall Six	Month Survey: No Ch	ange			_							
Comments:		.age]							
2024 Fall Six	Month Survey: No Ch	ange			1							
Comments:	,]							
2024 Spring	Six Month Survey: No	Change			1							
Comments:	•											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

003	2' x 4' Lay In Ceiling Panels	25550	SF	Classrooms, Bathrooms, Library, Offices, Teacher's Lounge, Conference Room and Kitchen	Miscellaneous	Yes	None	0	SF	YES
2023 S	pring Six Month Survey: No	Change								
Comme										
2023 Fa	all Six Month Survey: No Cha	ange								
Comme	ents:									

2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Throughout 1938

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
004	2' x 2' Lay In Ceiling Panels	300	SF	Main Office		Miscellaneous	Yes	None	0	SF	YES	X NO
2023 Spring Comments:	Six Month Survey: No	Change			-							
2023 Fall Siz	x Month Survey: No Ch	ange										
2024 Fall Siz	x Month Survey: No Ch	ange										
2024 Spring	Six Month Survey: No	Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
005	2' x 4' Lay In Ceiling Panels	1280	SF	Classroom off Gym Balcony		Miscellaneous	Yes	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
006	1' x 1' White Pinhold Ceiling Tile	2400	SF	Cafeteria		Miscellaneous	Yes	Loc	30	SF	YES	X NO
2023 Fall Six	Month Survey: No Ch	ange]							

2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	1' x 1' White Pinhold Ceiling Tile	2400	SF	Cafeteria		Miscellaneous	Yes	Loc	30	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

007	1' x 1' White Pinhole Ceiling Tile Adhesive	2400	SF	Cafeteria		Miscellaneous	No	Loc	30	SF	YES	X NO
2023 Spring Six Month Survey: No Change												
Comments:												
2023 Fall Six	Month Survey: No Cha	ange										
Comments:												
2024 Fall Six	Month Survey: No Cha	ange										
Comments:	•											
2024 Spring Six Month Survey: No Change												

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
008	2' x 2' Lay In Ceiling Panels	400	SF	Basement - Room 9		Miscellaneous	Yes	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

009	Gold/blue carpet adhesive	4750	SF	Conference Room, Offices, Library, Classrooms 200 & 201		Miscellaneous	No	None	0	SF	YES	X NO
2023 Spring	Six Month Survey: No	Change			7							
Comments:												
	Month Survey: No Ch	ange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Spring Comments:	Six Month Survey: No	Change			_							
Commonto.												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
010	Blue carpet adhesive	580	SF	Classroom 206		Miscellaneous	No	None	0	SF	YES	X NO
2023 Spring Comments:	g Six Month Survey: No	Change										
2023 Fall S	ix Month Survey: No Ch	nange										

Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Conference Room,

2024 Spring Six Month Survey: No Change Comments:

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
011	Purple carpet adhesive	16250	SF	Conference Room, Classrooms: 104, 105, 108, 110, 202-204, 207- 210, 300-303, 305, 307- 310, 314 & 315		Miscellaneous	No	None	0	SF	YES X NO
0000 0	O' Marth O a a Na	01			1						

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
012	12" x 12" Beige Floor Tile	400	SF	Entrance Halls to Bathrooms, In Front of Elevator Doors and Classroom 319		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
013	Mastic Associated With 12" x 12" Beige Floor Tile	400	SF	Entrance Halls to Bathrooms, In Front of Elevator Doors, and Classroom 319		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
014	12" x 12" White Floor Tile w/Brown Streaks	576	SF	Classroom 206		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

2023 Spring	Six Month Survey: No	Change									
Comments:											
2023 Fall Si	x Month Survey: No C	hange									
Comments:											
	x Month Survey: No C	hange									
Comments:											
	Six Month Survey: No	Change									
Comments:	Comments:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
-	†	1	1	†		1	1	1	1	1	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

SF

HA No

015

016

Material Description

Mastic assoc. W/12" x 12"

White Floor Tile w/Brown

9" x 9" Gray Floor Tile

Material

Units

SF

Material Quantity

576

Material Location

Classroom 206

Gym Storage

Change in Assessment Category

X NO

X NO

YES

YES

017	Mastic Associated With 9" x 9" Gray Floor Tile	Gym Storage		Miscellaneous					YES	X NO
2023 Spri	ng Six Month Survey: No Change									
Comment	<u> </u>									
2023 Fall	Six Month Survey: No Change		_							
Comment										
2024 Fall	Six Month Survey: No Change									
Comment	S:									
2024 Sprii	ng Six Month Survey: No Change		=							
Comment	s:									
LIA NI-	Material Description Material	Material Material Leasting	A a b a a t a a	Matarial	Frields	D	Damas	Damana	Ohanas in Assess	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
018	12" x 12" Brown Streaked Floor Tile	775	SF	Locker Room by Gym and Room Next to Locker Room		Miscellaneous	No	None	0	SF	YES	X NO
2023 Spring S Comments:	Six Month Survey: No	Change										

Comments:

2023 Fall Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change
Comments:

2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

019	Mastic assoc. W/ 12" x 12" Brown Streaked Floor Tile	775	SF	and Room Next to Locker Room	Miscellaneous	No	None	0	SF	YES	X NO
2022 Sprin	g Six Month Survey: No	Changa		·						•	
		Change	1								
Comments	:										
2023 Fall S	Six Month Survey: No Ch	ange									
Comments	:										
2024 Fall S	Six Month Survey: No Ch	ange									
Comments											
2024 Sprin	g Six Month Survey: No	Change									
Comments	:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
020	12" x 12" Beige Floor Tile	1280	SF	Classroom off Gym Balcony		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2023 Spring	Six Month Survey: No	Change			7						
Comments:											
2023 Fall Six	Month Survey: No Ch	nange									
Comments:											
	Month Survey: No Ch	nange									
Comments:					_						
2024 Spring	Six Month Survey: No	Change									
Comments:					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

HA No

021

022

Material Description

Beige Floor Tile

Mastic assoc. W/ 12" x 12"

9" x 9" Green Floor Tile

Material

Units

SF

Material

Quantity

1280

Material Location

Classroom off Gym

Basement Room by Pool

Balcony

Change in Assessment Category

X NO

X NO

YES

YES

Damage

Units

SF

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
			•		-							
Comments	: :											
2024 Sprir	ng Six Month Survey: No	Change										
Comments	: :											
	•	iange										
2024 Fall 9	Six Month Survey: No Ch	2222										
Comments	S:											
	•	ialiye										
2023 Fall 9	Six Month Survey: No Ch	nango										
Comments).											
Comments	· · · · · · · · · · · · · · · · · · ·											
2023 Sprir	ng Six Month Survey: No	Change										
							l					
023	Mastic assoc. W/9" x 9" Green Floor Tile			Basement Room by Pool		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

		Quantity	Units		Туре	Category		Туре	Quantity	Units	3
024	12" x 12" Yellow Floor Tile	1000	SF	Basement Bathrooms, Classrooms 108 and 110		Miscellaneous	No	None	0	SF	YES
2023 Spri	ing Six Month Survey: No	Change]						
Comment	ts:										
2023 Fall	Six Month Survey: No Ch	ange									
Comment	ts:										
2024 Fall	Six Month Survey: No Ch	ange			-						

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

X NO

2023 Spring Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments:	
Comments: 2023 Fall Six Month Survey: No Change	
2023 Fall Six Month Survey: No Change	
, -	
, -	
Comments:	
2024 Fall Six Month Survey: No Change	
Comments:	
2024 Spring Six Month Survey: No Change	
Comments:	

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
026	9" x 9" Black Floor Tile	250	SF	Room 26		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
027	Mastic asoc. W/9" x 9" Black Floor Tile	250	SF	Room 26		Miscellaneous	No	None	0	SF	YES X NO
2023 Spring Six Month Survey: No Change Comments:											
2023 Fall Six Month Survey: No Change											

2023 Fall Six Month Survey: No Change	
Comments:	
2024 Fall Six Month Survey: No Change	
Comments:	

2024 Spring Six Month Survey: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
028	9" x 9" Gray Floor Tile	500	SF	Rooms 8 and 26		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
029	Mastic assoc. W/9" x 9" Gray Floor Tile	500	SF	Rooms 8 and 26		Miscellaneous	No	None	0	SF	YES	X NO
2023 Spring S	Six Month Survey: No	Change										

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
030	12" x 12" Alligator Skin Patterned Floor Tile	400	SF	Room 9		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Page 16

031	Mastic assoc. W/ 12" x 12" Alligator Skin Floor Tile	400	SF	Room 9		Miscellaneous	No	None	0	SF	YES	X NO
2023 Spring	Six Month Survey: No	Change										
Comments:		Onlango										
COMMITTEE INC.												
2023 Fall Si	x Month Survey: No Ch	ange										
Comments:	•	Ü										
2024 Fall C	Sy Manth Cumiani Na Ch											
	x Month Survey: No Ch	ange										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
	·			<u> </u>								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessr	nent Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

Switching Room

HA No

032

Material Description

Mastic assoc. W/ 12" x 12"

12" x 12" Beige Floor Tile

YES

X NO

033	Mastic assoc. W/12" x 12" Beige Floor Tile			Switching Room		Miscellaneous					YES	X NO
2023 Spring	g Six Month Survey: No	Change]							
Comments:												
2023 Fall S	ix Month Survey: No Ch	nange			=							
Comments:												
2024 Fall S	ix Month Survey: No Ch	nange			_							
Comments:					-							
2024 Spring	g Six Month Survey: No	Change										
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
034	4" Black vinyl baseboard	150	LF	Hall to 3rd Floor Bathrooms, Gym Locker Room, Room Next to	, , , , , , , , , , , , , , , , , , ,	Miscellaneous	No	None	0	LF	YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Comments:

Comments:

Comments:

Comments:

Material Description

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material

Units

Material

Quantity

Material Location

Locker Room

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
035	4" Black vinyl baseboard adhesive	150	LF	Hall to 3rd Floor Bathrooms, Gym Locker Room, Room Next to Locker Room		Miscellaneous	No	None	0	LF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
036	4" Light brown vinyl baseboard	300	LF	Halls to Bathrooms, Gym, in Front of 2nd Floor Elevator Doors		Miscellaneous	No	None	0	LF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

037	4" Light brown vinyl baseboard	300	LF	in Front of 2nd Floor Elevator Doors	Miscellaneous	No	None	0	LF	YES	X NO
0000 0	- Circ Manth Common N		•	•	•	•	•	•		•	
2023 Sprin	g Six Month Survey: N	io Change	!								
Comments	:										
2023 Fall S	Six Month Survey: No	Change									
Comments	:										
2024 Fall S	Six Month Survey: No	Change									
Comments	:										
2024 Sprin	g Six Month Survey: N	lo Change	-								

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
038	4" Yellow vinyl baseboard	100	LF	Basement Bathrooms and Library		Miscellaneous	No	None	0	LF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

039	4" Yellow vinyl baseboard adhesive	100	LF	Basement Bathrooms and Library		Miscellaneous	No	None	0	LF	YES	X NO
2023 Spri	ing Six Month Survey: No	Change										
Commen		Onlange										
Commen					\dashv							
2023 Fall	Six Month Survey: No Ch	nange										
Commen	ts:	· ·										
2024 Fall	Six Month Survey: No Ch	nange										
Commen	ts:											
2024 Cm #	ing Circ Month Criminary No	Change										
	ing Six Month Survey: No	Change			_							
Commen	ts:											
		,		1		1		_	1		•	
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
				1st, 2nd & 3rd Floor							l 	

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

SF

HA No

040

Comments:

Comments:

Comments:

Comments:

Drywall

2023 Spring Six Month Survey: No Change

2023 Fall Six Month Survey: No Change

2024 Fall Six Month Survey: No Change

2024 Spring Six Month Survey: No Change

Material Description

4" Yellow vinyl baseboard

Material

Quantity

6300

SF

Material

Units

Material Location

Basement Bathrooms

Bathrooms and Adjacent

Corridors and Classroom

201

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
041	Drywall compound	6300	SF	1st, 2nd & 3rd Floor Bathrooms and Adjacent Corridors and Classroom 201		Miscellaneous	No	None	0	SF	YES X NO
2023 Spring	Six Month Survey: No	Change									

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
042	Ceramic floor tile grout	1700	SF	Bathrooms		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

043	Ceramic floor tile adhesive	1700	SF	Bathrooms		Miscellaneous	No	None	0	SF	YES	X NO
2023 Spring	Six Month Survey: No	Change]							
Comments:					1							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:					=							
2024 Spring	Six Month Survey: No	Change										
Comments:					 							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

SF

5700

HA No

044

Material Description

Ceramic eall tile grout

Material

Units

SF

Material Quantity

Material Location

Bathrooms, Kitchen,

Cafeteria, West-Jackson

Street Entrance Foyer

Change in Assessment Category

X NO

YES

045	Ceramic wall tile adhesive	5700	SF	Bathrooms, Kitchen, Cafeteria, West-Jackson Street Entrance Foyer		Miscellaneous	No	None	0	SF	YES	X NO
2023 Spring	Six Month Survey: No	Change	•	<u> </u>]							
Comments:		_]							
2023 Fall Six	Month Survey: No Ch	ange										
Comments:					-							
	Month Survey: No Ch	ange			1							
Comments:					-							
	Six Month Survey: No	Change			-							
Comments:					-							
L					1							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Bathrooms, Kitchen,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
046	Ceramic floor tile grout	900	SF	West- Jackson Street Entrance Foyer		Miscellaneous	No	None	0	SF	YES	X NO
2023 Spring Six Month Survey: No Change Comments:												

2023 Fall Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

047	Ceramic floor tile adhesive	900	SF	West- Jackson Street Entrance Foyer		Miscellaneous	No	None	0	SF	YES	X NO
					İ							
2023 Spring \$	Six Month Survey: No	Change										
Comments:	Comments:											
2023 Fall Six	Month Survey: No Cha	ange										
Comments:												
2024 Fall Six	Month Survey: No Cha	ango										
	World Survey. No Ch	arige										
Comments:												
2024 Caring (Civ. Month Cumrour No.	Changa										
	Six Month Survey: No	Change										
Comments:												

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
048	Block window grout	500	LF	Gym Wing		Miscellaneous	No	None	0	LF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
049	Block window caulk	300	LF	Gym Wing		Miscellaneous	No	None	0	LF	YES	X NO
2023 Spring Comments:	Six Month Survey: No	Change										
2023 Fall Six Comments:	k Month Survey: No Ch	nange										
2024 Fall Six Comments:	Month Survey: No Ch	nange			<u>-</u> 							
2024 Spring	Six Month Survey: No	Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
050	Insulation	32	SF	Above Pan Ceiling in Hall By Gym Entrance		TSI	Yes	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

Page 26

		Quantity	Units		Туре	Category		Type	Quantity	Units		
052	Aircell pipe insulation	1000	LF	Basements		TSI	Yes	None	0	LF	YES	X NO
					1							
2023 Spring 8	Six Month Survey: No	Change										
Comments:												
2023 Fall Six	Month Survey: No Cha	ange										
Comments:												

Material

Friable

Damage

Damage

2024 Fall Six Month Survey: No Change Comments:

Material

Material Location

2024 Spring Six Month Survey: No Change

Material Description

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
053	Joint Insulation on Aircell Insulated Piping	100	LF	Basements		TSI	Yes	None	0	LF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
054	Cardboard pipe insulation	7	LF	Gym Storage Room		TSI	Yes	None	0	LF	YES	X NO
2023 Spring	Six Month Survey: No	Change										

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
055	Joint Insulation on Cardboard Insulated Piping	2	LF	Gym Storage Room		TSI	Yes	None	0	LF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
056	Joint Insulation on Fiberglass Insulated Piping	100	LF	Throughout Building in Unexposed Areas		TSI	Yes	None	0	LF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
057	Insulation Inside of Fire Doors	10	EA	Throughout Facility		TSI	Yes	None	0	EA	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
058	Plumbers tape pipe insulation	6	LF	Slop Sink Room		TSI	No	None	0	LF	YES	X NO
2023 Spring Six Month Survey: No Change												

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
059	Elevator brake shoes	3	SF	Elevator Brake Shoes		Miscellaneous	No	None	0	SF	YES X NO	

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

060	Adhesive Beneath Poster Boards and Marker Boards	1000	SF	Throughout Facility	Miscellaneous	No	None	0	SF	YES	X NO
2023 Spring	Six Month Survey: No	Change									
Comments:	SIX MONTH Carvey: 140	Onlange									
Comments.											
2023 Fall Six	Month Survey: No Cha	ange									
Comments:	•	Ĭ									
2024 Spring	Six Month Survey: No	Change									
Comments:											
2024 Fall Six	Month Survey: No Cha	ange									
Comments:	•										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
061	Door caulk	120	LF	Throughout Facility		Miscellaneous	No	None	0	LF	YES	X NO
2023 Sprir Comments	ng Six Month Survey: No s:	Change										
2023 Fall \$	Six Month Survey: No Cl											

Comments:

2024 Spring Six Month Survey: No Change
Comments:

2024 Fall Six Month Survey: No Change

HA No

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

Change in Assessment Category

Damage

Units

		1								1		
62	Gray white black terrazzo flooring	12000	SF	1st, 2nd, 3rd Floor Halls, Stairways and Landings		Miscellaneous	No	None	0	SF	YES	X NO
					1	•						
2023 Fall Six	Month Survey: No Cha	ange										
Comments:		•										
Commonto.												
2022 Carina	Six Month Curvey No.	Changa										
2023 Spring 3	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Cha	ange										
Comments:	,											
Comments.												
2024 Spring S	Six Month Survey: No	Change										
Less : Opining (Six ivioriai Survey. 140	onange			1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Green black white terrazzo flooring	8000	SF	Cafeteria		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	White gray orange terrazzo floor	200	SF	Cafeteria		Miscellaneous	No	None	0	SF	YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Oracle Unit: 66151

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Alain Locke Charter School
Date: 12/6/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.