Chicago Public Schools

Namaste Charter School

School:

Comments:

6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Oracle Unit:

66271

Address: 3737 S. Paulina Street Region: 02 Mail Room: 39 Asbestos Surveyor: Aleman, Rosie X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/13/2025 raleman@namastechart Email Address: erschool.org A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other HA No Material Description Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Quantity Units Type Metal Deck of 2009 X NO 01 Spray-on fireproofing YES Surface Addition 2024 Fall Six Month Survey: No Change Comments: HA No Material Description Material Material Location Material Change in Assessment Category Material **Asbestos** Friable Damage Damage Damage Quantity Units Type Category Type Quantity Units **Throughout Original** 02 X NO YES Plaster walls Surface Building 2024 Fall Six Month Survey: No Change

6530

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
03	Plaster ceiling			Throughout Original Building		Surface					YES	X NO
2024 Fall S	ix Month Survey: No Ch	ange										
Comments:	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
04	Drywall, Tape and Joint Compound			Throughout 2009 Addition		Miscellaneous					YES	X NO
2024 Fall S	ix Month Survey: No Ch	ange										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
05	12" x 12" Light Gray Tones Mottled Floor Tile	4150	SF	Hallways and Lobby		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall S	ix Month Survey: No Ch	ange										
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
06	12" x 12" Light Gray Tones Mottled Floor Tile Mastic	4150	SF	Hallways and Lobby		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall S	ix Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
07	12" x 12" Medium Gray Tones Mottled Floor Tile	850	SF	Stairwell Landings		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	•	<u> </u>										
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
08	12" x 12" Medium Gray Tones Mottled Floor Tile Mastic	850	SF	Stairwell Landings		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	•	Ŭ										
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
09	12" x 12" Dark Blue Tones Mottled Floor Tile	775	SF	Pantry, Work Area, Copy Room Learning Room		Miscellaneous	No	Loc	1	SF	YES	X NO
2024 Fall Six	Month Survey: No Ch	ange]							
Comments:		y -										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
10	12" x 12" Dark Blue Tones Mottled Floor Tile Mastic	475	SF	Pantry, Work Area, Copy Room		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Six	Month Survey: No Ch	ange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	nt Category
11	12" x 12" Blue Gray Tones Mottled Floor Tile	570	SF	Servery		Miscellaneous	No	None	0	SF	YES		X NO
2024 Fall Six	Month Survey: No Ch	ange											
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	nt Category
12	12" x 12" Blue/Gray Tones Mottled Floor Tile Mastic			Servery		Miscellaneous					YES		X NO
2024 Fall Six	Month Survey: No Ch	ange											
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	nt Category
13	12" x 12" Green Tones Mottled Floor Tile	450	SF	Teachers Resource Room 019		Miscellaneous	No	None	0	SF	YES		X NO
2024 Fall Six	Month Survey: No Ch	ange											
Comments:	•												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	nt Category
14	12" x 12" Green Tones Mottled Floor Tile Mastic	450	SF	Teachers Resource Room 019		Miscellaneous	No	None	0	SF	YES		X NO
2024 Fall Six	Month Survey: No Ch	ange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
15	Wood pattern roll out vinyl sheeting	4375	SF	3rd Floor Gym, 1st Floor Fitness Center		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si	x Month Survey: No Ch	ange			7							
Comments:	•	•			1							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
16	Wood pattern roll out vinyl sheeting mastic	4375	SF	3rd Floor Gym, 1st Floor Fitness Center		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si	x Month Survey: No Ch	ange			7							
Comments:	•	•										
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
17	9"x 9" floor tile	900	SF	Church		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si	x Month Survey: No Ch	ange			7							
Comments:		J-										
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
18	Old 9" x 9" Floor Tile Mastic Under Carpet	3900	SF	Classrooms and Closets rooms - 101, 102, 103, 104, 105		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si	x Month Survey: No Ch	ange			7							

Г		T		T	1 -	F	1	1 -	_	_	T	_
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
19	Old 9" x 9" Floor Tile Under Carpet	3900	SF	Classrooms and Closets rooms - 201, 202, 204, 205		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si	ix Month Survey: No Ch	ange										
Comments:		J										
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
20	Old 9" x 9" Floor Tile Mastic Under Carpet	3900	SF	Classrooms and Closets rooms - 201, 202, 204, 205		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si Comments:	ix Month Survey: No Ch	ange			_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
21	Green terrazzo flooring	5000	SF	Hallways and Bathrooms, 203		Miscellaneous	No	None	0	SF	YES	X NO
	ix Month Survey: No Ch	ange										
Comments:]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
22	Black terrazzo flooring	1500	SF	Hallways, Stairways, Bathrooms, 203		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si	ix Month Survey: No Ch	ange		•]	•	•	•	•	•		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
23	2" x 2" Dark Gray Ceramic Tile Grout	700	SF	Boys/Girls Bathrooms Baseemnt and 3rd Floor edging		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Six	Month Survey: No Ch	ange		•	7							
Comments:	World Sarvey. No on	ungo										
	Tara da la	T	T		T		1 =		1_	T		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
24	Gey/white/black epoxy flooring			Lunch Room		Miscellaneous					YES	X NO
2024 Fall Six	Month Survey: No Ch	ange			7							
Comments:	Month Survey. No On	ange			=							
	<u> </u>	_		.							T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
25	Mastic under beige carpet	3100	SF	Offices		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Six	Month Survey: No Ch	ange			1							
Comments:	Month Survey. No On	ange			=							
	<u> </u>	_		.							T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
26	Mastic Under Brown w/ Purple Carpet	4300	SF	Rooms 106, 206, 207, 208, 209, 304, 304, Library, Library Office, 303		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Six	Month Survey: No Ch	ange			7							
Comments:		- J-			1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
27	Gray/dark blue carpet squares mastic	2450	SF	Rooms - 102, 104, 105, 202, 201, 205		Miscellaneous	No	Loc	1	SF	YES	X NO
2024 Fall S	Six Month Survey: No Ch	nange										
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
28	Gray/maroon carpet squares mastic	1100	SF	Rooms 101, 103, 204, 302, 108		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall S	Six Month Survey: No Ch	nange										
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
29	Mastic under gray carpet	640	SF	Room 301		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall S	Six Month Survey: No Ch	nange										
Comments	•	<u> </u>										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
30	Gray vinyl baseboard			Throughout 2009 Addition		Miscellaneous					YES	X NO
2024 Fall S	Six Month Survey: No Ch	nange		<u> </u>	7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
31	Gray vinyl baseboard mastic	2750	LF	Throughout 2009 Addition		Miscellaneous	No	None	0	LF	YES	X NO
2024 Fall S	ix Month Survey: No Ch	ange			\neg							
Comments:		g -										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
32	Tan vinyl baseboard			Teachers Resource Room 019		Miscellaneous					YES	X NO
2024 Fall S	ix Month Survey: No Ch	ange										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
33	Tan vinyl baseboard mastic	100	LF	Teachers Resource Room 019		Miscellaneous	No	None	0	LF	YES	X NO
2024 Fall S	ix Month Survey: No Ch	ange										
Comments:		arigo										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
34	Black vinyl baseboard	100	LF	Servery		Miscellaneous	No	None	0	LF	YES	X NO
2024 Fall Si	ix Month Survey: No Ch	ange	1	1		l	1	1	l	- I	<u>I</u>	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
35	Black vinyl baseboard mastic	100	LF	Servery		Miscellaneous	No	None	0	LF	YES	X NO
2024 Fall S	Six Month Survey: No Cl	hange										
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
36	12" x 12" Purple Tones Mottled Floor Tile	325	SF	Parent Resource Room 027		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall S	Six Month Survey: No Cl	hange										
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37	12" x 12" Purple Tones Mottled Floor Tile Mastic	325	SF	Parent Resource Room 027		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall S	Six Month Survey: No Cl	hange										
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
38	Canvas wall covering		SF	Room 301		Miscellaneous				SF	YES	X NO
2024 Fall S	Six Month Survey: No Cl	hange				.	•	•	•	•		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
39	Red caulking material			Throughout Building		Miscellaneous					YES	X NO
2024 Fall Six	Month Survey: No Cl	nange										
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
40	Sink caulk			Bathrooms		Miscellaneous					YES	X NO
2024 Fall Six	Month Survey: No Cl	nange								•		
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
41	Fire doors	15	EA	Mechanical Areas, Kitchen		Miscellaneous	No	None	0	EA	YES	X NO
2024 Fall Six	Month Survey: No Cl	nange										
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
42	Fire door frames	15	EA	Mechanical Areas		Miscellaneous	No	None	0	EA	YES	X NO
2024 Fall Six	Month Survey: No Cl	nange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessn	nent Category
43	White ceramic wall tile grout	1300	SF	Basement and 3rd floor Bathrooms		Miscellaneous	No	None	0	SF	YES		X NO
2024 Fall S	ix Month Survey: No Ch	ange											
Comments:		arige											
HA No	Material Description	Matarial	Matarial	Material Leasting	A sharter	Matarial	Frield		Damana	Damana	Channa in A		t O - t
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessii	nent Category
44	Blue ceramic wall tiles grout	2400	SF	1st and 2nd Floor Bathrooms		Miscellaneous	No	None	0	SF	YES		X NO
2024 Fall S	ix Month Survey: No Ch	ange			7								
Comments:		arigo											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domoso	Domoso	Domoseo	Change in A		nont Cotogomi
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessii	nent Category
45	Blue ceramic wall tile grout	1000	SF	1st, 2nd and 3rd Floor Hallways in Original Building		Miscellaneous	No	None	0	SF	YES		X NO
2024 Fall S	ix Month Survey: No Ch	ange			7								
Comments:		<u>go</u>											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	coccn	nent Category
TIANO	Material Description	Quantity	Units	Waterial Location	Type	Category	Thable	Type	Quantity	Units	Change in A	3363311	ient Category
46	Elevator brake pads	1	EA	Elevator Mechanical		Miscellaneous	No	None	0	EA	YES		X NO
2024 Fall S	ix Month Survey: No Ch	ange			7								
Comments:		۵. igo											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
48	2' x 4' White Textured Ceiling Tile			Throughout 2009 Addition, Hallways, Rooms 202 &203		Miscellaneous					YES	X NO
2024 Fall 9	Six Month Survey: No Ch	ange										
Comments		ango										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
49	1' x 1' Small Holes Ceiling Tile (Spline System)			Servery		Miscellaneous					YES	X NO
2024 Fall S	Six Month Survey: No Ch	ange										
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
50	Gray vinyl stair tread	1400	SF	Stairs		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall 9	Six Month Survey: No Ch	ange										
Comments		ugu										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
51	Gray vinyl stair tread mastic	1400	SF	Stairs		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall 9	Six Month Survey: No Ch	ange	1	1		<u>I</u>				<u>l</u>	I	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
52	Ceramic Wall tile	600	SF	East Stairwell		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si	x Month Survey: No C	hange										
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
53	Leveling compound	20	SF	Basement Hallway outside Parent Center		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si Comments:	x Month Survey: No C	hange										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
54	Duct sealant	40	SF	Third Floor Hallway and Gross Motor Room		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si	x Month Survey: No C	hange			7							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
55	Brown carpet	2000	SF	Room 025, Room 023, Room 022, Office #1, Office #2, Office #6, Office #3, Office #4, Conference Room, Meeting Room		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall Si	x Month Survey: No C	hange			7							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
56	Brown carpet mastic	2000	SF	Room 025, Room 023, Room 022, Office #1, Office #2, Office #6, Office #3, Office #4, Conference Room, Meeting Room		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall S	ix Month Survey: No C	hange			7							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
57	12" x 12" White w/ Blue Streaks Floor Tile	250	SF	Office #5		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall S	ix Month Survey: No C	hange]							
Comments:	,	J										
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
58	12" x 12" White w/ Blue Streaks Floor Tile Mastic	250	SF	Office #5		Miscellaneous	No	None	0	SF	YES	X NO
2024 Fall S	ix Month Survey: No C	hange			7							
Comments:		y -]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
T1	Aircell pipe insulation	20	LF	East Stairs At Basement Level		TSI	Yes	None	0	LF	YES	X NO
2024 Fall S	ix Month Survey: No C	hange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T2	2" Cardboard pipe insulation	35	LF	Lunch Room (Above Drop Ceiling on Southeast Side)		TSI	Yes	None	0	LF	YES X NO
2024 Fall S	Six Month Survey: No Ch	nange		<u> </u>]						
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Т3	6" Cardboard pipe insulation	1000	LF	Basement West Hallway (Above Drop Ceiling), Pipe Chases (assumed)		TSI	Yes	None	0	LF	YES X NO
2024 Fall S	Six Month Survey: No Ch	nange			1						
Comments:											
]						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
T4	Hard Fittings on 6" Cardboard Pipe Insulation	100	LF	Basement West Hallway (above drop ceiling), Pipe Chases (assumed)		Miscellaneous	Yes	None	0	LF	YES X NO
2024 Fall S	Six Month Survey: No Ch	nange]						

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Namaste Charter School
Date: 12/5/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 66271

SCHOOL'S ASBESTOS MANAGEMENT PLAN.