## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2024 Fall Six Month Survey

Erie Elementary Charter School 66331 7510 School: **Oracle Unit: Building ID:** Address: 1405 N. Washtenaw Region: 02 Mail Room: Asbestos Surveyor: **VSAHABI** X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/2/2024 Email Address: vsahabi@cps.edu A copy of the 2022/2023 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 1' x 1' Decorative Ceiling YES 001 X NO School Foyer Miscellaneous 2022 Fall Six Month Survey: No Change Comments: 2023 Fall Six Month Survey: No Change Comments: 2023 Spring Six Month Survey: No Change Comments: 2024 Spring Six Month Survey: No Change Comments: 2024 Fall Six Month Survey: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
002	1'x1' Fissured Ceiling Tile			School Foyer		Miscellaneous					YES	X NO
2022 Fall Six	Month Survey: No Ch	ange										
Comments:	•	•										
2023 Fall Six	Month Survey: No Ch	ange										
Comments:												
2023 Spring	Six Month Survey: No	Change										
Comments:												
2024 Spring	Six Month Survey: No	Change										
Comments:												
2024 Fall Six	Month Survey: No Ch	ange										
Comments:	_											
_												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
003	1'x1' Decorative/Fissured Ceiling Tile Adhesive			School Foyer		TSI					YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
004	2'x4' Fissured Lay In Ceiling Panels			School Multi-Purpose Room		Miscellaneous					YES	X NO
2022 Fall Six Comments:	Month Survey: No Ch	nange										
2023 Fall Six Comments:	Month Survey: No Ch	nange										
2023 Spring Comments:	Six Month Survey: No	Change										
2024 Spring Comments:	Six Month Survey: No	Change										
2024 Fall Six Comments:	Month Survey: No Ch	nange										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
005	9"x9" Gray Floor Tile	500	SF	Classrooms 207, 301, 303, 307, 3rd Floor Lounge		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006	9"x9" Gray Floor Tile Mastic	500	SF	Classrooms 207, 301, 303, 307, 3rd Floor Lounge		Miscellaneous	No	None	0		YES X NO
									-		

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
007	9"x9" Green Floor Tile	1500	SF	Main Office and Room 308		Miscellaneous	No	None	0		YES X NO

2022 Fall Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2023 Spring Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
800	9"x9" Green Floor Tile Mastic	1500	SF	Main Office and Room 308		Miscellaneous	No	None	0		YES	X NO
2023 Spring	Six Month Survey: No	Change										
Comments:	•											
2023 Fall Siz	x Month Survey: No Ch	ange										
Comments:												
2024 Fall Siz	x Month Survey: No Ch	ange										
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
009	9"x9" Brown w/Brown and White Streaks Floor Tile	14950	SF	Throughout Classrooms		Miscellaneous	No	None	0		YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Comments:

2024 Spring Six Month Survey: No Change

010	9"x9" Brown w/Brown and White Streaks Floor Tile Mastic	15350	SF	Throughout Classrooms		Miscellaneous	No	None	0	YES	X NO
	•	•	•		1	•	<del>-</del>	·	•		
2023 Spring S	Six Month Survey: No	Change									
Comments:											
2023 Fall Six	Month Survey: No Ch	ange									
Comments:											
2024 Fall Six	Month Survey: No Ch	ange									
	World Survey. No Cri	arige									
Comments:											
22212		<u> </u>									
2024 Spring S	Six Month Survey: No	Change									
Comments:											
					1						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
011	12"x12" Brown Designed Floor Tile	400	SF	Space Behind Stage		Miscellaneous	No	None	0		YES X NO
2022 Spring 9	Six Month Survey: No.	Chango				_					

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

012	12"x12" Brown Designed Floor Tile Mastic	1800	SF	Space Behind Satge		Miscellaneous	No	None	0		YES	X NO
2023 Sprin	g Six Month Survey: No	Change										
Comments	<u> </u>											
2023 Fall S	Six Month Survey: No Ch	ange										
Comments	:	•										
2024 Fall S	Six Month Survey: No Ch	ange										
Comments												
2024 Sprin	g Six Month Survey: No	Change										
Comments												
HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units	Boy's and Girl's	Туре	Category		Туре	Quantity	Units		
013	Brown and White Terrazzo	2530	SF	Washrooms, First Floor Teacher's Washroom and		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Slop Sink Room,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
014	Black with White and Green Terrazzo	8900	SF	Basement Lunchroom, Kitchen, Sorage Room, School Stainways, Corridors, Girl's and Boy's Washrooms, Teacher's Washrooms, Slop Sink Rooms, Entry Foyer		Miscellaneous	No	None	0		YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
015	Green Terrazzo	160	SF	Entry Foyer		Miscellaneous	No	None	0		YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

016	Paneling	900	SF	All Purpose Room		Miscellaneous	NO	None	0		YES	X NO
2023 Spring	Six Month Survey: No	Change			1							
Comments:					<b>=</b> 							
2023 Fall Si	x Month Survey: No Ch	nange			-							
Comments:					1 -							
2024 Fall Si	x Month Survey: No Ch	nange			_							
Comments:												
2024 Spring	Six Month Survey: No	Change			_							
Comments:					-							
					J							
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

				_
2023 Spring Six	Month Survey: No	Change		
Comments:				
2023 Fall Six M	onth Survey: No Cha	ange		
Comments:				
2024 Fall Six M	onth Survey: No Cha	ange		
Comments:				
2024 Spring Six	Month Survey: No	Change		
Comments:		-		

Quantity

70

Units

LF

Material

Quantity

900

Material

Units

SF

Material Location

All Purpose Room

Area Behind Stage

HA No

016

017

Material Description

Adhesive Beneath Wood

4" Brown Baseboard

Change in Assessment Category

X NO

X NO

YES

YES

018	Adhesive	70	LF	Area Behind Stage		Miscellaneous	No	None	0	YES	X NO
000000	0: 14 (1.0	01			1						
2023 Spring	Six Month Survey: No	Change									
Comments:											
2023 Fall Si	x Month Survey: No C	hange									
Comments:											
2024 Fall Si	x Month Survey: No C	hange									
Comments:											
2024 Spring	Six Month Survey: No	Change									
Comments:					1						

Type

Material

Category

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
019	Door Caulk	900	LF	Classrooms and Office Doors Throughout Facility		Miscellaneous	No	None	0		YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

020	Insulation on Roof Drain Piping	25	LF	Third Floor Lounge		TSI	Yes	None	0		YES	X NO
2023 Spring	Six Month Survey: No	Change			1							
Comments:	,	J										
2023 Fall Si	x Month Survey: No Ch	nange			1							
Comments:	,	<u> </u>			]							
2024 Fall Si	x Month Survey: No Ch	nange			1							
Comments:												
2024 Spring	Six Month Survey: No	Change			-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Surface

Friable

Yes

None

0

Damage

Type

Damage

Quantity

Damage

Units

			ROOM
2023 Spring	Six Month Survey: No	Change	
Comments:			
2023 Fall S	x Month Survey: No Cha	ange	
Comments:			
2024 Fall S	x Month Survey: No Cha	ange	
Comments:			
2024 Spring	Six Month Survey: No	Change	
Comments:			
			•

6

SF

HA No

021

Material Description

Pipe Joint Fittings on Fiberglass Pipe Insulation

Material

Quantity

Material

Units

Material Location

Throughout Facility in

Pipe Chases and Maintenance Storage

YES

X NO

022	Breaching Insulation Adhesive	20	LF	Boiler Room		TSI	Yes	None	0	YES	X NO
2023 Spring S Comments:	Six Month Survey: No	Change									
2023 Fall Six Comments:	Month Survey: No Ch	nange									
2024 Fall Six Comments:	Month Survey: No Cl	nange			-						
2024 Spring S Comments:	Six Month Survey: No	Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
023	Hard Plaster Ceiling	12000	SF	Throughout School Facility in Washrooms, Stairways, Slop Sink Rooms, Kitchen, Basement Storage and Third Floor Lounge		Surface	Yes	None	0		YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2023 Fall Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:
2024 Spring Six Month Survey: No Change
Comments:

HA No

Material Description

Breaching Insulation

Material

Quantity

Material

Units

024	Boiler Gasket	20	LF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2023 Sprin	g Six Month Survey: No	Change			]							
Comments	:				]							
2023 Fall S	ix Month Survey: No Ch	nange			_							
Comments	:				-							
	g Six Month Survey: No	Change										
Comments	:				_							
2024 Fall S	ix Month Survey: No Ch	nange										
Comments												
					┙							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

			_	
2023 Fall Six	Month Survey: No Cha	ange		
Comments:				
2023 Spring	Six Month Survey: No	Change		
Comments:				
2024 Spring	Six Month Survey: No	Change		
Comments:				
2024 Fall Six	Month Survey: No Cha	ange		
Comments:			•	

Quantity

400

Units

SF

HA No

025

Material Description

Carpet Adhesive

Material

Quantity

Material

Units

Material Location

Multi-Purpose Room

Stage

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
026	Acoustical Ceiling Plaster	7000	SF	Classrooms and Corridor, lunchroom/multipurpose room, stairwell ceilngs		Surface	Yes	None	0		YES	X NO
2023 Spring	Six Month Survey: No	Change										
Comments:	OIX WORLT GUIVEY. NO	Orlange			-							
	Month Survey: No Ch	nange										
Comments:					-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessme	nt Category
11/(140	Waterial Description	Quantity	Units	Waterial Education	Type	Category	THADIO	Type	Quantity	Units	Change in 7 toocoome	in oatogory
027	2' x 2' Textured Ceiling Tiles	7850	SF	1st, 2nd, and 3rd Floor Hallways, Rooms 109, 113-118, Main Lobby G14 and G10		Miscellaneous	Yes	None	0		YES	X NO
2023 Spring	Six Month Survey: No	Change			]							
Comments:	Circ Worker Carvoy: 110	Change										
	Month Survey: No Ch	nange			-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
028	Drywall	10000	SF	Throughout New Addition		Miscellaneous	No	None	0		YES	X NO
2023 Spring	Six Month Survey: No	Change			 ]							
Comments:	OIA MOHILI SULVEY. INO	Change										
Commonto.					1							

2024 Fall Six Month Survey: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
029	Drywall Compound	2000	LF	Throughout New Addition		Miscellaneous	No	None	0		YES	X NO
2023 Sprin	g Six Month Survey: No	Change			1							
Comments		•										
2024 Fall C	Six Manth Common No Ch											
Comments	Six Month Survey: No Ch	ange										
Comments	·											
					<del>-</del>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
030	12" x 12" White, Red, Blue, and Yellow Pattern Floor Tile	2000	SF	1st, 2nd, 3rd, Floor Hallways, and Main Lobby		Miscellaneous	No	None	0		YES	X NO
2023 Sprin	g Six Month Survey: No	Change			]							
Comments		Change										
	Six Month Survey: No Ch	ange										
Comments	:											
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
031	Mastic Associated w/ 12" x 12" White, Red, Blue, and Yellow Pattern Floor Tile	2000	SF	1st, 2nd, 3rd, Floor Hallways, and Main Lobby		Miscellaneous	No	None	0		YES	X NO
2023 Sprin	g Six Month Survey: No	Change			7							
Comments	<u> </u>	Change										
	Six Month Survey: No Ch	ange										
Comments	:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
032	Yellow Carpet Mastic	2500	SF	Room 113, 114, G16, G12, G10, G09, G14		Miscellaneous	No	None	0		YES X NO

2023 Spring Six Month Survey: No Change
Comments:
2024 Fall Six Month Survey: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Richard J.Schleyer

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Erie Elementary Charter School
Date: 12/6/2024
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2022. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.